UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Baiada Beresfield	**Date:**	30 December 2025
Site Address:		**Site Contact:**	Dale Hunt
		Phone:	0428100594
Customer PO #:		**Internal Job #:**	5903

Subject: Vacuum and sealing issues

Equipment Type:	Serial Number:	Customer Line # (if applicable):
TRAVE 590	A/21/A-12636	Value added

Equipment condition:

Work Performed:

TRAVE 590
A/21/A-12636

Arrived on site at 14:00. Ha d to find out what was wrong with the machine and what had been done to the machine. Sealing issues was reported together with concaved trays and a unbalanced cycle.

It was reported that there were water issues in the air lines.

- *I started with a vacuum cycle and there was a banging noise once the tool opened.*
- *I had a look at the pneumatic cards and saw that the bottom vacuum valve condition had been changed to an open position.*
- *I reset the condition on card no bottom vacuum.*
- *The override button was sticky and release slowly.*
- *I made a call to replace the vacuum valve card and the compensation valve card*
- *Machine was powered down and the valve bank was opened up*
- *The whole air valve bank was full of water due to water in the air system.*
- *The banks were dried out and assembled*
- *The pneumatic oil holder was removed it was filled up with water.*
- *The water was removed but I could not find oil for the air system*
- *Water was removed from the air system*
- *The machine was powered up and tested*
- *Product was put through the machine*
- *There was a couple of trays that did not sealed but contamination was also present*
- *The upper air delay was increase to 0.15 seconds*
- *Trays was wiped cleaned*
- *10 cycles were put through the machine with all trays sealing*

GENERAL SERVICE REPORT

- *I did not find any imbalance in the tool*
- *The valve bank will have to replaced as the one phasor is not working and this is a new card, due to water damage.*
- *The air system has been contaminated, and the valves can become sticky*
- *The pneumatic holder needs to be filled up with oil*

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☒	No☐
Comments: Good		
Revisit Required?	Yes☐	No☐
Comments:		

RECOMMENDATIONS
Comments:

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	**Henry Nieuwenhuis**	
Time	**Start**	**Finish**
Travel To Site:	11:30	14:00
Onsite:	14:00	19:00
Travel From Site:	19:00	21:30
Remote assistance:		
Report writing:	30 mins	
Overnight stay	☐	
Overnight stay with flights	☐	

TECHNICIAN HOURS		
Time	**Start**	**Finish**
Travel To Site:		
Onsite:		
Travel From Site:		
Remote assistance:		
Report writing:		
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	30/12/2025
Technician:	Henry Nieuwenhuis		