UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Hilton Food Australia	**Date:**	04/09/2025
Site Address:	22 Seeana place Heathwood QLD 4110	**Site Contact:**	Niyomy Rasanayagam
		Phone:	0425400020
Customer PO #:		**Internal Job #:**	5676

Subject: Line 14–16–18 (BU2) Infeed issue

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590 XL	A18A-11947	Line 18

Equipment condition:

Work Performed:

- Follow-Up Visit (Lines 18, 16, 14)**

Line 18

- After discussion with the production team, it was agreed to target a stable speed of 112 ppm.
- With the improvements made the previous day, only a few fine-tuning tasks were required:

- Adjustment of the denester magazine, which was occasionally dropping two trays. This was traced to an incorrect air connection on the tray stack holding blocks. The reversed connection created excess pressure on the last two trays, preventing proper separation.
- Re-adjustment of the infeed stoppers.
- Following these adjustments, the line ran reliably for an extended period at 112 ppm.
- The line requires an **urgent overhaul**, as many components are either broken or heavily deteriorated.

Line 16

- The line was running MAP paper trays.
- A critical issue was identified, as also noted by the operator: the back stopper cylinder on side 1 was intermittently getting stuck in the closed position.

- The cylinder must be replaced.
- Additionally, the line requires an **urgent overhaul**, as many components are either broken or heavily deteriorated.

GENERAL SERVICE REPORT

- Adjustments were also made to improve tray positioning on the spacer belts and tray delivery under the tool, which were slightly misaligned.

Line 14

- Jacques focused on line 14. Due to an internal issue, the line was operating with only one Vemag, resulting in a significantly reduced feed speed.
- As per the other two lines this one also requires an **urgent overhaul**, as many components are either broken or heavily deteriorated like the pusher arms system

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

STATUS		
Machine Tested?	Yes☒	No☐
Comments: Good		
Revisit Required?	Yes☐	No☐
Comments:		

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	Paolo	
Time	**Start**	**Finish**
Travel To Site:	10:00	11:00
Onsite:	11:00	13:00
Travel From Site:	13:00	14:00
Remote assistance:	0	
Report writing:	30 Min	
Overnight stay	☐	
Overnight stay with flights	☐	

TECHNICIAN HOURS	Jacques	
Time	**Start**	**Finish**
Travel To Site:	10:00	11:00
Onsite:	11:00	13:00
Travel From Site:	13:00	14:00
Remote assistance:	0	
Report writing:	0	
Overnight stay	☐	
Overnight stay with flights	☐	

GENERAL SERVICE REPORT

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Niyomy Rasanayagam	X _____	04/09/2025
Technician:	Gianpaolo Orisio		