UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Huon Aquaculture	**Date:**	19/02/2026
Site Address:	7218 Bass Highway East SASSAFRAS Tasmania	**Site Contact:**	Anthony
		Phone:	0428776039
Customer PO #:		**Internal Job #:**	6011

Subject: PLC Fault and Pusher arm fault

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 340	A/14/A-00912	Skin Line

Equipment condition:

Work Performed:

- Travelled to site and met with Chris.
- Went to line and inspected water traps before production started. Both water traps were still empty.
- Also went through the alarm history to check if there were any PLC power supply alarms again after I changed the card that might have happened during the night. There were no new alarms.
- Production started running product. Monitored line for 5 hours' worth of production producing +- 3000 units.
- The line ran well with minimal reworks do to film popping. The new seal bars and fixing the knife made a huge improvement.
- Did not have any issue with pusher arms during the run.
- Did not have any PLC power supply alarms again.
- After 4 hours of production I stopped the line and drained out water traps to see how much water we have accumulated. Outside trap was basically empty with +- 20ml of water in the trap on the air service unit.
- Please not although there was not too much water build up in the 4 hours, it is still very easy to see that the air has a lot of moisture in it. The outside water trap has misty haze to it.
- I recommend that the water traps are emptied out at lease ones a day before production and we keep on managing the issue until the new air drier is on site.
- Installed the faulty power supply card back in to the spare Mondini.
- Will request quote on x2 new power supply and connection cards.
- Will also request a quote on a complete valve bank. Recommend that complete unit is swapped out when the new air drier is installed and air quality back to normal, just to prevent future down time as the current cards are exposed to moisture and might fail at a later stage.
- Left site and travel back to SA

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

STATUS

TECHNICIAN HOURS	David van der Merwe	
Time	**Start**	**Finish**
Travel To Site:	5:00	5:30
Onsite:	5:30	11:00
Travel From Site:	11:00	17:45
Remote assistance:		
Report writing: (20/02/2026)	13:30	14:00
Overnight stay	☐	
Overnight stay with flights	☒	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Anthony	X	19/02/2026
Technician:	David		