

# DATACOM



**DmOS**

DATACOM OPERATING SYSTEM

Version 12.4.0

RELEASE NOTES

204.4295.98 - July 14, 2026

## Contacts

### Technical Support

Datacom has available a support portal - DmSupport, to help the customers in use and config of our equipment.

Access to the DmSupport can be made through link: <https://supportcenter.datacom.com.br>

In this site the following are available: firmwares, technical datasheets, config guide, MIBs and manuals for download. In addition, it allows opening of calls for assistance with our technical team.

Telephone Number: **+55 51 3933-3122**

We would like to highlight that our assistance through telephone support is available from Monday through Friday from 08:00 AM through 05:30 PM.

**Important:** For support assistance 24x7, please request a quotation to our sales department.

### General Information

For any other additional information, please visit the <https://www.datacom.com.br/en> or call:

**DATAKOM**

**Rua América, 1000**

**92990-000 - Eldorado do Sul - RS - Brazil**

**+55 51 3933-3000**

## Product Documentation

This document is part of a set of documents prepared to provide all necessary information about DATACOM products.

### Software Platform

- **Quick Configuration Guide** - Provides instructions on how to set functionalities in a quick manner in the equipment
- **Troubleshooting Guide** - Provides instructions on how to analyze, identify and solve problems with the product
- **Command Reference** - Provides all the commands related to the product
- **Release Notes** - Provides instructions on the new functionalities, identified defects and compatibilities between Software and Hardware

### Hardware Platform

- **Datasheet** - Provides the Hardware and Software technical characteristics of product
- **Installation Guide** - Provides instructions on the procedures covering product installation

The availability of some documents can vary depending on the type of product.

Access <https://supportcenter.datacom.com.br> to locate the related documents or contact the Technical Support for additional information.



## Introduction to the document

### About this Document

This report provides information regarding a new software release version for DmOS product. The Release Notes also intends to inform relevant changes that have occurred in software, hardware and documentation.

It is assumed the reader is familiar with network protocols concepts and has previous knowledge about DmOS products.

### Audience

This document is intended for Network Administrators, Engineers and any other qualified service personnel who are responsible for configuring and maintaining networks deployed with DmOS.

### Text Convention

This report uses these text conventions to convey instructions and information:

| Convention            | Description                                                                                                                  |
|-----------------------|------------------------------------------------------------------------------------------------------------------------------|
| Hyperlink             | Internet site or an e-mail address. It is also applied to indicate a local link inside the document itself (e.g. a chapter). |
| Terminal              | System commands and screen outputs.                                                                                          |
| <i>Object</i>         | Indicates a reference to something. Used to emphasize this referenced object.                                                |
| <b>Menu &gt; Path</b> | GUI (Graphic User Interface) menu paths.                                                                                     |
| [Key]                 | Keyboard buttons.                                                                                                            |

# Table of Contents

|                                                       |           |
|-------------------------------------------------------|-----------|
| <b>Contacts</b>                                       | <b>2</b>  |
| <b>Product Documentation</b>                          | <b>3</b>  |
| <b>Introduction to the document</b>                   | <b>4</b>  |
| <b>1 Important Notes</b>                              | <b>6</b>  |
| <b>2 Hardware and Software Compatibility</b>          | <b>8</b>  |
| 2.1 Released Software . . . . .                       | 8         |
| 2.2 Product Compatibility . . . . .                   | 8         |
| 2.3 Compatibility Between Software Versions . . . . . | 10        |
| 2.4 Compatibility of Electrical Modules . . . . .     | 17        |
| 2.5 Compatibility of Electrical Cables . . . . .      | 18        |
| 2.6 SSL Encryption Compatibility . . . . .            | 19        |
| <b>3 New Features and Enhancements</b>                | <b>20</b> |
| 3.1 New Features . . . . .                            | 20        |
| 3.2 Enhancements . . . . .                            | 21        |
| 3.3 Changes in protocols management . . . . .         | 21        |
| <b>4 Solved Issues and Restrictions</b>               | <b>22</b> |
| 4.1 Solved Issues . . . . .                           | 22        |
| 4.2 Restrictions . . . . .                            | 24        |
| <b>5 Document Versions</b>                            | <b>46</b> |
| 5.1 Software Platform . . . . .                       | 46        |
| 5.2 Hardware Platform . . . . .                       | 46        |
| <b>Legal Note</b>                                     | <b>48</b> |
| <b>Warranty</b>                                       | <b>48</b> |

## 1 Important Notes

The table below provides important notes that should be observed when using the product.

| Note                                                                                                                                                                                                                                                                                                                                                                                                    | Product |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| Unable to load configuration XML files with dot1q that were saved DmOS versions before 8.0.0. Text mode config files works perfectly. In case you need to load an xml file that contains vlan configuration, you will need edit the xml file changing from <i>http://tail-f.com/ns/dmvlan-manager</i> to <i>urn:dmos:dmos-dot1q</i> .                                                                   | All     |
| Unable to load configuration XML files with lag that were saved DmOS versions before 9.2.0. Text mode config files works perfectly. In case you need to load an xml file that contains lag configuration, you will need edit the xml file changing from <i>http://tail-f.com/ns/lacp</i> to <i>urn:dmos:dmos-lag</i> .                                                                                  | All     |
| Increasing the number of objects or decreasing the interval between SNMP requests might lead to management latency or SNMP errors.                                                                                                                                                                                                                                                                      | All     |
| DmOS devices support autocorrection for occurrences of data corruption in memory. There may be cases after power outages or swings where the system cannot perform data autocorrection and may cause loss of logs or configurations.                                                                                                                                                                    | All     |
| The memory can be allocated by internal processes due to successive link-flaps. After flap stop, the memory will return to initial state. It is recommended to use the Link-Flap-Detection feature in ethernet interfaces.                                                                                                                                                                              | All     |
| VPN configurations that use the default MTU size configuration before DmOS 3.0.0 must observe the change in the default value from 1500 to 9198, which may cause a configuration mismatch.                                                                                                                                                                                                              | All     |
| In version 9.0.0 or above it will not be possible to configure weak passwords for local database users. If there is a need to change the password configuration of the equipment, it will be necessary to change the configuration to a strong password, according to the requirements presented in the CLI on the equipment.                                                                           | All     |
| It is possible to update all ONUs in a PONLink simultaneously provided that all ONUs are model equivalent. If there are ONUs of different models in a PONLink, it is not recommended to use the "all" parameter in command request firmware onu install <image> interface gpon <id> .                                                                                                                   | DM461X  |
| It is not recommended to configure the snmp real-time option for more than 128 ONUs. Large scale monitoring can cause performance impacts, such as an increase in ONU status update time. When using the DM461X products (OLT GPON) and operating near the maximum supported ONUs by the platform, it is recommended that the SNMP requests interval is no lower than 15 minutes.                       | DM461X  |
| The PON SDK update to version 9.8.0 may impact the operation of non-homologated transceivers GPON/XGSPON.                                                                                                                                                                                                                                                                                               | DM461X  |
| The <i>-native-vlan</i> suffix will no longer be displayed in the command tree, becoming a configuration. For this reason, starting with firmware version 10.4.0, the <i>native-vlan vlan-id &lt;VID&gt;</i> configuration will be displayed on the same line. This new configuration will require manual configuration adjustment when imported from a device with firmware version lower than 10.4.0. | All     |

| Note                                                                                                                                                                                                                                                             | Product |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| On the DM4920, starting on version 11.4.0, the link-Propagation between 100 Gbps and 400 Gbps interfaces runs on hardware. Feature's configurations and shows will be removed from CLI and Command Reference. can be found in <b>Quick Configuration Guide</b> . | DM4920  |
| It is possible to create up to 256 VLAN Mapping rules. However, hash collisions consistency check is performed to prevent users from configuring interfaces and VLANs that would result in such collisions.                                                      | DM4340  |

## 2 Hardware and Software Compatibility

This chapter lists hardware and software compatibility for this software release.

### 2.1 Released Software

This session presents the software release details:

| Product | Release Version |
|---------|-----------------|
| DmOS    | 12.4.0          |



The downtime after upgrading to the 12.4.0 version on the DM4360, DM4370 and DM4370 SAT platforms will be longer if it is in a firmware version that has a oldest FPGA version.



**DmOS 5.0** is the LTS release (Long-Term Support) for platform **DM4610 OLT 8GPON+8GX+4GT+2XS** (P/N 800.5081.xx). The platform will still receive maintenance releases based on DmOS 5.0, if necessary, with bug fixes. However, there will be no updates with new features. Other OLTs will still receive new features and bug fixes.



**DmOS 5.2** is the LTS release (Long-Term Support) for platform **DM4775 32CX** (P/N 820.0014.00). The platform will still receive maintenance releases based on DmOS 5.2, if necessary, with bug fixes. However, there will be no updates with new features.



For scalability values per platform, check document DmOS – DmOS Datasheet.

### 2.2 Product Compatibility



To use management via DmView with the DmOS version 12.4.0 it is necessary to update DmView to version 11.4.0-3 or greater.

The table below shows the product compatibility matrix stating the **minimum** hardware version, minimum software version and the minimum version of DmView (management software).



| Product                            | Hardware Version                          | Software Version         | DmView Version |
|------------------------------------|-------------------------------------------|--------------------------|----------------|
| DM4050 24GT+6XS                    | 800.5189.00                               | 2.2.0                    | 10.3           |
| DM4050 24GX+6XS                    | 800.5190.00                               | 2.2.0                    | 10.3           |
| DM4170 24GX+4XS+2QX                | 800.5184.01                               | 3.0.0                    | 10.3           |
| DM4170 24GX+12XS                   | 800.5186.01                               | 2.2.0                    | 10.3           |
| DM4250 24XS+2QX                    | 800.5197.02                               | 4.0.0                    | 10.3           |
| DM4270 24XS+2CX                    | 800.5231.53<br>800.5231.60                | 4.7.0<br>8.2.0           | 10.3           |
| DM4270 48XS+6CX                    | 800.5213.53<br>800.5213.61<br>800.5304.61 | 4.9.0<br>8.0.4<br>8.0.4  | 10.3           |
| DM4270 8XS+16VS+6CX                | 800.5313.62                               | 9.2.0                    | 10.3           |
| <b>DM4340 2GT+4GX</b>              | <b>800.5331.65</b>                        | <b>12.4.0</b>            | <b>11.7</b>    |
| DM4340 4GT+2GX                     | 800.5293.6x                               | 11.0.0                   | 11.4           |
| DM4360 4GT+4GX                     | 800.5259.50<br>800.5259.70<br>800.5259.75 | 4.10.0<br>8.0.6<br>8.2.0 | 10.3           |
| DM4370 4GT+4GX+4XS                 | 800.5191.00<br>800.5191.70<br>800.5191.75 | 3.0.0<br>8.0.6<br>8.2.0  | 10.3           |
| DM4370 4GT+4GX+4XS+SAT             | 800.5273.53<br>800.5273.70<br>800.5273.75 | 7.4.0<br>8.0.6<br>8.2.0  | 10.3           |
| DM4376 2GT+4GX+4XS                 | 800.5322.51                               | 10.0.0                   | 11.5           |
| DM4380 12XS+3CX                    | 800.5258.00<br>800.5258.60                | 5.0.0<br>8.2.0           | 10.3           |
| DM4610 OLT 8GPON+8GX+4GT+2XS       | 800.5081.03                               | 1.4.0                    | 10.3           |
| DM4610 OLT 4GPON+4GX+2XS (HW2)     | 800.5193.01                               | 2.4.0                    | 10.3           |
| DM4610 OLT 8GPON+8GX+4GT+2XS (HW2) | 800.5165.01                               | 2.2.0                    | 10.3           |
| DM4611 OLT 4GPON+2GT+2XS           | 800.5283.51                               | 6.2.0                    | 10.3           |
| DM4612 OLT 8GPON+2GT+2XS           | 800.5285.51                               | 6.2.0                    | 10.3           |
| DM4615 OLT 16GPON+4GT+4XS          | 800.5198.01                               | 4.2.0                    | 10.3           |

| Product                 | Hardware Version           | Software Version | DmView Version |
|-------------------------|----------------------------|------------------|----------------|
| DM4616 OLT 4XGS-PON+4XS | 800.5298.51                | 9.0.0            | 11.3.0         |
| DM4618 OLT 32GPON       | 800.5275.51                | 8.2.0            | 11.2           |
| DM4770 16CX             | 800.5280.51                | 6.0.0            | 10.3           |
| DM4770 32CX             | 800.5255.52                | 5.8.0            | 10.3           |
| DM4775 32CX             | 820.0015.00<br>820.0016.00 | 4.9.0            | 10.3           |
| DM4780 16CX+8DX         | 800.5309.52                | 12.0.0           | 11.6           |
| DM4920                  | 800.5299.51                | 9.4.0            | 11.4           |



**Bold items - new hardware platform available in the current version of DmOS.**

## 2.3 Compatibility Between Software Versions

The tables below shows the compatibility matrix between firmware versions, including the notes for the firmware update process.

### Software Upgrade

#### Notes

It is always recommend save the configuration before firmware update process. To save the configuration use the **save <arquivo>** command.

In case of doubt, please call to Datacom technical support.

For **DM4050** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version | Mandatory Intermediate Versions |       |       |       | Final Version |
|----------|-----------------|---------------------------------|-------|-------|-------|---------------|
| DM4050   | 2.2.0           | 2.2.2                           | 3.0.4 | 4.6.2 | 5.2.0 | 12.4.0        |
| DM4050   | 2.2.2           | -                               | 3.0.4 | 4.6.2 | 5.2.0 | 12.4.0        |

| Platform | Initial Version | Mandatory Intermediate Versions |   |       |       | Final Version |
|----------|-----------------|---------------------------------|---|-------|-------|---------------|
| DM4050   | 3.0.4 or higher | -                               | - | 4.6.2 | 5.2.0 | 12.4.0        |
| DM4050   | 4.6.2 or higher | -                               | - | -     | 5.2.0 | 12.4.0        |
| DM4050   | 5.2.0 or higher | -                               | - | -     | -     | 12.4.0        |

For **DM4170** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version | Mandatory Intermediate Versions |       |       |       | Final Version |
|----------|-----------------|---------------------------------|-------|-------|-------|---------------|
| DM4170   | 2.2.0           | 2.2.2                           | 3.0.4 | 4.6.2 | 5.2.0 | 12.4.0        |
| DM4170   | 2.2.2           | -                               | 3.0.4 | 4.6.2 | 5.2.0 | 12.4.0        |
| DM4170   | 3.0.4 or higher | -                               | -     | 4.6.2 | 5.2.0 | 12.4.0        |
| DM4170   | 4.6.2 or higher | -                               | -     | -     | 5.2.0 | 12.4.0        |
| DM4170   | 5.2.0 or higher | -                               | -     | -     | -     | 12.4.0        |

For **DM4250** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version | Mandatory Intermediate Versions |       | Final Version |
|----------|-----------------|---------------------------------|-------|---------------|
| DM4250   | 4.0.0 or higher | 4.6.2                           | 5.2.0 | 12.4.0        |
| DM4250   | 4.6.2 or higher | -                               | 5.2.0 | 12.4.0        |
| DM4250   | 5.2.0 or higher | -                               | -     | 12.4.0        |

For **DM4270 24XS+2CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform        | Initial Version | Mandatory Intermediate Versions | Final Version |
|-----------------|-----------------|---------------------------------|---------------|
| DM4270 24XS+2CX | 4.7.0 or higher | 5.2.0                           | 12.4.0        |
| DM4270 24XS+2CX | 5.2.0 or higher | -                               | 12.4.0        |

For **DM4270 48XS+6CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform        | Initial Version | Mandatory Intermediate Versions | Final Version |
|-----------------|-----------------|---------------------------------|---------------|
| DM4270 48XS+6CX | 4.9.0 or higher | 5.2.0                           | 12.4.0        |
| DM4270 48XS+6CX | 5.2.0 or higher | -                               | 12.4.0        |

For **DM4270 8XS+16VS+6CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform            | Initial Version | Mandatory Intermediate Versions | Final Version |
|---------------------|-----------------|---------------------------------|---------------|
| DM4270 8XS+16VS+6CX | 9.2.0 or higher | -                               | 12.4.0        |

For **DM4340 2GT+4GX** platform, DmOS has the following compatibility matrix:

| Platform       | Initial Version  | Mandatory Intermediate Versions | Final Version |
|----------------|------------------|---------------------------------|---------------|
| DM4340 2GT+4GX | 12.4.0 or higher | -                               | 12.4.0        |

For **DM4340 4GT+2GX** platform, DmOS has the following compatibility matrix:

| Platform       | Initial Version  | Mandatory Intermediate Versions | Final Version |
|----------------|------------------|---------------------------------|---------------|
| DM4340 4GT+2GX | 11.0.0 or higher | -                               | 12.4.0        |

For **DM4360** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version  | Mandatory Intermediate Versions | Final Version |
|----------|------------------|---------------------------------|---------------|
| DM4360   | 4.10.0 or higher | 5.2.0                           | 12.4.0        |
| DM4360   | 5.2.0 or higher  | -                               | 12.4.0        |

For **DM4370 4GT+4GX+4XS** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version | Mandatory Intermediate Versions |       |       | Final Version |
|----------|-----------------|---------------------------------|-------|-------|---------------|
| DM4370   | 3.0.0           | 3.0.4                           | 4.6.2 | 5.2.0 | 12.4.0        |
| DM4370   | 3.0.4 or higher | -                               | 4.6.2 | 5.2.0 | 12.4.0        |
| DM4370   | 4.6.2 or higher | -                               | -     | 5.2.0 | 12.4.0        |
| DM4370   | 5.2.0 or higher | -                               | -     | -     | 12.4.0        |

For **DM4370 4GT+4GX+4XS+SAT** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform   | Initial Version | Mandatory Intermediate Versions | Final Version |
|------------|-----------------|---------------------------------|---------------|
| DM4370 SAT | 7.4.0 or higher | -                               | 12.4.0        |

For **DM4376 2GT+4GX+4XS** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version  | Mandatory Intermediate Versions | Final Version |
|----------|------------------|---------------------------------|---------------|
| DM4376   | 10.0.0 or higher | -                               | 12.4.0        |

For **DM4380** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version | Mandatory Intermediate Versions | Final Version |
|----------|-----------------|---------------------------------|---------------|
| DM4380   | 5.0.0 or higher | 5.2.0                           | 12.4.0        |
| DM4380   | 5.2.0 or higher | -                               | 12.4.0        |

For **DM4610 HW1** platform, the DmOS has the following compatibility matrix:

| Platform   | Initial Version | Mandatory Intermediate Versions |       |       |       | Final Version |
|------------|-----------------|---------------------------------|-------|-------|-------|---------------|
| DM4610 HW1 | 1.8.0 or lower  | 1.8.2                           | 2.2.2 | 3.0.4 | 4.0.2 | 5.0.6         |
| DM4610 HW1 | 1.8.2 to 2.0.4  | -                               | 2.2.2 | 3.0.4 | 4.0.2 | 5.0.6         |
| DM4610 HW1 | 2.2.2 to 3.0.2  | -                               | -     | 3.0.4 | 4.0.2 | 5.0.6         |
| DM4610 HW1 | 3.0.4 to 4.0.0  | -                               | -     | -     | 4.0.2 | 5.0.6         |
| DM4610 HW1 | 4.0.2 or higher | -                               | -     | -     | -     | 5.0.6         |

For **DM4610 HW2** platform, the DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform   | Initial Version | Mandatory Intermediate Versions |       |       |       |       | Final Version |
|------------|-----------------|---------------------------------|-------|-------|-------|-------|---------------|
| DM4610 HW2 | 1.8.0 or lower  | 1.8.2                           | 2.2.2 | 3.0.4 | 4.0.2 | 5.2.0 | 12.4.0        |
| DM4610 HW2 | 1.8.2 to 2.0.4  | -                               | 2.2.2 | 3.0.4 | 4.0.2 | 5.2.0 | 12.4.0        |
| DM4610 HW2 | 2.2.2 to 3.0.2  | -                               | -     | 3.0.4 | 4.0.2 | 5.2.0 | 12.4.0        |
| DM4610 HW2 | 3.0.4 to 4.0.0  | -                               | -     | -     | 4.0.2 | 5.2.0 | 12.4.0        |
| DM4610 HW2 | 4.0.0 to 4.0.2  | -                               | -     | -     | -     | 5.2.0 | 12.4.0        |
| DM4610 HW2 | 5.2.0 or higher | -                               | -     | -     | -     | -     | 12.4.0        |

For **DM4611 and DM4612** platforms, the DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform          | Initial Version | Mandatory Intermediate Versions | Final Version |
|-------------------|-----------------|---------------------------------|---------------|
| DM4611 and DM4612 | 6.0.0 or higher | -                               | 12.4.0        |

For **DM4615** platform, the DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version | Mandatory Intermediate Versions | Final Version |
|----------|-----------------|---------------------------------|---------------|
| DM4615   | 4.0.0 or higher | 5.2.0                           | 12.4.0        |
| DM4615   | 5.2.0 or higher | -                               | 12.4.0        |

For **DM4618** platform, the DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform | Initial Version | Mandatory Intermediate Versions | Final Version |
|----------|-----------------|---------------------------------|---------------|
| DM4618   | 8.0.0 or higher | -                               | 12.4.0        |

For **DM4770 16CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform    | Initial Version | Mandatory Intermediate Versions | Final Version |
|-------------|-----------------|---------------------------------|---------------|
| DM4770 16CX | 6.0.0 or higher | -                               | 12.4.0        |

For **DM4770 32CX** platform, DmOS has the following compatibility matrix:



There are hardware version codes for certain platforms that have version different minimum version, please refer to the [Product Compatibility](#) table

| Platform    | Initial Version | Mandatory Intermediate Versions | Final Version |
|-------------|-----------------|---------------------------------|---------------|
| DM4770 32CX | 5.8.0 or higher | -                               | 12.4.0        |

For **DM4775** platform, DmOS has the following compatibility matrix:

| Platform | Initial Version | Mandatory Intermediate Versions | Final Version |
|----------|-----------------|---------------------------------|---------------|
| DM4775   | 4.9.0 or higher | -                               | 5.2.0         |

For **DM4780** platform, DmOS has the following compatibility matrix:

| Platform | Initial Version  | Mandatory Intermediate Versions | Final Version |
|----------|------------------|---------------------------------|---------------|
| DM4780   | 12.0.0 or higher | -                               | 12.4.0        |

For **DM4920** platform, DmOS has the following compatibility matrix:

| Platform | Initial Version | Mandatory Intermediate Versions | Final Version |
|----------|-----------------|---------------------------------|---------------|
| DM4920   | 9.4.0 or higher | -                               | 12.4.0        |

## Software Downgrade

### Notes

From version 8.2.0 or later it is not possible to perform a firmware downgrade in DM4360, DM4370 and DM4370 SAT platforms to versions lower than 8.2.0. If this operation is performed you must contact Datacom's Technical Support.

From version 2.4.0 it is only possible to perform firmware downgrade to version 2.0.0 or 2.2.2. Firmware downgrade to older versions is not allowed by the system.





There is no support to maintain current database in downgrade. When performing the downgrade, the previous database is restored and any configuration changes made after upgrade to version 4.x or higher will be lost in the downgrade process. In case of downgrade to version different from previous, the equipment will boot with factory configuration.

## 2.4 Compatibility of Electrical Modules

The table below shows the matrix about electrical modules support (SFP Copper) by each product line and which version initiated its support. It's advised the use of **negotiation** on interfaces with copper SFPs.



The SFP Copper supported has **377.7000.00** Datacom code. Datacom does not guarantee compatibility with other modules. Contact us for more information.

| Product Line      | Software Version                  |
|-------------------|-----------------------------------|
| DM4050            | 2.2.0                             |
| DM4170            | 2.2.0                             |
| DM4250            | 4.8.0                             |
| DM4270 24XS+2CX   | 4.8.0                             |
| DM4270 48XS+6CX   | 5.0.0 (forced only <sup>1</sup> ) |
| DM4340            | 12.1.0                            |
| DM4360            | 4.10.0                            |
| DM4370            | 3.0.0                             |
| DM4376            | Not available                     |
| DM4380            | 5.0.0                             |
| DM4610            | 2.2.0                             |
| DM4611            | 6.2.0                             |
| DM4612            | 6.2.0                             |
| DM4615            | 4.2.0                             |
| DM4616            | 9.0.0                             |
| DM4618 OLT 32GPON | 8.0.0                             |
| DM4770 16CX       | 6.0.0 (forced only <sup>1</sup> ) |
| DM4770 32CX       | 5.8.0                             |

| Product Line | Software Version |
|--------------|------------------|
| DM4775       | 4.9.0            |
| DM4780       | Not available    |
| DM4920       | Not available    |



<sup>1</sup> **DM4270 48XS+6CX** and **DM4770 16CX** don't support negotiation on ten-gigabit interfaces and twenty-five-gigabit interfaces, but it's possible to make use of copper modules setting the interface to forced mode (no negotiation). The presence of a copper module makes the interface negotiate with the link partner advertising 1 Gbps speed only, with no support for pause frames or lower speeds, regardless of its current configuration. When operating in this mode, a link down status may take up to 10 seconds to be reported.

## 2.5 Compatibility of Electrical Cables

The table below shows the electrical cables support matrix recommended by Datacom.



The use of non recommended cables can cause performance problems.

| Code        | Description                                      |
|-------------|--------------------------------------------------|
| 377.6204.00 | DAC Passive Cable 40GbE QSFP+ to QSFP+ (1m)      |
| 377.6205.00 | DAC Passive Cable 40GbE QSFP+ to QSFP+ (3m)      |
| 377.6208.00 | DAC Passive Cable 100GbE QSFP28 to QSFP28 (1m)   |
| 377.6209.00 | DAC Passive Cable 100GbE QSFP28 to QSFP28 (3m)   |
| 377.6202.00 | DAC Passive Cable 40GbE QSFP+ to 4xSFP+ (1m)     |
| 377.6203.00 | DAC Passive Cable 40GbE QSFP+ to 4xSFP+ (3m)     |
| 377.6206.00 | DAC Passive Cable 100GbE QSFP28 to 4xSFP28 (1m)  |
| 377.6207.00 | DAC Passive Cable 100GbE QSFP28 to 4xSFP28 (3m)  |
| 377.6210.00 | DAC Passive Cable 400GbE QSFP-DD to QSFP-DD (1m) |
| 377.6214.00 | DAC Passive Cable 400GbE QSFP-DD to QSFP-DD (3m) |

## 2.6 SSL Encryption Compatibility

The table below lists the OpenSSL versions for each software version and which version initiated its support.

| Software Version | OpenSSL Version |
|------------------|-----------------|
| 1.4.2            | 1.0.1f          |
| 1.10.0           | 1.0.2j          |
| 1.12.0           | 1.0.2k          |
| 2.4.0            | 1.0.2l          |
| 4.0.0            | 1.0.2o          |
| 4.9.0            | 1.0.2r          |
| 5.0.0            | 1.0.2t          |
| 8.0.0            | 1.0.2u          |
| 10.4.0           | 1.1.1k          |

## 3 New Features and Enhancements

This chapter lists new features, enhancements and changes in commands introduced in this release.

### 3.1 New Features

The features below are global to **DmOS**.



Consult the DmOS **Datasheet** to check which platforms are supported for the features below.

| Feature           | Description                                                                                 | ID    |
|-------------------|---------------------------------------------------------------------------------------------|-------|
| <b>BFD</b>        | Support for BFD timers configuration per neighbor.                                          | F1916 |
| <b>IP Routing</b> | Support for using a prefix-list in the OSPF into BGP redistribute.                          | F2764 |
| <b>IP Routing</b> | Support for using a prefix-list in the BGP into OSPF redistribute.                          | F2764 |
| <b>IP Routing</b> | Support for using a prefix-list in the redistribute of directly connected routes into OSPF. | F2765 |
| <b>IP Routing</b> | Support for using a prefix-list in the redistribute of static routes into OSPF.             | F2134 |
| <b>IP Routing</b> | Support for match by next-hop and route-source with a prefix-list in the route-map.         | F2899 |
| <b>Interfaces</b> | Support for Versatile Diagnostics Monitoring for CMIS modules.                              | 1832  |

The features below are specific to the **DM4780** platform.

| Feature                | Description                                    | ID    |
|------------------------|------------------------------------------------|-------|
| <b>CPU-DoS-Protect</b> | Support for cpu-dos-protect.                   | F2990 |
| <b>IP Routing</b>      | Support for VRRP for IPv4 and IPv6.            | F3084 |
| <b>Interfaces</b>      | Support for breakout on the 400 GB interfaces. | F2987 |
| <b>Interfaces</b>      | Support for breakout on the 200 GB interfaces. | F3018 |
| <b>Interfaces</b>      | Support for breakout on the 100 GB interfaces. | F3019 |
| <b>L2</b>              | Support for <i>Loopback Detection</i> .        | F3068 |
| <b>MPLS</b>            | Support for VPLS Selective Encapsulation.      | F2980 |
| <b>MPLS</b>            | Support for service-delimiting in VPLS.        | F2995 |
| <b>MPLS</b>            | Support for port-based VPLS.                   | F2994 |

The features below are specific to the **DM4920** platform.

| Feature           | Description                                                                                             | ID    |
|-------------------|---------------------------------------------------------------------------------------------------------|-------|
| <b>Interfaces</b> | Support for shutdown on the EDFA/Raman card interfaces.                                                 | F2945 |
| <b>Interfaces</b> | Support for OSC management in Ring topologies, through the STP protocol hard-coded on these interfaces. | F2620 |

### 3.2 Enhancements

| Feature    | Description                                      | ID    |
|------------|--------------------------------------------------|-------|
| <b>QoS</b> | Support for match by PCP and DSCP on the DM4340. | F3058 |
| <b>QoS</b> | Support for the Policer counters on the DM4340.  | F3058 |
| <b>QoS</b> | Support for Flow mode in the DM4340 Policer.     | F3058 |

### 3.3 Changes in protocols management

| Feature | Description | ID |
|---------|-------------|----|
| -       | -           | -  |

## 4 Solved Issues and Restrictions

This section lists solved issues and known restrictions for this software release.

- **Solved Issues:** Fixed bugs in this version.
- **Restrictions:** DmOS Software restrictions per hardware platforms.

### 4.1 Solved Issues

| Feature                    | Description                                                                                                                                                                                                                                                                                                   | ID     | Affected Platforms |
|----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>AAA</b>                 | Authentication and Authorization packets did not report the client IP of the SSH/Telnet connection (Remote Address 0.0.0.0).                                                                                                                                                                                  | 274830 | DM4370             |
| <b>ACL</b>                 | ACLs are not applied to ethertype IPv6 packets (0x86DD). In case of an attempt to block IPv6 traffic, this traffic will continue to be routed, for example.                                                                                                                                                   | 252329 | DM4340             |
| <b>ACL</b>                 | On the DM4780 platform, the "show acl-resources" command does not correctly count resources when creating rules with L3 and L4 matches where it is necessary to use two resources for the rule to function correctly in IPv4 and IPv6. The final result will only count one resource instead of two per rule. | 264491 | DM4780             |
| <b>ACL</b>                 | On the DM4780 platform, <i>UNKNOWN-HOSTS</i> type packets are affected by CPU Protection ACLs.                                                                                                                                                                                                                | 263699 | DM4780             |
| <b>Backup-Link</b>         | Possibility of generating a core dump in the Backup-link process if this feature is configured in a single commit together with the VLAN configuration (dot1q).                                                                                                                                               | 269924 | DM4780             |
| <b>BGP</b>                 | Removing the prefix-list from a route-map in BGP does not change the configuration.                                                                                                                                                                                                                           | 272223 | All                |
| <b>BGP</b>                 | The SNMP request was not answered when it was made through one L3 interface and should have been answered through another L3 interface, both in the same VRF.                                                                                                                                                 | 196482 | All                |
| <b>BPDU Tunneling</b>      | <i>IEEE</i> packets with VLAN will not be tunneled.                                                                                                                                                                                                                                                           | 262265 | DM4780             |
| <b>DWDM</b>                | It is not possible to view the status of the Line-Protection and Raman amplifier boards via DmView.                                                                                                                                                                                                           | 254557 | DM4920             |
| <b>GPON PON Interfaces</b> | The "Available upstream bandwidth" information collected from the OLTs via the command "show interface gpon x/y/z" is returning zero values.                                                                                                                                                                  | 271802 | DM461x             |

| Feature                       | Description                                                                                                                                                                                                                                                                                                                                              | ID                         | Affected Platforms |
|-------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|--------------------|
| <b>IP Routing</b>             | When using the L2 and L3 Overlay scenario, in the event of a link failure, after the link is restored, the host-table is not updated.                                                                                                                                                                                                                    | 265024                     | All                |
| <b>L2VPN<br/>L2 Protocols</b> | GMRP protocol BPDUs do not pass through VPLS, even with TLS enabled.                                                                                                                                                                                                                                                                                     | 133639                     | All                |
| <b>L2VPN<br/>PHP</b>          | When the DM4780 is used in the PHP position, packets that arrive only with an infrastructure label containing an IP header encapsulation are corrupted. This makes it impossible to use the equipment for establishing services, such as LDP, between direct neighbors and other network equipment that encapsulate services in the MPLS infrastructure. | 271116                     | DM4780             |
| <b>L2VPN<br/>VLAN</b>         | In the LER equipment, instead of the VLAN PCP received on access being copied to the EXP field of the MPLS header, the equipment is assigning EXP 0. As a consequence, on the equipment output at the other end of the VPN, the EXP value is copied to the VLAN PCP also as 0.                                                                           | 269433                     | DM4780             |
| <b>L2VPN<br/>VLAN</b>         | In an L2VPN VPLS VLAN-based pw-type VLAN configuration with asymmetric VLANs (different VLANs on the access of VPN), the packet is forwarded with the wrong VLAN on the DM4780.                                                                                                                                                                          | 269128                     | DM4780             |
| <b>L2VPN<br/>VLAN</b>         | In an L2VPN VPLS VLAN-based pw-type ethernet configuration, if a packet with two tags is sent through the VPN access, both tags are removed (not just the outer tag).                                                                                                                                                                                    | 268649                     | DM4780             |
| <b>LAG</b>                    | Interface LAG with LACP configuration in short mode goes Down after equipment reboot.                                                                                                                                                                                                                                                                    | 268554                     | DM4340             |
| <b>LAG</b>                    | When all member interfaces of a LAG are changed in a single commit, the LAG becomes inconsistent and stops to forward data.                                                                                                                                                                                                                              | 267242<br>271835<br>270864 | DM4340             |
| <b>LAG</b>                    | Changing LAG members when the LAG is configured as the source of a Port Mirror can cause the Mirror to malfunction.                                                                                                                                                                                                                                      | 268564                     | DM4340             |
| <b>MPLS</b>                   | On DM4780 platform, there is a limit of up to 4000 entries in the forwarding table. Above this limit, no new rules will be created.                                                                                                                                                                                                                      | 268937                     | DM4780             |
| <b>OSPF</b>                   | Administrative distance is not considered when choosing the prefix when the equipment has a static route configuration with an administrative distance (AD) greater than the administrative distance of the protocols.                                                                                                                                   | 235078                     | All                |
| <b>OSPF</b>                   | Removing a redistribute configuration in OSPF when the equipment has more than one redistribute configured causes the prefixes of the remaining redistributes to stop being advertised in OSPF.                                                                                                                                                          | 163789                     | All                |

| Feature              | Description                                                                                                                                                                              | ID     | Affected Platforms |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>OSPF</b>          | OSPFv3 adjacencies do not come up after migrating the OSPFv3 configuration from the global instance to within a VRF.                                                                     | 271746 | All                |
| <b>QoS - Policer</b> | After applying the QoS Policer configuration and associating it with an interface and VLAN, it may take up to 3 minutes for traffic to start being throttled by the policer.             | 271113 | DM4340             |
| <b>System</b>        | 100G interfaces of an already provisioned LC-800 did not contain DWDM after the config-update.                                                                                           | 272465 | DM4920             |
| <b>System</b>        | A power reboot (hard reset) at a specific moment during the equipment initialization caused the loss of the configuration, forcing the equipment to return to the factory configuration. | 263705 | DM4270-48XS        |
| <b>System CPU</b>    | IEEE frames 01:80:C2:00:00:XX are forwarded to the equipment's CPU even when there are no protocols related to those MACs enabled on the interface.                                      | 272615 | DM4780             |
| <b>System LED</b>    | DM4780 alarm LED is not lighting up when there are critical severity alarms.                                                                                                             | 272042 | DM4780             |
| <b>System Memory</b> | Memory may be allocated by internal processes due to Ethernet link flaps for an extended period of time.                                                                                 | 237695 | All                |

## 4.2 Restrictions

| Feature    | Description                                                                                                                                                                                                     | ID     | Affected Platforms |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>AAA</b> | Commands rejected by TACACS are being logged in the accounting log.                                                                                                                                             | 122945 | All                |
| <b>AAA</b> | Error message generation in the log when applying the banner configuration using the multiline mode.                                                                                                            | 111616 | All                |
| <b>AAA</b> | The message <i>"No modifications to commit"</i> is generated when changing the password using the command <i>"aaa user &lt;username&gt; change-password"</i> even though the password was successfully changed. | 265146 | All                |
| <b>AAA</b> | Commands longer than 243 characters are not sent to the accounting server.                                                                                                                                      | 111614 | All                |
| <b>AAA</b> | When a user is present on both the remote RADIUS server and on the local database, authenticating through RADIUS causes DmOS to grant that user's privileges as defined in both databases.                      | 253061 | All                |



| Feature        | Description                                                                                                                                               | ID     | Affected Platforms                   |
|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------------------------|
| AAA            | In the first moments after a reboot caused by a Tacacs user, a login failure with a local user may occur. After a short period of time, this is resolved. | 257361 | All                                  |
| AAA            | A core-dump may occur in the authentication process when pasting a config snippet into the CLI using copy-paste.                                          | 276671 | All                                  |
| ACL            | CPU-protection ACLs do not match packets that contain an MPLS label.                                                                                      | 255756 | All                                  |
| ACL            | CPU-protection ACL may interfere with the operation of LAGs that use LACP.                                                                                | 255095 | DM4770 16CX                          |
| ACL            | ACL rule with <i>set pcp</i> on untagged traffic causes MAC address learning to occur in VLAN zero instead of the native VLAN.                            | 146732 | DM4270                               |
| ACL            | ACL action of PCP set is not being performed when QinQ is configure an interface.                                                                         | 112774 | DM4270                               |
| ACL            | ACLs do not block traffic classified as <i>unknown hosts</i> which is used as a trigger for DmOS to attempt to resolve an unknown host.                   | 140054 | DM4050<br>DM4250<br>DM4270<br>DM4770 |
| ACL            | The ACLs with <i>ethertype permit arp</i> are blocking ARP request packets.                                                                               | 208459 | DM4250<br>DM4170<br>DM437x           |
| Assistant-task | If there is a <b>show</b> command in the script, the next commands are not executed.                                                                      | 121680 | All                                  |
| Banner         | Equipment may not display a login banner when accessed via telnet.                                                                                        | 252404 | DM4340                               |
| BFD            | BFD failure caused by a fiber fault not directly connected to the DmOS causes failure of all L2VPNs using the BFD interface as uplink.                    | 214077 | All                                  |
| BFD            | BFD sessions are not shown in DmView.                                                                                                                     | 127350 | All                                  |
| BFD            | The <i>show bfd session</i> command is slower due to the new columns added with information about the timers negotiation.                                 | 274951 | All                                  |
| BGP            | In scenarios where multiple BGP neighbors are configured in VRF, DmOS only logs the last configured one.                                                  | 241433 | All                                  |
| BGP            | <i>show ip bgp community</i> command takes 2 minutes to execute, regardless of the number of prefixes.                                                    | 247002 | All                                  |
| BGP            | SNMP communication failure when BGP neighbors are active in VRF mgmt.                                                                                     | 279125 | DM4250                               |

| Feature               | Description                                                                                                                                                                                                                                                                                         | ID     | Affected Platforms |
|-----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>BGP</b>            | MED attribute was not sent when the route-map is applied in a VRF.                                                                                                                                                                                                                                  | 250903 | All                |
| <b>BGP</b>            | Removing BGP configuration from a device that has an L3VPN causes a core-dump in the nbase-stub process and triggers a reboot of the equipment.                                                                                                                                                     | 255760 | All                |
| <b>BGP</b>            | The <i>show ip bgp community</i> command may time-out when a large number of communities are configured.                                                                                                                                                                                            | 256176 | All                |
| <b>BPDU Tunneling</b> | BPDU tunneling is not performing the <i>tunnel-priority</i> check for proper prioritization.                                                                                                                                                                                                        | 262264 | DM4780             |
| <b>Breakout Cable</b> | When configuring Breakout Cable through DmView there is no message informing that the equipment will be restarted.                                                                                                                                                                                  | 213004 | DM4770             |
| <b>Breakout Cable</b> | DmOS informs <b>Unknown reason</b> via <i>show system reboot</i> when the reboot was performed to enable or disable the Breakout Cable feature.                                                                                                                                                     | 213054 | DM4770             |
| <b>CFM</b>            | When adding a interface that blocked by CFM to a LAG that is also blocked by CFM, it can be unblocked.                                                                                                                                                                                              | 124046 | All                |
| <b>CFM</b>            | Communication between MEPs may not work, being necessary to remove the CFM configuration and reapply it.                                                                                                                                                                                            | 119632 | All                |
| <b>CFM</b>            | CFM linktrace status remains on command <i>show oam cfm linktrace</i> after removing the CFM configuration.                                                                                                                                                                                         | 136881 | All                |
| <b>CLI - Database</b> | After version 10.4.0, invalid outputs in JSON format are generated when executing the command <i>"show running-config &lt;config&gt;   display json"</i> if the equipment configuration is extensive. To assist in this situation, it is recommended to use the extension: <i>"  display xml"</i> . | 247885 | All                |
| <b>CLI - Database</b> | Some show commands may not show full output when using the <i>  display json, xpath, etc</i> option.                                                                                                                                                                                                | 160442 | All                |
| <b>CLI - Database</b> | Although the option appears in the CLI, is not supported utilities after the pipe <i> </i> in debug commands.                                                                                                                                                                                       | 134410 | All                |
| <b>CLI - Database</b> | Using <i>config exclusive</i> , there is no information about the commit/ rollback performed when <i>commit confirmed</i> is not executed and the equipment automatically recovers the configuration.                                                                                               | 214543 | All                |
| <b>CLI - Database</b> | Hostname configuration always appears in <i>show configuration diff</i> when loading factory-config, even if it has not been modified.                                                                                                                                                              | 248405 | All                |
| <b>CLI - Database</b> | The <i>(show running-config dot1q vlan   context-match)</i> command does not display all vlans associated with the interface.                                                                                                                                                                       | 236403 | All                |

| Feature         | Description                                                                                                                                                                                                                                                       | ID     | Affected Platforms |
|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| CLI - Database  | Order of transceivers is not displayed in ascending order on command <b>show interface transceivers</b> .                                                                                                                                                         | -      | All                |
| CLI - Database  | Load override configuration with RSVP explicit path makes commit impossible even if the difference between the current and candidate configuration has nothing to do with RSVP.                                                                                   | 168158 | All                |
| CLI - Database  | After reboot, rollback files may be removed, and it is not possible to revert settings using the <i>rollback</i> command. Settings can be reverted directly using the cli.                                                                                        | 213488 | All                |
| CLI - Database  | Using the   <i>tab</i> parameter may cause slowness in displaying information from the <i>show interface hundred-gigabit-ethernet * statistics</i> command.                                                                                                       | 190591 | DM4920             |
| CLI - Database  | The command <i>show interface transceiver application   display json</i> does not display any information.                                                                                                                                                        | 262571 | DM4780             |
| CLI - Database  | It is not possible to perform a backup DCB files in some equipment via DmView because there is a failure in " <i>get-running-config-text</i> " via NETCONF.                                                                                                       | 271670 | DM4615             |
| DHCP Relay L2   | After removing a service-port from a manual entry in anti-IP spoofing, the rebinds sent by the ONUs are not sufficient for that entry to be added to allowed-ip. It is recommended that each ONUs be rebooted.                                                    | 251516 | DM461X             |
| DHCP Relay L2   | Changing the Service Type of a VLAN from TLS to N:1 while DHCP L2 Relay is enabled causes IP assignment failures on that VLAN.                                                                                                                                    | 154137 | DM461X             |
| DWDM            | The command <i>show link status</i> does not allow diagnosing which link failed due to Link Propagation.                                                                                                                                                          | 258835 | DM4920             |
| EAPS            | EAPS protocol control packets can be dropped in cases of congestion, even with QoS enabled.                                                                                                                                                                       | 155888 | All                |
| EAPS            | The eapsDomainName object of the MIB DMOS-EAPS is only created when configured causing failure in EAPS domain information of prototypes used in templates in Zabbix. To workaround configure eaps <eaps_id> name on all configured EAPS instances.                | 170864 | All                |
| ECMP            | ECMP configuration in OSPFv2 and OSPFv3 causes BGP to use ECMP in BGP. It is not possible to disable ECMP only in BGP.                                                                                                                                            | 170142 | All                |
| Firmware Update | Firmware update 9.8.0 or higher may fail on the first activation attempt when executing <i>request firmware activate</i> . If the message " <b>Firmware upgrade: The firmware activation has failed.</b> " occurs, it will be necessary to repeat the activation. | 172425 | DM4616<br>DM4920   |

| Feature                      | Description                                                                                                                                                                                                                                                                | ID     | Affected Platforms |
|------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>Firmware Update</b>       | Firmware download may trigger a <i>CPU_LOAD_HIGH</i> alarm.                                                                                                                                                                                                                | 251897 | DM4340             |
| <b>Firmware Update</b>       | Firmware update may generate a core-dump in gpon-mgr. A new reboot is required to normalize the equipment.                                                                                                                                                                 | 210819 | DM4610             |
| <b>Firmware Update</b>       | The FPGA update if needs in a DmOS version will only be completed after the equipment is restarted due to power failure or removal and insertion of the power cord. Even if the update has not been completed, there will be no problem in the operation of the equipment. | -      | DM4360<br>DM4370   |
| <b>GPON Autoprovisioning</b> | Alarm of autoprovisioning may get stuck under some configuration conditions of GPON interface.                                                                                                                                                                             | 99261  | DM461x             |
| <b>GPON Line Profile</b>     | DHCPv6 service does not work with VLAN tagged in ONU LAN and line-profile with more than one GEM.                                                                                                                                                                          | 155121 | DM461x             |
| <b>GPON Multicast</b>        | After reboot, IGMP traffic may fail on XGSPON ONUs. It is necessary to delete the service-port and recreate it.                                                                                                                                                            | 217041 | DM4616             |
| <b>GPON ONU</b>              | After several ONU firmware update executions using the parameter all, new firmware update commands are not processed until shut/no shut is performed in the PON links where the firmware update processes took place.                                                      | 126539 | DM461x             |
| <b>GPON ONU</b>              | After link failure, some ONUs may remain in the down/inactive state. To recover them, ONU reboot is required.                                                                                                                                                              | 200682 | DM4615             |
| <b>GPON ONU</b>              | OLT overrides the dial plan configuration configured on the ONU Web.                                                                                                                                                                                                       | 149521 | DM461x             |
| <b>GPON ONU</b>              | After the reboot performed in the OLT firmware update, the management of ONU DM985-100 via IPHost does not return. As a workaround it is necessary to execute the <i>onu-reset</i> command.                                                                                | 132639 | DM461x             |
| <b>GPON ONU</b>              | Some ONU IDs may become unavailable with an Alloc-ID of 0. ONUs provisioned with these IDs will not function. To resolve this, we recommend provisioning these ONUs with other IDs or restarting the OLT.                                                                  | 206413 | DM4610 HW1         |
| <b>GPON ONU Discovery</b>    | ONU may remain in discovery mode after being provisioned.                                                                                                                                                                                                                  | 238491 | DM4616<br>DM4615   |
| <b>GPON ONU SNMP</b>         | Monitoring of Ethernet ports ONU traffic by SNMP with flow greater than 38 Mbps does not work properly.                                                                                                                                                                    | 129353 | DM461x             |

| Feature                    | Description                                                                                                                                                                                                                                                                | ID     | Affected Platforms |
|----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>GPON ONU SNMP</b>       | Placing an ONU in anti-roogue mode generates a trap from the same ONU in discovery.                                                                                                                                                                                        | 207020 | DM461x             |
| <b>GPON ONU Status</b>     | After power failure, some ONUs may have <i>Operational state Down</i> and <i>Primary status Active</i> impacting the ONU service. It is necessary to reprovision the ONU to resolve this failure.                                                                          | 184035 | DM461x             |
| <b>GPON ONU Status</b>     | ONUs from other manufacturers may have the power value displayed with the wrong value.                                                                                                                                                                                     | 132635 | DM461x             |
| <b>GPON Policer</b>        | Policer may stop limiting traffic on a service-port after OLT reboot.                                                                                                                                                                                                      | 214674 | DM461x             |
| <b>GPON PON Interfaces</b> | It is not possible to execute some commands of GPON when using a range of GPON interfaces.                                                                                                                                                                                 | 102236 | DM461x             |
| <b>GPON PON Interfaces</b> | Delay may occur to update PON status after link state change in scenarios with many ONUs.                                                                                                                                                                                  | 147361 | DM461x             |
| <b>GPON Service-Port</b>   | Configuration file containing service-port configured with <i>action vlan add vlan-id &lt;VLAN&gt; description &lt;DESC&gt;</i> does not apply service-port configuration. To work around it is necessary to remove the description before loading the configuration file. | 183597 | DM461x             |
| <b>GPON SIP Profile</b>    | It is allowed to configure the field display-name in a SIP agent profile with a string greater than 25 character, but the only first 25 characters are used.                                                                                                               | 108932 | DM461x             |
| <b>GPON SNMP</b>           | DMOS-TRANSCEIVER-MIB::laneRxPower(RxPower) returns random values for GPON/XGSPON transceivers.                                                                                                                                                                             | 204319 | DM461x             |
| <b>GPON SNMP</b>           | Poor performance of GEM counters via SNMP is causing errors in graphs from external tools like Zabbix.                                                                                                                                                                     | 148476 | DM461x             |
| <b>GPON System</b>         | NOKIA-G-140W-ME GPON ONU generates a core-dump, preventing any ONU from being provisioned.                                                                                                                                                                                 | 205668 | DM4616             |
| <b>GPON System</b>         | The use of ONUs from the manufacturer PADTEC can generate high CPU consumption by OLTs Datacom causing disconnections in some PPPoE sessions.                                                                                                                              | 271115 | DM4610 HW2         |
| <b>GPON System</b>         | Counters on PON interfaces display summed counts in groups of four ports. 01, 02, 05 e 06 03, 04, 07 e 08 09, 10, 13 e 14 11, 12, 15 e 16 17, 18, 21 e 22 19, 20, 23 e 24 25, 26, 29 e 30 27, 28, 31 e 32                                                                  | 183723 | DM4618             |

| Feature                       | Description                                                                                                                                                                                                                                                                                  | ID     | Affected Platforms |
|-------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>GPON System</b>            | Line Card removal after equipment boot causes alarm OLT_ADAPT_FAILURE, it can also impact services running on the mainboard, for this reason it is recommended to restart the equipment after removing the Line Card.                                                                        | 166666 | DM4618             |
| <b>ICMP Probe</b>             | ICMP Probe cannot be used in DmView.                                                                                                                                                                                                                                                         | 238656 | All                |
| <b>Interfaces CLI</b>         | Commit warnings are not generated if changes are made to a range of interfaces rather than a specific interface.                                                                                                                                                                             | 99138  | All                |
| <b>Interfaces CLI</b>         | The " <i>show interface link</i> " command may present problems if user performs a downgrade of firmware from version 12.0.0 or higher to version 11.4. After reverting to version 12.0.0 or higher, the problem no longer occurs.                                                           | 266766 | All                |
| <b>Interfaces CLI</b>         | The first execution of the <i>show interface utilization</i> command shows zero counters.                                                                                                                                                                                                    | 189451 | DM4618             |
| <b>Interfaces CLI</b>         | Commits involving Ethernet ports may take longer than usual.                                                                                                                                                                                                                                 | 255700 | DM4340             |
| <b>Interfaces CLI</b>         | The <i>show interface utilization</i> command may temporarily display inconsistent values.                                                                                                                                                                                                   | 249740 | DM4340             |
| <b>Interfaces Counters</b>    | PDU packets of L2 protocol <i>LACP</i> , <i>STP</i> , <i>EFM</i> , ... erroneously increment InDiscards counters on the interfaces on which they are configured.                                                                                                                             | 195934 | All                |
| <b>Interfaces Counters</b>    | Packets are counted in TX statistics even when the interface is down.                                                                                                                                                                                                                        | 245771 | DM4340             |
| <b>Interfaces Counters</b>    | The inDiscard and UnknownProto counters are not supported, displaying the value zero in show and through SNMP queries.                                                                                                                                                                       | 189689 | DM4920             |
| <b>Interfaces Link Status</b> | 100 Gbps links with OPTLaser OPT-8PLHG40DL QSFP transceivers may not turn up after restarting DmOS. In this situation, we recommend removing and reinserting the transceiver.                                                                                                                | 257266 | All                |
| <b>Interfaces Link Status</b> | If the 10G interface is configured as 1Gbps and using an electrical SFP, but the remote equipment is not forced to 1Gbps or has the 1Gbps capability disabled, the DM4780 will report link UP, however, the remote equipment will report link DOWN. In this case, no traffic will be passed. | 269126 | DM4780             |

| Feature                           | Description                                                                                                                                                                                                                                                                                                                                                                                                                             | ID     | Affected Platforms  |
|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|---------------------|
| <b>Interfaces<br/>Link Status</b> | If the 10G interface is configured as 1G and using an electrical SFP, after restarting the equipment, the 10G interface will be in a Down state. To assist in this situation, it is recommended to access the product and apply the following commands within the 10G interface: <i>"shutdown"</i> , <i>"commit"</i> , <i>"no shutdown"</i> e <i>"commit"</i> .                                                                         | 272099 | DM4780              |
| <b>Interfaces<br/>Link Status</b> | The interface LEDs on the LC-800 may display a <i>Link Down</i> status even though the interfaces are Up and operating normally.                                                                                                                                                                                                                                                                                                        | 252921 | DM4920              |
| <b>Interfaces<br/>Link Status</b> | When using 25Gbps interface with 25Gbps modules, the OLT may keep the interface in a Down state after OLT restart. To assist in this situation, it is recommended to access the product and apply the following commands within the 25G interface: <i>"shutdown"</i> , <i>"commit"</i> , <i>"no shutdown"</i> e <i>"commit"</i> .                                                                                                       | 271668 | DM4618              |
| <b>Interfaces<br/>Link Status</b> | Interface 25G operating at 1G speed and electrical SFP may take up to 7 seconds to detect a link down, causing delays in protocol convergence.                                                                                                                                                                                                                                                                                          | 176787 | DM4770              |
| <b>Interfaces<br/>Link Status</b> | When enabling negotiation in 10 Gbps interface the link will transition from UP to DOWN and then returning to UP, remaining stable.                                                                                                                                                                                                                                                                                                     | 116953 | DM4050<br>DM4250    |
| <b>Interfaces<br/>Link Status</b> | After a link flap, a 400G interface may remain operationally DOWN (Admin UP and without shutdown configured) when the three interface modes (100G, 200G and 400G) of the same physical slot are configured simultaneously.                                                                                                                                                                                                              | 276616 | DM4780              |
| <b>Interfaces<br/>Performance</b> | When a fiber is broken, making the link unidirectional, on a non-negotiated interface, the convergence time will depend on the timers of the protocols that are in use on the interface in question, greatly affecting the convergence time. To assist in this situation, it is recommended to use link verification protocols such as EFM and LACP (short mode) to force interface blocking and convergence of higher level protocols. | 213156 | All                 |
| <b>Interfaces</b>                 | Ports 1/1/3 and 1/1/4 of the DM4340 4GX do not work with electrical transceivers.                                                                                                                                                                                                                                                                                                                                                       | 271808 | DM4340 - 2GT<br>4GX |
| <b>IP Routing</b>                 | Static routes configuration with administrative distance equal to that of the protocols causes the installation of prefix with all received nexthops as if it had ECMP between protocols. To assist in this situation, it is recommended to configure the administrative distance on the static route different from the values used by the protocols, which are: connected 0, eBGP 20, OSPF 30, OSPF IA 30, OSPF E2 110 and iBGP 200.  | 269819 | All                 |

| Feature         | Description                                                                                                                                                                                                                                                                                                             | ID     | Affected Platforms |
|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| IP Routing      | It is not supported to use the same network address of an L3 interface in the vrf of MGMT interface.                                                                                                                                                                                                                    | 270398 | All                |
| IP Routing      | If the VRF is changed between the L3 or Loopback interfaces, traffic will no longer work. It is recommended to remove the interface configurations and reconfigure again.                                                                                                                                               | 267406 | All                |
| IP Routing      | Poor performance in <i>show ip route</i> , <i>show ipv6 route</i> , <i>show ip fib brief</i> , <i>show ipv6 fib brief</i> and <i>show ip bgp prefixes</i> commands when the equipment has a number of prefixes close to the chip's limit.                                                                               | 158636 | All                |
| IP Routing      | Installing a number of routes exceeding the limit specified in the Product Specifications may result in excessive memory consumption, causing automatic equipment reboot.                                                                                                                                               | 213519 | All                |
| IP Routing      | DmOS continues forwarding traffic to a next-hop that was resolved, even if this next-hop stops responding.                                                                                                                                                                                                              | 210767 | All                |
| IP Routing      | DmOS does not correctly recognize packets with VLANs and MPLS labels in the context of Traceroute, resulting in no response to Traceroutes.                                                                                                                                                                             | 189793 | All                |
| IP Routing      | Static routes configured in VRF are not installed in the RIB when pointing to a remote host via L3VPN tunnel.                                                                                                                                                                                                           | 196401 | All                |
| IP Routing      | The option to change the OSPF area type to NSSA does not appear. As a workaround, it is necessary to remove and add the area again as NSSA.                                                                                                                                                                             | 276961 | All                |
| L2VPN Backup PW | The Backup PW uses the PW Status TLV to signal the main and backup PW information, for this reason it is necessary that neighbors have support for PW Status TLV and this TLV is enabled in L2VPN.                                                                                                                      | 144471 | All                |
| L2VPN CLI       | The <b>show mpls l2vpn hardware</b> command works only for VPWS.                                                                                                                                                                                                                                                        | 159872 | All                |
| L2VPN CLI       | Command <i>show mpls l2vpn vpws-group detail   name</i> keep doing pagination.                                                                                                                                                                                                                                          | 148448 | All                |
| L2VPN CLI       | It is not supported L2VPN configuration in interface which is MPLS access and uplink. Despite the commit being accepted, a warning is generated in this condition <i>Some MPLS VPN's have access and uplink interfaces in common. In this way those access interfaces will not be able to encapsulate MPLS traffic.</i> | 135480 | All                |
| L2VPN CLI       | In VPLS configurations, the <i>show mpls l2vpn vpls-group detail</i> command incorrectly shows the Status of Remote Access Interface as up even when the remote physical interface is down.                                                                                                                             | 203302 | All                |



| Feature                   | Description                                                                                                                                                                                                                                                                                                                                                            | ID     | Affected Platforms |
|---------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>L2VPN CLI</b>          | The command <i>show mpls l2vpn vpls-group mac</i> can become slow when there is a large number of learned MAC addresses.                                                                                                                                                                                                                                               | 251846 | All                |
| <b>L2VPN Counters</b>     | When there is a lag interface with LACP as a VPWS or VPLS access, the VPN counters are incremented by LACP control packets.                                                                                                                                                                                                                                            | 99727  | All                |
| <b>L2VPN Counters</b>     | VPN access interface counters can be incremented even when TX traffic is discarded.                                                                                                                                                                                                                                                                                    | 121403 | All                |
| <b>L2VPN Counters</b>     | Multicast packets encapsulated in L2VPNs are not registered in ingress counters of VPN uplink interfaces.                                                                                                                                                                                                                                                              | 127464 | All                |
| <b>L2VPN GPON</b>         | It is not possible to configure a vpls-group with access-interface service-port when another vpls-group with access-interface gigabit-ethernet already exists. You must remove the Ethernet group before committing the service-port group.                                                                                                                            | 197833 | All                |
| <b>L2VPN Interop</b>      | After changing the MTU on the L2VPN between Juniper and DmOS, it may be necessary to perform a shutdown/no shutdown operation on the access interface, if the operational status of the L2VPN is not Up.                                                                                                                                                               | 179558 | All                |
| <b>L2VPN Interop</b>      | L2VPN tunnel between Cisco and DmOS remains Up even when the PW is Down.                                                                                                                                                                                                                                                                                               | 158596 | All                |
| <b>L2VPN L2 Protocols</b> | It is not supported xSTP, EAPS and ERPS protocols in L2VPN access ports.                                                                                                                                                                                                                                                                                               | 241045 | All                |
| <b>L2VPN L3 Protocols</b> | Changes in OSPF VLAN cost may impact VPN traffic in VPWS that forward STP, LACP, and LLDP packets.                                                                                                                                                                                                                                                                     | 264992 | All                |
| <b>L2VPN L3 Protocols</b> | MPLS packets with TTL = 1 that have encapsulated L3 packets, such as the ICMP used in traceroute, are not being copied to the CPU and therefore the hop does not respond to ICMP.                                                                                                                                                                                      | 272043 | DM4780             |
| <b>L2VPN LAG</b>          | Traffic forwarding failure via LAG in VPN configurations between two devices, where received data does not exit through the uplink. The issue is related to adding VLANs to "untagged" uplinks, which automatically adds a VLAN tag before the MPLS label. This causes a forwarding failure, as the LAG does not process packets with inconsistent VLAN tags properly. | 215732 | All                |
| <b>L2VPN LAG</b>          | Using a LAG as an access interface for a VPN, if the LACP causes the LAG to go down, the VPN is not notified and remains in Up state.                                                                                                                                                                                                                                  | 213603 | All                |

| Feature                  | Description                                                                                                                                                                                                                                                               | ID     | Affected Platforms                   |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------------------------|
| <b>L2VPN LAG</b>         | LACPDUs packets are dropped on access interfaces of MPLS VPNs when the OAM EFM protocol is configured on this interface. To LACP work it is necessary remove the OAM EFM configuration in the access interface.                                                           | 170840 | All                                  |
| <b>L2VPN LAG</b>         | There is no data traffic on a VPLS VPN if an untagged LAG is used in the uplink and the neighbor is a different (non Datacom) vendor. The alternative is to change the uplink to tagged.                                                                                  | 182353 | DM4270<br>DM4380<br>DM4770           |
| <b>L2VPN Performance</b> | Poor performance in troubleshooting commands of LDP or RSVP VPNs, GET of configuration via NETCONF, configuration save and configuration commit when equipment have many L2VPNs or prefixes.                                                                              | F1898  | All                                  |
| <b>L2VPN VLAN</b>        | Double tagged packets in a port based L2VPN lose outer tag when traffic is sent to the access interface.                                                                                                                                                                  | 134999 | DM4270<br>DM4380<br>DM4770<br>DM4775 |
| <b>L2VPN VLAN</b>        | Selective Encapsulation with Double Tag packets does not work.                                                                                                                                                                                                            | 274445 | DM4780                               |
| <b>L3VPN</b>             | L3VPN may not install prefixes when the neighbor's community attribute is set to Standard. We recommend changing the neighbor's configuration to Extended mode (the default for DmOS) or configuring the "both" mode available from some vendors.                         | 253548 | All                                  |
| <b>L3VPN</b>             | It is not possible to change VRF name of an existing BGP instance.                                                                                                                                                                                                        | 113503 | All                                  |
| <b>L3VPN</b>             | Removing an L3 interface from an L3VPN that contains more than one other L3 interface may cause up to 35 seconds delay before communication works again on the remaining interfaces of that VPN. For example, ping and traceroute will not function during this interval. | 255634 | All                                  |
| <b>LAG</b>               | Dynamic LAG balancing can cause traffic to be port migrating when near the full bandwidth limit of the LAG.                                                                                                                                                               | 149885 | All                                  |
| <b>LAG</b>               | LACP between Huawei and DmOS may experience instability due to synchronization of the LACP Key.                                                                                                                                                                           | 164088 | All                                  |
| <b>LAG</b>               | If any of the members are link-down when creating a LAG, traffic failure may occur when the link change to the UP state. In this case, it is recommended to recreate the LAG with the members in the link-UP state.                                                       | 268563 | DM4340                               |
| <b>LAG</b>               | It is not possible to configure LAG members as a port-mirror source, only the entire LAG.                                                                                                                                                                                 | 273649 | DM4340                               |

| Feature             | Description                                                                                                                                                                                          | ID     | Affected Platforms         |
|---------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------------|
| License             | In equipment with MPLS license enabled, it could occur a failure when loading a configuration file with load override.                                                                               | 106007 | All                        |
| License             | Commit check does not work properly in MPLS license in some cases return valid instead invalid and in other cases the opposite.                                                                      | 136296 | All                        |
| MAC Addresses       | The <b>show mac-address-table</b> command presents invalid parameters in autocomplete of CLI.                                                                                                        | 91495  | All                        |
| MAC Addresses       | The <b>show mac-address-table type static</b> command shows all entries of MAC table.                                                                                                                | 91496  | DM4618                     |
| MAC Addresses       | Device shows MAC table entries with bogus addresses, when destination MAC is IEEE.                                                                                                                   | 253063 | DM4340                     |
| MAC Addresses       | Packets sent to a specific MAC address prevent the aging process from acting on that MAC address, even if there is no longer traffic with that source MAC.                                           | 263595 | DM4780                     |
| MAC Addresses       | The mac-limit for a LAG was relearned on every member change.                                                                                                                                        | 274252 | DM4340                     |
| Management Out-Band | Mgmt interface negotiated in 1 Gbps cause problems in equipment services. As workaround use management via L3 interface.                                                                             | 143985 | DM4050<br>DM4170<br>DM4615 |
| Management          | After a reboot, the device may temporarily lose TELNET/SSH management.                                                                                                                               | 255009 | DM4340                     |
| MPLS                | MPLS commands can break columns in a way that make it difficult to understand, automating commands in the CLI and making it impossible to use of filters present in the CLI.                         | 172237 | All                        |
| MPLS                | Excessive prefixes can cause the <i>show ldp database</i> command to return application timeout.                                                                                                     | 245338 | All                        |
| MPLS                | Removing and reinserting LDP and RSVP in a commit generates application timeout. If the user tries to reapply the configuration, application communication failure occurs and the equipment reboots. | 244569 | All                        |
| MPLS                | Using static LSPs with IPs not present in the infrastructure generates high processing in DmOS equipment, potentially causing instability and failures.                                              | 209530 | All                        |
| MPLS                | When the VPN is established between two directly connected neighbors, the PCP to EXP mapping does not work.                                                                                          | 274032 | DM4780                     |

| Feature              | Description                                                                                                                                                                                                                                                                                                                                                                    | ID     | Affected Platforms |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>MPLS L2VPN</b>    | In VPLS scenarios with the DM4780 acting as LER, when the first character of the encapsulated frame's destination MAC address is 4 or 6, the packet is misinterpreted as IPv4 or IPv6 and dropped on the uplink.                                                                                                                                                               | 268711 | DM4780             |
| <b>OSPF</b>          | It's not possible to show details of a specific OSPF neighbor. Through the <b>show ip ospf neighbor detail</b> command, it is possible to check all neighbors simultaneously.                                                                                                                                                                                                  | 91647  | All                |
| <b>OSPF</b>          | If OSPF configuration was removed and reinserted with area index changed in a single commit, it is necessary to reinsert the L3 interface in OSPF configuration.                                                                                                                                                                                                               | 96565  | All                |
| <b>OSPF</b>          | OSPF export prefix-list does not work in prefix redistributed by ASBR in the ABR.                                                                                                                                                                                                                                                                                              | 168392 | All                |
| <b>OSPF</b>          | Removing and adding new OSPF router in the same commit creates an invalid OSPF router. To avoid the failure, it is necessary to perform the configuration in separate commits.                                                                                                                                                                                                 | 168219 | All                |
| <b>OSPF</b>          | In case of reboot, it is possible that LSA type 4 will not be created and disseminated by the ASBR, affecting prefix learning in other OSPFv3 areas. To normalize it is necessary to execute the <i>clear ospfv3</i> command in the ASBR or disable and enable the link (s) for the router that does not have an LSA Summary so that the LSAs are created and published again. | 216581 | All                |
| <b>OSPF</b>          | DmOS allows configuring more than one OSPF process in the global VRF if the commit is performed when exiting configuration mode confirming the message <i>"Uncommitted changes found, commit them? yes/no/CANCEL"</i> . Although accepted, the protocol does not become operational.                                                                                           | 252994 | All                |
| <b>QoS</b>           | Policer or ACL by DSCP does not match if packet has the ECN bit with value different from 0.                                                                                                                                                                                                                                                                                   | 146120 | All                |
| <b>QoS</b>           | The PCP configuration on the interface only acts on untagged packets, that is, if the interface has QinQ, the PCP of interface will not be set in the QinQ tag for tagged packets. The QinQ tag will have the PCP copied from the packet's original tag.                                                                                                                       | 267545 | DM4780             |
| <b>QoS - Policer</b> | Policer egress counters do not work when there is an user-defined counter in the same VLAN.                                                                                                                                                                                                                                                                                    | 126935 | All                |
| <b>QoS - Policer</b> | Policer may not correctly limit bandwidth on QinQ VPN access interfaces that encapsulate more than 200 VLANs.                                                                                                                                                                                                                                                                  | 251845 | All                |

| Feature                | Description                                                                                                                                                                                               | ID     | Affected Platforms |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>QoS - Policer</b>   | It is not possible to limit the bandwidth of a group of VLANs in MPLS deencapsulation.                                                                                                                    | 170558 | All                |
| <b>QoS - Policer</b>   | Drop counters in egress stage policers are not supported in DM461x platforms.                                                                                                                             | 126822 | DM461x             |
| <b>QoS - Policer</b>   | Counters are supported for only one policer at a time.                                                                                                                                                    | 276364 | DM4340             |
| <b>QoS - Policer</b>   | It is not possible to police bandwidth modified by ACL actions.                                                                                                                                           | 277818 | DM4340             |
| <b>QoS - Policer</b>   | Packets dropped by the policer feature are not shown in the discard counters.                                                                                                                             | 277819 | DM4340             |
| <b>QoS - Shapper</b>   | Burst configuration on egress rate-limit is not fully achieved.                                                                                                                                           | 249390 | DM4340             |
| <b>QoS - Scheduler</b> | The queue <i>Strict Priority - SP</i> will not be fully served when the WFQ Scheduler is used with other queues configured with their respective weights.                                                 | 249736 | DM4340             |
| <b>PBR</b>             | It does not support PBR with ECMP.                                                                                                                                                                        | 138443 | All                |
| <b>Ping</b>            | Ping does not for work for local address destination when it is specified a source interface.                                                                                                             | 105307 | All                |
| <b>Ping</b>            | The IP address specified by the source interface parameter in the ping command is not respected when in VRFs.                                                                                             | 120791 | All                |
| <b>Ping</b>            | Ping does not for work for IPv6 local address destination in VRF.                                                                                                                                         | 152836 | All                |
| <b>Ping</b>            | In an equipment with VRF leaking and redistribute BGP in OSPF, it is not possible ping directly connected addresses.                                                                                      | 123157 | All                |
| <b>Ping</b>            | Inactive L3 interface continues to respond to ICMP echo request (ping) packets.                                                                                                                           | 161120 | All                |
| <b>Ping</b>            | In some situations the error <i>Failed to load BPF prog: 'Operation not permitted'</i> may occur in Ping IPv6 in VRF, after this error Ping does not work anymore, being necessary restart the equipment. | 168676 | All                |
| <b>Port Mirror</b>     | Port Mirror does not mirror L2 layer protocol packets (LLDP, EFM...) sent by CPU in the TX direction of the interface.                                                                                    | 272098 | DM4780             |
| <b>Provision</b>       | Equipment will restart if the Line Card 800 is physically inserted and removed within an interval of less than 10 seconds.                                                                                | 200219 | DM4920             |

| Feature                 | Description                                                                                                                                                                                                                                                                                                                                 | ID     | Affected Platforms |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>RDM</b>              | After removing the RDM configuration from a slave equipment that had already established connection with a master RDM, show commands will keep displaying RDM informations that are not in the configuration anymore.                                                                                                                       | 126618 | All                |
| <b>RSVP</b>             | When the LSP priority is changed, there is no immediate update, leading to a timeout and the re-establishment of the LSP. In this LSP failure scenario, data will be lost.                                                                                                                                                                  | 213425 | All                |
| <b>RSVP</b>             | When there is a bandwidth shortage on an L3 interface configured in RSVP, the wrong node is the one reporting the failure. In this same situation, the error message is also incorrect, reporting an unknown error instead of <b>Requested bandwidth unavailable</b> . Tunnel links must be analyzed to check where bandwidth is exhausted. | 211869 | All                |
| <b>RSVP Interop</b>     | There is no interoperability between Cisco IOS XR's RSVP hello and DmOS due to DmOS not supporting the RSVP hello node-id.                                                                                                                                                                                                                  | 183958 | All                |
| <b>RSVP MTU</b>         | RSVP interface tunnel MTU does not used in L2VPNs.                                                                                                                                                                                                                                                                                          | 164084 | All                |
| <b>RSVP MTU</b>         | DmOS takes time to update the interface MTU on the LSPs after convergence, in some cases this time can reach minutes. Depending on the MTU of the L3 interface before convergence, the data passing through the LSPs using Path MTU Discovery will be smaller than expected until DmOS updates the MTU.                                     | 190789 | All                |
| <b>RSVP Performance</b> | Core-dump in nbase may cause the L3 interface used in VPNs to go Down, affecting traffic. In this case, a reboot of the equipment is required.                                                                                                                                                                                              | 201826 | All                |
| <b>RSVP Performance</b> | TE Tunnel reconvergence may fail after network failures due to the OSPF protocol failing to recalculate routes after network recovery.                                                                                                                                                                                                      | 240738 | All                |
| <b>RSVP Performance</b> | Convergence of MPLS-RSVP Tunnels using Hello messages can take longer than expected.                                                                                                                                                                                                                                                        | 192367 | All                |
| <b>RSVP - Tunnel</b>    | Tunnels may not go up if the equipment has more than one area configured in the equipment. To solve it is necessary to remove the excess areas and restart the OSPF process using the command <i>clear ospf process &lt;process_id&gt;</i> .                                                                                                | 160143 | All                |
| <b>RSVP - Tunnel</b>    | Tunnel in headend may not work if OSPF router-id was changed in tailend. Workaround is run <i>clear ospf process</i> command in the tailend equipment.                                                                                                                                                                                      | 154174 | All                |

| Feature              | Description                                                                                                                                                                                                                                                            | ID     | Affected Platforms   |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|
| <b>RSVP - Tunnel</b> | Removing the RSVP Tunnel on one side causes the other side to remove the Tunnel only after receiving RSVP Hello.                                                                                                                                                       | 187397 | All                  |
| <b>RSVP - Tunnel</b> | L2VPN configured with a tunnel that is destined for the wrong equipment causes L2VPN stays UP, but the data will be forwarded to the wrong equipment.                                                                                                                  | 149350 | All                  |
| <b>Sensors</b>       | Possibility of error log from sensors of equipment.                                                                                                                                                                                                                    | 117219 | All                  |
| <b>sflow</b>         | The sflow_245.sysuptime field in the SFLOW packet incorrectly displays equipment uptime.                                                                                                                                                                               | 205524 | All                  |
| <b>SNMP</b>          | Removing the engine-id via Netconf causes the engine-id to become a fixed MAC different from the device's global MAC. To resolve this, it is necessary to change the engine-id via CLI or Netconf.                                                                     | 239640 | All                  |
| <b>SNMP</b>          | If SNMP agent listen was configured in a L3/loopback interface and the IP/VRF configuration of this interface was changed, the SNMP get would not work. To workaround this issue it is necessary configure the interface before adding interface in SNMP agent listen. | 125267 | All                  |
| <b>SNMP</b>          | It is not possible configure the <i>snmp vacm access</i> with global VRF via DmView.                                                                                                                                                                                   | 151642 | All                  |
| <b>SNMP</b>          | With Zabbix default polling time, the DM4920 port counters may return an error.                                                                                                                                                                                        | 270403 | DM4920               |
| <b>SNMP</b>          | There is no support to SNMP queue packets.                                                                                                                                                                                                                             | -      | DM4050<br>DM4250     |
| <b>SNMP - MIB</b>    | The first index of the MIB object ENTITY-MIB::entPhysicalSerialNum does not return the equipment serial number.                                                                                                                                                        | 137978 | All                  |
| <b>SNMP - MIB</b>    | The Ifindex returned in the ipAdEntIfIndex object does not point to any interface, meaning that tools that use SNMP are unable to correlate the IP address read with any equipment interface.                                                                          | 191764 | All                  |
| <b>SNMP - MIB</b>    | The object TWAMP-MIB::twampTestDescription does not return a value when the <i>Twamp test session</i> fails.                                                                                                                                                           | 253119 | All                  |
| <b>SNMP - MIB</b>    | ENTITY-MIB returns triplicate slot informations.                                                                                                                                                                                                                       | 146733 | DM4610-HW2<br>DM4615 |
| <b>SNMP - MIB</b>    | The SNMP object GPON-ONU-IF-MIB::onuifType returns an incorrect value for the ONU's GEM interface.                                                                                                                                                                     | 252453 | DM461X               |

| Feature             | Description                                                                                                                                                                                                               | ID                 | Affected Platforms |
|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|--------------------|
| <b>SNMP - MIB</b>   | ifAlias for GPON interface is only created after configuring a description on the GPON interface.                                                                                                                         | 168099             | DM461x             |
| <b>SNMP - MIB</b>   | SNMP Get Bulk returns values for objects outside the selected MIB tree.                                                                                                                                                   | 251397             | All                |
| <b>SNMP - MIB</b>   | The interface MAC Address may be returned as zero via SNMP.                                                                                                                                                               | 252033             | DM4340             |
| <b>SNMP - Traps</b> | Sending traps or informs of Dying Gasp using SNMPv3 is not supported.                                                                                                                                                     | 270076             | All                |
| <b>SNMP - Traps</b> | Dying Gasp SNMP traps are not sent for SNMP targets associated to mgmt VRF or user VRFs.                                                                                                                                  | US90189<br>US90190 | DM4360<br>DM4370   |
| <b>SNTP</b>         | IPv6 addresses with more than 15 characters are not fully displayed in the <i>show sntp brief</i> command.                                                                                                                | 214837             | All                |
| <b>Synchronism</b>  | Using syncE without ESMC quality information may lead to switching failure in case of link failure.                                                                                                                       | 211884             | DM4376             |
| <b>Synchronism</b>  | SyncE does not work when there is no active PTP configuration.                                                                                                                                                            | 211879             | DM4376             |
| <b>Synchronism</b>  | Firmware update may generate core-dump in PTP. However, the application continues to work correctly.                                                                                                                      | 215131             | DM4376             |
| <b>Syslog</b>       | Possibility of core-dumps when performing <b>load override</b> command for load some specific configuration.                                                                                                              | 117306             | All                |
| <b>Syslog</b>       | Modification in L3 interfaces used for reaching the syslog server may cause the syslog server not to work. As a workaround, it is needed to remove the syslog configuration, commit it and configured it again.           | 127781             | All                |
| <b>System</b>       | When receiving an ESMC packet with additional padding, the sync_mgr process may generate repeated core-dumps.                                                                                                             | 278530             | DM4370             |
| <b>System ARP</b>   | RARP packets do not update the host-table causing the convergence of the VMs from software using RARP such as VMware take longer. This longer time is due to the need for a VM ARP to be the trigger for host resolution. | -                  | DM4618             |
| <b>System CPU</b>   | Packets with broadcast or network destinations address are sent to CPU. This unexpected traffic can increase the CPU usage.                                                                                               | 248922             | All                |
| <b>System CPU</b>   | High CPU usage scenarios may cause equipment reboot.                                                                                                                                                                      | 269622             | All                |
| <b>System CPU</b>   | Corrupted log files can increase CPU usage and cause the equipment to execute <i>show log</i> command slowly.                                                                                                             | 255759             | All                |
| <b>System CPU</b>   | IGMP protocol packets are sent to the CPU via incorrect queues.                                                                                                                                                           | 268940             | DM4780             |



| Feature                | Description                                                                                                                                                                                                                                                                                                                  | ID     | Affected Platforms |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>System CPU</b>      | Cpu-dos-protect counters erroneously increment Rx of packets in all queues.                                                                                                                                                                                                                                                  | 188867 | DM4170             |
| <b>System CPU</b>      | The device does not have <i>cpu-dos-protection</i> functionality, even though that feature shows up in the CLI.                                                                                                                                                                                                              | 252458 | DM4340             |
| <b>System CPU</b>      | IPv6 unknown hosts packets are forwarded to queue 38, which handles ICMPv4_v6, instead of the correct queue 37, which handles unknown hosts.                                                                                                                                                                                 | 273965 | DM4780             |
| <b>System FAN</b>      | DM4610-HW2 equipment operating FANs with speed above necessary, causing excessive noise.                                                                                                                                                                                                                                     | 154171 | DM4610             |
| <b>System Memory</b>   | No alarm is raised for high flash memory usage, total memory usage may affect equipment operation.                                                                                                                                                                                                                           | 273050 | All                |
| <b>System NET-CONF</b> | The equipment may reach the maximum number of SSH sessions when using <i>nmap -sT</i> when the TCP connection closes without sending the SSH Banner. The device can only be recovered by rebooting. This can be avoided by using the <i>-sS</i> parameter instead of <i>-sT</i> in the nmap requests.                        | 274496 | All                |
| <b>System PSU</b>      | PSU 200 DC does not have temperature sensors.                                                                                                                                                                                                                                                                                | -      | All                |
| <b>System Reboot</b>   | DmOS may restart if there is any equipment connected to serial sending signals with invalid characters.                                                                                                                                                                                                                      | 162834 | All                |
| <b>System Reboot</b>   | SNMP queries of the OSPF table can cause the device to reboot when it has more than 100 OSPF areas configured.                                                                                                                                                                                                               | 253178 | All                |
| <b>System Reboot</b>   | Reboot logs may be missing on CLI, however, logs are still sent to the remote server if configured.                                                                                                                                                                                                                          | 251895 | DM4340             |
| <b>System Reboot</b>   | After a reboot, the equipment loses its configured clock. If an SNTP server is configured, it will synchronize and the device will get the correct time.                                                                                                                                                                     | 251894 | DM4340             |
| <b>System Reboot</b>   | Device does not send confirmation when reboot is executed via netconf.                                                                                                                                                                                                                                                       | 250044 | DM4340             |
| <b>System Reboot</b>   | Inserting the Line Card after the restarting the equipment will cause it to be in the blocked state and shows CARD_UNINITIALIZED alarm. In order for it to become operational it will be necessary to restart the DM4618. The status of the platform and Line Card can be checked through the command <i>show platform</i> . | -      | DM4618             |

| Feature              | Description                                                                                                                    | ID     | Affected Platforms                                                                     |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------|--------|----------------------------------------------------------------------------------------|
| <b>System Config</b> | <b>Save-</b> The config save may now take up to twice as long on some platforms. The commit time remains the same.             | 277910 | DM4050,<br>DM4170,<br>DM4250,<br>DM4270,<br>DM4370,<br>DM4610-HW,<br>DM4612,<br>DM4615 |
| <b>Traceroute</b>    | Equipment does not show in the traceroute path if does not exist prefix installed in route table.                              | -      | All                                                                                    |
| <b>Traceroute</b>    | Traceroute in ECMP scenarios may yield duplicate results and timeouts in some requests.                                        | 241879 | All                                                                                    |
| <b>Transceivers</b>  | The QSFP 100G transceiver (MJ-QSFP100G-LR4) may experience problems and the link with the remote equipment may not occur.      | 268877 | All                                                                                    |
| <b>Transceivers</b>  | QSFP-DD 400G transceivers display incorrect Ethernet Standard information.                                                     | 267542 | All                                                                                    |
| <b>Transceivers</b>  | Only are supported 100 Mbps optical transceivers in forced mode and only in GX interfaces.                                     | -      | All                                                                                    |
| <b>Transceivers</b>  | Log of link UP is generated whenever an SFP Copper is inserted even without physical cable.                                    | 94344  | All                                                                                    |
| <b>Transceivers</b>  | Transceiver inventory informations are shown duplicated in DmView.                                                             | 126537 | All                                                                                    |
| <b>Transceivers</b>  | The GX interfaces do not support SFP Copper.                                                                                   | 206400 | DM4376                                                                                 |
| <b>Transceivers</b>  | Removal of a SFP and insertion of another one in an interface may not be identified if it is performed in less than 3 seconds. | 109496 | DM4170                                                                                 |
| <b>Transceivers</b>  | The 10 Gbps interfaces do not support autonegotiation.                                                                         | -      | DM4270-48XS                                                                            |
| <b>Transceivers</b>  | The 25 Gbps interfaces do not support autonegotiation.                                                                         | -      | DM4770-16CX<br>DM4618<br>DM4270<br>8XS+16VS+6CX                                        |

| Feature             | Description                                                                                                                                                                                                                                                                                                                                                                                                    | ID     | Affected Platforms                                    |
|---------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|-------------------------------------------------------|
| <b>Transceivers</b> | The 100 Gbps interfaces do not support autonegotiation.                                                                                                                                                                                                                                                                                                                                                        | -      | DM4618,<br>DM4770,<br>DM4270,<br>DM4780 and<br>DM4920 |
| <b>Transceivers</b> | The GX interfaces of DM4610 platform do not support Copper SFPs at speeds of 10 and 100 Mbps. Some models of Copper SFPs can operate at speeds of 1 Gbps, but are not homologated by Datacom.                                                                                                                                                                                                                  | -      | DM461x                                                |
| <b>Transceivers</b> | There is no support for non-homologated transceivers. The use of non-approved QSFP modules may harm the DWDM infrastructure with inadequate lambda or may keep the module's laser turned on. Interfaces with non-homologated transceivers must be in shutdown. If a non-homologated module is connected to the equipment, an alarm will be displayed, which can be viewed using the <b>show alarm</b> command. | EP1200 | DM4920                                                |
| <b>Transceivers</b> | After removing the 400G transceiver from the interface, inserting it again does not establish the link. To normalize, reboot the DmOS.                                                                                                                                                                                                                                                                         | 201652 | DM4920                                                |
| <b>Transceivers</b> | Coherent link quality statistics do not provide reliable values when the link is in failure and/or administratively disabled.                                                                                                                                                                                                                                                                                  | 200261 | DM4920                                                |
| <b>Transceivers</b> | 25 Gbps interfaces do not support FEC cl108.                                                                                                                                                                                                                                                                                                                                                                   | 160838 | DM4618                                                |
| <b>Transceivers</b> | The transmitter bias current (TX Bias) measurement is reported incorrectly for transceiver 377.1515.00. A scale multiplier is not being considered, causing an incorrect value.                                                                                                                                                                                                                                | 273049 | DM4920                                                |
| <b>Transceivers</b> | QSFP56 transceivers of the QSFP_PLUS_CMIS type do not support Appsel configuration; therefore, when the interface is split, since it is not possible to change the Appsel, the new split interfaces will not work.                                                                                                                                                                                             | 274829 | DM4780                                                |
| <b>Transceivers</b> | On QSFP56 200G modules with 4 optical lanes, the digital diagnostics information (current, Tx and Rx power) for lanes 2, 3 and 4 is not displayed in the <i>show interface transceivers</i> command.                                                                                                                                                                                                           | 274828 | DM4780                                                |
| <b>Transceivers</b> | For some third-party transceivers with a power class higher than 3.5W (class 4), DmOS may not enable the module to leave low-power mode as required by the SFF8636 specification. As a result, the transceiver laser is not enabled (TX Power around -40 dBm) and consequently the link does not come up.                                                                                                      | 278762 | DM4770 16CX                                           |
| <b>TWAMP</b>        | It takes time to run <i>show oam twamp</i> command.                                                                                                                                                                                                                                                                                                                                                            | 135553 | All                                                   |

| Feature      | Description                                                                                                                                                                            | ID     | Affected Platforms |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>TWAMP</b> | After failure in the TWAMP test-session, the SNMP objects remain with the values of the last successful test.                                                                          | 131279 | All                |
| <b>TWAMP</b> | Logging <b>TWAMP-SERVWAIT_TIMEOUT</b> in case of protocol communication failure. It does not impact the service.                                                                       | 183902 | All                |
| <b>TWAMP</b> | Reboot may generate a core-dump in the Twamp Client process.                                                                                                                           | 209664 | All                |
| <b>TWAMP</b> | Using non-default ports for Twamp may prevent connection initiation after reboot.                                                                                                      | 207290 | All                |
| <b>TWAMP</b> | TWAMP sender may remain in failure state even after connectivity recovery with the reflector.                                                                                          | 172387 | All                |
| <b>TWAMP</b> | A <i>TWAMP test-session</i> fails when the <i>reflector</i> is located more than one hop away.                                                                                         | 254622 | DM4340             |
| <b>TWAMP</b> | During the interval in which TWAMP starts a new session and finishes the measurements, the SNMP MIB returns zeroed values instead of the values from the last finished session.        | 273760 | All                |
| <b>VLAN</b>  | Take a long time to do show, commit, save and netconf of large amount of VLAN.                                                                                                         | -      | All                |
| <b>VLAN</b>  | The interfaces after VLAN (dot1q) refactoring are in alphabetical order and not in numerical order in the command <i>show running-config</i> .                                         | 159954 | All                |
| <b>VLAN</b>  | Due to a lack of consistency in the CLI, the VLAN Translate rules configuration across VLAN ranges can exceed the available hardware resource limits when using VLAN mapping and QinQ. | 272142 | DM4780             |
| <b>VLAN</b>  | No support for adding a third tag to packets that are already double-tagged.                                                                                                           | 256028 | DM4780             |
| <b>VLAN</b>  | In double-tagged packets with different priorities, the internal VLAN priority is overwritten by the external VLAN priority.                                                           | 260639 | DM4780             |
| <b>VLAN</b>  | MPLS frames encapsulated in a GRE tunnel may be discarded at the switch ingress if there is a vlan-mapping rule at the ingress.                                                        | 274949 | DM4270             |
| <b>VLAN</b>  | Packets arriving at the switch with a VLAN tag equal to the native VLAN do not receive the native VLAN tag when sent to the CPU, even with QinQ enabled.                               | 276361 | DM4780             |

| Feature        | Description                                                                                                                                                                                                                                                                                                                        | ID     | Affected Platforms |
|----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|
| <b>XGS-PON</b> | The default profile for the DM4616 from version 9.4 is XGS-PON. Therefore, if the user does not specify their profile, all ONUs will be configured with the XGS (10GB) profile, regardless of whether it is a GPON or XGS-GPON ONU. If it is a GPON ONU, the ONU will even go to Up, however, it will not forwarding traffic data. | 184045 | DM4616             |
| <b>XGS-PON</b> | ONUs may have <i>Down/Active pending</i> status after ONU or OLT shutdown. It is necessary to restart the ONU to return to normal operation.                                                                                                                                                                                       | 182587 | DM4616             |
| <b>XGS-PON</b> | If the xgspon interface mode is set to gpon, switching to xgspon and returning to gpon mode will only be applied after rebooting the OLT.                                                                                                                                                                                          | 183105 | DM4616             |
| <b>XGS-PON</b> | ONU DM984-42x data traffic failure when using LAN ports 2, 3 or 4.                                                                                                                                                                                                                                                                 | 181558 | DM4616             |
| <b>XGS-PON</b> | If an ONU DM986-100 SFU with 2 GEMs is used, 1 GEM for ethernet and a second for IPHost, the first GEM must be configured for IPHost and the second GEM for ethernet. Otherwise, you may lose data in the upstream direction.                                                                                                      | 176959 | DM4616             |
| <b>xSTP</b>    | The cost of STP on interfaces by default is 20000 regardless of the interface speed, making the paths chosen by STP links with lower speed. As a workaround it is possible to change the cost in the interfaces manually as desired.                                                                                               | 154927 | All                |
| <b>xSTP</b>    | BPDUs are processed and discarded in the CPU instead of being discarded in the chipset, this can generate an overload on the equipment's CPU if a significant amount of BPDUs is received.                                                                                                                                         | 132238 | All                |

## 5 Document Versions

The following table lists all documents for DmOS products. Datacom do not recommend the usage of previous versions.

### 5.1 Software Platform

| Document                         | Version     |
|----------------------------------|-------------|
| DmOS - Quick Configuration Guide | 204.4292.60 |
| DmOS - Command Reference         | 204.4284.66 |
| DmOS - Datasheet                 | 134.4918.41 |
| DmOS - MIB Reference             | 204.4381.23 |
| DmOS - Troubleshooting Guide     | 204.4293.51 |

### 5.2 Hardware Platform

| Document                                      | Version     |
|-----------------------------------------------|-------------|
| DM4050 - Installation Guide                   | 204.4317.05 |
| DM4170 - Installation Guide                   | 204.4308.06 |
| DM4250 - Installation Guide                   | 204.4312.01 |
| DM4270 - Installation Guide                   | 204.4331.10 |
| DM4340 - Installation Guide                   | 204.4356.03 |
| DM4360 - Installation Guide                   | 204.4337.02 |
| DM4370 - Installation Guide                   | 204.4314.03 |
| DM4376 - Installation Guide                   | 204.0401.02 |
| DM4380 - Installation Guide                   | 204.4336.00 |
| DM4610 - Installation Guide                   | 204.4291.04 |
| DM4611 - Installation Guide                   | 204.4349.01 |
| DM4612 - Installation Guide                   | 204.4350.01 |
| DM4615 - Installation Guide                   | 204.4323.03 |
| DM4616 - Installation Guide                   | 204.4386.00 |
| DM4618 - Installation Guide                   | 204.4351.00 |
| DM4770 - Installation Guide                   | 204.4339.13 |
| DM4775 - Installation Guide (Portuguese only) | 204.0337.00 |

| Document                    | Version     |
|-----------------------------|-------------|
| DM4780 - Installation Guide | 204.4405.03 |
| DM4920 - Installation Guide | 204.4377.15 |

## Legal Note

In spite the fact that all the precautions were taken in development of the present document, DATACOM shall not be held responsible for eventual errors or omissions as well as no obligation is assumed due to damages resulting from the use of the information included in this guide. The specifications provided in this manual shall be subject to changes with no prior notification and are not acknowledged as any type of contract.

© 2026 DATACOM - All rights reserved.

## Warranty

DATACOM's products are covered by a warranty against manufacturing defects during a minimum period of 12 (twelve) months including the legal term of 90 days, as from the date of issue of the supply Nota Fiscal (Invoice).

Our warranty is standard counter warranty, this means, for exercise of the warranty, the customer should send the product to DATACOM Authorized Technical Assistance with paid freight. The return freight of the equipment will be DATACOM responsibility.

To obtain additional information, see our warranty policy in <https://www.datacom.com.br/en>.

Telephone Number: **+55 51 3933-3094**