

Babcock Ranch Inverter Fan-System Inspection

Operations Procedure · SD-8400 Fleet

DOCUMENT	BR-SOP-INV-FAN-016
VERSION	1.6
EFFECTIVE	June 30, 2026
STATUS	Approved — Synthetic
OWNER	Babcock Ranch Operations (Synthetic)

5. Field Inspection

Use this procedure for an SD-8400 inverter placed in Maintenance Hold after fault A12. The steps below are limited to operator-authorized observation and exterior inspection.

5.1 Preconditions

- Confirm the asset identifier, A12 event time, maintenance-hold state, and control-room work authorization.
- Record the peak and latest fan variance plus ambient conditions from the approved diagnostic window.
- Stop if there is visible damage, smoke, water intrusion into an electrical compartment, abnormal heat, or another unsafe condition.
- Do not remove guards or open an enclosure without the separate isolation and lockout/tagout procedure.

Stop-work boundary: This procedure does not authorize energized internal inspection, fan replacement, or bypass of protective controls.

5.2 Authorized fan-system inspection

- 1 Verify INV-102 remains in Maintenance Hold and notify the control room that inspection is beginning.
- 2 From the exterior, inspect intake screens, exhaust openings, fan guards, and the visible cooling-air path for vegetation, dust loading, loose material, water, or physical damage.
- 3 Review fan command and fan-feedback trends for the same time window. Record whether feedback is present, stable, and responsive when command changes.
- 4 If the latest variance remains above 12 percentage points, feedback is missing or unstable, or abnormal noise or vibration is reported, keep the inverter in Maintenance Hold and create a qualified-maintenance work order.
- 5 If corrective work is performed, record the disposition and use the approved return-to-service checklist. Acknowledging A12 is not sufficient for release.

Escalate to qualified maintenance when

- Access beyond exterior inspection is required.
- Debris cannot be safely removed under the current work authorization.
- Command/feedback disagreement persists after the exterior cooling path is confirmed clear.