



Happy Link Claude TLDR Ticket Summary

AI-powered HappyFox ticket analysis — Problem · Actions · Next Steps · Timeline

Ticket number

128936

Show Recent Ticket IDs



Investigate Ticket

fgmm1000自动重启

GB FGMM1000 auto restart

<https://support.linksys.com/staff/ticket/128936>

TICKET	CATEGORY	STATUS	UPDATES	PRIORITY
#128...	Links...	Upda...	66	P2

Customer Details

Name: 张女士

Email: kelvincheung247@gmail.com

Phone: +85261206455

Country: Hong Kong

Device Details

Problem Category 1: Hardware Failure

Problem Category 2: Connectivity

Model Number: FGMM1000

Serial Number: 47K10FA9B00323

Warranty Start Date: 2025-05-01

Warranty Status: Active

The Problem

The customer's FGMM1000 router automatically restarts and loses connectivity when the network mode is set to 5G or 4G/5G using CSL SIM cards. The issue does not occur when using a 4G-only SIM card or a '3' network SIM card.

✓ Actions Taken

- Customer called in reporting router auto-restarts when set to 5G or 4G/5G mode with CSL SIM cards
- Support asked customer to send email with description and video of the issue
- Customer provided detailed problem description, system logs, invoice, firmware version (1.1.25.000001), and YouTube video link
- Support suggested trying a different carrier SIM card
- Support noted a firmware upgrade was performed
- Support asked if issue occurs in 4G-only mode and after reset
- Customer confirmed issue does not occur with 4G-only SIM or '3' network SIM, but all desired data SIMs are 5G
- Support asked customer to test with another carrier's 5G SIM card

- Customer replied they do not have another carrier's 5G SIM for testing
- Internal note escalated to Kris Qin noting customer cannot test with another 5G SIM
- Kris Qin instructed agent to request screenshots of router UI signal display in 5G and 4G modes, and SIM card signal on phone
- Agent emailed customer requesting screenshots of router backend UI signal in 5G and 4G modes and phone signal with SIM
- Agent attempted callback on 2026-05-19 but customer did not answer
- Agent attempted callback again on 2026-05-21 but customer did not answer

Summary: Support collected logs and video, performed a firmware upgrade, narrowed the issue to 5G mode specifically with CSL SIMs, and is now awaiting router UI and phone signal screenshots from the customer after two unsuccessful callback attempts.

Insights: The issue is reproducible specifically when the router is set to 5G or 4G/5G mode and appears to be SIM/carrier or 5G band compatibility related rather than a pure hardware fault, as the router works fine in 4G-only mode. The customer cannot perform broader carrier testing, and the case is stalling due to unreachable customer and a pending screenshot request.

Next Steps

- Continue attempting to contact the customer via phone and email to obtain router UI screenshots in 5G and 4G modes along with phone signal screenshots
- Review submitted logs and video for any firmware or band compatibility clues
- If screenshots confirm a signal/band issue, escalate to engineering or consider RMA given the device is under warranty and cannot function as intended with 5G SIM cards

Timeline (14 entries)

2026-05-11 | *Customer*

Customer called in reporting the FGMM1000 auto-restarts when set to 5G or 4G/5G mode with CSL SIM cards; support requested email with video evidence.

2026-05-11 | *Charlotte (Support)*

Support emailed customer requesting problem description and video.

2026-05-11 | *Customer (Kelvin Cheung)*

Customer replied with detailed problem description, firmware version 1.1.25.000001, serial number, system logs, invoice, and YouTube video link.

2026-05-12 | *Charlotte (Support)*

Support advised a firmware upgrade was performed and again suggested testing with a different carrier SIM; requested video as attachment.

2026-05-12 | *Customer (Kelvin Cheung)*

Customer sent a video attachment showing the issue occurring.

2026-05-13 | *Charlotte (Support)*

Support asked whether the issue occurs in 4G-only mode and whether it persists after the reset.

2026-05-14 | *Customer*

Customer confirmed issue does not occur with 4G-only SIM or '3' SIM, but all preferred data SIMs are 5G.

2026-05-14 | *Charlotte (Support)*

Support asked if the '3' SIM is 5G and requested testing with another carrier's 5G SIM.

2026-05-18 | *Charlotte (Support)*

Support followed up again asking if another carrier's 5G SIM was tested.

2026-05-18 | *Customer*

Customer replied they do not have another carrier's 5G SIM available for testing.

2026-05-18 | *Zhiliang Chen (Support)*

Internal note sent to Kris Qin advising that customer cannot test with another 5G SIM.

2026-05-19 | *Kris Qin (Support)*

Kris Qin instructed agent to request UI signal screenshots in 5G and 4G modes and phone signal screenshot from customer.

2026-05-19 | *Zhiliang Chen (Support)*

Agent attempted callback but customer did not answer; follow-up email sent requesting UI and phone signal screenshots.

2026-05-21 | *Zhiliang Chen (Support)*

Agent attempted another callback but customer did not answer.

 Download Executive Report

 Print / Save as PDF

>  Raw ticket data (JSON)