TLP:AMBER Restricted to the recipient’s organization and its trusted clients/contractors on a need-to-know basis.

CYBER THREAT INTELLIGENCE REPORT

D-Link warns of unpatched zero-days in DGS-3130 managed switches

From **Cybersecurity Briefing** · 2026-11-02 to 2026-11-07 · Briefing generated 2026-11-07

REPORT ID	VERSION	HANDLING	BRIEFING SECTION
CTI-20261110-05	1.0 · 2026-11-10 08:06 EST	TLP:AMBER	United States
ORIGINAL PUBLISHED	**LAST UPDATE**	**CVES**	**ANALYST**
2026-11-06	No update	None	Nick Sturgeon

VULNERABILITY | MEDIUM | UNPATCHED | OVERALL CONFIDENCE: MODERATE

BOTTOM LINE UP FRONT

On 2026-11-06 D-Link published interim security announcement SAP10523 about several unpatched flaws in its DGS-3130 series of stackable managed Gigabit switches. The flaws were reported to D-Link on 2026-11-02 by Giresh Kumar Enugu, a network engineer at Spectrum Community Solutions, after an independent assessment of a DGS-3130-30TS. The main group of flaws is in the D-Link Discovery Protocol (DDP), the vendor's own device discovery and basic setup protocol, and covers weak authentication, weak access control and poor handling of information. A second group, which D-Link treats separately and is still reviewing, concerns the firmware security design: SSH service configuration, protection of operating system credentials, and firmware encryption with embedded cryptographic keys [S2] [S3] [S4].

The confirmed affected unit is the DGS-3130-30TS, hardware revision B1. The researcher tested firmware 2.00.B014, 2.00.B034, 2.04.000 and 2.04.001, although D-Link has not said that every flaw is present in all four builds. Other DGS-3130 models and other D-Link switch platforms are under investigation. An attacker who can reach the switch over the network could read device and network configuration data, change administrator credentials or settings, obtain SNMP community strings, and force reboots or factory resets. No CVE IDs, CVSS scores or technical details have been published, there is no fixed firmware and no release date, and D-Link says it has no reports of attacks in the wild [S2] [S3] [S5].

The risk is moderate for now because the attacker needs a foothold on a network that can reach the switch, and no exploit details are public in

the sources we opened. The risk is not low, however: a switch is a high-value pivot point, leaked SNMP communities and changed credentials give an intruder durable control of the network layer, and a factory reset of a core or stack switch is an outage. Organizations that run DGS-3130 switches should disable DDP now (the vendor command is 'no ddp', verified with 'show ddp', then save the configuration), remove default SNMP communities, restrict SSH, web and SNMP management to an isolated management network and named administrator hosts, keep offline configuration backups, and watch switch logs for unexpected configuration changes, reboots or resets [S2] [S3] [S4].

Caveat on sourcing: the vendor advisory page could not be retrieved by our automated fetch (it returned an 'Article Not Found' page), so this report relies on consistent secondary reporting of the advisory. Details should be checked against SAP10523 in a browser before acting on version-specific points [S1].

Key judgments

LIKELY · MODERATE CONFIDENCE
It is likely that D-Link will add more DGS-3130 models, and possibly other switch families that ship DDP, to the affected list, because DDP is a shared vendor protocol and D-Link has already said other platforms are under review. [S2] [S3] [S9]

UNLIKELY · MODERATE CONFIDENCE
Widespread opportunistic exploitation from the internet is unlikely in the next 30 days, because the reported flaws need access to the affected network and no technical details are published. Use by an intruder who is already inside a network, including ransomware operators looking to disrupt or hide, is a realistic scenario once details emerge. [S2] [S4] [S5]

VERY LIKELY · LOW CONFIDENCE
It is very likely that CVE IDs and technical descriptions will be published once fixed firmware ships, and that proof-of-concept code will follow soon after, because the researcher has already described the attack surface and DDP has a history of analyzable flaws on other D-Link products. [S2] [S9]

LIKELY · MODERATE CONFIDENCE
Disabling DDP is likely to block the DDP attack paths that were reported, but it is unlikely to address the separate firmware design issues (SSH configuration, credential storage, firmware encryption keys), which will need new firmware. [S3] [S4]

INDICATORS OF COMPROMISE

No attacker infrastructure, malware or exploit artifacts have been published, and no exploitation is reported. The entries below are exposure identifiers and behavior to look for, taken from reporting dated 2026-11-06 and 2026-11-07, plus indicators derived from the described impact. The network port

used by DDP is not stated in any source we opened, so no port is listed.

Type	Indicator (defanged)	Context	Provenance	First seen	Source
other	`DGS-3130-30TS hardware revision B1`	Confirmed affected model and hardware revision. Use for asset inventory matching. Other DGS-3130 models are under vendor review.	REPORTED	2026-11-06	[S2] [S3]
other	`Firmware 2.00.B014`	Firmware build tested by the researcher on the DGS-3130-30TS. D-Link has not confirmed that every flaw affects every tested build.	REPORTED	2026-11-06	[S3]
other	`Firmware 2.00.B034`	Firmware build tested by the researcher on the DGS-3130-30TS.	REPORTED	2026-11-06	[S3]
other	`Firmware 2.04.000`	Firmware build tested by the researcher on the DGS-3130-30TS.	REPORTED	2026-11-06	[S3]
other	`Firmware 2.04.001`	Firmware build tested by the researcher on the DGS-3130-30TS.	REPORTED	2026-11-06	[S3]
other	`SNMP community string: public`	Default SNMP community that the vendor guidance says to remove. Its presence in a running configuration is a weakness indicator, and SNMP requests using it from hosts outside the management network are suspicious.	REPORTED	2026-11-06	[S3]
other	`SNMP community string: private`	Default read-write SNMP community that the vendor guidance says to remove. Same reasoning as for 'public'; a read-write community in attacker hands allows configuration changes.	REPORTED	2026-11-06	[S3]
command	`show ddp`	Switch CLI command to check whether DDP is enabled. Output showing DDP enabled on an affected switch means the reported attack surface is exposed. Not an attacker command.	REPORTED	2026-11-06	[S3]
other	`DDP (D-Link Discovery Protocol) packets sent to switch management addresses from hosts that are not the D-Link management station`	Derived from the report that the flaws are reached through DDP by an attacker with network access. DDP is normally used only by D-Link management tools, so DDP traffic from user, guest, server or IoT segments is anomalous. The port is not stated in the sources; confirm it from the device documentation or a packet capture before building a network rule.	DERIVED		[S2] [S3]

Type	Indicator (defanged)	Context	Provenance	First seen	Source
other	`Switch syslog or SNMP trap entries for configuration change, administrator password change, reboot or factory reset with no matching change ticket`	Derived from the reported impact (unauthorized configuration and credential changes, forced reboots, factory resets) and from the vendor advice to monitor logs for these events.	DERIVED		[S2] [S4]

Indicators are defanged (hxxp, [.], [@]) so they cannot be clicked. "Reported" means stated in a source; "Derived" means inferred by the analyst from the source material and should be validated before blocking.

TACTICS, TECHNIQUES & PROCEDURES (TTPS)

No attack has been observed, so the following describes the reported attack surface, not a real intrusion. An attacker who already has access to a network that can reach an affected DGS-3130 switch sends DDP messages to it. Because DDP authentication and access control are weak, the attacker can query the switch for device and configuration information, including SNMP community strings, and can carry out administrative actions such as changing credentials or settings, rebooting the switch or resetting it to factory defaults. Leaked SNMP communities, especially read-write ones, give a second route to read and change configuration. Separate weaknesses in SSH configuration, OS credential protection and firmware encryption with embedded keys are still under vendor review and could make credential recovery or firmware analysis easier. D-Link has not published the technical details, so the exact message types, port and preconditions are unknown [S2] [S3] [S4].

MITRE ATT&CK mapping

Tactic	Technique	Procedure observed	Detection opportunity
Lateral Movement	T1210 Exploitation of Remote Services	An attacker on a network that can reach the switch abuses weak authentication and access control in the DDP service to act on the switch without valid administrator credentials. [S2] [S3]	Alert on DDP traffic to switch management addresses from any host other than the designated D-Link management station. Baseline which hosts normally speak DDP; in most networks the answer should be none.

Tactic	Technique	Procedure observed	Detection opportunity
Collection	T1602.002 Data from Configuration Repository: Network Device Configuration Dump	DDP information-handling flaws let the attacker read device and network configuration details from the switch. [S2] [S3]	Network monitoring for unusual query volume to switch management interfaces from non-management hosts; review switch logs for configuration reads or exports outside change windows.
Collection	T1602.001 Data from Configuration Repository: SNMP (MIB Dump)	SNMP community strings disclosed through DDP, or default communities left in place, can be used to walk the MIB and collect topology, VLAN and interface data. [S2] [S3]	Alert on SNMP requests to switches from sources outside the monitoring servers, on use of the 'public' or 'private' communities, and on SNMP authentication-failure traps.
Persistence	T1098 Account Manipulation	The reported impact includes unauthorized changes to administrator credentials and device settings on the switch. [S3] [S5]	Forward switch logs to the SIEM and alert on account or password changes and configuration saves that do not match an approved change. Compare running configurations against the offline backup on a schedule.
Impact	T1529 System Shutdown/ Reboot	An attacker can force the switch to reboot, interrupting every network that depends on it or on its stack. [S2] [S3]	Alert on switch cold-start or warm-start traps, uptime resets and link-flap storms that have no matching maintenance record.
Impact	T1485 Data Destruction	An attacker can trigger a factory reset, which wipes the switch configuration and causes a prolonged outage until the configuration is restored from backup. [S2] [S4]	Alert when a managed switch stops answering with its known hostname or management address, reappears with default settings, or logs a reset-to-default event.

Detection & hunting

Queries are built from the reported behavior and indicators. They are untested; tune field names for your environment.

D-Link switch: configuration change, credential change, reboot or factory reset in syslog `SPLUNK SPL`

```
index=network sourcetype=syslog host IN (<dgs3130_hostnames_or_ips>)
("configuration" AND ("saved" OR "changed" OR "modified")) OR ("password" AND ("changed" OR "modified")) OR "user account" OR "reboot" OR
"system started up" OR "cold start" OR "warm start" OR "factory" OR "reset to default"
| eval event_type=case(searchmatch("factory OR \"reset to default\""),"factory_reset", searchmatch("reboot OR \"system started up\" OR
\"cold start\" OR \"warm start\""),"reboot", searchmatch("password OR \"user account\""),"credential_change", true(),"config_change")
| stats count min(_time) as first_seen max(_time) as last_seen values(_raw) as samples by host event_type
| convert ctime(first_seen) ctime(last_seen)
```

Replace the host list with the DGS-3130 inventory. Message wording varies by firmware; tune the keywords against real log samples from the switches. Compare hits with change tickets.

SNMP request to D-Link switches using a default community from a non-management host `SURICATA`

```
alert snmp !$MGMT_HOSTS any -> $DLINK_SWITCHES 161 (msg:"HUNT SNMP default community 'public' to D-Link switch from non-management host";
snmp.community; content:"public"; nocase; threshold:type limit, track by_src, count 1, seconds 300; classtype:attempted-recon; sid:9100001;
rev:1;)
alert snmp !$MGMT_HOSTS any -> $DLINK_SWITCHES 161 (msg:"HUNT SNMP default community 'private' to D-Link switch from non-management host";
snmp.community; content:"private"; nocase; threshold:type limit, track by_src, count 1, seconds 300; classtype:attempted-admin;
sid:9100002; rev:1;)
```

Define MGMT_HOSTS and DLINK_SWITCHES in the Suricata address variables. Needs a sensor that sees traffic to the switch management VLAN. Applies to SNMP v1 and v2c only.

Unexpected hosts talking to D-Link switch management addresses `KQL`

```
let SwitchMgmtIPs = dynamic(["<switch_mgmt_ip_1>", "<switch_mgmt_ip_2>"]);
let AllowedMgmtHosts = dynamic(["<nms_ip>", "<admin_jump_host_ip>"]);
CommonSecurityLog
| where TimeGenerated > ago(14d)
| where DestinationIP in (SwitchMgmtIPs)
| where SourceIP !in (AllowedMgmtHosts)
| summarize Connections = count(), FirstSeen = min(TimeGenerated), LastSeen = max(TimeGenerated), Ports = make_set(DestinationPort, 50) by
SourceIP, DestinationIP, Protocol
| order by Connections desc
```

Uses firewall or flow logs in Microsoft Sentinel. It only sees traffic that crosses a logging device, so it will miss same-VLAN traffic. The DDP port is not published in the sources, so the query looks at all ports; once the port is confirmed from device documentation, add a filter for it.

Network device reboot or factory reset (generic syslog) `SIGMA`

```
title: D-Link Switch Unexpected Reboot Or Factory Reset
status: experimental
description: Detects reboot, restart or reset-to-default messages from D-Link managed switches, which may indicate abuse of the unpatched
DDP flaws reported in D-Link SAP10523.
logsource:
  category: network
  product: dlink
  service: syslog
detection:
  keywords:
    - 'reboot'
    - 'System started up'
    - 'cold start'
    - 'warm start'
    - 'factory default'
    - 'reset to default'
  condition: keywords
falsepositives:
  - Planned maintenance, firmware upgrades and power events
level: medium
```

Scope the rule to the switch log sources in the SIEM pipeline. Keyword strings are generic and should be matched to the actual message format of the installed firmware.

REMEDIATION ACTIONS

Exposure

Product	Affected	Fixed in	CVE	CVSS	EPSS	CISA KEV	KEV due date
D-Link DGS-3130-30TS (hardware revision B1)	Researcher tested firmware 2.00.B014, 2.00.B034, 2.04.000 and 2.04.001; D-Link has not confirmed which flaws affect which build	No fixed firmware; no release date announced	None assigned publicly	Not scored	N/A (no CVE)	No	N/A
Other D-Link DGS-3130 models and other D-Link switch platforms	Under vendor investigation; not confirmed	N/A	None assigned publicly	Not scored	N/A (no CVE)	No	N/A

Immediate (0–24 hours)

- Inventory all D-Link DGS-3130 switches (and note any other D-Link managed switches that run DDP). Record model, hardware revision and firmware version for each. `IT OPS` [S3] [S4]
- Disable DDP on every DGS-3130 switch: run 'no ddp' globally (and per interface where needed), confirm with 'show ddp', then save the configuration so the change survives a reboot. `IT OPS` [S2] [S3]
- Remove the default SNMP communities 'public' and 'private' and any other community that is not in use. `IT OPS` [S2] [S3]
- Take a fresh configuration backup of each switch and store a copy offline, so a factory reset can be recovered quickly. `IT OPS` [S2] [S4]
- Confirm that switch syslog and SNMP traps reach the SIEM, and start alerting on unexpected configuration changes, reboots and factory resets. `SOC` [S2] [S4]

Short term (1–7 days)

- Restrict SSH, web UI and SNMP on the switches to an isolated management network and to named administrator hosts, using management ACLs or trusted-host lists. Confirm that no switch management interface is reachable from the internet, guest Wi-Fi or user VLANs. `IT OPS` [S2] [S3]
- Rotate all SNMP community strings and switch administrator passwords on affected devices, on the assumption that they could have been read while DDP was enabled. Move to SNMPv3 with authentication and privacy where the monitoring platform supports it. `IT OPS` [S2] [S8]
- Hunt back through available switch logs, flow data and firewall logs for unexplained configuration changes, reboots, resets, and for non-management hosts contacting switch management addresses. `SOC` [S2] [S4]
- Compare each switch's running configuration against the last known-good backup and investigate differences such as new accounts, changed communities, new VLANs, port mirroring or altered ACLs. `IT OPS` [S2] [S4]

- Assign someone to check D-Link announcement SAP10523 at least weekly for added models, CVE IDs and fixed firmware. `IT OPS` [S1] [S4]

Long term

- Install fixed firmware when D-Link releases it, in a planned maintenance window, and then re-check that DDP remains disabled unless there is a clear operational need for it. `IT OPS` [S2] [S3]
- Make disabling vendor discovery and setup protocols, removing default SNMP communities and using a dedicated management VLAN part of the standard build for all network devices. `IT OPS` [S2] [S3]
- Review network hardware purchasing and lifecycle plans in light of the vendor's response time on this issue, and decide what patch timeline is acceptable for core switching. `LEADERSHIP` [S2] [S4]

Workarounds & compensating controls

- If DDP cannot be turned off immediately on some switches, place their management interfaces behind an ACL or firewall that drops all traffic except from the management station, and treat this as temporary: reporting indicates disabling DDP is the only mitigation tested against the reported attack paths. `IT OPS` [S2] [S3]
- Use 802.1X or port security on access ports, and keep guest, IoT and operational technology devices in VLANs that cannot reach switch management addresses, to reduce the number of hosts that could send DDP traffic. `IT OPS` [S2]
- Keep a tested recovery runbook and a spare or pre-staged configuration for critical stacks so that a hostile factory reset is a short outage and not a long one. `LEADERSHIP` [S4]

Actions marked with an owner: SOC = security operations, IT Ops = system and network administration, Leadership = risk and communications decisions.

SOURCES

[S1] D-Link: Security announcement SAP10523 (DGS-3130-30TS: DDP and firmware security architecture findings)
Published 2026-11-06 · `A6` Completely reliable, truth cannot be judged
Primary vendor advisory, linked by BleepingComputer. Our automated fetch received an 'Article Not Found' page on three attempts, so the content could not be read directly; it is represented here only through secondary reporting. Verify in a browser.

[S2] BleepingComputer: D-Link warns of multiple zero-days in DGS-3130 Series switches
Published 2026-11-06 · B2 Usually reliable, probably true
Briefing source. Summarizes the vendor advisory, names the researcher, lists mitigations and states no CVE IDs are assigned.

[S3] SecurityLab.ru: 0Day in D-Link switches: no patch, and one command may save the network (Russian-language article)
Published 2026-11-06 · C2 Fairly reliable, probably true
Most detailed secondary account of the advisory: hardware revision B1, the four tested firmware builds, the 'no ddp' and 'show ddp' commands, the 2026-11-02 report date, and the vendor statement that it has no reports of attacks.

[S4] Hunter Strategy: The Fix Isn't the Finish Line: Exploited OpenSSH, Unpatched Switches, and Ransomware That Outlasts Recovery
Published 2026-11-06 · C2 Fairly reliable, probably true
Consulting firm's threat brief. Notes that disabling DDP does not resolve every firmware issue under review and that exploitation is not established.

[S5] Mallory: D-Link Warns of Unpatched DGS-3130 Switch Flaws, Urges Management Access Restrictions
Published 2026-11-06 · C2 Fairly reliable, probably true
Aggregated story page citing BleepingComputer, SC Media and CERT social posts. Consistent with other reporting; no exploitation or PoC claims.

[S6] TechTalkThai: D-Link warns of multiple zero-day flaws in DGS-3130 switches with no patch, advises disabling DDP (Thai-language article)
Published 2026-11-07 · C2 Fairly reliable, probably true
Derivative of BleepingComputer. Confirms no update as of 2026-11-07.

[S7] The420.in: Critical Zero-Day Vulnerabilities Found in D-Link Enterprise Gigabit Switches
Published 2026-11-07 · C3 Fairly reliable, possibly true
Derivative coverage. Headline says 'critical', which no vendor score supports; spells the researcher's first name differently.

[S8] Carthage Electronics: November 7 2026 CVE Threat Brief
Published 2026-11-07 · C3 Fairly reliable, possibly true
Small IT provider's daily brief, derived from BleepingComputer. Adds the recommendation to move to SNMPv3. States no firmware is available.

[S9] Zero Day Initiative: ZDI-23-1270: D-Link DAP-2622 DDP Set IPv6 Address Default Gateway Stack-based Buffer Overflow Remote Code Execution Vulnerability
Published 2023-08-25 · `A1` Completely reliable, confirmed by other sources
Historical context only: an earlier unauthenticated, network-adjacent DDP flaw (CVE-2023-37316, CVSS 8.8) on a different D-Link product. Shows DDP has been a weak point before; not part of the current disclosure.

[S10] Blog elhacker.NET: D-Link alerta sobre varias vulnerabilidades zero-day en los switches de la serie DGS-3130 (Spanish-language article)
Published 2026-11-06 · `C2` Fairly reliable, probably true
Derivative of BleepingComputer. States that D-Link has a firmware update in development.

Grades use the Admiralty scale: letter = source reliability (A completely reliable to F cannot be judged), number = information credibility (1 confirmed to 6 cannot be judged).

MISCELLANEOUS

Timeline

Date	Event	Source
2023-08-25	ZDI publishes an unauthenticated DDP remote code execution flaw in the D-Link DAP-2622 access point (CVE-2023-37316), an earlier example of DDP weakness on a different product.	[S9]
2026-11-02	Giresh Kumar Enugu of Spectrum Community Solutions reports the DGS-3130-30TS findings to D-Link through coordinated disclosure.	[S3]
2026-11-06	D-Link publishes interim announcement SAP10523 with mitigations and no firmware fix; BleepingComputer and others report it.	[S1] [S2] [S3]
2026-11-07	Follow-on coverage confirms no CVE IDs, no fixed firmware and no reported exploitation.	[S6] [S7] [S8]
2026-11-10	Report prepared. No newer vendor update, CVE assignment or exploitation report found in open sources.	[S2]

Relevance to Indianapolis, Indiana & managed clients

D-Link managed switches are sold mainly on price, so in Indiana they are most often found in small and mid-size businesses, small municipal and township offices, K-12 schools and libraries, small clinics and dental or specialty practices, and on the plant floor or in warehouse closets at manufacturers and logistics firms. These are also the environments that most often run flat networks with no separate management VLAN, default SNMP settings and no switch logging, which is exactly the condition these flaws need. For Indianapolis-area healthcare and manufacturing sites, the main concern is availability: a forced factory reset of a stack that carries clinical, production or building-control traffic is an outage, and many small sites have no current configuration backup. For local government and schools, the concern is that an intruder who gets onto a guest or student network that can reach switch management could alter VLANs or mirror traffic. Managed IT service clients should have their switch inventories checked for DGS-3130 units this week, DDP disabled and SNMP defaults removed as a standard change, and switch logs brought into monitoring. Sites with no D-Link switching can treat this as awareness only, but it is a useful prompt to check that every network device, of any brand, has discovery protocols limited and management access isolated.

Intelligence gaps

- The vendor advisory SAP10523 could not be read directly by our tooling; version-specific and wording-specific points rest on secondary reporting and should be verified against the advisory.
- No CVE IDs, CVSS scores or CWE classifications are published, so the number of distinct flaws and their individual severity are unknown.
- D-Link has not said which of the four tested firmware builds is affected by which flaw, or whether any existing build is unaffected.
- The DDP port and message types involved are not stated in any source we opened, which limits network detection. Confirm from device documentation or a packet capture.
- It is unknown whether the flaws can be triggered only from the same Layer 2 segment or from any routed network that can reach the switch.
- Whether other DGS-3130 models and other D-Link switch families are affected is still under vendor investigation.
- The status and severity of the separate firmware design issues (SSH configuration, OS credential protection, firmware encryption and embedded keys) are unresolved.
- No fix date has been announced. Watch for updated firmware, CVE publication, researcher write-ups, proof-of-concept code and any CISA advisory or KEV addition.

Other notes

- The term 'zero-day' in the headlines means disclosed without a patch. No source reports exploitation, and SecurityLab relays a vendor statement that no real-world attacks are known [S3].
- A search summary surfaced two claims that we could not confirm on any page we opened and that are therefore not used in the assessment: that a public proof-of-concept exists for the DGS-3130 flaws, and that a specific fixed build number exists. The pages we opened say the opposite on both points [S4] [S8].
- A search summary of the vendor advisory also said that removing SNMP community strings does not by itself fix the DDP information-disclosure

issue. This is consistent with the rest of the reporting (disable DDP first) but could not be verified at the source.

- Severity labels differ between outlets: one headline calls the flaws 'critical' [S7], while the briefing rates the item Medium. With no vendor score and a requirement for network access, Medium is reasonable for now; it would rise if details show unauthenticated administrative control from routed networks or if exploit code appears.
- BleepingComputer notes that in September 2026 D-Link warned of CVE-2026-86296, an unpatched maximum-severity flaw with public exploit code in end-of-life DIR-822A routers. That is a separate issue in a different product line [S2].
- SC Media and Mezha also covered the story but their pages blocked our fetch, so they are not cited.

CTI-20261110-05 v1.0 · Generated 2026-11-10 08:06 EST from public reporting. Drafted with AI assistance and reviewed by Nick Sturgeon. Verify indicators and actions before operational use. Summaries are in the analyst's own words.

Back to the daily briefing.

TLP:AMBER Restricted to the recipient’s organization and its trusted clients/contractors on a need-to-know basis.