TLP:AMBER Restricted to the recipient’s organization and its trusted clients/contractors on a need-to-know basis.

CYBER THREAT INTELLIGENCE REPORT

D-Link discloses unpatched zero-days in DGS-3130 switches

From **Cybersecurity Briefing** · 2026-11-08 to 2026-11-09 (24 hours; stretched to 2026-11-04 because the window was thin, and for the Indiana sections) · Briefing generated 2026-11-09

REPORT ID	VERSION	HANDLING	BRIEFING SECTION
CTI-20261110-06	1.0 · 2026-11-10 12:45 EST	TLP:AMBER	United States
ORIGINAL PUBLISHED	**LAST UPDATE**	**CVES**	**ANALYST**
2026-11-06	No update	None	Nick Sturgeon

VULNERABILITY | MEDIUM | UNPATCHED | OVERALL CONFIDENCE: MODERATE

BOTTOM LINE UP FRONT

On 2026-11-06 D-Link published interim security announcement SAP10523 about several unpatched flaws in its DGS-3130 series of stackable managed Gigabit switches. The flaws were found by Giresh Kumar Enugu, a network engineer at Spectrum Community Solutions, and reported to D-Link on 2026-11-02. The main group is in the D-Link Discovery Protocol (DDP), the vendor's own discovery and basic setup protocol, and covers weak authentication, weak access control and poor handling of information. A second group, still under vendor review, concerns the firmware security design: SSH service configuration, protection of operating system credentials, and firmware encryption with embedded cryptographic keys [S2] [S3] [S4] [S5].

The confirmed affected unit is the DGS-3130-30TS, hardware revision B1. Firmware builds 2.00.B014, 2.00.B034, 2.04.000 and 2.04.001 were examined, but D-Link has not said which flaw affects which build. Other DGS-3130 models and other D-Link switch platforms are still being checked. An attacker who can reach the switch over the network could read device and network configuration data, obtain SNMP community strings, change administrator credentials or settings, and force reboots or factory resets. No CVE IDs, CVSS scores or technical details are public, no fixed firmware or release date exists, and no source reports attacks in the wild [S2] [S3] [S6] [S7].

As of 2026-11-10 we found nothing new since the first reports: no advisory revision, no CVE assignment, no firmware, no proof-of-concept and

no exploitation report. The vendor advisory page itself still returns 'Article Not Found' to our automated fetch, and an independent write-up dated 2026-11-07 also says the advisory link was unavailable that day. We cannot tell whether D-Link has withdrawn the page for revision or whether the site blocks automated readers, so version-specific details rest on consistent secondary reporting and should be checked in a browser [S1] [S3].

The risk is moderate. The attacker needs a foothold on a network that can reach the switch, and no exploit details are published. It is not low, because a switch is a strong pivot point, leaked SNMP communities and changed credentials give lasting control of the network layer, and a factory reset of a core or stack switch is an outage. Organizations running DGS-3130 switches should disable DDP now ('no ddp', check with 'show ddp', then save the configuration), remove default SNMP communities, restrict SSH, web and SNMP management to an isolated management network and named administrator hosts, keep offline configuration backups, and watch switch logs for unexpected configuration changes, reboots or resets. Disabling DDP does not fix the separate firmware design issues, which need new firmware [S2] [S3] [S4].

Key judgments

LIKELY · MODERATE CONFIDENCE

It is likely that D-Link will add more DGS-3130 models, and possibly other switch families that ship DDP, to the affected list, because DDP is a shared vendor protocol, D-Link has said other platforms are under review, and DDP flaws have been found on other D-Link products before. [S2] [S4] [S9]

UNLIKELY · MODERATE CONFIDENCE

Widespread opportunistic exploitation from the internet is unlikely in the next 30 days, because the flaws need access to a network that can reach the switch and no technical details are published. Use by an intruder who is already inside a network, for example to disrupt operations or hide lateral movement, becomes realistic once details emerge. [S2] [S3] [S4]

LIKELY · LOW CONFIDENCE

It is likely that fixed firmware will take weeks, not days, to arrive. Four days after disclosure there is no release date, the vendor is still scoping other platforms, and part of the findings concern firmware design (credential storage, embedded keys) that is harder to change than a single protocol handler. [S2] [S3] [S4]

LIKELY · MODERATE CONFIDENCE

Disabling DDP is likely to block the reported DDP attack paths, although that rests on the researcher's testing and D-Link had not independently confirmed it at the time of reporting. It will not address the SSH, credential-protection and firmware-encryption findings. [S2] [S3] [S4]

INDICATORS OF COMPROMISE

No attacker infrastructure, malware or exploit artifacts have been published and no exploitation is reported. The entries below are exposure identifiers and behaviors to look for, taken from reporting dated 2026-11-06 and 2026-11-07 and rechecked on 2026-11-10, plus indicators derived from the described impact. No source states the network port used by DDP, so no port is listed.

Type	Indicator (defanged)	Context	Provenance	First seen	Source
other	`DGS-3130-30TS hardware revision B1`	Confirmed affected model and hardware revision. Use for asset inventory matching. Other DGS-3130 models and revisions have not been assessed yet.	REPORTED	2026-11-06	[S2] [S3]
other	`Firmware 2.00.B014`	Firmware build examined on the DGS-3130-30TS. D-Link has not confirmed which findings affect which build.	REPORTED	2026-11-06	[S3] [S5]
other	`Firmware 2.00.B034`	Firmware build examined on the DGS-3130-30TS.	REPORTED	2026-11-06	[S3] [S5]
other	`Firmware 2.04.000`	Firmware build examined on the DGS-3130-30TS.	REPORTED	2026-11-06	[S3] [S5]
other	`Firmware 2.04.001`	Firmware build examined on the DGS-3130-30TS.	REPORTED	2026-11-06	[S3] [S5]
command	`show ddp`	Switch CLI command to check whether DDP is enabled. DDP shown as enabled on an affected switch means the reported attack surface is exposed. This is an administrator check, not an attacker command.	REPORTED	2026-11-06	[S3] [S5]
command	`no ddp`	Switch CLI command that disables DDP globally or on an interface. Listed as a configuration marker: its absence from the saved configuration of an affected switch means the mitigation is not applied or did not survive a reboot.	REPORTED	2026-11-06	[S3] [S5]

Type	Indicator (defanged)	Context	Provenance	First seen	Source
other	`SNMP community string: public`	Default SNMP community that the guidance says to remove. Its presence in a running configuration is a weakness indicator, and SNMP requests using it from hosts outside the management network are suspicious. The literal name comes from a source read on 2026-11-07 that could not be reopened on 2026-11-10.	REPORTED	2026-11-06	[S5]
other	`SNMP community string: private`	Default read-write SNMP community that the guidance says to remove. A read-write community in attacker hands allows configuration changes. Same sourcing caveat as for 'public'.	REPORTED	2026-11-06	[S5]
other	`DDP (D-Link Discovery Protocol) packets sent to switch management addresses from hosts that are not the D-Link management station`	Derived from the report that the flaws are reached through DDP by an attacker with network access. DDP is normally used only by D-Link management tools, so DDP traffic from user, guest, server or IoT segments is anomalous. The port is not stated in the sources; confirm it from device documentation or a packet capture before building a network rule.	DERIVED		[S2] [S3]
other	`Switch syslog or SNMP trap entries for configuration change, administrator password change, SNMP community change, interface shutdown, reboot or factory reset with no matching change ticket`	Derived from the reported impact (unauthorized configuration and credential changes, forced reboots, factory resets) and from the advice to monitor logs for these events.	DERIVED		[S2] [S3] [S4]
other	`Managed switch that reappears with factory-default hostname, address or credentials`	Derived from the reported ability to trigger a factory reset. A switch that drops out of monitoring and returns with default settings should be treated as a possible hostile reset until explained.	DERIVED		[S2] [S4]

Indicators are defanged (hxxp, [.], [@]) so they cannot be clicked. "Reported" means stated in a source; "Derived" means inferred by the analyst from the

source material and should be validated before blocking.

TACTICS, TECHNIQUES & PROCEDURES (TTPS)

No attack has been observed, so this describes the reported attack surface, not a real intrusion. An attacker who already has access to a network that can reach an affected DGS-3130 switch sends DDP messages to it. Because DDP authentication and access control are weak, the attacker can query the switch for device and configuration information, including SNMP community strings, and can carry out administrative actions such as changing credentials or settings, rebooting the switch or resetting it to factory defaults. Leaked SNMP communities, especially read-write ones, give a second route to read and change configuration. Separate weaknesses in SSH configuration, OS credential protection and firmware encryption with embedded keys are still under vendor review and could make credential recovery or firmware analysis easier. The researcher reproduced some of these conditions in a test environment. D-Link has not published technical details, so the exact message types, port and preconditions are unknown [S2] [S3] [S4].

MITRE ATT&CK mapping

Tactic	Technique	Procedure observed	Detection opportunity
Lateral Movement	T1210 Exploitation of Remote Services	An attacker on a network that can reach the switch abuses weak authentication and access control in the DDP service to act on the switch without valid administrator credentials. [S2] [S3]	Alert on DDP traffic to switch management addresses from any host other than the designated D-Link management station. Baseline which hosts normally speak DDP; in most networks the answer should be none. Where switch logs are thin, use a SPAN port, tap or upstream firewall for visibility.
Collection	T1602.002 Data from Configuration Repository: Network Device Configuration Dump	DDP information-handling flaws let the attacker read device and network configuration details from the switch. [S2] [S3]	Monitor for unusual query volume to switch management interfaces from non-management hosts; review switch logs for configuration reads or exports outside change windows.
Collection	T1602.001 Data from Configuration Repository: SNMP (MIB Dump)	SNMP community strings disclosed through DDP, or default communities left in place, can be used to walk the MIB and collect topology, VLAN and interface data. [S2] [S3] [S7]	Alert on SNMP requests to switches from sources outside the monitoring servers, on use of default communities, and on SNMP authentication-failure traps.

Tactic	Technique	Procedure observed	Detection opportunity
Persistence	T1098 Account Manipulation	The reported impact includes unauthorized changes to administrator credentials and device settings on the switch. [S2] [S3]	Forward switch logs to the SIEM and alert on account or password changes and configuration saves that do not match an approved change. Check local, RADIUS and TACACS+ authentication logs. Compare running configurations against the offline backup on a schedule.
Impact	T1529 System Shutdown/ Reboot	An attacker can force the switch to reboot, interrupting every network that depends on it or on its stack. [S2] [S4]	Alert on switch cold-start or warm-start traps, uptime resets and link-flap storms that have no matching maintenance record.
Impact	T1485 Data Destruction	An attacker can trigger a factory reset, which wipes the switch configuration and causes a prolonged outage until it is restored from backup. [S2] [S3] [S4]	Alert when a managed switch stops answering with its known hostname or management address, reappears with default settings, or logs a reset-to-default event.

Detection & hunting

Queries are built from the reported behavior and indicators. They are untested; tune field names for your environment.

D-Link switch: configuration change, credential change, reboot or factory reset in syslog `SPLUNK SPL`

```
index=network sourcetype=syslog host IN (<dgs3130_hostnames_or_ips>)
("configuration" AND ("saved" OR "changed" OR "modified")) OR ("password" AND ("changed" OR "modified")) OR "user account" OR "community"
OR "reboot" OR "system started up" OR "cold start" OR "warm start" OR "factory" OR "reset to default"
| eval event_type=case(searchmatch("factory OR \"reset to default\""),"factory_reset", searchmatch("reboot OR \"system started up\" OR
\"cold start\" OR \"warm start\""),"reboot", searchmatch("password OR \"user account\" OR community"),"credential_change",
true(),"config_change")
| stats count min(_time) as first_seen max(_time) as last_seen values(_raw) as samples by host event_type
| convert ctime(first_seen) ctime(last_seen)
```

Replace the host list with the DGS-3130 inventory. Message wording varies by firmware; tune the keywords against real log samples from the switches. Compare hits with change tickets.

SNMP request to D-Link switches using a default community from a non-management host `SURICATA`

```
alert snmp !$MGMT_HOSTS any -> $DLINK_SWITCHES 161 (msg:"HUNT SNMP default community 'public' to D-Link switch from non-management host";
snmp.community; content:"public"; nocase; threshold:type limit, track by_src, count 1, seconds 300; classtype:attempted-recon; sid:9100001;
rev:1;)
alert snmp !$MGMT_HOSTS any -> $DLINK_SWITCHES 161 (msg:"HUNT SNMP default community 'private' to D-Link switch from non-management host";
snmp.community; content:"private"; nocase; threshold:type limit, track by_src, count 1, seconds 300; classtype:attempted-admin;
sid:9100002; rev:1;)
```

Define MGMT_HOSTS and DLINK_SWITCHES in the Suricata address variables. Needs a sensor that sees traffic to the switch management VLAN. Applies to SNMP v1 and v2c only.

Unexpected hosts talking to D-Link switch management addresses `KQL`

```
let SwitchMgmtIPs = dynamic(["<switch_mgmt_ip_1>", "<switch_mgmt_ip_2>"]);
let AllowedMgmtHosts = dynamic(["<nms_ip>", "<admin_jump_host_ip>"]);
CommonSecurityLog
| where TimeGenerated > ago(14d)
| where DestinationIP in (SwitchMgmtIPs)
| where SourceIP !in (AllowedMgmtHosts)
| summarize Connections = count(), FirstSeen = min(TimeGenerated), LastSeen = max(TimeGenerated), Ports = make_set(DestinationPort, 50) by
SourceIP, DestinationIP, Protocol
| order by Connections desc
```

Uses firewall or flow logs in Microsoft Sentinel. It only sees traffic that crosses a logging device, so it misses same-VLAN traffic. The DDP port is not published in the sources, so the query looks at all ports; add a port filter once it is confirmed from device documentation.

Network device reboot or factory reset (generic syslog) `SIGMA`

```
title: D-Link Switch Unexpected Reboot Or Factory Reset
status: experimental
description: Detects reboot, restart or reset-to-default messages from D-Link managed switches, which may indicate abuse of the unpatched
DDP flaws described in D-Link SAP10523.
logsource:
  category: network
  product: dlink
  service: syslog
detection:
  keywords:
    - 'reboot'
    - 'System started up'
    - 'cold start'
    - 'warm start'
    - 'factory default'
    - 'reset to default'
  condition: keywords
falsepositives:
  - Planned maintenance, firmware upgrades and power events
level: medium
```

Scope the rule to the switch log sources in the SIEM pipeline. Keyword strings are generic and should be matched to the message format of the installed firmware.

REMEDIATION ACTIONS

Exposure

Product	Affected	Fixed in	CVE	CVSS	EPSS	CISA KEV	KEV due date

Product	Affected	Fixed in	CVE	CVSS	EPSS	CISA KEV	KEV due date
D-Link DGS-3130-30TS (hardware revision B1)	Firmware 2.00.B014, 2.00.B034, 2.04.000 and 2.04.001 were examined; D-Link has not confirmed which flaws affect which build	No fixed firmware; no release date announced	None assigned publicly	Not scored	N/A (no CVE)	No	N/A
Other D-Link DGS-3130 models and other D-Link switch platforms	Under vendor investigation; not confirmed	N/A	None assigned publicly	Not scored	N/A (no CVE)	No	N/A

Immediate (0–24 hours)

- Inventory all D-Link DGS-3130 switches, and note any other D-Link managed switches that run DDP. Record model, hardware revision, firmware version, whether DDP is enabled and whether default SNMP communities are present. `IT OPS` [S2] [S3]
- Disable DDP on every DGS-3130 switch: run 'no ddp' globally and on interfaces where needed, confirm with 'show ddp', save the configuration, and confirm the setting is still in place after the next reboot. `IT OPS` [S2] [S3]
- Remove default SNMP communities and any community that is not in use. Do this in addition to disabling DDP, not in place of it; removing communities does not fix the DDP information exposure. `IT OPS` [S2] [S3]
- Take a fresh configuration backup of each switch and store a copy offline, so a factory reset can be recovered quickly. `IT OPS` [S2] [S4]
- Confirm that switch syslog and SNMP traps reach the SIEM, and start alerting on unexpected configuration changes, reboots and factory resets. `SOC` [S2] [S4]

Short term (1–7 days)

- Restrict SSH, web UI and SNMP on the switches to an isolated management network and named administrator hosts, using management ACLs, trusted-host lists and upstream ACLs. Confirm that no switch management interface is reachable from the internet, guest Wi-Fi or user VLANs. `IT OPS` [S2] [S3]
- Rotate SNMP community strings and switch administrator passwords on affected devices, on the assumption that they could have been read while DDP was enabled. Move to SNMPv3 with authentication and privacy where the monitoring platform supports it. `IT OPS` [S3] [S7]
- Hunt back through switch logs, flow data, firewall logs and RADIUS or TACACS+ logs for unexplained configuration changes, reboots, resets, and non-management hosts contacting switch management addresses. Preserve configurations and logs if anything is found. `SOC` [S2] [S3]
- Compare each switch's running configuration against the last known-good backup and investigate differences such as new accounts, changed

communities, new VLANs, port mirroring or altered ACLs. `IT OPS` [S2] [S4]
- Assign someone to check D-Link announcement SAP10523 in a browser at least twice a week for added models, CVE IDs and fixed firmware. The page did not load for automated tools on 2026-11-07 or 2026-11-10, so do not rely on a feed or scraper. `IT OPS` [S1] [S3]

Long term

- Install fixed firmware when D-Link releases it, in a planned maintenance window, then re-check that DDP stays disabled unless there is a clear operational need for it. `IT OPS` [S2] [S7]
- Make disabling vendor discovery and setup protocols, removing default SNMP communities, using SNMPv3 and using a dedicated management VLAN part of the standard build for every network device. `IT OPS` [S2] [S3]
- Review network hardware purchasing and lifecycle plans in light of how long this fix takes, and decide what patch timeline is acceptable for core switching. `LEADERSHIP` [S2] [S4]

Workarounds & compensating controls

- If DDP cannot be turned off at once on some switches, place their management interfaces behind an ACL or firewall that drops everything except traffic from the management station. Treat this as temporary: disabling DDP is the only mitigation reported as tested against the DDP attack paths, and filtering does not help against a host on the same segment as the switch. `IT OPS` [S2] [S3]
- Use 802.1X or port security on access ports, and keep guest, IoT and operational technology devices in VLANs that cannot reach switch management addresses, to reduce the number of hosts able to send DDP traffic. `IT OPS` [S2]
- Keep a tested recovery runbook and a spare or pre-staged configuration for critical stacks so a hostile factory reset is a short outage. `LEADERSHIP` [S4]

Actions marked with an owner: SOC = security operations, IT Ops = system and network administration, Leadership = risk and communications decisions.

SOURCES

[S1] D-Link: Security announcement SAP10523 (DGS-3130-30TS H/W Rev. B1: multiple DDP protocol and firmware security vulnerabilities reported)
Published 2026-11-06 · `A6` Completely reliable, truth cannot be judged
Primary vendor advisory, linked by BleepingComputer. Our fetch on 2026-11-10 returned an 'Article Not Found' page, as it did on 2026-11-07, so the content could not be read directly. It is represented here only through secondary reporting. Verify in a browser.

[S2] BleepingComputer: D-Link warns of multiple zero-days in DGS-3130 Series switches
Published 2026-11-06 · B2 Usually reliable, probably true
Briefing source. Summarizes the vendor advisory, names the researcher, lists mitigations, states no CVE IDs are published. Reread on 2026-11-10; no update to the article.

[S3] DEV Community (user Anoymask): D-Link DGS-3130-30TS: Unpatched Issues in DDP Authentication, Access Control, and Firmware Protection
Published 2026-11-07 · F2 Reliability cannot be judged, probably true
Pseudonymous community post that paraphrases the advisory in detail: hardware revision B1, four firmware builds, the 'no ddp' and 'show ddp' commands, the caveat that D-Link had not independently verified the DDP workaround, and that the advisory link was unavailable on 2026-11-07. Author cannot be judged, but the content matches other reporting. It rates the issue High, which no vendor score supports.

[S4] Hunter Strategy: The Fix Isn't the Finish Line: Exploited OpenSSH, Unpatched Switches, and Ransomware That Outlasts Recovery
Published 2026-11-06 · C2 Fairly reliable, probably true
Consulting firm's threat brief. Notes that disabling DDP does not resolve every issue under review and that exploitation is not established.

[S5] SecurityLab.ru: 0Day in D-Link switches: no patch, and one command may save the network (Russian-language article)
Published 2026-11-06 · C2 Fairly reliable, probably true
Read for the 2026-11-07 report; could not be reopened on 2026-11-10 because the fetch tool refused the domain. Used only for points recorded from that earlier reading: the 2026-11-02 report date, the default community names, and the vendor statement that it has no reports of attacks. The firmware builds and CLI commands are independently confirmed by S3.

[S6] TechTalkThai: D-Link warns of multiple zero-day flaws in DGS-3130 switches with no patch, advises disabling DDP (Thai-language article)
Published 2026-11-07 · C2 Fairly reliable, probably true
Derivative of BleepingComputer. Consistent on all points; no exploitation claim.

[S7] Carthage Electronics: November 7 2026 CVE Threat Brief
Published 2026-11-07 · C3 Fairly reliable, possibly true
Small IT provider's daily brief, derived from BleepingComputer. Adds the recommendation to move to SNMPv3. States no firmware is available.

[S8] Tech Bytes: D-Link warns of multiple zero-days in DGS-3130 Series switches
Published 2026-11-07 · `C3` Fairly reliable, possibly true
Rewrite of the BleepingComputer article. Opened to test claims in search summaries about reserved CVE IDs and ACL or VLAN controls being insufficient; the page says neither.

[S9] Zero Day Initiative: ZDI-23-1270: D-Link DAP-2622 DDP Set IPv6 Address Default Gateway Stack-based Buffer Overflow Remote Code Execution Vulnerability
Published 2023-08-25 · `A1` Completely reliable, confirmed by other sources
Historical context only: an earlier unauthenticated, network-adjacent DDP flaw (CVE-2023-37316, CVSS 8.8) on a different D-Link product. Shows DDP has been a weak point before; not part of the current disclosure.

[S10] CISA: Known Exploited Vulnerabilities catalog (JSON feed, version 2026.11.09)
Published 2026-11-09 · `A2` Completely reliable, probably true
Checked on 2026-11-10. Only the first part of the feed could be read by our tool and it showed no D-Link DGS-3130 entry. KEV entries require a CVE ID and none exists for these flaws, so a listing is not possible yet.

Grades use the Admiralty scale: letter = source reliability (A completely reliable to F cannot be judged), number = information credibility (1 confirmed to 6 cannot be judged).

MISCELLANEOUS

Timeline

Date	Event	Source
2023-08-25	ZDI publishes an unauthenticated DDP remote code execution flaw in the D-Link DAP-2622 access point (CVE-2023-37316), an earlier DDP weakness on a different product.	[S9]
2026-11-02	Giresh Kumar Enugu of Spectrum Community Solutions reports the DGS-3130-30TS findings to D-Link through coordinated disclosure.	[S5]
2026-11-06	D-Link publishes interim announcement SAP10523 with mitigations and no firmware fix; BleepingComputer and others report it.	[S1] [S2] [S4]

Date	Event	Source
2026-11-07	Follow-on coverage confirms no CVE IDs, no fixed firmware and no reported exploitation. One write-up notes the advisory link was unavailable that day.	[S3] [S6] [S7]
2026-11-09	CISA KEV catalog version 2026.11.09 released; no entry for these flaws is possible because no CVE is assigned.	[S10]
2026-11-10	Report prepared. No vendor update, CVE assignment, firmware release, proof-of-concept or exploitation report found. Advisory page still returns 'Article Not Found' to automated fetch.	[S1] [S2]

Relevance to Indianapolis, Indiana & managed clients

D-Link managed switches are sold mainly on price, so in Indiana they are most often found in small and mid-size businesses, small municipal and township offices, K-12 schools and libraries, small clinics and dental or specialty practices, and in plant-floor or warehouse closets at manufacturers and logistics firms. These are also the environments that most often run flat networks with no separate management VLAN, default SNMP settings and no switch logging, which is the condition these flaws need. For Indianapolis-area healthcare and manufacturing sites the main concern is availability: a forced factory reset of a stack carrying clinical, production or building-control traffic is an outage, and many small sites have no current configuration backup. For local government and schools the concern is that someone on a guest or student network that can reach switch management could alter VLANs or mirror traffic. Managed IT service clients should have switch inventories checked for DGS-3130 units this week, DDP disabled and SNMP defaults removed as a standard change, and switch logs brought into monitoring. Because there is no patch and no date for one, these mitigations are the whole defense for now and should be verified, not assumed. Sites with no D-Link switching can treat this as awareness only, but it is a useful prompt to check that every network device, of any brand, has discovery protocols limited and management access isolated.

Intelligence gaps

- The vendor advisory SAP10523 could not be read directly on 2026-11-07 or 2026-11-10. It is unknown whether D-Link withdrew it for revision or whether the site blocks automated readers. Version-specific and wording-specific points rest on secondary reporting.
- No CVE IDs, CVSS scores or CWE classifications are published, so the number of distinct flaws and their individual severity are unknown.
- D-Link has not said which of the four firmware builds is affected by which flaw, or whether any existing build is unaffected.
- The DDP port and message types involved are not stated in any source we opened, which limits network detection. Confirm from device documentation or a packet capture.
- It is unknown whether the flaws can be triggered only from the same Layer 2 segment or from any routed network that can reach the switch. This decides how much protection ACLs and VLAN separation give.
- Whether D-Link has now independently confirmed that 'no ddp' stops processing on the tested attack paths is unknown.
- Whether other DGS-3130 models, other hardware revisions and other D-Link switch families are affected is still under vendor investigation.

- The status and severity of the separate firmware design issues (SSH configuration, OS credential protection, firmware encryption and embedded keys) are unresolved.
- No fix date has been announced. Watch for updated firmware, CVE publication, a researcher write-up, proof-of-concept code and any CISA advisory or KEV addition.

Other notes

- Nothing material has changed since the 2026-11-07 report on this item. This file refreshes the sourcing and confirms the status as of 2026-11-10.
- 'Zero-day' in the headlines means disclosed without a patch. No source reports exploitation, and SecurityLab relayed a vendor statement that no real-world attacks are known [S5].
- Search summaries surfaced three claims that we could not confirm on any page we opened, so they are not used in the assessment: that a public proof-of-concept exists for the DGS-3130 flaws, that CVE IDs are reserved or submitted but not yet public, and that D-Link considers management ACLs and VLAN separation insufficient against the DDP issues. The proof-of-concept claim most likely confuses this item with the separate DIR-822A router flaw mentioned in the same BleepingComputer article [S2] [S8].
- Severity labels differ between outlets: one community write-up says High [S3], while the briefing rates the item Medium. With no vendor score and a requirement for network access, Medium is reasonable for now. It would rise if details show unauthenticated administrative control from routed networks or if exploit code appears.
- BleepingComputer notes that in September 2026 D-Link warned of CVE-2026-86296, an unpatched maximum-severity flaw with public exploit code in legacy DIR-822A routers. That is a separate issue in a different product line [S2].
- SC Media, SecNews and Mezha also covered the story but their pages returned HTTP 403 to our fetch, so they are not cited. SecurityLab.ru could not be reopened on 2026-11-10 and is cited only for points recorded when it was read on 2026-11-07.

CTI-20261110-06 v1.0 · Generated 2026-11-10 12:45 EST from public reporting. Drafted with AI assistance and reviewed by Nick Sturgeon. Verify indicators and actions before operational use. Summaries are in the analyst's own words.

Back to the daily briefing.

TLP:AMBER Restricted to the recipient’s organization and its trusted clients/contractors on a need-to-know basis.