

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 74497 - Jaguar F-Type - Headlamp Lens Micro-Cracking

Models : F-Type / X152

Engineer Chris Davies

Name :

Last 20 AUG 2019 15:24:27

Modified :

Category : Body

Symptom : 108000 Ext. Trim/Accessories

Content : Issue:

Headlamp lens micro cracking - A small number of customer's may report that the lens surface of the headlamp is cracking (as per attached image 1.0).

Cause:

A combination of heat and strong cleaning products may affect the lens surface.

Action:

1. This repair is **only** applicable to the following part numbers:

- T2R18044 - Bi Xenon Headlamp RH Black Bezel
- T2R18058 - Bi Xenon Headlamp LH Black Bezel
- T2R18041 - Active/Adaptive Headlamp RH Black Bezel
- T2R18055 - Active/Adaptive Headlamp LH Black Bezel
- T2R18038 - Bi Xenon Headlamp RH Chrome Bezel
- T2R18052 - Bi Xenon Headlamp LH Chrome Bezel
- T2R18037 - Active/Adaptive Headlamp RH Chrome Bezel
- T2R18051 - Active/Adaptive Headlamp LH Chrome Bezel

2. *Ensure the new headlamp is marked with a green dot (as per attached image 2.0).*

3. Replace only the affected head lamp unit as per topix (407-01: Exterior Lighting, Removal and Installation –

Headlamp Assembly).

File : [1.0 F-Type Micro Cracking Headlamp Example Reference Image.JPG](#)
[2.0 F-Type Micro Cracking Headlamp Clean Stock Green Spot Reference Image.jpg](#)

Jaguar Land Rover Limited 2000 - 2019 (Rel. 2672)