

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC: AUDIO AMPLIFIER MODULE [AAM] [G2345173]

DESCRIPTION AND OPERATION

AUDIO AMPLIFIER MODULE [AAM]

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If the control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system)
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests
- Inspect connectors and modules for signs of water ingress, and pins for damage and/or corrosion
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals
- Where an 'on demand self-test' is referred to, this can be accessed via the 'diagnostic trouble code monitor' tab on the manufacturers approved diagnostic system
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all diagnostic trouble codes (DTCs) that could be logged in the audio amplifier module, for additional diagnosis and testing information refer to the relevant diagnosis and testing section. For additional information, refer to: [Information and Entertainment System](#) (415-00 Information and Entertainment System - General Information, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B128A-11	Speaker #13 - Circuit short to ground	■ Wiring harness fault ■ Incorrect calibration ■ Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel ■ Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest ■ If fault persists, configure the audio amplifier to the latest software level and retest ■ If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128A-12	Speaker #13 - Circuit short to battery	■ Wiring harness fault ■ Incorrect calibration ■ Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel ■ Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest ■ If fault persists, configure the audio amplifier to the latest software level and retest ■ If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128A-13	Speaker #13 - Circuit open	■ Wiring harness fault ■ Incorrect calibration ■ Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel ■ Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest ■ Configure the audio amplifier to the latest software level and retest ■ If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128A-1A	Speaker #13 - Circuit resistance below threshold	■ Wiring harness fault ■ Incorrect calibration ■ Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel ■ Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest ■ If fault persists, configure the audio amplifier to the latest software level and retest ■ If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B128A-4A	Speaker #13 - Incorrect component installed	- Incorrect speaker installed - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128B-11	Speaker #14 - Circuit short to ground	- Wiring harness fault - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128B-12	Speaker #14 - Circuit short to battery	- Wiring harness fault - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128B-13	Speaker #14 - Circuit open	- Wiring harness fault - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - Configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B128B-1A	Speaker #14 - Circuit resistance below threshold	- Wiring harness fault - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128B-4A	Speaker #14 - Incorrect component installed	- Incorrect speaker installed - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128C-11	Speaker #15 - Circuit short to ground	NOTE: Circuit reference - CTR(SPKR15)+/CTR(SPKR15)- - Centre speaker circuit short circuit to ground - Failure of centre speaker - Audio amplifier module internal failure	NOTE: Only applies to vehicles fitted with a Meridian® surround sound system. This is a co-axial circuit with connections to a mid-range and a tweeter speaker - Refer to the electrical circuit diagrams and check the centre speaker circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B128C-12	Speaker #15 - Circuit short to battery	NOTE: Circuit reference - CTR(SPKR15)+/CTR(SPKR15)- - Centre speaker circuit short circuit to power - Failure of centre speaker - Audio amplifier module internal failure	NOTE: Only applies to vehicles fitted with a Meridian® surround sound system. This is a co-axial circuit with connections to a mid-range and a tweeter speaker - Refer to the electrical circuit diagrams and check the centre speaker circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B128C-13	Speaker #15 - Circuit open	NOTE: Circuit reference - CTR(SPKR15)+/CTR(SPKR15)- - Centre speaker circuit open circuit, high resistance - Failure of centre speaker - Audio amplifier module internal failure	NOTE: Only applies to vehicles fitted with a Meridian® surround sound system. This is a co-axial circuit with connections to a mid-range and a tweeter speaker - Refer to the electrical circuit diagrams and check the centre speaker circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new rear left surround speaker - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B128C-1A	Speaker #15 - Circuit resistance below threshold	NOTE: Circuit reference - CTR(SPKR15)+/CTR(SPKR15)- - Centre surround speaker circuit short circuit - Failure of centre speaker - Audio amplifier module internal failure	NOTE: Only applies to vehicles fitted with a Meridian® surround sound system. This is a co-axial circuit with connections to a mid-range and a tweeter speaker - Refer to the electrical circuit diagrams and check the centre speaker circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B128C-4A	Speaker #15 - Incorrect component installed	NOTE: Circuit reference - CTR(SPKR15)+/CTR(SPKR15)- - Incorrect speaker installed - Failure of centre speaker - Audio amplifier module internal failure	NOTE: Only applies to vehicles fitted with a Meridian® surround sound system. This is a co-axial circuit with connections to a mid-range and a tweeter speaker - Check that the correct component has been installed to the centre position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B128D-11	Speaker #16 - Circuit short to ground	- Wiring harness fault - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128D-12	Speaker #16 - Circuit short to battery	- Wiring harness fault - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128D-13	Speaker #16 - Circuit open	- Wiring harness fault - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - Configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B128D-1A	Speaker #16 - Circuit resistance below threshold	- Wiring harness fault - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B128D-4A	Speaker #16 - Incorrect component installed	- Incorrect speaker installed - Incorrect calibration - Audio amplifier module internal failure	NOTE: No speaker is connected to this output channel - Check the speaker harness and connectors for damage or contamination, also check for any cables or speakers that have been connected to this channel. Repair the circuit as required, clear the DTC and retest - If fault persists, configure the audio amplifier to the latest software level and retest - If fault persists and if no evident issue is seen, install a new audio amplifier module as required. Clear the DTCs and retest
B1297-01	Digital Headphone Module - General electrical failure	- Headphone transmitter circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headphone transmitter internal failure - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the headphone transmitter circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new headphone transmitter - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1297-11	Digital Headphone Module - Circuit short to ground	- Headphone transmitter circuit short circuit to ground - Headphone transmitter internal failure - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the headphone transmitter circuit for short circuit to ground. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new headphone transmitter - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A01-11	Speaker #1 - Circuit short to ground	NOTE: Circuit reference - FL HI (SPKR1)+/FL HI (SPKR1)- - Front left tweeter speaker circuit short circuit to ground - Failure of front left tweeter speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left tweeter speaker circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A01-12	Speaker #1 - Circuit short to battery	NOTE: Circuit reference - FL HI (SPKR1)+/FL HI (SPKR1)- - Front left tweeter speaker circuit short circuit to power - Failure of front left tweeter speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left tweeter speaker circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A01-13	Speaker #1 - Circuit open	NOTE: Circuit reference - FL HI (SPKR1)+/FL HI (SPKR1)- - Front left tweeter speaker circuit open circuit, high resistance - Failure of front left tweeter speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left tweeter speaker circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A01-1A	Speaker #1 - Circuit resistance below threshold	NOTE: Circuit reference - FL HI (SPKR1)+/FL HI (SPKR1)- - Front left tweeter speaker circuit short circuit - Failure of front left tweeter speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left tweeter speaker circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A01-4A	Speaker #1 - Incorrect component installed	NOTE: Circuit reference - FL HI (SPKR1)+/FL HI (SPKR1)- - Incorrect speaker installed - Failure of front left tweeter speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the front left tweeter speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A02-11	Speaker #2 - Circuit short to ground	NOTE: Circuit reference - FL LOW(SPKR2)+/FL LOW(SPKR2)- - Front left bass speaker circuit short circuit to ground - Failure of centre front left bass speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left bass speaker circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A02-12	Speaker #2 - Circuit short to battery	NOTE: Circuit reference - FL LOW(SPKR2)+/FL LOW(SPKR2)- - Front left bass speaker circuit short circuit to power - Failure of front left bass speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left bass speaker circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A02-13	Speaker #2 - Circuit open	NOTE: Circuit reference - FL LOW(SPKR2)+/FL LOW(SPKR2)- - Front left bass speaker circuit open circuit, high resistance - Failure of front left bass speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left bass speaker circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A02-1A	Speaker #2 - Circuit resistance below threshold	NOTE: Circuit reference - FL LOW(SPKR2)+/FL LOW(SPKR2)- - Front left bass speaker circuit short circuit - Failure off front left bass speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left bass speaker circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A02-4A	Speaker #2 - Incorrect component installed	NOTE: Circuit reference - FL LOW(SPKR2)+/FL LOW(SPKR2)- - Incorrect speaker installed - Failure of front left bass speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the front left bass speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A03-11	Speaker #3 - Circuit short to ground	NOTE: Circuit reference - FR HI (SPKR3)+/FR HI (SPKR3)- - Front right tweeter speaker circuit short circuit to ground - Failure of front right tweeter speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right tweeter speaker circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A03-12	Speaker #3 - Circuit short to battery	NOTE: Circuit reference - FR HI (SPKR3)+/FR HI (SPKR3)- - Front right tweeter speaker circuit short circuit to power - Failure of front right tweeter speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right tweeter speaker circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A03-13	Speaker #3 - Circuit open	NOTE: Circuit reference - FR HI (SPKR3)+/FR HI (SPKR3)- - Front right tweeter speaker circuit open circuit, high resistance - Failure of front right tweeter speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right tweeter speaker circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A03-1A	Speaker #3 - Circuit resistance below threshold	NOTE: Circuit reference - FR HI (SPKR3)+/FR HI (SPKR3)- - Front right tweeter speaker circuit short circuit - Failure of front right tweeter speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right tweeter speaker circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A03-4A	Speaker #3 - Incorrect component installed	NOTE: Circuit reference - FR HI (SPKR3)+/FR HI (SPKR3)- - Incorrect speaker installed - Failure of front right tweeter speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the front right tweeter speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A04-11	Speaker #4 - Circuit short to ground	NOTE: Circuit reference - FR LO (SPKR4)+/FR LO (SPKR4)- - Front right bass speaker circuit short circuit to ground - Failure of front right bass speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right bass speaker circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A04-12	Speaker #4 - Circuit short to battery	NOTE: Circuit reference - FR LO (SPKR4)+/FR LO (SPKR4)- - Front right bass speaker circuit short circuit to power - Failure of front right bass speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right bass speaker circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A04-13	Speaker #4 - Circuit open	NOTE: Circuit reference - FR LO (SPKR4)+/FR LO (SPKR4)- - Front right bass speaker circuit open circuit, high resistance - Failure of front right bass speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right bass speaker circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A04-1A	Speaker #4 - Circuit resistance below threshold	NOTE: Circuit reference - FR LO (SPKR4)+/FR LO (SPKR4)- - Front right bass speaker circuit short circuit - Failure of front right bass speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right bass speaker circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A04-4A	Speaker #4 - Incorrect component installed	NOTE: Circuit reference - FR LO (SPKR4)+/FR LO (SPKR4)- - Incorrect speaker installed - Failure of front right bass speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the front right bass speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A05-11	Speaker #5 - Circuit short to ground	NOTE: Circuit reference - RL (SPKR5)+/RL (SPKR5)- - Left surround speaker circuit short circuit to ground - Failure of front left surround speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left surround speaker circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A05-12	Speaker #5 - Circuit short to battery	NOTE: Circuit reference - RL (SPKR5)+/RL (SPKR5)- - Left surround speaker circuit short circuit to power - Failure of front left surround speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left surround speaker circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A05-13	Speaker #5 - Circuit open	NOTE: Circuit reference - RL (SPKR5)+/RL (SPKR5)- - Left surround speaker circuit open circuit, high resistance - Failure of front left surround speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left surround speaker circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A05-1A	Speaker #5 - Circuit resistance below threshold	NOTE: Circuit reference - RL (SPKR5)+/RL (SPKR5)- - Left surround speaker circuit short circuit - Failure of front left surround speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left surround speaker circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A05-4A	Speaker #5 - Incorrect component installed	NOTE: Circuit reference - RL (SPKR5)+/RL (SPKR5)- - Incorrect speaker installed - Failure of front left surround speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the front left surround speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A06-11	Speaker #6 - Circuit short to ground	NOTE: Circuit reference - LSUB2 (SPKR6)+/LSUB2 (SPKR6)- - Left sub woofer channel 2 circuit short circuit to ground - Failure of left sub woofer channel 2 - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the left sub woofer channel 2 circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A06-12	Speaker #6 - Circuit short to battery	NOTE: Circuit reference - LSUB2 (SPKR6)+/LSUB2 (SPKR6)- - Left sub woofer channel 2 circuit short circuit to power - Failure of left sub woofer channel 2 - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the left sub woofer channel 2 circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A06-13	Speaker #6 - Circuit open	NOTE: Circuit reference - LSUB2 (SPKR6)+/LSUB2 (SPKR6)- - Left sub woofer channel 2 circuit open circuit, high resistance - Failure of left sub woofer channel 2 - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the left sub woofer channel 2 circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A06-1A	Speaker #6 - Circuit resistance below threshold	NOTE: Circuit reference - LSUB2 (SPKR6)+/LSUB2 (SPKR6)- - Left sub woofer channel 2 circuit short circuit - Failure of left sub woofer channel 2 - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the left sub woofer channel 2 circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A06-4A	Speaker #6 - Incorrect component installed	NOTE: Circuit reference - LSUB2 (SPKR6)+/LSUB2 (SPKR6)- - Incorrect speaker installed - Failure of left sub woofer channel 2 - Audio amplifier module internal failure	- Check that the correct component has been installed to the left sub woofer channel 2 position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A07-11	Speaker #7 - Circuit short to ground	NOTE: Circuit reference - RR (SPKR7)+/RR (SPKR7)- - Right surround speaker circuit short circuit to ground - Failure of right surround speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right surround speaker circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A07-12	Speaker #7 - Circuit short to battery	NOTE: Circuit reference - RR (SPKR7)+/RR (SPKR7)- - Right surround speaker circuit short circuit to power - Failure of right surround speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right surround speaker circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A07-13	Speaker #7 - Circuit open	NOTE: Circuit reference - RR (SPKR7)+/RR (SPKR7)- - Right surround speaker circuit open circuit, high resistance - Failure of right surround speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right surround speaker circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A07-1A	Speaker #7 - Circuit resistance below threshold	NOTE: Circuit reference - RR (SPKR7)+/RR (SPKR7)- - Right surround speaker circuit short circuit - Failure of right surround speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right surround speaker circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A07-4A	Speaker #7 - Incorrect component installed	NOTE: Circuit reference - RR (SPKR7)+/RR (SPKR7)- - Incorrect speaker installed - Failure of right surround speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the right surround speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A08-11	Speaker #8 - Circuit short to ground	NOTE: Circuit reference - RSUB2 (SPKR8)+/RSUB2 (SPKR8)- - Right sub woofer channel 2 circuit short circuit to ground - Failure of right sub woofer channel 2 - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right sub woofer channel 2 circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A08-12	Speaker #8 - Circuit short to battery	NOTE: Circuit reference - RSUB2 (SPKR8)+/RSUB2 (SPKR8)- - Right sub woofer channel 2 circuit short circuit to power - Failure of right sub woofer channel 2 - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right sub woofer channel 2 circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A08-13	Speaker #8 - Circuit open	NOTE: Circuit reference - RSUB2 (SPKR8)+/RSUB2 (SPKR8)- - Right sub woofer channel 2 circuit open circuit, high resistance - Failure of right sub woofer channel 2 - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right sub woofer channel 2 circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A08-1A	Speaker #8 - Circuit resistance below threshold	NOTE: Circuit reference - RSUB2 (SPKR8)+/RSUB2 (SPKR8)- - Right sub woofer channel 2 circuit short circuit - Failure of right sub woofer channel 2 - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right sub woofer channel 2 circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A08-4A	Speaker #8 - Incorrect component installed	NOTE: Circuit reference - RSUB2 (SPKR8)+/RSUB2 (SPKR8)- - Incorrect speaker installed - Failure of right sub woofer channel 2 - Audio amplifier module internal failure	- Check that the correct component has been installed to the right sub woofer channel 2 position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A09-11	Speaker #9 - Circuit short to ground	NOTE: Circuit reference - FL MID (SPKR9)+/FL MID (SPKR9)- - Front left mid-range speaker circuit short circuit to ground - Failure of front left mid-range speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left mid-range circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A09-12	Speaker #9 - Circuit short to battery	NOTE: Circuit reference - FL MID (SPKR9)+/FL MID (SPKR9)- - Front left mid-range speaker circuit short circuit to power - Failure of front left mid-range speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left mid-range circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A09-13	Speaker #9 - Circuit open	NOTE: Circuit reference - FL MID (SPKR9)+/FL MID (SPKR9)- - Front left mid-range speaker circuit open circuit, high resistance - Failure of front left mid-range speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left mid-range circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A09-1A	Speaker #9 - Circuit resistance below threshold	NOTE: Circuit reference - FL MID (SPKR9)+/FL MID (SPKR9)- - Front left mid-range speaker circuit short circuit - Failure of front left mid-range speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front left mid-range circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A09-4A	Speaker #9 - Incorrect component installed	NOTE: Circuit reference - FL MID (SPKR9)+/FL MID (SPKR9)- - Incorrect speaker installed - Failure of front left mid-range speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the front left mid-range speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A10-11	Speaker #10 - Circuit short to ground	NOTE: Circuit reference - FR MID (SPKR10)+/FR MID (SPKR10)- - Front right mid-range speaker circuit short circuit to ground - Failure of front right mid-range speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right mid-range speaker circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A10-12	Speaker #10 - Circuit short to battery	NOTE: Circuit reference - FR MID (SPKR10)+/FR MID (SPKR10)- - Front right mid-range circuit speaker short circuit to power - Failure of front right mid-range speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right mid-range speaker circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A10-13	Speaker #10 - Circuit open	NOTE: Circuit reference - FR MID (SPKR10)+/FR MID (SPKR10)- - Front right mid-range speaker circuit open circuit, high resistance - Failure of front right mid-range speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right mid-range speaker circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A10-1A	Speaker #10 - Circuit resistance below threshold	NOTE: Circuit reference - FR MID (SPKR10)+/FR MID (SPKR10)- - Front right mid-range speaker circuit short circuit - Failure of front right mid-range speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the front right mid-range speaker circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A10-4A	Speaker #10 - Incorrect component installed	NOTE: Circuit reference - FR MID (SPKR10)+/FR MID (SPKR10)- - Front right mid-range speaker not connected - Incorrect speaker installed - Failure of front right mid-range speaker - Audio amplifier module internal failure	- Refer to electrical circuit diagrams and check connections between audio amplifier module and front right mid-range speaker - Check that the correct component has been installed to the front right mid-range speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A11-11	Speaker #11 - Circuit short to ground	NOTE: Circuit reference - LSUB1 (SPKR11)+/LSUB1 (SPKR11)- - Left sub-woofer channel 1 circuit short circuit to ground - Failure of left sub-woofer speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the left sub-woofer channel 1 circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A11-12	Speaker #11 - Circuit short to battery	NOTE: Circuit reference - LSUB1 (SPKR11)+/LSUB1 (SPKR11)- - Left sub-woofer channel 1 circuit short circuit to power - Failure of left sub-woofer speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the left sub-woofer channel 1 circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A11-13	Speaker #11 - Circuit open	NOTE: Circuit reference - LSUB1 (SPKR11)+/LSUB1 (SPKR11)- - Left sub-woofer channel 1 circuit open circuit, high resistance - Failure of left sub-woofer speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the left sub-woofer channel 1 circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A11-1A	Speaker #11 - Circuit resistance below threshold	NOTE: Circuit reference - LSUB1 (SPKR11)+/LSUB1 (SPKR11)- - Left sub-woofer channel 1 circuit short circuit - Failure of left sub-woofer speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the left sub-woofer channel 1 circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A11-4A	Speaker #11 - Incorrect component installed	NOTE: Circuit reference - LSUB1 (SPKR11)+/LSUB1 (SPKR11)- - Incorrect speaker installed - Failure of left sub-woofer speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the left sub-woofer speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A12-11	Speaker #12 - Circuit short to ground	NOTE: Circuit reference - RSUB1 (SPKR12)+/RSUB1 (SPKR12)- - Right sub-woofer channel 1 circuit short circuit to ground - Failure of right sub woofer speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right sub-woofer channel 1 circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A12-12	Speaker #12 - Circuit short to battery	NOTE: Circuit reference - RSUB1 (SPKR12)+/RSUB1 (SPKR12)- - Right sub-woofer channel 1 circuit short circuit to power - Failure of right sub-woofer speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right sub-woofer channel 1 circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A12-13	Speaker #12 - Circuit open	NOTE: Circuit reference - RSUB1 (SPKR12)+/RSUB1 (SPKR12)- - Right sub-woofer channel 1 circuit open circuit, high resistance - Failure of right sub-woofer speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right sub-woofer channel 1 circuit for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A12-1A	Speaker #12 - Circuit resistance below threshold	NOTE: Circuit reference - RSUB1 (SPKR12)+/RSUB1 (SPKR12)- - Right sub-woofer channel 1 circuit short circuit - Failure of right sub-woofer speaker - Audio amplifier module internal failure	- Refer to the electrical circuit diagrams and check the right sub-woofer channel 1 circuit for short circuit. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1A12-4A	Speaker #12 - Incorrect component installed	NOTE: Circuit reference - RSUB1 (SPKR12)+/RSUB1 (SPKR12)- - Incorrect speaker installed - Failure of centre right sub-woofer speaker - Audio amplifier module internal failure	- Check that the correct component has been installed to the right sub-woofer speaker position - Confirm speaker operation to check for internal failure, replace if necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D9F-11	Engine speed input - Circuit short to ground	NOTE: Circuit reference - RPM SIG - Audio amplifier crank signal input short circuit to ground - Audio amplifier module internal failure	NOTE: This DTC is not related to any infotainment audio functionality or chimes/beeps/warnings - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, refer to the electrical circuit diagrams and test the audio amplifier module crank signal input circuit for short circuit to ground. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1D9F-12	Engine speed input - Circuit short to battery	NOTE: Circuit reference - RPM SIG - Audio amplifier crank signal input short circuit to power - Audio amplifier module failure	NOTE: This DTC is not related to any infotainment audio functionality or chimes/beeps/warnings - Refer to the electrical circuit diagrams and test the audio amplifier module crank signal input circuit for short circuit to power. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
B1D9F-13	Engine speed input - Circuit open	NOTE: Circuit reference - RPM SIG - Audio amplifier crank signal input open circuit - Audio amplifier module incorrect power mode configuration - Audio amplifier module failure	NOTE: This DTC is not related to any infotainment audio functionality or chimes/beeps/warnings - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, refer to the electrical circuit diagrams and test the audio amplifier module crank signal input circuit for open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, check the power mode sent to the audio amplifier module from the infotainment master controller. If the audio amplifier module power mode is correct check the communication between the Infotainment Master Controller (IMC) and the audio amplifier module. Repair as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new audio amplifier module
U201B-55	Control module calibration data #2 - Not configured	Audio amplifier module is not correctly configured	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the audio amplifier module with the latest level software
U201B-57	Control module calibration data #2 - Invalid/incomplete software component	Audio amplifier module is not correctly configured	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the audio amplifier module with the latest level software

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2300-57	Central Configuration - Invalid/incomplete software component	Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary
U2300-64	Central Configuration - Signal plausibility failure	- Car configuration file mismatch with vehicle specification - Incorrect audio amplifier module installed	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary - Install a new audio amplifier module as necessary
U3000-55	Control Module - Not configured	- Audio amplifier module is not configured correctly - New audio amplifier module	- Using the Jaguar Land Rover approved diagnostic equipment, re-configure the audio amplifier module with the latest level software - This DTC will occur once if a new module is installed. Clear the DTC, cycle the ignition state to off. Lock the vehicle (to ensure the infotainment system has reset). Unlock the vehicle, cycle the ignition state to on. Retest the system
U3000-96	Control Module - Component internal failure	Audio amplifier module internal failure	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new audio amplifier module
U3000-98	Control Module - Component or system over temperature	- Audio amplifier module cooling vents obstructed - One or more speaker circuit faults - Audio amplifier module internal failure	- Check that the audio amplifier module ventilation is not obstructed - Using the Jaguar Land Rover approved diagnostic equipment, check for speaker circuit related DTCs and perform the relevant corrective actions. Clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, check for audio amplifier module failure DTCs and perform the relevant corrective actions. Clear the DTCs and retest