

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC: BODY CONTROL MODULE [G2019693]

DESCRIPTION AND OPERATION

BODY CONTROL MODULE [BCM]

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If the control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system)
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals
- Where an 'on demand self-test' is referred to, this can be accessed via the 'diagnostic trouble code monitor' tab on the manufacturers approved diagnostic system
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all diagnostic trouble codes (DTCs) that could be logged in the body control module, for additional diagnosis and testing information refer to the relevant diagnosis and testing section For additional information, refer to: [Communications Network](#) (418-00 Module Communications Network, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1008-11	Wiper Mode Switch - Circuit short to ground	Wipers and washers control switch circuit short circuit to ground	NOTE: To validate the repair firstly run the engine for at least ten seconds, then use the Jaguar Land Rover approved diagnostic equipment to check the DTCs within the body control module. If the repair is successful this DTC will no longer be logged Refer to the electrical circuit diagrams and check the wipers and washers control switch circuit for short circuit to ground. Repair the wiring harness as necessary
B1008-15	Wiper Mode Switch - Circuit short to battery or open	Wipers and washers control switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly run the engine for at least ten seconds, then use the Jaguar Land Rover approved diagnostic equipment to check the DTCs within the body control module. If the repair is successful this DTC will no longer be logged Refer to the electrical circuit diagrams and check the wipers and washers control switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1008-1C	Wiper Mode Switch - Circuit voltage out of range	- Wipers and washers control switch circuit short circuit to ground, short circuit to power, open circuit, high resistance - Wipers and washers control switch internal failure	NOTE: To validate the repair firstly run the engine for at least ten seconds, then use the Jaguar Land Rover approved diagnostic equipment to check the DTCs within the body control module. If the repair is successful this DTC will no longer be logged - Refer to the electrical circuit diagrams and check the wipers and washers control switch circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - If no wiring faults are detected, install a new steering column right multifunction switch
B1009-51	Ignition Authorization - Not programmed	NOTE: This DTC is only likely to occur following component replacement applications failing prior to completion Start authorisation system not correctly configured	NOTE: To validate the repair firstly check the engine cranking, then use the Jaguar Land Rover approved diagnostic equipment to check the DTCs within the body control module. If the repair is successful this DTC will no longer be logged Using the Jaguar Land Rover approved diagnostic equipment run the "start authorisation" application to perform re-configuration of the module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1009-62	Ignition Authorization - Signal compare failure	NOTE: This DTC is only likely to occur following component replacement applications failing prior to completion Start authorisation system not correctly configured	NOTE: To validate the repair firstly check the engine cranking, then use the Jaguar Land Rover approved diagnostic equipment to check the DTCs within the body control module. If the repair is successful this DTC will no longer be logged Using the Jaguar Land Rover approved diagnostic equipment run the "start authorisation" application to perform re-configuration of the module
B100D-51	Column Lock Authorization - Not programmed	NOTE: This DTC is only likely to occur following component replacement applications failing prior to completion Start authorisation system not correctly configured	Using the Jaguar Land Rover approved diagnostic equipment run the "start authorisation" application to perform re-configuration of the module
B100D-61	Column Lock Authorization - Signal calculation failure	- Anti-lock brake system fault - High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	- Using the Jaguar Land Rover approved diagnostic equipment, check the anti-lock brake system control module for related DTCs and refer to the relevant DTC index - Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B100D-81	Column Lock Authorization - Invalid serial data received	NOTE: This DTC is only likely to occur following component replacement Start authorisation system not correctly configured	Using the Jaguar Land Rover approved diagnostic equipment run the "start authorisation" application to perform re-configuration of the module
B100D-82	Column Lock Authorization - Alive/sequence counter incorrect/not updated	- Anti-lock brake system fault - High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	- Using the Jaguar Land Rover approved diagnostic equipment, check the anti-lock brake system control module for related DTCs and refer to the relevant DTC index - Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B100D-84	Column Lock Authorization - Signal below allowable range	■ Anti-lock brake system fault ■ High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	■ Using the Jaguar Land Rover approved diagnostic equipment, check the anti-lock brake system control module for related DTCs and refer to the relevant DTC index ■ Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B100D-85	Column Lock Authorization - Signal above allowable range	■ Anti-lock brake system fault ■ High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	■ Using the Jaguar Land Rover approved diagnostic equipment, check the anti-lock brake system control module for related DTCs and refer to the relevant DTC index ■ Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B100D-86	Column Lock Authorization - Signal invalid	■ Anti-lock brake system fault ■ High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	■ Using the Jaguar Land Rover approved diagnostic equipment, check the anti-lock brake system control module for related DTCs and refer to the relevant DTC index ■ Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B100D-87	Column Lock Authorization - Missing message	■ Anti-lock brake system fault ■ High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	■ Using the Jaguar Land Rover approved diagnostic equipment, check the anti-lock brake system control module for related DTCs and refer to the relevant DTC index ■ Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B100D-94	Column Lock Authorization - Unexpected operation	■ Electric steering column lock power or ground circuits short circuit, open circuit, high resistance	■ Refer to the electrical circuit diagrams and check the electric steering column lock power and ground circuits for short circuit, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1024-87	Start Control Unit - Missing message	- Active key transceiver module power or ground circuit open circuit, short circuit, high resistance - Active key transceiver module LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly remove the battery from the Smart key and check that the vehicle can be started via the back-up start procedure (holding the Smart key next to the active key transceiver module and operating the stop start switch) - Refer to the electrical circuit diagrams and check the active key transceiver module power and ground circuits for open circuit, short circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the active key transceiver module LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1026-11	Steering Column Lock - Circuit short to ground	Electric steering column lock control module circuit short circuit to ground	NOTE: After ensuring any faults have been repaired, inspect if Diagnostic Trouble Code(s) (DTC) U1000-00 is stored in the Body Control Module (BCM). If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method Refer to the electrical circuit diagrams and check the electric steering column lock control module circuit for short circuit to ground. Repair the wiring harness as necessary. Clear the DTCs and retest
B1026-12	Steering Column Lock - Circuit short to battery	Electric steering column lock control module power and/or ground circuits for short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair firstly run the engine for at least 60 seconds, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged - Refer to the electrical circuit diagrams and check the electric steering column lock control module power and ground circuits for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B102B-67	Passive Key - Signal incorrect after event	NOTE: This DTC is only likely to occur following component replacement applications failing prior to completion Start authorisation system not correctly configured	NOTE: To validate the repair firstly check the engine cranking, then use the Jaguar Land Rover approved diagnostic equipment to check the DTCs within the body control module. If the repair is successful this DTC will no longer be logged Using the Jaguar Land Rover approved diagnostic equipment run the "start authorisation" application to perform re-configuration of the module
B103C-09	Left Headlamp Control - Component failures	Left headlamp assembly internal failure	NOTE: To validate the repair check the headlamp operation, then use the Jaguar Land Rover approved diagnostic equipment to check the DTCs within the body control module. If the repair is successful this DTC will no longer be logged Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B103C-11	Left Headlamp Control - Circuit short to ground	Left headlamp assembly power supply circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC U1000-00</u> is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp assembly power supply circuit for short circuit to ground. Repair the wiring harness as necessary
B103C-1C	Left Headlamp Control - Circuit voltage out of range	- Left headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Battery/charging system fault	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp assembly power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the relevant section of the workshop manual and check the battery and charging system. Rectify as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B103C-49	Left Headlamp Control - Internal electronic failure	Left headlamp assembly internal failure	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B103C-86	Left Headlamp Control - Signal invalid	- Left headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B103C-87	Left Headlamp Control - Missing message	- Left headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B103C-96	Left Headlamp Control - Component internal failure	Left headlamp assembly internal failure	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B103C-98	Left Headlamp Control - Component or system over temperature	Left headlamp assembly over temperature	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest while the vehicle is under normal ambient temperature conditions. If the fault persists, install a new left headlamp assembly
B103D-09	Right Headlamp Control - Component failures	Right headlamp assembly internal failure	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B103D-11	Right Headlamp Control - Circuit short to ground	Right headlamp assembly power supply circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp assembly power supply circuit for short circuit to ground. Repair the wiring harness as necessary
B103D-1C	Right Headlamp Control - Circuit voltage out of range	- Right headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Battery/charging system fault	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp assembly power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the relevant section of the workshop manual and check the battery and charging system. Rectify as required

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B103D-49	Right Headlamp Control - Internal electronic failure	Right headlamp assembly internal failure	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B103D-86	Right Headlamp Control - Signal invalid	- Right headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B103D-87	Right Headlamp Control - Missing message	- Right headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B103D-96	Right Headlamp Control - Component internal failure	Right headlamp assembly internal failure	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B103D-98	Right Headlamp Control - Component or system over temperature	Right headlamp assembly over temperature	NOTE: To validate the repair check all of the headlamp functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest while the vehicle is under normal ambient temperature conditions. If the fault persists, install a new right headlamp assembly
B1041-54	Levelling Control - Missing calibration	NOTE: Ensure all headlamp related DTCs are rectified before attempting to run headlamp levelling calibration routine Headlamp levelling calibration routine has not been run successfully	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Rectify any headlamp related DTCs first. Using the Jaguar Land Rover approved diagnostic equipment, run the diagnostic routine - Calibrate levelling sensors (0x200D)
B1047-11	Rear Fog Lamp Control Switch - Circuit short to ground	Rear fog lamp switch circuit short circuit to ground	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the rear fog lamp switch circuit for short circuit to ground. Repair the wiring harness as necessary
B1047-15	Rear Fog Lamp Control Switch - Circuit short to battery or open	Rear fog lamp switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the rear fog lamp switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1047-1C	Rear Fog Lamp Control Switch - Circuit voltage out of range	Rear fog lamp switch circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the rear fog lamp switch circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1051-11	Front Washer Switch - Circuit short to ground	Wipers and washers control switch circuit short circuit to ground	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the wipers and washers control switch circuit for short circuit to ground. Repair the wiring harness as necessary
B1051-15	Front Washer Switch - Circuit short to battery or open	Wipers and washers control switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the wipers and washers control switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1051-1C	Front Washer Switch - Circuit voltage out of range	Wipers and washers control switch circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the wipers and washers control switch circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B108B-11	Start Button Circuit "A" - Circuit short to ground	Stop/start switch circuit 1 short circuit to ground	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the stop/start switch circuit 1 for short circuit to ground. Repair the wiring harness as necessary
B108B-12	Start Button Circuit "A" - Circuit short to battery	Stop/start switch circuit 1 short circuit to power	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the stop/start switch circuit 1 for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B108B-13	Start Button Circuit "A" - Circuit open	Stop/start switch circuit 1 open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the stop/start switch circuit 1 for open circuit, high resistance. Repair the wiring harness as necessary
B108B-23	Start Button Circuit "A" - Signal stuck low	- Stop/start switch stuck active - Stop/start switch circuit 1 circuit short circuit to ground	NOTE: To validate the repair firstly run the engine for two minutes, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Check the operation of the stop/start switch. Install a new stop/start switch as necessary - Refer to the electrical circuit diagrams and check the stop/start switch circuit 1 for short circuit to ground. Repair the wiring harness as necessary
B108B-56	Start Button Circuit "A" - Invalid/incomplete configuration	Body control module is not configured correctly	NOTE: To validate the repair run the engine for at least two minutes, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, check the latest software has been downloaded to the body control module and up-date the car configuration file as necessary. Clear the DTCs and retest
B108C-11	Start Button Circuit "B" - Circuit short to ground	Stop/start switch circuit 2 short circuit to ground	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the stop/start switch circuit 2 for short circuit to ground. Repair the wiring harness as necessary
B108C-12	Start Button Circuit "B" - Circuit short to battery	Stop/start switch circuit 2 short circuit to power	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the stop/start switch circuit 2 for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B108C-13	Start Button Circuit "B" - Circuit open	Stop/start switch circuit 2 open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the stop/start switch circuit 2 for open circuit, high resistance. Repair the wiring harness as necessary
B108C-23	Start Button Circuit "B" - Signal stuck low	- Stop/start switch stuck active - Stop/start switch circuit 2 circuit short circuit to ground	NOTE: To validate the repair run the engine for at least two minutes, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Check the operation of the stop/start switch. Install a new stop/start switch as necessary - Refer to the electrical circuit diagrams and check the stop/start switch circuit 2 circuit for short circuit to ground. Repair the wiring harness as necessary
B108C-56	Start Button Circuit "B" - Invalid/incomplete configuration	Body control module is not configured correctly	NOTE: To validate the repair run the engine for at least two minutes, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, check the latest software has been downloaded to the body control module and up-date the car configuration file as necessary. Clear the DTCs and retest
B1095-12	Wiper On/Off Relay - Circuit short to battery	- Wiper on/off relay internal failure - Incorrect wiper on/off relay installed - Windshield wiper motor on/off relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new wiper on/off relay as necessary - Refer to the electrical circuit diagrams and check the windshield wiper motor on/off relay circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1095-14	Wiper On/Off Relay - Circuit short to ground or open	- Wiper on/off relay internal failure - Incorrect wiper on/off relay installed - Windshield wiper motor on/off relay circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new wiper on/off relay as necessary - Refer to the electrical circuit diagrams and check the windshield wiper motor on/off relay circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B1096-12	Wiper High/Low Relay - Circuit short to battery	- Wiper fast/slow relay internal failure - Incorrect fast/slow wiper relay installed - Windshield wiper motor fast/slow relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new wiper fast/slow relay as necessary - Refer to the electrical circuit diagrams and check the windshield wiper motor fast/slow relay circuit for short circuit to power. Repair the wiring harness as necessary
B1096-14	Wiper High/Low Relay - Circuit short to ground or open	- Wiper fast/slow relay internal failure - Incorrect fast/slow wiper relay installed - Windshield wiper motor fast/slow relay circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new wiper fast/slow relay as necessary - Refer to the electrical circuit diagrams and check the windshield wiper motor fast/slow relay circuit short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1097-12	Heated Windshield Relay - Circuit short to battery	- Heated windshield relay internal failure - Incorrect heated windshield relay installed - Heated windshield relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new heated windshield relay as necessary - Refer to the electrical circuit diagrams and check the heated windshield relay circuit for short circuit to power. Repair the wiring harness as necessary
B1097-14	Heated Windshield Relay - Circuit short to ground or open	- Heated windshield relay internal failure - Incorrect heated windshield relay installed - Heated windshield relay circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new heated windshield relay as necessary - Refer to the electrical circuit diagrams and check the heated windshield relay circuit short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B109E-51	Remote Keyless Entry - Not programmed	NOTE: This DTC is only likely to occur following component replacement Remote function actuator is not configured correctly	NOTE: To validate the repair check the remote key fob operates the locking/unlocking functions, then use the Jaguar Land Rover approved diagnostic equipment to check that this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the remote function actuator with the latest level software
B10A2-31	Crash Input - No signal	- Crash signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Restraints system fault	- Using the Jaguar Land Rover approved diagnostic equipment, inspect the communication with the Restraints Control Module. If there is no communication, inspect the Restraints Control Module (RCM) power supply and ground. Repair as necessary - Inspect the <u>RCM</u> for related <u>DTC</u> and refer to the relevant <u>DTC</u> index - Refer to the electrical circuit diagrams and check the crash signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10A2-38	Crash Input - Signal frequency incorrect	- Crash signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Restraints system fault	- Using the Jaguar Land Rover approved diagnostic equipment, inspect the communication with the Restraints Control Module. If there is no communication, inspect the <u>RCM</u> power supply and ground. Repair as necessary - Inspect the <u>RCM</u> for related Diagnostic Trouble Code(s) (DTC) and refer to the relevant <u>DTC</u> index - Refer to the electrical circuit diagrams and check the crash signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10A6-00	Main Light Switch - No sub type information	Lighting control switch internal failure	NOTE: To validate the repair check all the lighting switch functions with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new lighting control switch
B10A6-11	Main Light Switch - Circuit short to ground	Lighting control switch circuit short circuit to ground	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the lighting control switch circuit for short circuit to ground. Repair the wiring harness as necessary
B10A6-15	Main Light Switch - Circuit short to battery or open	Lighting control switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the lighting control switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10AB-51	Remote Keyless Entry Synchronization - Not programmed	NOTE: This DTC is only likely to occur following component replacement Remote function actuator is not configured correctly	NOTE: To validate the repair check the remote key fob operates the locking/unlocking functions, then use the Jaguar Land Rover approved diagnostic equipment to check that this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the remote function actuator with the latest level software

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10AD-87	Rain Sensor - Missing message	■ Rain/light sensor incorrectly installed ■ Rain/light sensor LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rain/light sensor power or ground circuit open circuit, high resistance	NOTE: To validate the repair run the engine for at least 10 seconds and check the auto lights function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ■ Check the security and installation of the rain/light sensor. Rectify as necessary ■ Refer to the electrical circuit diagrams and check the rain/light sensor LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary ■ Refer to the electrical circuit diagrams and check the rain/light sensor power and ground circuits for open circuit, high resistance. Repair the wiring harness as necessary
B10AD-96	Rain Sensor - Component internal failure	■ Rain/light sensor failure	NOTE: To validate the repair run the engine for at least 10 seconds and check the auto lights function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new rain/light sensor
B10AE-11	Headlamp Levelling Motor - Circuit short to ground	■ Headlamp levelling motor circuit short circuit to ground	NOTES: ■ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ■ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module ■ Refer to the electrical circuit diagrams and check the headlamp levelling motor circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10AE-12	Headlamp Levelling Motor - Circuit short to battery	Headlamp levelling motor circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the headlamp levelling motor circuit for short circuit to power. Repair the wiring harness as necessary
B10C0-53	Fuel Pump Power Supply - Deactivated	NOTE: This DTC indicates that the fuel pump has been disabled diagnostically to protect the in-tank fuel pump from dry running following replacement of the fuel tank or replacement of the body control module/gateway module assembly Fuel pump power supply deactivated	NOTE: To validate the repair run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Ensure there is sufficient fuel in the fuel tank to submerge the fuel pump (minimum of 10 litres). Using the Jaguar Land Rover approved diagnostic equipment, check the datalogger signal - Fuel Pump Supply Status (0x41DD), and set the fuel pump control to "enable"
B10E5-11	PCM Wake-Up Signal - Circuit short to ground	Powertrain control module wake-up signal circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the powertrain control module wake up circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10E5-15	PCM Wake-Up Signal - Circuit short to battery or open	Powertrain control module wake up circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the powertrain control module wake up circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10E7-11	Ignition On Relay - Circuit short to ground	Power supply feed to engine junction box Ignition ON relay circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the power supply feed to engine junction box Ignition ON relay circuit for short circuit to ground. Repair the wiring harness as necessary
B10E7-15	Ignition On Relay - Circuit short to battery or open	Power supply feed to engine junction box Ignition ON relay circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the power supply feed to engine junction box Ignition ON relay circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10EA-12	Positive Temperature Coefficient Heater - Circuit short to battery	Electric booster heater circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the electric booster heater circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10EA-14	Positive Temperature Coefficient Heater - Circuit short to ground or open	Electric booster heater circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the electric booster heater circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B10F2-4B	Sunroof control - Over temperature	- Debris in the channels/guides - Roof opening panel mechanical failure - Roof opening panel control module failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the sunroof open/close function several times, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Check the roof opening panel for mechanical failure. Rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Check the roof opening panel for smooth operation and obstructions that would cause the motor to overheat. Rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new roof opening panel control module
B10F2-74	Sunroof control - Actuator slipping	- Debris in the channels/guides - Roof opening panel mechanical failure - Roof opening panel control module internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the sunroof open/close function several times, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Check the roof opening panel for smooth operation and obstructions that would cause the motor to slip. Rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Check the roof opening panel for mechanical failure. Rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new roof opening panel control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10F2-93	Sunroof control - No operation	Roof opening panel not calibrated	NOTE: To validate the repair firstly run the engine for 30 seconds and operate the roof opening panel several times, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Sunroof Calibration (2039). Clear the DTCs and retest. If the fault persists, install a new roof opening panel control module
B10F2-9A	Sunroof control - Component or system operating conditions	NOTE: This DTC may be set when the roof opening panel has been operated repeatedly, causing the roof opening panel motor to be temporarily disabled - Excessive operation of the roof opening panel - Roof opening panel open/close switch stuck active	NOTE: To validate the repair run the engine for at least 30 seconds and operate the sunroof open/close function several times, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and check the operation of the switch and roof opening panel for correct operation. Rectify as necessary. Clear the DTCs and retest - Test the operation of the roof opening panel open/close switch. Install a new roof opening panel open/close switch as necessary
B10F3-11	Left Front Position Light - Circuit short to ground	Front left side lamp circuit short circuit to ground	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the front left side lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B10F3-12	Left Front Position Light - Circuit short to battery	Front left side lamp circuit short circuit to power	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the front left side lamp circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10F3-15	Left Front Position Light - Circuit short to battery or open	Front left side lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the front left side lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10F3-84	Left Front Position Light - Signal below allowable range	- Front left headlamp power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the headlamp operation with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front left headlamp power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10F3-85	Left Front Position Light - Signal above allowable range	- Front left headlamp power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the headlamp operation with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front left headlamp power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10F3-86	Left Front Position Light - Signal invalid	- Front left headlamp power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the headlamp operation with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front left headlamp power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10F4-11	Right Front Position Light - Circuit short to ground	Front right side lamp circuit short circuit to ground	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the front right side lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B10F4-12	Right Front Position Light - Circuit short to battery	Front right side lamp circuit short circuit to power	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the front right side lamp circuit for short circuit to power. Repair the wiring harness as necessary
B10F4-15	Right Front Position Light - Circuit short to battery or open	Front right side lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the front right side lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10F4-84	Right Front Position Light - Signal below allowable range	- Front right headlamp power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the headlamp operation with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front right headlamp power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10F4-85	Right Front Position Light - Signal above allowable range	- Front right headlamp power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the headlamp operation with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front right headlamp power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10F4-86	Right Front Position Light - Signal invalid	- Front right headlamp power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the headlamp operation with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front right headlamp power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10F5-11	Left Rear Position Light - Circuit short to ground	Left tail lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the left tail lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B10F5-15	Left Rear Position Light - Circuit short to battery or open	Left tail lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the left tail lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10F6-11	Right Rear Position Light - Circuit short to ground	Right tail lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the right tail lamp circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10F6-15	Right Rear Position Light - Circuit short to battery or open	Right tail lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the right tail lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B10F8-12	Accessory Socket 'A' Relay - Circuit short to battery	12 volt accessory socket relay internal failure - Incorrect 12 volt accessory socket relay installed 12 volt accessory socket relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new 12 volt accessory socket relay as necessary - Refer to the electrical circuit diagrams and check the 12 volt accessory socket relay circuit for short circuit to power. Repair the wiring harness as necessary
B10F8-14	Accessory Socket 'A' Relay - Circuit short to ground or open	12 volt accessory socket relay internal failure - Incorrect 12 volt accessory socket relay installed 12 volt accessory socket relay circuit short circuit to ground or open circuit	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new 12 volt accessory socket relay as necessary - Refer to the electrical circuit diagrams and check the 12 volt accessory socket relay circuit for short circuit to ground or open circuit. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10F9-12	Accessory Socket 'B' Relay - Circuit short to battery	■ Cigar lighter relay internal failure ■ Incorrect cigar lighter relay installed ■ Cigar lighter relay circuit short circuit to power	NOTES: ■ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ■ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module ■ Install a new cigar lighter relay as necessary ■ Refer to the electrical circuit diagrams and check the cigar lighter relay control circuit for short circuit to power. Repair the wiring harness as necessary
B10F9-14	Accessory Socket 'B' Relay - Circuit short to ground or open	■ Cigar lighter relay internal failure ■ Incorrect cigar lighter relay installed ■ Cigar lighter relay circuit short circuit to ground or open circuit	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module ■ Install a new cigar lighter relay as necessary ■ Refer to the electrical circuit diagrams and check the cigar lighter relay circuit for short circuit to ground or open circuit. Repair the wiring harness as necessary
B1101-11	Comfort Relay - Circuit short to ground	■ Comfort relay internal failure ■ Incorrect comfort relay installed ■ Comfort relay circuit short circuit to ground	NOTES: ■ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ■ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module ■ Install a new comfort relay as necessary ■ Refer to the electrical circuit diagrams and check the comfort relay circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1101-15	Comfort Relay - Circuit short to battery or open	- Comfort relay internal failure - Incorrect comfort relay installed - Comfort relay circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new comfort relay as necessary - Refer to the electrical circuit diagrams and check the comfort relay circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1102-11	Trailer stop lamp - Circuit short to ground	Trailer stop lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair check the stop lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test of the body control module with the trailer or light board disconnected, if the fault is still present refer to the electrical circuit diagrams and check the trailer stop lamp circuit for a short to ground. Repair the wiring harness as necessary. If the fault is no longer present the fault is with the trailer/light board

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1102-12	Trailer Stop Lamp - Circuit short to battery	Trailer stop lamp circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair check the stop lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test of the body control module, with the trailer or light board disconnected. If the fault is still present refer to the electrical circuit diagrams and check the trailer stop lamp circuit for a short to power. Repair the wiring harness as necessary. If the fault is no longer present the fault is with the trailer/light board
B1112-11	Park Aid Ignition - Circuit short to ground	Parking assist control module supply circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair check the parking aid function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the parking assist control module power supply circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1115-11	High Mounted Stop Lamp control - Circuit short to ground	High mounted stop lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair check the high mounted stop lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the high mounted stop lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B1115-12	High Mounted Stop Lamp control - Circuit short to battery	High mounted stop lamp circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair check the high mounted stop lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the high mounted stop lamp circuit for short circuit to power. Repair the wiring harness as necessary
B1115-15	High Mounted Stop Lamp control - Circuit short to battery or open	High mounted stop lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the high mounted stop lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the high mounted stop lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B111A-11	Number Plate Lamps - Circuit short to ground	License plate lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair check the license plate lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the license plate lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B111A-12	Number Plate Lamps - Circuit short to battery	License plate lamp circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair check the license plate lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the license plate lamp circuit for short circuit to power. Repair the wiring harness as necessary
B111A-15	Number Plate Lamps - Circuit short to battery or open	License plate lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the license plate lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the license plate lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B111E-11	Boot/Trunk Lamps - Circuit short to ground	Luggage compartment lamp power supply circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair check the luggage compartment lamp function with the engine running, then use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check luggage compartment lamp power supply circuit for short circuit to ground. Repair the wiring harness as necessary
B112B-87	Steering Wheel Module - Missing message	- Steering wheel module power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Steering wheel module LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds and check the headlamp functions, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical diagrams and check the steering wheel module power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the steering wheel module LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the harness as necessary
B112C-67	Interior Motion Sensor - Signal incorrect after event	- Volumetric sensor power or ground circuit short circuit to ground, short circuit to power, open circuit, high resistance - Volumetric sensor LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair lock the vehicle for at least 30 seconds and check volumetric sensor functions, then using the Jaguar Land Rover approved diagnostic equipment check this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the volumetric sensor power and ground circuits for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the volumetric sensor LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B112C-87	Interior Motion Sensor - Missing message	■ Volumetric sensor power or ground circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Volumetric sensor LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair lock the vehicle for at least thirty seconds and check volumetric sensor functions, then using the Jaguar Land Rover approved diagnostic equipment check this DTC is not logged ■ Refer to the electrical circuit diagrams and check the volumetric sensor power and ground circuits for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary ■ Refer to the electrical circuit diagrams and check the volumetric sensor LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B113C-11	Hazard Switch Illumination - Circuit short to ground	■ Hazard switch illumination circuit short circuit to ground	NOTES: ■ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ■ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the hazard warning switch illumination function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ■ Refer to the electrical circuit diagrams and check hazard switch illumination circuit for short circuit to ground. Repair the wiring harness as necessary
B113C-15	Hazard Switch Illumination - Circuit short to battery or open	■ Hazard warning lamp switch illumination circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the hazard warning switch illumination function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ■ Refer to the electrical circuit diagrams and check the hazard warning lamp switch illumination circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1140-11	Engine Crank Authorization - Circuit short to ground	Engine crank request signal circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair run the vehicle for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the engine crank request signal circuit for short circuit to ground. Repair the wiring harness as necessary
B1140-15	Engine Crank Authorization - Circuit short to battery or open	Engine crank request signal circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the vehicle for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the engine crank request signal circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1144-12	Heated Steering Wheel Supply - Circuit short to battery	Heated steering wheel supply circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the heated steering wheel function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the heated steering wheel supply circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1144-14	Heated Steering Wheel Supply - Circuit short to ground or open	Heated steering wheel supply circuit open circuit or high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the heated steering wheel function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the heated steering wheel supply circuit for open circuit or high resistance. Repair the wiring harness as necessary
B1146-11	Passive Sounder Supply - Circuit short to ground	Passive sounder control circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair attempt to lock the vehicle with a side door ajar and listen for the error tone emitted from the passive sounder, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the security passive sounder control circuit for short circuit to ground. Repair the wiring harness as necessary
B1146-15	Passive Sounder Supply - Circuit short to battery or open	Passive sounder control circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair attempt to lock the vehicle with a side door ajar and listen for the error tone emitted from the passive sounder, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the security passive sounder control circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B11A2-11	Master Exterior Light Switch - Circuit short to ground	Master exterior light switch circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the exterior light functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check master exterior light switch circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B11A2-15	Master Exterior Light Switch - Circuit short to battery or open	Master exterior light switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the exterior light functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check master exterior light switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B11DC-1C	Rear Wiper Mode Switch - Circuit voltage out of range	Steering column right multifunction switch internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the rear wiper functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column right multifunction switch
B1216-23	Boot/Trunk Motor Close Sensor - Signal stuck low	- Luggage compartment lid soft close position switch circuit short circuit to ground - Luggage compartment lid soft close position switch stuck active - Luggage compartment lid soft close actuator jammed	NOTE: To validate the repair run the engine for at least 30 seconds and check the luggage compartment lid soft close functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the luggage compartment lid soft close position switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the luggage compartment lid soft close position switch. Replace as necessary - Check soft close actuator mechanism. Repair as necessary
B1219-11	Interior Boot/Trunk Release Switch - Circuit short to ground	Instrument panel luggage compartment lid open switch circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the instrument panel luggage compartment lid functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the instrument panel luggage compartment lid open switch circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1219-15	Interior Boot/Trunk Release Switch - Circuit short to battery or open	Instrument panel luggage compartment lid open switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the instrument panel luggage compartment lid functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the instrument panel luggage compartment lid open switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B123A-04	Left Front Turn Indicator - System internal failures	Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B123A-11	Left Front Turn Indicator - Circuit short to ground	Front left turn signal indicator lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC U1000-00</u> is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the front left indicator lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front left turn signal indicator lamp circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B123A-15	Left Front Turn Indicator - Circuit short to battery or open	Front left turn signal indicator lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the front left indicator lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front left turn signal indicator lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B123A-23	Left Front Turn Indicator - Signal stuck low	- Front left turn signal indicator circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left front headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front left turn signal indicator circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left front headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B123A-24	Left Front Turn Indicator - Signal stuck high	- Front left turn signal indicator circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left front headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front left turn signal indicator circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left front headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B123A-86	Left Front Turn Indicator - Signal invalid	- Front left turn signal indicator circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left front headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front left turn signal indicator circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left front headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B123B-04	Right Front Turn Indicator - System internal failures	Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B123B-11	Right Front Turn Indicator - Circuit short to ground	Front right turn signal indicator lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the front right indicator lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front right turn signal indicator lamp circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B123B-15	Right Front Turn Indicator - Circuit short to battery or open	Front right turn signal indicator lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the front right indicator lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front right turn signal indicator lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B123B-23	Right Front Turn Indicator - Signal stuck low	- Front right turn signal indicator circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right turn signal indicator function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front right turn signal indicator circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B123B-24	Right Front Turn Indicator - Signal stuck high	- Front right turn signal indicator circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right turn signal indicator function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front right turn signal indicator circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B123B-86	Right Front Turn Indicator - Signal invalid	- Front right turn signal indicator circuit short circuit to ground, short circuit to power, open circuit, high resistance - Headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right turn signal indicator function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front right turn signal indicator circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1247-11	Left Rear Turn Indicator - Circuit short to ground	Rear left turn signal indicator lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear left turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the rear left turn signal indicator lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B1247-15	Left Rear Turn Indicator - Circuit short to battery or open	Rear left turn signal indicator lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear left turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the rear left turn signal indicator lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1248-11	Right Rear Turn Indicator - Circuit short to ground	Rear right turn signal indicator lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear right turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the rear right turn signal indicator lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B1248-15	Right Rear Turn Indicator - Circuit short to battery or open	Rear right turn signal indicator lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear right turn signal indicator functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the rear right turn signal indicator lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1249-11	Start Button Illumination - Circuit short to ground	Stop/start switch illumination circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the start switch illumination function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the stop/start switch illumination circuit for short circuit to ground. Repair the wiring harness as necessary
B1249-15	Start Button Illumination - Circuit short to battery or open	Stop/start switch illumination circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the start switch illumination function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the stop/start switch illumination circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B124A-11	Right Daytime Running Light - Circuit short to ground	Right side daytime running light circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right side daytime running light circuit for short circuit to ground. Repair the wiring harness as necessary
B124A-15	Right Daytime Running Light - Circuit short to battery or open	Right side daytime running light circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the right side daytime running light circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B124A-84	Right Daytime Running Light - Signal below allowable range	Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B124A-85	Right Daytime Running Light - Signal above allowable range	Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B124A-86	Right Daytime Running Light - Signal invalid	Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B124B-11	Left Daytime Running Light - Circuit short to ground	Left side daytime running light circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left side daytime running light circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B124B-15	Left Daytime Running Light - Circuit short to battery or open	Left side daytime running light circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the left side daytime running light circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B124B-84	Left Daytime Running Light - Signal below allowable range	Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B124B-85	Left Daytime Running Light - Signal above allowable range	Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B124B-86	Left Daytime Running Light - Signal invalid	Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the daytime running lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B124C-04	Turn Indicator Stalk Switch Pack - System internal failures	Steering column left multifunction switch failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column left multifunction switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column left multifunction switch
B124C-71	Turn Indicator Stalk Switch Pack - Actuator stuck	Steering column left multifunction switch failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column left multifunction switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column left multifunction switch
B124E-04	Wiper Stalk Switch Pack - System internal failures	Steering column right multifunction switch failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column right multifunction switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column right multifunction switch
B124E-71	Wiper Stalk Switch Pack - Actuator stuck	Steering column right multifunction switch internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column right multifunction switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column right multifunction switch

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1277-11	Reverse Lamp - Circuit short to ground	Reverse lamp circuit short circuit to ground	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column right multifunction switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the reverse lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B1277-15	Reverse Lamp - Circuit short to battery or open	Reverse lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the reverse lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the reverse lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B127B-11	Ambient Lighting Zone 1 Output Red LED - Circuit short to ground	Red ambience lighting circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the red ambience light function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the red ambience lighting circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B127B-12	Ambient Lighting Zone 1 Output Red LED - Circuit short to battery	Red ambience lighting circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC U1000-00</u> is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the red ambience light function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the red ambience lighting circuit for short circuit to power. Repair the wiring harness as necessary
B1282-11	Ambient Lighting Zone 2 Output Blue LED - Circuit short to ground	Blue ambience lighting circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC U1000-00</u> is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the blue ambience light function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the blue ambience lighting circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1282-12	Ambient Lighting Zone 2 Output Blue LED - Circuit short to battery	Blue ambience lighting circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the blue ambience light function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the blue ambience lighting circuit for short circuit to power. Repair the wiring harness as necessary
B1298-73	Steering Column Adjust Up Switch - Actuator stuck closed	Steering column adjustment switch internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 120 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column adjustment switch
B1299-73	Steering Column Adjust Down Switch - Actuator stuck closed	Steering column adjustment switch internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 120 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column adjustment switch

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12A1-73	Steering Column Adjust Out Switch - Actuator stuck closed	Steering column adjustment switch internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 120 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column adjustment switch
B12A2-73	Steering Column Adjust In Switch - Actuator stuck closed	Steering column adjustment switch internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 120 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column adjustment switch
B12A3-11	Steering Column Adjust Motor Drive A - Circuit short to ground	Steering column adjustment tilt motor circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the steering column adjustment tilt motor circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12A3-12	Steering Column Adjust Motor Drive A - Circuit short to battery	Steering column tilt adjustment motor circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the steering column tilt adjustment motor circuit for short circuit to power. Repair the wiring harness as necessary
B12A3-15	Steering Column Adjust Motor Drive A - Circuit short to battery or open	Steering column adjustment tilt motor circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the steering column adjustment tilt motor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12A4-11	Steering Column Adjust Motor Drive B - Circuit short to ground	Steering column reach adjustment motor circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the steering column reach adjustment motor circuit for short circuit to ground. Repair the wiring harness as necessary
B12A4-12	Steering Column Adjust Motor Drive B - Circuit short to battery	Steering column reach adjustment motor circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the steering column reach adjustment motor circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12A4-15	Steering Column Adjust Motor Drive B - Circuit short to battery or open	Steering column reach adjustment motor circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the steering column reach adjustment motor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B12A7-31	Steering Column Tilt Sensor A - No signal	Steering column tilt adjustment motor circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the steering column tilt adjustment motor circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B12A8-31	Steering Column Telescope Sensor A - No signal	Steering column reach adjustment motor circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the steering column reach adjustment motor circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12CA-11	Start/Stop "Eco-Start" Status Indicator - Circuit short to ground	Auto stop/start warning indicator circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the auto stop/start warning indicator function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the auto stop/start warning indicator circuit for short circuit to ground. Repair the wiring harness as necessary
B12CA-12	Start/Stop "Eco-Start" Status Indicator - Circuit short to battery	Auto stop/start warning indicator circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the auto stop/start warning indicator function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the auto stop/start warning indicator circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12CB-23	Start/Stop "Eco-Start" Enable Button - Signal stuck low	NOTE: This DTC can be logged if the user has held the auto stop start switch active for more than 60 seconds - Auto stop/start switch circuit short circuit to ground - Auto stop/start switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the auto stop/start switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the auto stop/start switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check auto stop/start switch operation. Replace as necessary
B12E2-23	Rear Door Unlock Switch - Interior - Signal stuck low	NOTE: This DTC can be logged if the user has held the rear left/right door unlock switch active for more than 60 seconds - Rear left/right door unlock switch stuck pressed - Rear left/right door interior unlock switch circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 120 seconds and check the rear left/right door unlock switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Check operation of left/right door unlock switch operation. Replace as necessary - Refer to the electrical circuit diagrams and check the rear left/right door interior unlock switch circuit for short circuit to ground. Repair the wiring harness as necessary
B12E4-23	Rear Door Lock Switch - Interior - Signal stuck low	NOTE: This DTC can be logged if the user has held the rear left/right door unlock switch active for more than 60 seconds - Rear left/right door interior unlock switch circuit short circuit to ground - Rear left/right door unlock switch stuck pressed	NOTE: To validate the repair run the engine for at least 120 seconds and check the rear left/right door unlock switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the rear left/right door interior unlock switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check operation of left/right door unlock switch operation. Replace as necessary
B12E7-23	Glove-box Locking Switch - Signal stuck low	NOTE: This DTC can be logged if the user has held the lower glovebox latch switch active for more than 60 seconds - Glovebox latch switch circuit short circuit to ground - Glovebox latch switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the lower glovebox latch switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the glovebox latch switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the glovebox latch switch. Replace as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12E8-23	Liftgate/Tailgate Control/Release Switch - Signal stuck low	NOTE: This DTC can be logged if the user has held the exterior tailgate open switch active for more than 60 seconds - Exterior tailgate open switch circuit short circuit to ground - Exterior tailgate open switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the exterior tailgate open switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the exterior tailgate open switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the exterior tailgate open switch. Replace as necessary
B12EE-11	Liftgate/Tailgate/Trunk Release - Circuit short to ground	Tailgate central door locking motor circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the tailgate release function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the tailgate central door locking motor circuit for short circuit to ground. Repair the wiring harness as necessary
B12EE-15	Tailgate/Trunk Release - Circuit short to battery or open	Tailgate central door locking motor circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the tailgate release function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the tailgate central door locking motor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12EF-11	Trailer Fog Lamp - Circuit short to ground	Trailer fog lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine and check the trailer fog lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test, of the body control module, with the trailer or light board disconnected. If the fault is still present refer to the electrical circuit diagrams and check the trailer fog lamp circuit for short circuit to ground. If the fault is no longer present the fault is with the trailer/light board
B12F3-11	Secondary Tailgate Release - Circuit short to ground	Secondary tailgate release circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the secondary tailgate release function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the secondary tailgate release circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12F3-15	Secondary Tailgate Release - Circuit short to battery or open	Secondary tailgate release circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the secondary tailgate release function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the secondary tailgate release circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B12F4-12	Vehicle Speed Output - Circuit short to battery	NOTE: This DTC refers to a hardwired speed output from the body control module that can be used for aftermarket/accessory fitting where a pulse-width modulation speed signal is required. The circuit is not used on the standard vehicle, but required for aftermarket fitments Accessory circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the accessories road speed signal function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and disconnect any accessories and aftermarket systems connected to the accessory road speed signal circuit, then using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test, of the body control module, with any trailer or light boards disconnected. If the fault is still present refer to the electrical circuit diagrams and check the accessories road speed signal circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12F5-12	Fridge Relay Control - Circuit short to battery	- Engine running relay internal failure - Incorrect engine running relay installed - Engine running relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the engine running feed to trailer function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Install a new engine running relay as necessary - Refer to the electrical circuit diagrams and check the engine running relay circuit for short circuit to power. Repair the wiring harness or install a new engine running relay as necessary
B12F6-11	Headlamp Power Supply A - Circuit short to ground	Left headlamp power supply circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the left front position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp power supply circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12F6-12	Headlamp Power Supply A - Circuit short to battery	Left headlamp power supply circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the left front position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp power supply circuit for short circuit to power. Repair the wiring harness as necessary
B12F6-15	Headlamp Power Supply A - Circuit short to battery or open	Left headlamp power supply circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the left front position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the left headlamp power supply circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B12F7-11	Single Wipe Switch - Circuit short to ground	Single wipe switch circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the single wipe switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check body control module single wipe switch circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B12F7-15	Single Wipe Switch - Circuit short to battery or open	Single wipe switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the single wipe switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check body control module single wipe switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B12F7-1C	Single Wipe Switch - Circuit voltage out of range	- Single wipe switch circuit short circuit to ground, short circuit to power, open circuit, high resistance - Single wipe switch internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the single wipe switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the single wipe switch circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new single wipe switch
B130B-11	Right Rear Fog Lamp - Circuit short to ground	Rear right fog lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear right fog lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the rear right fog lamp circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B130B-12	Right Rear Fog Lamp - Circuit short to battery	Rear right fog lamp circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear right fog lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the rear right fog lamp circuit for short circuit to power. Repair the wiring harness as necessary
B130B-15	Right Rear Fog Lamp - Circuit short to battery or open	Rear right fog lamp circuit short circuit to power, open circuit, high resistance or open	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear right fog lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the rear right fog lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B130E-11	Left Rear Fog Lamp - Circuit short to ground	Rear left fog lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear left fog lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the rear left fog lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B130E-12	Left Rear Fog Lamp - Circuit short to battery	Rear left fog lamp circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear left fog lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the rear left fog lamp circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B130E-15	Left Rear Fog Lamp - Circuit short to battery or open	Rear left fog lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the rear left fog lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the rear left fog lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1311-87	Clock Module - Missing message	- Clock power supply circuit short circuit to battery, short circuit to ground, open circuit or high resistance - Clock LIN bus circuit short circuit to battery, short circuit to ground, open circuit or high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged - Refer to the electrical circuit diagrams and check the clock power supply circuit for short circuit to battery, short circuit to ground, open circuit or high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the clock LIN bus circuit for short circuit to battery, short circuit to ground, open circuit or high resistance. Repair the wiring harness as necessary
B1316-19	Boot/Trunk Latch Power Close Unit - Circuit current above threshold	Luggage compartment lid soft close actuator circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the luggage compartment lid soft close function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the luggage compartment lid soft close actuator circuit for short circuit to ground. Repair the wiring harness as necessary
B1323-23	Horn Switch - Signal stuck low	NOTE: This DTC can be logged if the user has held the horn switch active for more than 120 seconds - Horn switch circuit short circuit to ground - Horn switch fault	NOTE: To validate the repair run the engine for at least 300 seconds and check the horn function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check horn circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the horn switch and rectify as required

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B134E-14	Switch Illumination Adjustment Control - Circuit short to ground or open	Dimmer switch signal circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the dimmer switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the dimmer switch signal circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B136A-11	Heated Washer Jet/Nozzle Output Control - Circuit short to ground	Heated washer jet circuit short to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test, of the body control module, then check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the heated washer jet circuit for short circuit to ground. Repair the wiring harness as necessary
B136A-15	Heated Washer Jet/Nozzle Output Control - Circuit short to battery or open	Heated washer jet circuit short to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test, of the body control module, then check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the heated washer jet circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B136B-11	Suspension Control Module Wake-up Signal - Circuit short to ground	Air suspension wake up signal circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test, of the body control module, then check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the air suspension wake up signal circuit for short circuit to ground. Repair the wiring harness as necessary
B136B-15	Suspension Control Module Wake-up Signal - Circuit short to battery or open	Air suspension wake up signal circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test, of the body control module, then check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the air suspension wake up signal circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B136C-11	Headlamp Delay Control - Circuit short to ground	Headlamp delay control circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the headlamp delay switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the headlamp delay control circuit for short circuit to ground. Repair the wiring harness as necessary
B136C-15	Headlamp Delay Control - Circuit short to battery or open	Headlamp delay control circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the headlamp delay switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the headlamp delay control circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B136D-11	Front Wiper Intermittent Delay Control - Circuit short to ground	Front wiper intermittent delay control switch circuit short circuit to ground	NOTE: To validate the repair firstly run the engine for 30 seconds and check the wiper intermittent delay switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front wiper intermittent delay control switch circuit for short circuit to ground. Repair the wiring harness as necessary
B136D-15	Front Wiper Intermittent Delay Control - Circuit short to battery or open	Front wiper intermittent delay control switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair firstly run the engine for 30 seconds and check the wiper intermittent delay switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front wiper intermittent delay control switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B136D-1C	Front Wiper Intermittent Delay Control - Circuit voltage out of range	- Front wiper intermittent delay control switch circuit short circuit to ground - Front wiper intermittent delay control switch fault	NOTE: To validate the repair firstly run the engine for 30 seconds and check the wiper intermittent delay switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front wiper intermittent delay control switch circuit for short circuit to ground. Repair the wiring harness as necessary - If fault persists, check and install a new front wiper intermittent delay control switch as required

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B136E-11	Glove Box Release Motor - Circuit short to ground	Lower glovebox latch motor circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the glove box release function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the lower glovebox latch motor circuit for short circuit to ground. Repair the wiring harness as necessary
B136E-15	Glove Box Release Motor - Circuit short to battery or open	Lower glovebox latch motor circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the glove box release function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the lower glovebox latch motor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1375-15	Steering Column Tilt Motor - Circuit short to battery or open	Steering column tilt adjustment motor circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the steering column tilt adjustment motor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B137F-16	Steering Wheel Left Switch Pack - Circuit voltage below threshold	- Steering wheel left switchpack resistance out of range, due to contact corrosion in the system - Steering wheel left switchpack internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the cruise switch, steering wheel menu switches, steering wheel infotainment switches and paddle shift (if fitted) switchpack function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Disconnect the left switchpack wiring harness connectors and apply nyogel (or similar proprietary contact grease product) to the terminals, reconnect, clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering wheel left switchpack
B137F-17	Steering Wheel Left Switch Pack - Circuit voltage above threshold	- Steering wheel left switchpack resistance out of range, due to contact corrosion in the system - Steering wheel left switchpack internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the cruise switch, steering wheel menu switches, steering wheel infotainment switches and paddle shift (if fitted) switchpack function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Disconnect the left switchpack wiring harness connectors and apply nyogel (or similar proprietary contact grease product) to the terminals, reconnect, clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering wheel left switchpack
B137F-49	Steering Wheel Left Switch Pack - Internal electronic failure	Steering wheel left switchpack internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the cruise switch, steering wheel menu switches, steering wheel infotainment switches and paddle shift (if fitted) switchpack function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Firstly disconnect the steering wheel switch harness and reconnect, then using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering wheel left switchpack

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1380-16	Steering Wheel Right Switch Pack - Circuit voltage below threshold	- Steering wheel right switchpack resistance out of range, due to contact corrosion in the system - Left and/or right paddle shift switch fault - Steering wheel right switchpack internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the cruise switch, steering wheel menu switches, steering wheel infotainment switches and paddle shift (if fitted) switchpack function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Disconnect the right switchpack wiring harness connectors and apply nyogel (or similar proprietary contact grease product) to the terminals, reconnect, clear the DTCs and retest - Check the connections and operation of the left and/or right paddle shift switch. Repair/replace as required - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering wheel right switchpack
B1380-17	Steering Wheel Right Switch Pack - Circuit voltage above threshold	- Steering wheel right switchpack resistance out of range, due to contact corrosion in the system - Left and/or right paddle shift switch fault - Steering wheel right switchpack internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the cruise switch, steering wheel menu switches, steering wheel infotainment switches and paddle shift (if fitted) switchpack function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Disconnect the right switchpack wiring harness connectors and apply nyogel (or similar proprietary contact grease product) to the terminals, reconnect, clear the DTCs and retest - Check the connections and operation of the left and/or right paddle shift switch. Repair/replace as required - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering wheel right switchpack
B1380-49	Steering Wheel Right Switch Pack - Internal electronic failure	Steering wheel right switch pack internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the cruise switch, steering wheel menu switches, steering wheel infotainment switches and paddle shift (if fitted) switchpack function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Firstly disconnect the steering wheel switch harness and reconnect, then using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering wheel right switchpack

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1380-87	Steering Wheel Right Switch Pack - Missing message	- Steering wheel right switchpack power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Steering wheel LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the cruise switch, steering wheel menu switches, steering wheel infotainment switches and paddle shift (if fitted) switchpack function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the steering wheel right switchpack power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the steering wheel LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B13BD-87	Steering Wheel Heater Module - Missing message	- Steering wheel heater control module power supply circuit short circuit to ground, short circuit to power, open circuit high resistance - Steering wheel heater control module LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering wheel heater function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the steering wheel heater control module power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the steering wheel heater control module LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B13C0-1C	Washer Switch - Circuit voltage out of range	Steering column right multifunction switch internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column right multifunction switch functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column right multifunction switch
B13C1-1C	Fog Lamp Control Switch - Circuit voltage out of range	Steering column left multifunction switch internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column left multifunction switch functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new steering column left multifunction switch

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13C8-11	Headlamp Power Supply B - Circuit short to ground	Right headlamp power supply circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp power supply circuit for short circuit to ground. Repair the wiring harness as necessary
B13C8-12	Headlamp Power Supply B - Circuit short to battery	Right headlamp power supply circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp power supply circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13C8-15	Headlamp Power Supply B - Circuit short to battery or open	Right headlamp power supply circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the right headlamp power supply circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B13CB-46	Roof Blind Module - Calibration/parameter memory failure	Roof blind motor internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the roof blind function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Sunroof Calibration (2039). Clear the DTCs and retest. If the fault persists, install a new roof opening panel control module
B13CB-87	Roof Blind Module - Missing message	- Front roof blind motor power supply circuit short circuit ground, short circuit to power, open circuit, high resistance - Front roof blind motor LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the roof blind function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front roof blind motor power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the front roof blind motor LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13CD-4B	Roof Blind - Over temperature	- Front roof blind operation restricted by debris - Front roof blind mechanical failure - Front roof blind motor internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Check the front roof blind for smooth operation and obstructions that would cause the motor to overheat, rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Check the front roof blind for mechanical failure, rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new front roof blind control module
B13CD-74	Roof Blind - Actuator slipping	- Front roof blind operation restricted by debris or mechanical damage - Front roof blind mechanical failure - Front roof blind motor internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Check the operation of the front roof blind - Check the front roof blind for mechanical failure, rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new front roof blind motor
B13CD-93	Roof Blind - No operation	Front roof blind not calibrated	NOTE: To validate the repair run the engine for at least 30 seconds and operate the roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform the routine - Calibrate Roof Blind (204C). Clear the DTCs and retest. If the fault persists, install a new front roof blind control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13CD-9A	Roof Blind - Component or system operating conditions	NOTE: This DTC may set if the roof blind is operated repeatedly. Roof blind operation will be temporarily disabled - Excessive repeated operation of the front roof blind - Front roof blind open/close switch stuck active	NOTE: To validate the repair run the engine for at least 30 seconds and operate the roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Clear the DTCs and check the operation of the switch and front roof blind for correct operation, rectify as necessary. Clear the DTCs and retest - Test the operation of the front roof blind open/close switch. Install a new front roof blind open/close switch as necessary
B13CF-31	Roof Blind Position Sensor A - No signal	Front roof blind is not calibrated	NOTE: To validate the repair run the engine for at least 30 seconds and operate the roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Roof Blind (204C). Clear the DTCs and retest. If the fault persists, install a new front roof blind control module
B13D0-31	Roof Blind Position Sensor B - No signal	Front roof blind is not calibrated	NOTE: To validate the repair run the engine for at least 30 seconds and operate the roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Roof Blind (204C). Clear the DTCs and retest. If the fault persists, install a new front roof blind control module
B13D3-04	Left Daytime Running Lamp And Position Lamp Control - System internal failures	Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13D3-24	Left Daytime Running Lamp And Position Lamp Control - Signal stuck high	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B13D3-84	Left Daytime Running Lamp And Position Lamp Control - Signal below allowable range	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B13D3-85	Left Daytime Running Lamp And Position Lamp Control - Signal above allowable range	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13D3-86	Left Daytime Running Lamp And Position Lamp Control - Signal invalid	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B13D4-04	Right Daytime Running Lamp And Position Lamp Control - System internal failures	Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B13D4-24	Right Daytime Running Lamp And Position Lamp Control - Signal stuck high	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13D4-84	Right Daytime Running Lamp And Position Lamp Control - Signal below allowable range	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B13D4-85	Right Daytime Running Lamp And Position Lamp Control - Signal above allowable range	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B13D4-86	Right Daytime Running Lamp And Position Lamp Control - Signal invalid	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right position and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13D8-11	Right Reverse Lamp - Circuit short to ground	Right reverse lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the reverse lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right reverse lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B13D8-15	Right Reverse Lamp - Circuit short to battery or open	Right reverse lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the reverse lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the right reverse lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13DB-11	Left Reverse Lamp - Circuit short to ground	Left reverse lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the reverse lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left reverse lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B13DB-15	Left Reverse Lamp - Circuit short to battery or open	Left reverse lamp circuit short circuit to power, open circuit, high resistance or open	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the reverse lamp function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the left reverse lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13DC-11	Glove Box Release Motor 2 - Circuit short to ground	Upper glovebox latch motor circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the upper glove box release function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the upper glovebox latch motor circuit for short circuit to ground. Repair the wiring harness as necessary
B13DC-15	Glove Box Release Motor 2 - Circuit short to battery or open	Upper glovebox latch motor circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the upper glove box release function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the upper glovebox latch motor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B13FD-12	Active Exhaust Relay Control Circuit - Circuit short to battery	Active exhaust relay control circuit short circuit to power	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test, of the body control module, then check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the active exhaust relay control circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B13FD-14	Active Exhaust Relay Control Circuit - Circuit short to ground or open	Active exhaust relay control circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test, of the body control module, then check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the active exhaust relay control circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B1465-23	Glove Box Switch 2 - Signal stuck low	NOTE: This DTC may be set when the use has held the upper glove box release switch for more than 60 seconds - Upper glovebox latch switch circuit short circuit to ground - Upper glovebox latch switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the upper glove box release switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the upper glovebox latch switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the upper glovebox latch switch. Free the stuck switch or install a new upper glovebox latch switch as necessary
B146B-04	Left Front Side Marker Lamp - System internal failures	Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B146B-11	Left Front Side Marker Lamp - Circuit short to ground	Front left side marker lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front left side marker lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B146B-12	Left Front Side Marker Lamp - Circuit short to battery	Front left side marker lamp circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front left side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front left side marker lamp circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B146B-15	Left Front Side Marker Lamp - Circuit short to battery or open	Front left side marker lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front left side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the front left side marker lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B146B-23	Left Front Side Marker Lamp - Signal stuck low	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B146B-24	Left Front Side Marker Lamp - Signal stuck high	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B146B-29	Left Front Side Marker Lamp - Signal invalid	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front left side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B146C-04	Right Front Side Marker Lamp - System internal failures	Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B146C-11	Right Front Side Marker Lamp - Circuit short to ground	- Front right side marker lamp circuit short circuit to ground - Right headlamp assembly internal failure	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front right side marker lamp circuit for short circuit to ground. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B146C-12	Right Front Side Marker Lamp - Circuit short to battery	Front right side marker lamp circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front right side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the front right side marker lamp circuit for short circuit to power. Repair the wiring harness as necessary
B146C-15	Right Front Side Marker Lamp - Circuit short to battery or open	Front right side marker lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the front right side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the front right side marker lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B146C-23	Right Front Side Marker Lamp - Signal stuck low	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B146C-24	Right Front Side Marker Lamp - Signal stuck high	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B146C-29	Right Front Side Marker Lamp - Signal invalid	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the front right side marker and daytime running lamps function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B147A-12	Washer Fluid Transfer Pump Relay Control - Circuit short to battery	- Washer fluid transfer pump relay internal failure - Incorrect washer fluid transfer pump relay installed - Rear washer pump relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively check the washer fluid transfer pump function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Install a new washer fluid transfer pump relay as necessary - Refer to the electrical circuit diagrams and check the rear washer pump relay circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B147A-14	Washer Fluid Transfer Pump Relay Control - Circuit short to ground or open	- Washer fluid transfer pump relay internal failure - Incorrect washer fluid transfer pump relay installed - Rear washer pump relay circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively check the washer fluid transfer pump function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Install a new washer fluid transfer pump relay as necessary - Refer to the electrical circuit diagrams and check the rear washer pump relay circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B148E-23	Secondary Tailgate Release Switch - Signal stuck low	NOTE: This DTC can be logged if the user has held the secondary switch active for more than 60 seconds - Secondary tailgate open/close switch circuit short circuit to ground - Secondary tailgate switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the secondary tailgate switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the tailgate global open/close switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the secondary tailgate switch. Free the stuck switch or install a new lower tailgate close switch as necessary
B1491-11	Ignition Supply A - Circuit short to ground	Ignition 1 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the ignition 1 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B149B-87	Second Row Left Seat Squab Actuator - Missing message	- Left seat backrest release motor circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left seat backrest release motor LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the left seat backrest release motor function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the left seat backrest release motor circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left seat backrest release motor LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B14BA-87	Second Row Right Seat Squab Actuator - Missing message	- Right seat backrest release motor circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right seat backrest release motor LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the right seat backrest release motor function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the right seat backrest release motor circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right seat backrest release motor LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B14BB-11	Ignition Supply B - Circuit short to ground	Ignition 2 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the ignition 2 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14BC-11	Ignition Supply C - Circuit short to ground	Ignition 3 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the Ignition 3 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary
B14BD-11	Ignition Supply D - Circuit short to ground	Ignition 4 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the Ignition 4 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary
B14BE-11	Ignition Supply E - Circuit short to ground	Ignition 5 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the Ignition 5 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14BF-11	Ignition Supply F - Circuit short to ground	Ignition 6 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the Ignition 6 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary
B14C0-11	Ignition Supply G - Circuit short to ground	Ignition 7 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the Ignition 7 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary
B14C1-11	Ignition Supply H - Circuit short to ground	Ignition 8 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the Ignition 8 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14C2-11	Ignition Supply I - Circuit short to ground	Ignition 9 supply circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the Ignition 9 supply circuit(s) for short circuit to ground. Repair the wiring harness as necessary
B14C3-11	Ignition Supply J - Circuit short to ground	- Engine junction box extended ignition relay failure - Engine junction box extended ignition relay installed - Extended ignition control 2 circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new engine junction box extended ignition relay as necessary - Refer to the electrical circuit diagrams and check the extended ignition control 2 circuit(s) for short circuit to ground. Repair the wiring harness as necessary
B14C3-15	Ignition Supply J - Circuit short to battery or open	- Engine junction box extended ignition relay failure - Engine junction box extended ignition relay installed - Extended ignition control 2 circuit(s) short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Install a new engine junction box extended ignition relay as necessary - Refer to the electrical circuit diagrams and check the extended ignition control 2 circuit(s) for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14C4-11	Restraints Ignition Supply A - Circuit short to ground	Restraints ignition supply 1 circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the restraints ignition supply 1 circuit(s) for short circuit to ground. Repair the wiring harness as necessary
B14C5-11	Restraints Ignition Supply B - Circuit short to ground	Restraints ignition supply 2 circuit(s) short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the restraints ignition supply 2 circuit(s) for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14C6-11	Rear Washer Pump - Circuit short to ground	Rear washer pump circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively check the rear washer pump function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the washer pump circuit for short circuit to ground. Repair the wiring harness as necessary
B14C6-12	Rear Washer Pump - Circuit short to battery	Rear washer pump circuit short circuit to power, open circuit, high resistance	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Also check the rear washer pump function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the rear washer pump circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14C7-12	Quiescent Current Relay A On Control - Circuit short to battery	Quiescent current control module relay 1 ON circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the quiescent current control module relay 1 ON circuit for short circuit to power. Repair the wiring harness as necessary
B14C7-14	Quiescent Current Relay A On Control - Circuit short to ground or open	Quiescent current control module relay 1 ON circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the quiescent current control module relay 1 ON circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B14C8-12	Quiescent Current Relay A Off Control - Circuit short to battery	Quiescent current control module relay 1 OFF circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the quiescent current control module relay 1 OFF circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14C8-14	Quiescent Current Relay A Off Control - Circuit short to ground or open	Quiescent current control module relay 1 OFF circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the quiescent current control module relay 1 OFF circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B14C9-12	Quiescent Current Relay B On Control - Circuit short to battery	Quiescent current control module relay 2 ON circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the quiescent current control module relay 2 ON circuit for short circuit to power. Repair the wiring harness as necessary
B14C9-14	Quiescent Current Relay B On Control - Circuit short to ground or open	Quiescent current control module relay 2 ON circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the quiescent current control module relay 2 ON circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14CA-12	Quiescent Current Relay B Off Control - Circuit short to battery	Quiescent current control module relay 2 OFF circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the quiescent current control module relay 2 OFF circuit for short circuit to power. Repair the wiring harness as necessary
B14CA-14	Quiescent Current Relay B Off Control - Circuit short to ground or open	Quiescent current control module relay 2 OFF circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the quiescent current control module relay 2 OFF circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B14CB-12	Quiescent Current Relay C On Control - Circuit short to battery	Quiescent current control module relay 3 ON circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the quiescent current control module relay 3 ON circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14CB-14	Quiescent Current Relay C On Control - Circuit short to ground or open	Quiescent current control module relay 3 ON circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the quiescent current control module relay 3 ON circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B14CC-12	Quiescent Current Relay C Off Control - Circuit short to battery	Quiescent current control module relay 3 OFF circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the quiescent current control module relay 3 OFF circuit for short circuit to power. Repair the wiring harness as necessary
B14CC-14	Quiescent Current Relay C Off Control - Circuit short to ground or open	Quiescent current control module relay 3 OFF circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the quiescent current control module relay 3 OFF circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14CD-12	Quiescent Current Relay D On Control - Circuit short to battery	Quiescent current control module relay 4 ON circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the quiescent current control module relay 4 ON circuit for short circuit to power. Repair the wiring harness as necessary
B14CD-14	Quiescent Current Relay D On Control - Circuit short to ground or open	Quiescent current control module relay 4 ON circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the quiescent current control module relay 4 ON circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B14CE-12	Quiescent Current Relay D Off Control - Circuit short to battery	Quiescent current control module relay 4 OFF circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the quiescent current control module relay 4 OFF circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14CE-14	Quiescent Current Relay D Off Control - Circuit short to ground or open	Quiescent current control module relay 4 OFF circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the quiescent current control module relay 4 OFF circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B14CF-11	Trailer Reverse Light - Circuit short to ground	Trailer socket reverse light circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the trailer socket reverse lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test of the body control module with the trailer or light board disconnected, if the fault is still present refer to the electrical circuit diagrams and check the trailer socket reverse lamp circuit for a short to ground. If the fault is no longer present the fault is with the trailer/light board

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14D8-11	Left Trailer Position Lamp - Circuit short to ground	Trailer socket left tail light circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the trailer socket left tail lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test of the body control module with the trailer or light board disconnected, if the fault is still present refer to the electrical circuit diagrams and check the trailer socket left tail lamp circuit for a short to ground. If the fault is no longer present the fault is with the trailer/light board
B14DF-11	Right Trailer Position Lamp - Circuit short to ground	Trailer socket right tail light circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for at least 30 seconds and check the trailer socket right tail lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test of the body control module with the trailer or light board disconnected, if the fault is still present refer to the electrical circuit diagrams and check the trailer socket right tail lamp circuit for a short to ground. If the fault is no longer present the fault is with the trailer/light board

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A75-11	Fuel Sender No1. - Circuit short to ground	Active fuel level sensor circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the fuel level indication function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the active fuel level sensor circuit for short circuit to ground. Repair the wiring harness as necessary
B1A75-15	Fuel Sender No1 - Circuit short to battery or open	Active fuel level sensor circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the fuel level indication function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the active fuel level sensor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1A75-1C	Fuel Sender No1 - Circuit voltage out of range	Active fuel level sender unit failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the fuel level indication function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new active fuel level sender
B1A76-11	Fuel Sender No.2 - Circuit short to ground	Passive fuel level sensor circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the fuel level indication function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the passive fuel level sensor circuit for short circuit to ground. Repair the wiring harness as necessary
B1A76-15	Fuel Sender No.2 - Circuit short to battery or open	Passive fuel level sensor circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the fuel level indication function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the passive fuel level sensor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A76-1C	Fuel Sender No.2 - Circuit voltage out of range	Passive fuel level sender unit failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the fuel level indication function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new passive fuel level sender unit
B1A78-12	Front Fog Lamp - Circuit short to battery	Front fog lamp circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least 30 seconds and check the front fog lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front fog lamp circuit for short circuit to power. Repair the wiring harness as necessary
B1A78-14	Front Fog Lamp - Circuit short to ground or open	Front fog lamp circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least 30 seconds and check the front fog lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front fog lamp circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A79-11	Rear Fog Lamp - Circuit short to ground	Rear fog lamp circuit short circuit to ground	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least 30 seconds and check the rear fog lamp function then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the rear fog lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B1A79-12	Rear Fog Lamp - Circuit short to battery	Rear fog lamp circuit short circuit to power	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least 30 seconds and check the rear fog lamp function then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the rear fog lamp circuit for short circuit to power. Repair the wiring harness as necessary
B1A79-15	Rear Fog Lamp - Circuit short to battery or open	Rear fog lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least 30 seconds and check the rear fog lamp function then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the rear fog lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1A85-96	Ambient Light Sensor - Component internal failure	Rain/light sensor internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the auto lamps function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new rain/light sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A91-31	Speed/Position Sensor A - No signal	- Roof opening panel not calibrated - Roof opening panel control module internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the roof opening panel open/close function several times, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Sunroof (0x2039) - Clear the DTCs and retest if the fault persists, install a new roof opening panel control module
B1A92-31	Speed/Position Sensor B - No signal	- Roof opening panel not calibrated - Roof opening panel control module internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the roof opening panel open/close function several times, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Sunroof Calibration (2039) - Clear the DTCs and retest if the fault persists, install a new roof opening panel control module
B1B01-64	Key Transponder - Signal plausibility failure	NOTE: This DTC is only likely to occur following component replacement applications failing prior to completion Encrypted data exchange between the immobilizer antenna unit and the body control module does not match	NOTE: NOTE: To validate the repair firstly remove the battery from the Smart key and check that the vehicle can be started via the back-up start procedure (holding the Smart key next to the immobilizer antenna unit and operating the stop start switch) Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Start Authorisation Status
B1B01-81	Key Transponder - Invalid serial data received	NOTE: This DTC is only likely to occur following component replacement applications failing prior to completion Encrypted data exchange between the immobilizer antenna unit and the body control module does not match	NOTE: NOTE: To validate the repair firstly remove the battery from the Smart key and check that the vehicle can be started via the back-up start procedure (holding the Smart key next to the immobilizer antenna unit and operating the stop start switch) Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Start Authorisation Status
B1B33-51	Target ID Transfer - Not programmed	NOTE: This DTC is only likely to occur following component replacement applications failing prior to completion Immobilizer system not configured	NOTE: To validate the repair firstly run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Start Authorisation Status

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B33-81	PATS Challenge Error - Invalid serial data received	Encrypted data exchange between the powertrain control module and the body control module does not match	NOTE: To validate the repair, run the engine for a minimum of 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged in the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Start Authorisation Status
B1B56-46	Sunroof Module - Calibration/parameter memory failure	- Roof opening panel not calibrated - Roof opening panel control module internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the sunroof open/close function several times, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Sunroof Calibration (2039) - Clear the DTCs and retest if the fault persists, install a new roof opening panel control module
B1B56-87	Sunroof Module - Missing message	- Roof opening panel control module power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Roof opening panel LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the sunroof function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and test the roof opening panel control module power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and test the roof opening panel LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C32-11	Steering Column Tilt Solenoid - Circuit short to ground	Steering column tilt solenoid circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the steering column tilt solenoid circuit for short circuit to ground. Repair the wiring harness as necessary
B1C32-15	Steering Column Tilt Solenoid - Circuit short to battery or open	NOTE: This component is a serviceable item Steering column tilt solenoid circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the steering column tilt solenoid circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1C33-12	Steering Column Tilt Feedback Signal - Circuit short to battery	NOTE: This component is a serviceable item Steering column tilt sensor circuit short circuit to power	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column adjust function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the steering column tilt sensor circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C33-14	Steering Column Tilt Feedback Signal - Circuit short to ground or open	NOTE: This component is a serviceable item Steering column tilt feedback circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column adjust function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the steering column tilt feedback circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B1C34-11	Steering Column Telescope Solenoid - Circuit short to ground	NOTE: This component is a serviceable item Steering column telescope solenoid circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the steering column telescope solenoid circuit for short circuit to ground. Repair the wiring harness as necessary
B1C34-15	Steering Column Telescope Solenoid - Circuit short to battery or open	NOTE: This component is a serviceable item Steering column telescope solenoid circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the steering column adjust function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the steering column telescope solenoid circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C35-12	Steering Column Telescope Feedback Signal - Circuit short to battery	NOTE: This component is a serviceable item Steering column telescope solenoid feedback circuit short circuit to power	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column adjust function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the steering column telescope solenoid feedback circuit for short circuit to power. Repair the wiring harness as necessary
B1C35-14	Steering Column Telescope Feedback Signal - Circuit short to ground or open	NOTE: This component is a serviceable item Steering column telescope feedback signal circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column adjust function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the steering column telescope solenoid feedback circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B1C36-11	Steering Column Adjust Switch - Circuit short to ground	Steering column adjustment switch circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the steering column adjust switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the steering column adjustment switch circuit for short circuit to ground. Repair the wiring harness as necessary
B1C37-23	Master Lock Switch Stuck - Signal stuck low	NOTE: This DTC can be logged if the user has held the left/right door lock switch active for more than 60 seconds - Front left/right door central door locking lock switch circuit short circuit to ground - Front left/right door central door locking lock switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the left/right door lock switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front left/right door central door locking lock switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the front left/right door central door locking lock switch. Replace as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C38-23	Master Unlock Switch Stuck - Signal stuck low	NOTE: This DTC can be logged if the user has held the left/right door lock switch active for more than 60 seconds - Front left/right door central door locking unlock switch circuit short circuit to ground - Front left/right door central door locking unlock switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the left/right door lock switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the front left/right door central door locking unlock switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the front left/right door central door locking unlock switch. Replace as necessary
B1C43-23	Master Interior Lamp Switch Stuck - Signal stuck low	NOTE: This DTC can be logged if the user has held the interior lamp switch active for more than 60 seconds - Interior lamp switch circuit short circuit to ground - Interior lamp switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the interior light switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the interior lamp switch circuit for short circuit to ground. Repair the wiring harness as necessary - Check the operation of the interior lamp switch. Replace as necessary
B1C44-67	Rear Wiper Park Position Switch - Signal incorrect after event	- Rear wiper motor/mechanism seized/jammed - Rear wiper motor park switch circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the rear wiper function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Check that the rear wiper motor/mechanism is not jammed/seized. Repair as necessary - Refer to the electrical circuit diagrams and check the rear wiper motor park switch circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1C45-67	Front Wiper Park Position Switch Stuck - Signal incorrect after event	- Front wiper motor/mechanism seized/jammed - Front wiper park position switch circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the rear wiper function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Check that the front wiper motor/mechanism is not jammed/seized. Repair as necessary - Refer to the electrical circuit diagrams and check the front wiper motor park switch circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C55-12	Horn Relay - Circuit short to battery	▪ Horn relay internal failure ▪ Incorrect horn relay fitted ▪ Horn relay circuit short circuit to power	NOTES: ▪ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ▪ To validate the repair run the engine for at least 30 seconds and check the horn function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Install a new horn relay as necessary ▪ Refer to the electrical circuit diagrams and check the horn relay circuit for short circuit to power. Repair the wiring harness as necessary
B1C55-14	Horn Relay - Circuit short to ground or open	▪ Horn relay internal failure ▪ Incorrect horn relay fitted ▪ Horn relay circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the horn function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Install a new horn relay as necessary ▪ Refer to the electrical circuit diagrams and check the horn relay circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B1C77-12	Rear Wiper Relay - Circuit short to battery	▪ Rear wiper relay internal failure ▪ Incorrect rear wiper relay fitted ▪ Rear wiper circuit short circuit to power	NOTES: ▪ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ▪ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the rear wiper function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Install a new wiper relay as necessary ▪ Refer to the electrical circuit diagrams and check the rear wiper circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C77-14	Rear Wiper Relay - Circuit short to ground or open	▪ Rear wiper relay internal failure ▪ Incorrect rear wiper relay fitted ▪ Rear wiper circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the rear wiper function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Install a new wiper relay as necessary ▪ Refer to the electrical circuit diagrams and check the rear wiper circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B1C79-11	Front Washer Pump - Circuit short to ground	▪ Washer pump circuits short circuit to ground	NOTES: ▪ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ▪ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the front washer pump function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Refer to the electrical circuit diagrams and check the washer pump circuits for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C79-12	Front Washer Pump - Circuit short to battery	Washer pump circuits short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the front washer pump function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the washer pump circuits for short circuit to power. Repair the wiring harness as necessary
B1C82-12	Headlamp Washer Relay A - Circuit short to battery	- Left headlamp washer pump relay internal failure - Incorrect left headlamp washer pump relay installed - Left headlamp washer pump relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the left headlamp washer pump function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Replace the left headlamp washer pump relay as necessary - Refer to the electrical circuit diagrams and check the left headlamp washer pump relay circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C82-14	Headlamp Washer Relay A - Circuit short to ground or open	- Left headlamp washer pump relay internal failure - Incorrect left headlamp washer pump relay installed - Left headlamp washer pump relay circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module. Alternatively run the engine for 30 seconds and check the left headlamp washer pump function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Replace the left headlamp washer pump relay as necessary - Refer to the electrical circuit diagrams and check the left headlamp washer pump relay circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B1C84-12	Heated Rear Window Relay Output - Circuit short to battery	- Heated rear window relay internal failure - Incorrect heated rear window relay fitted - Heated rear window relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the heated rear window function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Replace the heated rear window relay as necessary - Refer to the electrical circuit diagrams and check the heated rear window relay circuit for short circuit to power. Repair the wiring harness as necessary
B1C84-14	Heated Rear Window Relay Output - Circuit short to ground or open	- Heated rear window relay internal failure - Incorrect heated rear window relay fitted - Heated rear window relay circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the heated rear window function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Replace the heated rear window relay as necessary - Refer to the electrical circuit diagrams and check the heated rear window relay circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C90-12	Auxiliary Driving Lamps Relay - Circuit short to battery	■ Auxiliary driving lamps relay internal failure ■ Incorrect auxiliary driving lamps relay fitted ■ Auxiliary driving lamps relay circuit short circuit to power	NOTES: ■ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ■ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the auxiliary driving lamps function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ■ Replace the auxiliary driving lamps relay as necessary ■ Refer to the electrical circuit diagrams and check the auxiliary driving lamps relay circuit for short circuit to power. Repair the wiring harness as necessary
B1C90-14	Auxiliary Driving Lamps Relay - Circuit short to ground or open	■ Auxiliary driving lamps relay internal failure ■ Incorrect auxiliary driving lamps relay fitted ■ Auxiliary driving lamps relay circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the auxiliary driving lamps function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ■ Replace the auxiliary driving lamps relay as necessary ■ Refer to the electrical circuit diagrams and check the auxiliary driving lamps relay circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B1C91-15	Fuel Flap/Door Lock Relay Coil Circuit - Circuit short to battery or open	■ Fuel flap release motor circuit(s) short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively check the fuel filler flap locking function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ■ Refer to the electrical circuit diagrams and check the fuel flap release motor circuit(s) for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C91-19	Fuel Flap/Door Lock Relay Coil Circuit - Circuit current above threshold	Fuel flap release motor circuit(s) short circuit to ground	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively check the fuel filler flap locking function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the fuel flap release motor circuit(s) for short circuit to ground. Repair the wiring harness as necessary
B1C96-11	Alarm LED - Circuit short to ground	Security system status indicator circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively check the security system status indicator function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the security system status indicator circuit for short circuit to ground. Repair the wiring harness as necessary
B1C98-04	Left Corner Lamp Circuit - System internal failures	Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C98-11	Left Corner Lamp Circuit - Circuit short to ground	Left side cornering lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the left hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left side cornering lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B1C98-15	Left Corner Lamp Circuit - Circuit short to battery or open	Left side cornering lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the left hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the left side cornering lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1C98-29	Left Corner Lamp Circuit - Signal invalid	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C98-84	Left Corner Lamp Circuit - Signal below allowable range	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1C98-85	Left Corner Lamp Circuit - Signal above allowable range	- Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1C99-04	Right Corner Lamp Circuit - System internal failures	Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C99-11	Right Corner Lamp Circuit - Circuit short to ground	Right side cornering lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the right hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right side cornering lamp circuit for short circuit to ground. Repair the wiring harness as necessary
B1C99-15	Right Corner Lamp Circuit - Circuit short to battery or open	Right side cornering lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the right hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the right side cornering lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1C99-29	Right Corner Lamp Circuit - Signal invalid	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly power or ground circuit open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the right hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp assembly power and ground circuits for open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1C99-84	Right Corner Lamp Circuit - Signal below allowable range	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1C99-85	Right Corner Lamp Circuit - Signal above allowable range	- Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right hand cornering lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D00-04	Left Low Beam - System internal failures	Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D00-11	Left Low Beam - Circuit short to ground	Left headlamp low beam circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the left headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp low beam circuit for short circuit to ground. Repair the wiring harness as necessary
B1D00-15	Left Low Beam - Circuit short to battery or open	Left headlamp low beam circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the left headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the left headlamp low beam circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1D00-23	Left Low Beam - Signal stuck low	- Left headlamp low beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp low beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D00-24	Left Low Beam - Signal stuck high	- Left headlamp low beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp low beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1D00-86	Left Low Beam - Signal invalid	- Left headlamp low beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp low beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1D00-92	Left Low Beam - Performance or incorrect operation	- Left headlamp low beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp low beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D01-04	Right Low Beam - System internal failures	Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D01-11	Right Low Beam - Circuit short to ground	Right headlamp low beam circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC U1000-00</u> is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the right headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp low beam circuit for short circuit to ground. Repair the wiring harness as necessary
B1D01-15	Right Low Beam - Circuit short to battery or open	Right headlamp low beam circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the right headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the right headlamp low beam circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D01-23	Right Low Beam - Signal stuck low	- Right headlamp low beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp low beam circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D01-24	Right Low Beam - Signal stuck high	- Right headlamp low beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp low beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D01-86	Right Low Beam - Signal invalid	- Right headlamp low beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp low beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D01-92	Right Low Beam - Performance or incorrect operation	- Right headlamp low beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp low beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp low beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D02-04	Left High Beam Circuit - System internal failures	Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1D02-11	Left High Beam Circuit - Circuit short to ground	Left side high beam circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the left headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left side high beam circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D02-15	Left High Beam Circuit - Circuit short to battery or open	Left headlamp high beam circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the left headlamp high beam circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1D02-23	Left High Beam Circuit - Signal stuck low	- Left headlamp high beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp high beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1D02-24	Left High Beam Circuit - Signal stuck high	- Left headlamp high beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp high beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D02-86	Left High Beam Circuit - Signal invalid	- Left headlamp high beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the left headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left headlamp high beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1D03-04	Right High Beam Circuit - System internal failures	Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D03-11	Right High Beam Circuit - Circuit short to ground	Right headlamp high beam circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the right headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp high beam circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D03-15	Right High Beam Circuit - Circuit short to battery or open	Right headlamp high beam circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the right headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the right headlamp high beam circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1D03-23	Right High Beam Circuit - Signal stuck low	- Right headlamp high beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp high beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D03-24	Right High Beam Circuit - Signal stuck high	- Right headlamp high beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp high beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D03-86	Right High Beam Circuit - Signal invalid	- Right headlamp high beam circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the right headlamp high beam function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right headlamp high beam circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D08-11	Left Trailer Direction Indicator - Circuit short to ground	Trailer left turn signal indicator circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively with the engine running check trailer left turn signal function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test of the body control module with the trailer or light board disconnected, if the fault is still present refer to the electrical circuit diagrams and check the trailer left turn signal indicator circuit for a short to ground. Repair the wiring harness as necessary. If the fault is no longer present the fault is with the trailer/light board

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D09-11	Right Trailer Direction Indicator - Circuit short to ground	Trailer right turn signal indicator circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively with the engine running check trailer right turn signal function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment perform the routine - On Demand Self Test of the body control module with the trailer or light board disconnected, if the fault is still present refer to the electrical circuit diagrams and check the trailer right turn signal indicator circuit for a short to ground. Repair the wiring harness as necessary. If the fault is no longer present the fault is with the trailer/light board
B1D13-11	Interior Lights Circuit "A" - Circuit short to ground	Interior lamps circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the interior lamps function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Lamps powered by circuit "A" (O_Interior_lighting_1), courtesy front overhead console, rear interior lamp left/right, footwell front/rear left/right, footwell ambient front/rear left/right, courtesy and ambient light front left/right, puddle front/rear left/right, treadplate front/rear left/right, illumination space finisher, load space lamp, upper tailgate lamp left/right. Not all of these lamps are fitted to all vehicles, refer to the electrical circuit diagrams - Refer to the electrical circuit diagrams and check the interior lamps circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D14-11	Interior Lights Circuit "B" - Circuit short to ground	▪ Demand interior lamp circuits short circuit to ground	NOTES: ▪ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ▪ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds and check the demand interior lamp function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Lamps powered by circuit “B” (O_Demand_interior_lighting_1), glove box, front overhead console map left/right, 2nd row dimmable cantrail lamp left/right, vanity mirror left/right, tri colour ambient B pillar uplighter left/right, footwell ambient with white LED front/rear left/right, tri colour trinket tray illumination, tri colour ambient console front/rear left/right, tri colour ambient door release/armrest/bin front/rear left/right. Not all of these lamps are fitted to all vehicles, refer to the electrical circuit diagrams ▪ Refer to the electrical circuit diagrams and check the demand interior lamp circuits for short circuit to ground. Repair the wiring harness as necessary
B1D17-67	Battery Backed Sounder - Signal incorrect after event	▪ Battery back-up sounder supply circuit short circuit to ground, short circuit to power, open circuit, high resistance ▪ Battery back-up sounder LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance ▪ Battery back-up sounder internal failure	NOTE: To validate the repair attempt to lock the vehicle with a side door ajar and listen for the error tone emitted from the battery back-up sounder, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module ▪ Refer to the electrical circuit diagrams and check the battery back-up sounder supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary ▪ Refer to the electrical circuit diagrams and check the battery back-up sounder LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new battery back-up sounder

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D17-87	Battery Backed Sounder - Missing message	▪ Battery back-up sounder supply circuit short circuit to ground, short circuit to power, open circuit, high resistance ▪ Battery back-up sounder LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair attempt to lock the vehicle with a side door ajar and listen for the error tone emitted from the battery back-up sounder, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module ▪ Refer to the electrical circuit diagrams and check the battery back-up sounder supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary ▪ Refer to the electrical circuit diagrams and check the battery back-up sounder LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1D35-23	Hazard Switch Stuck - Signal stuck low	NOTE: This DTC can be logged if the user has held the hazard switch active for more than 60 seconds ▪ Hazard warning lamp switch circuit short circuit to ground ▪ Hazard warning lamp switch stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the hazard switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Refer to the electrical circuit diagrams and check the hazard warning lamp switch circuit for short circuit to ground. Repair the wiring harness as necessary ▪ Check the operation of the hazard warning lamp switch. Replace as necessary
B1D36-11	Turn Indicator Switch - Circuit short to ground	▪ Turn signal indicator switch circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the turn indicator switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Refer to the electrical circuit diagrams and check the turn signal indicator switch circuit for short circuit to ground. Repair the wiring harness as necessary
B1D36-15	Turn Indicator Switch - Circuit short to battery or open	▪ Turn signal indicator switch circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the turn indicator switch function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module ▪ Refer to the electrical circuit diagrams and check the turn signal indicator switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D64-01	Left Headlamp Swivelling Motor - General electrical failure	- Adaptive front lighting LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the adaptive front lighting LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1D64-04	Left Headlamp Swivelling Motor - System internal failures	- Adaptive front lighting LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the adaptive front lighting LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1D64-87	Left Headlamp Swivelling Motor - Missing message	- Adaptive front lighting LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the adaptive front lighting LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D65-01	Right Headlamp Swivelling Motor - General electrical failure	- Adaptive front lighting LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the adaptive front lighting LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D65-04	Right Headlamp Swivelling Motor - System internal failures	- Adaptive front lighting LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the adaptive front lighting LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D65-87	Right Headlamp Swivelling Motor - Missing message	- Adaptive front lighting LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the adaptive front lighting LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right headlamp assembly power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D68-00	Left Headlamp Swivelling Feedback Sensor - No sub type information	- Adaptive front lighting LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Left headlamp assembly internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the adaptive front lighting LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left headlamp assembly
B1D69-00	Right Headlamp Swivelling Feedback Sensor - No sub type information	- Adaptive front lighting LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Right headlamp assembly internal failure	NOTE: To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. This DTC should no longer be logged. Alternatively run the engine for at least 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the adaptive front lighting LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right headlamp assembly
B1D97-67	Tilt Sensor - Signal incorrect after event	- Battery back-up sounder power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Battery back-up sounder LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance - Battery back-up sounder internal failure	NOTE: Validate the repair & check functionality as follows: Lock/Double Lock the vehicle via the remote key to arm the Tilt Sensor (Market dependent). Wait for at least 60 seconds and check the tilt sensor function by tilting the vehicle sufficiently with a vehicle jack mounted in the correct manner on any of the vehicle mounting points. The full alarm should sound. Then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged - Refer to the electrical circuit diagrams and check the battery back-up sounder power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the battery back-up sounder LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new battery back-up sounder

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1DAA-87	Anti-theft transceiver 'B' - Missing message	- Activity key transceiver supply circuit short circuit to ground, short circuit to power, open circuit, high resistance - Activity key transceiver LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair check the activity key locking and unlocking function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the activity key transceiver circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the activity key transceiver LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1DAF-31	Rear roof blind position sensor A - No signal	Rear roof blind not calibrated	NOTE: To validate the repair run the engine for at least 30 seconds and check the roof blind open/close function several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Rear Roof Blind (2207). Clear the DTCs and retest. If the fault persists, install a new roof blind control module
B1DB0-31	Rear roof blind position sensor B - No signal	Rear roof blind not calibrated	NOTE: To validate the repair run the engine for at least 30 seconds and check the roof blind open/close function several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Rear Roof Blind (2207). Clear the DTCs and retest. If the fault persists, install a new roof blind control module
B1DB6-46	Rear roof blind module - Calibration/parameter memory failure	Rear roof blind control module failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the roof blind open/close function several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Rear Roof Blind (2207). Clear the DTCs and retest. If the fault persists, install a new roof blind motor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1DB6-87	Rear roof blind module - Missing message	▪ Rear roof blind power supply circuit short circuit to ground, short circuit to power, open circuit, high resistance ▪ Rear roof blind LIN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the roof blind open/close function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module ▪ Refer to the electrical circuit diagrams and check the rear roof blind power supply circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary ▪ Refer to the electrical circuit diagrams and check the rear roof blind LIN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B1DB7-4B	Rear roof blind - Over temperature	▪ Rear roof blind operation restricted by debris or mechanical damage ▪ Rear roof blind mechanical failure ▪ Rear roof blind motor internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the rear roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module ▪ Check the rear roof blind for debris or damage that could cause obstruction to operation, rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ▪ Check the rear roof blind for mechanical failure, rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new rear roof blind motor
B1DB7-74	Rear roof blind - Actuator slipping	▪ Rear roof blind operation restricted by debris or mechanical damage ▪ Rear roof blind mechanical failure ▪ Rear roof blind motor internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and operate the rear roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module ▪ Check the rear roof blind for debris or damage that could cause obstruction to operation, rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ▪ Check the rear roof blind for mechanical failure, rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new rear roof blind motor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1DB7-93	Rear roof blind - No operation	Rear roof blind is not configured correctly	NOTE: To validate the repair run the engine for at least 30 seconds and operate the rear roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Rear Roof Blind. Clear the DTCs and retest. If the fault persists, install a new roof blind control module
B1DB7-9A	Rear roof blind - Component or system operating conditions	NOTE: This DTC may be set when the rear roof blind has been operated repeatedly, causing the roof blind motor to be temporarily disabled - Excessive repeated operation of the rear roof blind - Rear roof blind open/close switch stuck active	NOTE: To validate the repair run the engine for at least 30 seconds and operate the rear roof blind several times, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Clear the DTCs and check the operation of the switch and rear roof blind for correct operation, rectify as necessary. Clear the DTCs and retest - Test the operation of the rear roof blind open/close switch. Install a new rear roof blind open/close switch as necessary
B1DCF-11	Turn indication animation control - Circuit short to ground	Turn indicator animation circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and operate the turn indicator animation functions, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the turn indicator animation circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C111A-11	Right Stop Lamp - Circuit short to ground	Right side stop lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least ten seconds before checking the right stop lamp function. Then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the right side stop lamp circuit for short circuit to ground. Repair the wiring harness as necessary
C111A-15	Right Stop Lamp - Circuit short to battery or open	Right side stop lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least ten seconds before checking the right stop lamp function. Then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the right side stop lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
C111B-11	Left Stop Lamp - Circuit short to ground	Left side stop lamp circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least ten seconds before checking the left stop lamp function. Then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is no longer logged within the body control module - Refer to the electrical circuit diagrams and check the left side stop lamp circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C111B-15	Left Stop Lamp - Circuit short to battery or open	Left side stop lamp circuit short circuit to power, open circuit, high resistance	NOTE: To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least ten seconds before checking the left stop lamp function. Then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the left side stop lamp circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
C112B-12	Isolation Switch - Circuit short to battery	Deployable spoiler inhibitor relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Refer to the electrical circuit diagrams and check the deployable spoiler inhibitor relay circuit for short circuit to power. Repair the wiring harness as necessary
C112B-14	Isolation Switch - Circuit short to ground or open	Deployable spoiler inhibitor relay circuit open circuit, high resistance	NOTE: To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the deployable spoiler inhibitor relay circuit for open circuit, high resistance. Repair the wiring harness as necessary
C1A03-12	Left Front Height Sensor - Circuit short to battery	Front left height sensor signal circuit short circuit to power	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front left height sensor signal circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1A03-14	Left Front Height Sensor - Circuit short to ground or open	Front left height sensor signal circuit short circuit to ground, open circuit, high resistance	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front left height sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
C1A03-64	Left Front Height Sensor - Signal plausibility failure	Front left height sensor incorrectly installed	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Check that the front left height sensor has been installed correctly. Rectify as necessary
C1A04-12	Right Front Height Sensor - Circuit short to battery	Front right height sensor signal circuit short circuit to power	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front right height sensor signal circuit for short circuit to power. Repair the wiring harness as necessary
C1A04-14	Right Front Height Sensor - Circuit short to ground or open	Front right height sensor signal circuit short circuit to ground, open circuit, high resistance	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the front right height sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
C1A04-64	Right Front Height Sensor - Signal plausibility failure	Front right height sensor incorrectly installed	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Check that the front right height sensor has been installed correctly. Rectify as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1A05-12	Left Rear Height Sensor - Circuit short to battery	Rear left height sensor signal circuit short circuit to power	NOTE: To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Run the engine for at least ten seconds before checking height sensor operation Refer to the electrical circuit diagrams and check the rear left height sensor signal circuit for short circuit to power. Repair the wiring harness as necessary
C1A05-14	Left Rear Height Sensor - Circuit short to ground or open	Rear left height sensor signal circuit short circuit to ground, open circuit, high resistance	NOTE: To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Run the engine for at least ten seconds before checking height sensor operation Refer to the electrical circuit diagrams and check the rear left height sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
C1A05-64	Left Rear Height Sensor - Signal plausibility failure	Rear left height sensor incorrectly installed	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Check that the rear left height sensor has been installed correctly. Rectify as necessary
C1A06-12	Right Rear Height Sensor - Circuit short to battery	Rear right height sensor signal circuit short circuit to power	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the rear right height sensor signal circuit for short circuit to power. Repair the wiring harness as necessary
C1A06-14	Right Rear Height Sensor - Circuit short to ground or open	Rear right height sensor signal circuit short circuit to ground, open circuit, high resistance	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Refer to the electrical circuit diagrams and check the rear right height sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1A06-64	Right Rear Height Sensor - Signal plausibility failure	Rear right height sensor incorrectly installed	NOTE: To validate repair run the engine for at least ten seconds, then using the Jaguar Land Rover approved diagnostic equipment to check this DTC is no longer logged within the body control module Check that the rear right height sensor has been installed correctly. Rectify as necessary
C2004-12	Headlamp washer relay B - Circuit short to battery	- Right hand headlamp washer jet relay failure - Incorrect right hand headlamp washer jet relay installed - Right headlamp washer jet relay circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively check headlamp washer function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is not logged within the body control module - Replace the right headlamp washer pump relay as necessary - Refer to the electrical circuit diagrams and test the right headlamp washer jet relay circuit for short circuit to power. Repair the wiring harness as necessary
C2004-14	Headlamp Washer Relay B - Circuit short to ground or open	- Right hand headlamp washer jet relay failure - Incorrect right hand headlamp washer jet relay installed - Right hand headlamp washer jet relay circuits short circuit to ground or open circuit	NOTE: To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively check headlamp washer function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is not logged within the body control module - Replace the right headlamp washer pump relay as necessary - Refer to the electrical circuit diagrams and check the right hand headlamp washer jet relay circuits for short circuit to ground or open circuit. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
P0230-12	Fuel Pump Primary Circuit - Circuit short to battery	- Fuel pump relay failure - Incorrect fuel pump relay installed - Fuel pump control circuit short circuit to power	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module - Replace the fuel pump relay as necessary - Refer to the electrical circuit diagrams and check the fuel pump control circuit for short circuit to power. Repair the wiring harness as necessary
P0928-11	Gear Shift Lock Solenoid/Actuator Circuit A/Open - Circuit short to ground	Reverse gear inhibitor circuit short circuit to ground	NOTE: To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the reverse gear inhibitor circuit for short circuit to ground. Repair the wiring harness as necessary
P0928-15	Gear Shift Lock Solenoid/Actuator Circuit A/Open - Circuit short to battery or open	Reverse gear inhibitor circuit short circuit to power, open circuit, high resistance	NOTE: To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module Refer to the electrical circuit diagrams and check the reverse gear inhibitor circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U0001-81	High speed CAN communication bus - Invalid serial data received	Invalid data received from another control module via the high speed CAN bus (chassis)	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, check the snap shot data to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index - Using the Jaguar Land Rover approved diagnostic equipment, complete a CAN network integrity test. Refer to the electrical circuit diagrams and check the CAN network. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0001-87	High Speed CAN Communication Bus - Missing message	Invalid data received from another control module via the high speed CAN bus (powertrain)	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, check the snap shot data to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index - Using the Jaguar Land Rover approved diagnostic equipment, complete a CAN network integrity test. Refer to the electrical circuit diagrams and check the CAN network. Repair the wiring harness as necessary
U0001-88	High Speed CAN Communication Bus - Bus off	High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U0010-88	Medium Speed CAN Communication Bus - Bus off	Medium speed CAN bus (body) circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the medium speed CAN bus (body) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0011-87	Medium Speed CAN Communication Bus Performance - Missing message	Invalid data received from another control module via the medium speed CAN bus (body)	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index - Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the medium speed CAN bus (body) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U0300-00	Internal Control Module Software Incompatibility - No sub type information	- Body control module is not configured correctly - Gateway module is not configured correctly - Gateway module power supply circuit short circuit to power, short circuit to ground, open circuit or high resistance	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, re-configure the body control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, re-configure the gateway module with the latest level software - Refer to the electrical circuit diagrams and check the gateway module power supply circuit for short circuit to power, short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the circuits for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U1000-00	Solid State Driver Protection Active - Driver Disabled - No sub type information	NOTE: This DTC is set when one or more short circuits have been detected. The relevant output circuits have been disabled to protect the body control module from permanent damage Body control module output circuit short circuit to ground, short circuit to power	NOTE: To validate the repair run the engine and check the function of the previously non-functional equipment, for at least 30 seconds (where possible), then use the Jaguar Land Rover approved diagnostic equipment to check that the DTCs are no longer logged Using the Jaguar Land Rover approved diagnostic equipment, check for other short circuit to ground/power related DTCs and perform the relevant corrective actions. To re-enable the output circuits, using the Jaguar Land Rover approved diagnostic equipment, perform the routine – Ignition cycle counter reset (205E). The routine can be located on the diagnostic equipment within “BCM - ECU functions”

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U200E-11	Control Module Output Power B - Circuit short to ground	▪ Rear junction box extended ignition control 1 relay failure ▪ Incorrect rear junction box extended ignition control 1 relay installed ▪ Rear junction box extended ignition control 1 relay circuit short circuit to ground	NOTES: ▪ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ▪ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module ▪ Replace the rear junction box extended ignition control 1 relay as necessary ▪ Refer to the electrical circuit diagrams and check the rear junction box extended ignition control 1 relay circuit for short circuit to ground. Repair the wiring harness or install a new extended ignition control 1 relay as necessary
U200E-12	Control Module Output Power B - Circuit short to battery	▪ Rear junction box extended ignition control 1 relay failure ▪ Incorrect rear junction box extended ignition control 1 relay installed ▪ Rear junction box extended ignition control 1 relay circuit short circuit to power, open circuit	NOTES: ▪ After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method ▪ To validate the repair use the Jaguar Land Rover approved diagnostic equipment to perform the routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged within the body control module ▪ Replace the rear junction box extended ignition control 1 relay as necessary ▪ Refer to the electrical circuit diagrams and check the rear junction box extended ignition control 1 relay circuit for short circuit to power, open circuit. Repair the wiring harness or install a new extended ignition control 1 relay as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2010-11	Switch Illumination - Circuit short to ground	Switch illumination circuit short circuit to ground	NOTES: - After ensuring any faults have been repaired, inspect if <u>DTC</u> U1000-00 is stored in the <u>BCM</u>. If yes, using the Jaguar Land Rover approved diagnostic equipment, run the application 'Body systems - Ignition cycle counter reset' from the 'Highly recommended' section. The application re-enables the output and allows successful validation of the repair using the recommended method - To validate repair use the Jaguar Land Rover approved diagnostic equipment perform routine - On Demand Self Test. If the repair is successful this DTC will no longer be logged. Alternatively run the engine for at least 30 seconds and check the switch illumination function, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC is not logged - Refer to electrical circuit diagrams and check the switch illumination circuit for short circuit to ground. Repair the wiring harness as necessary
U201A-51	Control Module Main Calibration Data - Not programmed	Body control module is not configured correctly	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, re-configure the body control module with the latest level software
U201B-54	Control Module Calibration Data #2 - Missing calibration	Steering column calibration data not stored	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Steering Column
U2104-11	Trip Meter Reset Button - Circuit short to ground	Steering column left multifunction switch (trip switch) circuit short circuit to ground	NOTE: To validate the repair run the engine for at least 30 seconds and check the trip computer switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the steering column left multifunction switch (trip switch) circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2104-15	Trip Meter Reset Button - Circuit short to battery or open	Steering column left multifunction switch (trip switch) circuit short circuit to power, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds and check the trip computer switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the steering column left multifunction switch (trip switch) circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U2104-1C	Trip Meter Reset Button - Circuit voltage out of range	- Steering column left multifunction switch (trip switch) circuit short circuit to power, open circuit, high resistance - Steering column left multifunction switch (trip switch) internal failure	NOTE: To validate the repair run the engine for at least 30 seconds and check the trip computer switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Refer to the electrical circuit diagrams and check the steering column left multifunction switch (trip switch) circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary - Replace steering column left multifunction switch (trip switch) as necessary
U2104-23	Trip Meter Reset Button - Signal stuck low	NOTE: This DTC can be logged if the user has held the steering column left multifunction switch (trip switch) active for more than 60 seconds Steering column left multifunction switch (trip switch) stuck active	NOTE: To validate the repair run the engine for at least 120 seconds and check the trip computer switch function, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Check the operation of the steering column left multifunction switch (trip switch). Rectify as necessary
U2300-41	Central Configuration - General checksum failure	Car configuration file mismatch with vehicle specification	NOTE: To validate the repair run the engine for at least 120 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest
U2300-51	Central Configuration - Not programmed	Car configuration file mismatch with vehicle specification	NOTE: To validate the repair run the engine for at least 120 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2300-54	Central Configuration - Missing calibration	- Body control module is not configured correctly - Car configuration file mismatch with vehicle specification	NOTE: To validate the repair run the engine for at least 120 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, re-configure the body control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file within the body control module and gateway module as necessary
U2300-55	Central Configuration - Not configured	- Body control module is not configured correctly - Car configuration file mismatch with vehicle specification	NOTE: To validate the repair run the engine for at least 120 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, re-configure the body control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file within the body control module and gateway module as necessary
U2300-56	Central Configuration - Invalid/incomplete configuration	- Body control module is not configured correctly - Car configuration file mismatch with vehicle specification	NOTE: To validate the repair run the engine for at least 120 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module - Using the Jaguar Land Rover approved diagnostic equipment, re-configure the body control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file within the body control module and gateway module as necessary
U2300-62	Central Configuration - Signal compare failure	Car configuration file mismatch with vehicle specification	NOTE: To validate the repair run the engine for at least 120 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file within the body control module and gateway module as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U3000-49	Control Module - Internal electronic failure	NOTE: This DTC is set when one or more short circuits have been detected. The relevant output circuits have been disabled permanently Body control module internal failure due to an output circuit short circuit to ground, short circuit to power	NOTE: To validate the repair run the engine for 30 seconds, then use the Jaguar Land Rover approved diagnostic equipment to check this DTC and all other DTCs related to short circuit faults no longer logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, check for other short circuit to ground/power related DTCs and perform the relevant corrective actions. Once all other short circuit to ground/power related DTCs have been rectified perform the validation checks. If the fault persists, install a new body control module as necessary
U3001-54	Control Module Improper Shutdown - Missing calibration	Steering column calibration data not stored	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Calibrate Steering Column (0x203E)
U3006-13	Control module input power "A" - Circuit open	NOTE: Circuit Reference - VBATT_1 Body control module power supply circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the body control module power supply circuit for open circuit, high resistance. Repair the wiring harness as necessary
U3007-13	Control module input power "B" - Circuit open	NOTE: Circuit Reference - VBATT_2 Body control module power supply circuit short circuit to ground, open circuit, high resistance	NOTE: To validate the repair run the engine for at least 30 seconds, then using the Jaguar Land Rover approved diagnostic equipment check that this DTC is not logged within the body control module Refer to the electrical circuit diagrams and check the body control module power supply circuit for open circuit, high resistance. Repair the wiring harness as necessary