

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC:
FOLDING TOP CONTROL MODULE (LEFT/RIGHT)

[G2006791]

DESCRIPTION AND OPERATION

FOLDING TOP CONTROL MODULE - LEFT/RIGHT [FTCM/FTCMB]

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault and may also cause additional faults in the vehicle being tested and/or the donor vehicle

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If the control module or a component is not to specification and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval program is in operation, prior to the installation of a new module/component
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the Jaguar Land Rover approved diagnostic equipment)
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals
- Where an 'on demand self-test' is referred to, this can be accessed through the 'diagnostic trouble code monitor' tab on the manufacturers approved diagnostic system
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMS which may be valid for the specific customer complaint and complete the recommendations as required.

The table below lists all diagnostic trouble codes (DTCs) that could be set in the folding top control module, for additional diagnosis and testing information refer to the relevant diagnosis and testing section. For additional information, refer to: [Folding Top](#) (501-18 Folding Top, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1079-24	Hood Up Switch - Signal stuck high	- Folding top deploy switch stuck - Folding top deploy switch circuit short circuit to ground - Switch failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD90F) and check the switch status - Normal functionality - Switch status is inactive and becomes active when pressed - Fault - A permanent active status indicates that the switch is stuck in an open condition. Error/not available indicates that there is a problem with the circuit or switch - Check the switch operation and make sure the switch is not stuck in one position. If the switch appears to be operating correctly but not functioning, move onto the next step. If the switch is physically faulty, install a new folding top switchpack - Refer to the electrical circuit diagrams and check the folding top deploy switch circuit between the folding top switchpack and the left folding top control module for short circuit to ground. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top switchpack
B107A-24	Hood Down Switch - Signal stuck high	- Folding top stow switch stuck - Folding top stow switch circuit short circuit to ground - Switch failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD90F) and check the switch status - Normal functionality - Switch status is inactive and becomes active when pressed - Fault - A permanent active status indicates that the switch is stuck in a close condition. Error/not available indicates that there is a problem with the circuit or switch - Check the switch operation and make sure the switch is not stuck in one position. If the switch appears to be operating correctly but not functioning, move onto the next step. If the switch is physically faulty, install a new folding top switchpack - Refer to the electrical circuit diagrams and check the folding top stow switch circuit between the folding top switchpack and the right folding top control module for short circuit to ground. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top switchpack
B143C-00	Roof Package Down Lock Motor - No sub type information	- Folding top mechanism restricted movement - Right folding top control module rear folding top latch motor circuit short circuit to ground, short circuit to power, short circuit to each other - Rear folding top latch motor failure	- Inspect the rear folding top latch motor for any visual damage or mechanical blockages, rectify as necessary - Refer to the electrical circuit diagrams and check the rear folding top latch motor circuit(s) between the rear folding top latch motor and the right folding top control module for short circuit to ground, short circuit to power and short circuit to each other. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new rear folding top latch motor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B143C-11	Roof Package Down Lock Motor - Circuit short to ground	- Folding top mechanism restricted movement - Right folding top control module rear folding top latch motor circuit short circuit to ground - Rear folding top latch motor failure	- Inspect the rear folding top latch motor for any visual damage or mechanical blockages, rectify as necessary - Refer to the electrical circuit diagrams and check the rear folding top latch motor circuit(s) between the rear folding top latch motor and the right folding top control module for short circuit to ground. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new rear folding top latch motor
B143C-12	Roof Package Down Lock Motor - Circuit short to battery	- Folding top mechanism restricted movement - Right folding top control module rear folding top latch motor circuit short circuit to power - Rear folding top latch motor failure	- Inspect the rear folding top latch motor for any visual damage or mechanical blockages, rectify as necessary - Refer to the electrical circuit diagrams and check the rear folding top latch motor circuit(s) between the rear folding top latch motor and the right folding top control module for short circuit to power. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new rear folding top latch motor
B143C-13	Roof Package Down Lock Motor - Circuit open	- Folding top mechanism restricted movement - Right folding top control module rear folding top latch motor circuit open circuit, high resistance - Rear folding top latch motor failure	- Inspect the rear folding top latch motor for any visual damage or mechanical blockages, rectify as necessary - Refer to the electrical circuit diagrams and check the rear folding top latch motor circuit(s) between the rear folding top latch motor and the right folding top control module for open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new rear folding top latch motor
B143C-49	Roof Package Down Lock Motor - Internal electronic failure	- Right folding top control module rear folding top latch motor failure - Rear folding top latch motor failure	- Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest the folding top for a maximum of 6 full operations - If the fault persists, install a new rear folding top latch motor
B143C-98	Roof Package Down Lock Motor - Component or system over temperature	NOTE: Repeated usage without rest can cause the rear folding top latch motor to overheat - Consecutive folding/unfolding operation can cause over temperature conditions - Rear folding top latch motor over temperature - Temperature sensor defective or not calibrated - Folding top not correctly aligned - Rear folding top latch motor failure	NOTE: This DTC may set due to a design feature for shut down protection after more than 6 operations, dependant on ambient temperatures - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and inspect the folding top for smooth operation. Check for any obstructions or mechanical problems that can cause the motors to overheat and rectify as necessary - If the motors are overheated allow a minimum of 30 minutes for the mechanism to cool down. Check and monitor the system for recurrence without exceeding 6 consecutive operations - If the fault persists in less than 6 consecutive operations from an initially cold motor, install a new rear folding top latch motor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1442-00	Front Latch Motor - No sub type information	- Folding top mechanism restricted movement - Left folding top control module front folding top latch motor circuit short circuit to ground, short circuit to power, short circuit to each other - Front folding top latch motor failure	- Inspect the left folding top latch motor for any visual damage or mechanical blockages, rectify as necessary - Refer to the electrical circuit diagrams and check the front folding top latch motor circuit(s) between the front folding top latch motor and the left folding top control module for short circuit to ground, short circuit to power, short circuit to each other. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new front folding top latch motor
B1442-11	Front Latch Motor - Circuit short to ground	- Folding top mechanism restricted movement - Left folding top control module front folding top latch motor circuit short circuit to ground - Front folding top latch motor failure	- Inspect the left folding top latch motor for any visual damage or mechanical blockages, rectify as necessary - Refer to the electrical circuit diagrams and check the front folding top latch motor circuit(s) between the front folding top latch motor and the left folding top control module for short circuit to ground. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new front folding top latch motor
B1442-12	Front Latch Motor - Circuit short to battery	- Folding top mechanism restricted movement - Left folding top control module front folding top latch motor circuit short circuit to power - Front folding top latch motor failure	- Inspect the left folding top latch motor for any visual damage or mechanical blockages, rectify as necessary - Refer to the electrical circuit diagrams and check the front folding top latch motor circuit(s) between the front folding top latch motor and the left folding top control module for short circuit to power. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new front folding top latch motor
B1442-13	Front Latch Motor - Circuit open	- Folding top mechanism restricted movement - Left folding top control module front folding top latch motor circuit open circuit, high resistance - Front folding top latch motor failure	- Inspect the left folding top latch motor for any visual damage or mechanical blockages, rectify as necessary - Refer to the electrical circuit diagrams and check the front folding top latch motor circuit(s) between the front folding top latch motor and the left folding top control module for open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new front folding top latch motor
B1442-49	Front Latch Motor - Internal electronic failure	- Left folding top control module front folding top latch motor relay failure - Front folding top latch motor failure	- Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest the folding top for a maximum of 6 full operations - If the fault persists, install a new front folding top latch motor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1442-98	Front Latch Motor - Component or system over temperature	NOTE: Repeated usage without rest can cause the front folding top latch motor to overheat - Consecutive folding/unfolding operation can cause over temperature conditions - Front folding top latch motor over temperature - Temperature sensor defective or not calibrated - Folding top not correctly aligned - Front folding top latch motor failure	NOTE: This DTC may set due to a design feature for shut down protection after more than 6 operations, dependant on ambient temperatures - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and inspect the folding top for smooth operation. Inspect for any obstructions or mechanical problems that can cause the motors to overheat and rectify as necessary - If the motors are overheated allow a minimum of 30 minutes for the mechanism to cool down. Check and monitor the system for recurrence without exceeding 6 consecutive operations - If the fault persists in less than 6 consecutive operations from an initially cold motor, install a new front folding top latch motor
B1449-12	Foldable Top Open Sensor - Circuit short to battery	- Folding top open sensor circuit short circuit to power - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top open sensor circuit between the folding top open sensor and the left folding top control module for short circuit to power. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top open sensor
B1449-14	Foldable Top Open Sensor - Circuit short to ground or open	- Folding top open sensor circuit short circuit to ground, open circuit, high resistance - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top open sensor circuit between the folding top open sensor and the left folding top control module for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top open sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1449-29	Foldable Top Open Sensor - Signal invalid	- Folding top open sensor circuit short circuit to ground, short circuit to power, open circuit, high resistance - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top open sensor circuit between the folding top open sensor and the left folding top control module for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top open sensor
B144A-12	Foldable Top Closed Sensor - Circuit short to battery	- Folding top closed sensor circuit short circuit to power - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top closed sensor circuit between the folding top closed sensor and the right folding top control module for short circuit to power. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top closed sensor
B144A-14	Foldable Top Closed Sensor - Circuit short to ground or open	- Folding top closed sensor circuit short circuit to ground, open circuit, high resistance - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top closed sensor circuit between the folding top closed sensor and the right folding top control module for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top closed sensor
B144A-29	Foldable Top Closed Sensor - Signal invalid	- Folding top closed sensor circuit short circuit to ground, short circuit to power, open circuit, high resistance - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top closed sensor circuit between the folding top closed sensor and the right folding top control module for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top closed sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B144E-12	Wind Frame Striker Engaged Sensor - Circuit short to battery	- Folding top front latch engaged sensor circuit short circuit to power - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top front latch engaged sensor circuit between the folding top front latch engaged sensor and the left folding top control module for short circuit to power. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top front latch engaged sensor
B144E-14	Wind Frame Striker Engaged Sensor - Circuit short to ground or open	- Folding top front latch engaged sensor circuit short circuit to ground, open circuit, high resistance - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top front latch engaged sensor circuit between the folding top front latch engaged sensor and the left folding top control module for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top front latch engaged sensor
B144E-29	Wind Frame Striker Engaged Sensor - Signal invalid	- Folding top front latch engaged sensor circuit short circuit to ground, short circuit to power, open circuit, high resistance - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top front latch engaged sensor circuit between the folding top front latch engaged sensor and the left folding top control module for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top front latch engaged sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1452-12	Roof Package Down Lock Enable Sensor - Circuit short to battery	- Folding top rear latch engaged sensor circuit short circuit to power - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top rear latch engaged sensor circuit between the folding top rear latch engaged sensor and the right folding top control module for short circuit to power. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top rear latch engaged sensor
B1452-14	Roof Package Down Lock Enable Sensor - Circuit short to ground or open	- Folding top rear latch engaged sensor circuit short circuit to ground, open circuit, high resistance - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top rear latch engaged sensor circuit between the folding top rear latch engaged sensor and the right folding top control module for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top rear latch engaged sensor
B1452-29	Roof Package Down Lock Enable Sensor - Signal invalid	- Folding top rear latch engaged sensor circuit short circuit to ground, short circuit to power, open circuit, high resistance - Sensor failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD905) and check the sensor status - Normal functionality - State is inactive/active depending on the position of the roof - Fault - Error/not available indicates that there is a problem with the circuit or sensor - Refer to the electrical circuit diagrams and check the folding top rear latch engaged sensor circuit between the folding top rear latch engaged sensor and the right folding top control module for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top rear latch engaged sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1453-1C	Sensor/Switch 12 Volt Supply - Circuit voltage out of range	NOTE: Circuit reference - HALL+/K-LINE CODING POS/SP_FT_O - Folding top front and rear latch engaged sensors/folding top open and closed sensors supply circuit voltage too low - Sensor failure	NOTE: This DTC can be set by either the left or right folding top control module - Refer to the electrical circuit diagrams and check the folding top front and rear latch engaged sensor circuits and the folding top open and closed sensor circuits for correct battery supply voltage or short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install new sensor(s) as necessary
B1A84-51	Car Configuration Data - Not programed	Car configuration file not programed	- Using the Jaguar Land Rover approved diagnostic equipment check and update the car configuration file. Clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the folding top control module and the body control module with the latest level software
U0001-87	High Speed CAN Communication Bus - Missing Message	Left side folding top control module has lost CAN communication with right side folding top control module	- Refer to the electrical circuit diagrams and check the power and ground connections to the module. Repair the wiring harness as necessary, clear the DTCs and retest - Refer to the electrical circuit diagrams and check the CAN network between the left side folding top control module and the right side folding top control module. Repair the wiring harness as necessary, clear the DTCs and retest - Check the right side folding top control module for related DTCs and refer to the relevant DTC index
U0001-88	High Speed CAN Communication Bus - Bus Off	High speed CAN bus failure	NOTE: This DTC can be set by either the left or right folding top control module Refer to the electrical circuit diagrams and check the left and right side folding top control module high speed CAN bus for short circuit to ground, short circuit to power, open circuit, high resistance, or short circuit between the paired CAN wires. Repair the wiring harness as necessary, clear the DTCs and retest
U0121-00	Lost Communication With Anti-Lock Brake System (ABS) Control Module - No sub type information	Left side folding top control module has lost CAN communication with the ABS control module	- Refer to the electrical circuit diagrams and check the power and ground connections to the module. Repair the wiring harness as necessary, clear the DTCs and retest - Refer to the electrical circuit diagrams and check the CAN network between the left side folding top control module and the ABS control module. Repair the wiring harness as necessary, clear the DTCs and retest - Check the ABS control module for related DTCs and refer to the relevant DTC index

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0146-00	Lost Communication With Gateway "A" - No sub type information	Left side folding top control module has lost CAN communication with the gateway module	- Refer to the electrical circuit diagrams and check the power and ground connections to the module. Repair the wiring harness as necessary, clear the DTCs and retest - Refer to the electrical circuit diagrams and check the CAN network between the left side folding top control module and the gateway module. Repair the wiring harness as necessary, clear the DTCs and retest - Check the gateway module for related DTCs and refer to the relevant DTC index
U0206-00	Lost Communication With Folding Top Control Module - No sub type information	Right side folding top control module has lost CAN communication with the left side folding top control module	- Refer to the electrical circuit diagrams and check the power and ground connections to the module. Repair the wiring harness as necessary, clear the DTCs and retest - Refer to the electrical circuit diagrams and check the CAN network between the right side folding top control module and the left side folding top control module. Repair the wiring harness as necessary, clear the DTCs and retest - Check the left side folding top control module for related DTCs and refer to the relevant DTC index
U0300-00	Internal Control Module Software Incompatibility - No sub type information	CAN configuration error	- Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If fault persists, reconfigure the folding top control module with the latest level software using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest - If the software levels are already correct, or if the fault persists, install a new folding top control module
U1A14-49	CAN Initialization Failure - Internal electronic failure	Folding top control module failure	NOTE: This DTC can be set by either the left or right folding top control module - Complete a battery reset by disconnecting the main battery terminals for a minimum of 1 minute to allow the folding top control module to power down - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new folding top control module
U2011-49	Motor - Internal electronic failure	Folding top motor/control module failure	NOTE: This DTC can be set by either the left or right folding top control module - Complete a battery reset by disconnecting the main battery terminals for a minimum of 1 minute to allow the folding top control module to power down - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new folding top control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2011-64	Motor - Signal plausibility failure	Folding top motor/control module failure	NOTE: This DTC can be set by either the left or right folding top control module - Complete a battery reset by disconnecting the main battery terminals for a minimum of 1 minute to allow the folding top control module to power down - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new folding top control module
U2011-97	Motor - Component or system operation obstructed or blocked	- Folding top movement obstructed or restricted - Folding top not correctly aligned - Folding top motor/control module failure	NOTE: This DTC can be set by either the left or right folding top control module - Inspect the folding top for smooth operation, for any obstructions or mechanical problem that would impede deploy/stow movement. Rectify as necessary. Clear the DTCs and retest - If fault persists, install a new front folding top control module
U2011-98	Motor - Component or system over temperature	NOTE: Repeated usage without rest can cause the folding top motors to overheat - Consecutive folding/unfolding operation can cause over temperature conditions - Folding top motor over temperature - Temperature sensor defective or not calibrated - Folding top not correctly aligned - Folding top motor/control module failure	NOTES: - This DTC may set due to a design feature for shut down protection after more than 6 operations, dependant on ambient temperatures - This DTC can be set by either the left or right folding top control module - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and inspect the folding top for smooth operation. Inspect for any obstructions or mechanical problems that can cause the motors to overheat - If the motors are overheated allow a minimum of 30 minutes for the mechanism to cool down. Check and monitor the system for recurrence without exceeding 6 consecutive operations - If fault persists in less than 6 consecutive operations from an initially cold motor, install a new folding top control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2013-64	Switch Pack - Signal plausibility failure	- Folding top deploy switch stuck - Folding top deploy switch circuit short circuit to ground - Switch failure	- Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD90F) and check the switch status - Normal functionality - Switch status is inactive and becomes active when pressed - Fault - A permanent active status indicates that the switch is stuck with a plausibility failure. Error/not available indicates that there is a problem with the circuit or switch - Check the switch operation and make sure the switch is not stuck in one position. If the switch appears to be operating correctly but not functioning, move onto the next step. If the switch is physically faulty, install a new folding top switchpack - Refer to the electrical circuit diagrams and check the folding top deploy switch circuit between the folding top switchpack and the left folding top control module for short circuit to ground. Repair the wiring harness as necessary, clear the DTCs and retest - If the fault persists, install a new folding top switchpack
U3000-44	Control Module - Data memory failure	Folding top control module failure	NOTE: This DTC can be set by either the left or right folding top control module - Complete a battery reset by disconnecting the main battery terminals for a minimum of 1 minute to allow the folding top control module to power down - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If fault persists, install a new folding top control module
U3000-45	Control Module - Program memory failure	Folding top control module failure	NOTE: This DTC can be set by either the left or right folding top control module - Complete a battery reset by disconnecting the main battery terminals for a minimum of 1 minute to allow the folding top control module to power down - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If fault persists, install a new folding top control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U3000-46	Control Module - Calibration/parameter memory failure	- Folding top control module configuration incorrect - Folding top control module failure	NOTE: This DTC can be set by either the left or right folding top control module - Complete a battery reset by disconnecting the main battery terminals for a minimum of 1 minute to allow the folding top control module to power down - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If fault persists, configure the folding top control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest - If fault persists, install a new folding top control module
U3003-16	Battery Voltage - Circuit voltage below threshold	Circuit voltage < 9 volts threshold	NOTE: This DTC can be set by either the left or right folding top control module - Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD901) and check the voltage status - Normal operation - Normal1/Normal2/Normal3 (9 - 16 volts) - Failure circuit voltage - Low/Invalid indicates a fault (< 9 volts) - Refer to relevant section of workshop manual and battery care manual. Check battery state of charge and starting/charging system performance
U3003-17	Battery Voltage - Circuit voltage above threshold	Circuit voltage > 16 volts threshold	NOTE: This DTC can be set by either the left or right folding top control module - Using the Jaguar Land Rover approved diagnostic equipment, view live data (0xD901) and check the voltage status - Normal operation - Normal1/Normal2/Normal3 (9 - 16 volts) - Failure circuit voltage - High/Invalid indicates a fault (> 16 volts) - Refer to relevant section of workshop manual and battery care manual. Check battery state of charge and starting/charging system performance