

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC:
LUGGAGE COMPARTMENT LID CONTROL
MODULE (LCLCM) [G2006794]

DESCRIPTION AND OPERATION

LUGGAGE COMPARTMENT LID CONTROL MODULE (LCLCM)

CAUTIONS:

- Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle
- The vehicle latches are non-serviceable. Lubrication must not be sprayed into or around the door, hood, fuel flap or tailgate latches. Care should be taken when washing the vehicle to not spray water at or into the latches

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If the control module or a component is not to specification and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval program is in operation, prior to the installation of a new module/component
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system)
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always inspect for loose connections and corroded terminals
- Where an 'on demand self-test' is referred to, this can be accessed through the 'diagnostic trouble code monitor' tab on the manufacturers approved diagnostic system
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and complete the recommendations as required.

The table below lists all diagnostic trouble codes (DTCs) that could be set in the luggage compartment lid control module (LCLCM), for additional Diagnosis and Testing information refer to the relevant Diagnosis and Testing Section. For additional information, refer to: [Locks, Latches and Entry Systems](#) (501-14 Handles, Locks, Latches and Entry Systems, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1161-15	Left Rear Anti-Pinch Sensor - Circuit short to battery or open	NOTE: Circuit reference - UPPER ATB LHS - Luggage compartment lid movement restricted - Left side luggage compartment lid anti-trap sensor circuit short circuit to power, open circuit, high resistance - Left side luggage compartment lid anti-trap sensor failure - Luggage compartment lid control module failure	- Inspect the luggage compartment lid for mechanical blockages. Rectify fault - Refer to the electrical circuit diagrams and check both the power and ground circuits to the left side luggage compartment lid anti-trap sensor for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new left side luggage compartment lid anti-trap sensor. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
B1162-15	Right Rear Anti-Pinch Sensor - Circuit short to battery or open	NOTE: Circuit reference - UPPER ATB RHS - Luggage compartment lid movement restricted - Right side luggage compartment lid anti-trap sensor circuit short circuit to power, open circuit, high resistance - Right side luggage compartment lid anti-trap sensor failure - Luggage compartment lid control module failure	- Inspect the luggage compartment lid for mechanical blockages. Rectify fault - Refer to the electrical circuit diagrams and check both the power and ground circuits to the right side luggage compartment lid anti-trap sensor for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new right side luggage compartment lid anti-trap sensor. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
B1185-15	Trunk Anti-Pinch Sensor - Circuit short to battery or open	NOTE: This DTC will not log on X152 - Luggage compartment lid movement restricted - Luggage compartment lid anti-trap sensor circuit short circuit to power, open circuit, high resistance - Luggage compartment lid anti-trap sensor failure - Luggage compartment lid control module failure	- Inspect the luggage compartment lid for mechanical blockages. Rectify fault - Refer to the electrical circuit diagrams and check both the power and ground circuits to the luggage compartment lid anti-trap sensor for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid anti-trap sensor. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
B11C4-23	Boot/Trunk Close Button - Signal stuck low	NOTE: Circuit reference - TAILGATE CLOSE - Luggage compartment lid close switch circuit short circuit to ground - Luggage compartment lid close switch stuck active - Luggage compartment lid control module failure	- Refer to the electrical circuit diagrams and check the luggage compartment lid close switch circuit for short circuit to ground. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, test the operation of the luggage compartment lid close switch. Install a new luggage compartment lid close switch if required. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1316-02	Boot/Trunk Latch Power Close Unit - General signal failure	NOTE: Circuit reference - UPPER CINCH HOME POS SW ■ Luggage compartment lid latch not closed fully ■ Luggage compartment lid soft close actuator signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Luggage compartment lid soft close actuator failure ■ Luggage compartment lid control module failure	■ Inspect the luggage compartment lid for mechanical blockages. Rectify fault ■ Refer to the electrical circuit diagrams and check the luggage compartment lid soft close actuator signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest ■ If fault persists, install a new luggage compartment lid soft close actuator. Clear the DTCs and retest ■ If fault persists, install a new luggage compartment lid control module
B1316-93	Boot/Trunk Latch Power Close Unit - No operation	NOTE: Circuit reference - UPPER CINCH STRIKE MOTOR+ / UPPER CINCH STRIKE MOTOR- / UPPER CINCH HOME POS SW ■ Luggage compartment lid soft close actuator motor circuit(s) short circuit to ground, short circuit to power, open circuit, high resistance ■ Luggage compartment lid soft close actuator signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Luggage compartment lid soft close actuator failure ■ Luggage compartment lid control module failure	■ Refer to the electrical circuit diagrams and check the luggage compartment lid soft close actuator motor circuit(s) for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary ■ Refer to the electrical circuit diagrams and check the luggage compartment lid soft close actuator signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest ■ If fault persists, install a new luggage compartment lid soft close actuator. Clear the DTCs and retest ■ If fault persists, install a new luggage compartment lid control module
B1463-02	Upper Latch - Combined Pawl/Claw Switch - General signal failure	NOTE: Circuit reference - UPPER LATCH 1ST SIG ■ Tailgate latch soft close initiation switch circuit short circuit to power, open circuit, high resistance	■ Refer to the electrical circuit diagrams and check the tailgate latch soft close initiation switch circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness or install a new tailgate latch as necessary
B1463-11	Upper Latch - Combined Pawl/Claw Switch - Circuit short to ground	NOTE: Circuit reference - UPPER LATCH 1ST SIG ■ Tailgate latch soft close initiation switch circuit short circuit to ground	■ Refer to the electrical circuit diagrams and check the tailgate latch soft close initiation switch circuit for short circuit to ground. Repair the wiring harness or install a new tailgate latch as necessary
B1464-02	Upper Latch - Claw Switch - General signal failure	NOTE: Circuit reference - UPPER LATCH 2ND SIG ■ Tailgate ajar switch circuit short circuit to ground, short circuit to power, open circuit, high resistance	■ Refer to the electrical circuit diagrams and check the tailgate ajar switch circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness or install a new tailgate latch as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C2005-11	Right Actuator - Circuit short to ground	NOTE: Circuit reference - RH_SPINDLE_MOTOR_PWR_POS / RH_SPINDLE_COMMON_GND_NEG / UPPER HALL SUPPLY RHS - Right side powered luggage compartment lid actuator circuit short circuit to ground - Right side powered luggage compartment lid actuator failure - Luggage compartment lid control module failure	- Refer to the electrical circuit diagrams and check the right side powered luggage compartment lid actuator circuit for short circuit to ground. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new right side powered luggage compartment lid actuator. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
C2005-12	Right Actuator - Circuit short to battery	NOTE: Circuit reference - RH_SPINDLE_MOTOR_PWR_POS / RH_SPINDLE_COMMON_GND_NEG - Right side powered luggage compartment lid actuator circuit short circuit to power - Right side powered luggage compartment lid actuator failure - Luggage compartment lid control module failure	- Refer to the electrical circuit diagrams and check the right side powered luggage compartment lid actuator circuit for short circuit to power. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new right side powered luggage compartment lid actuator. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
C2005-13	Right Actuator - Circuit open	NOTE: Circuit reference - RH_SPINDLE_MOTOR_PWR_POS / RH_SPINDLE_COMMON_GND_NEG - Right side powered luggage compartment lid actuator circuit open circuit, high resistance - Right side powered luggage compartment lid actuator failure - Luggage compartment lid control module failure	- Refer to the electrical circuit diagrams and check the right side powered luggage compartment lid actuator circuit for open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new right side powered luggage compartment lid actuator. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
C2005-15	Right Actuator - Circuit short to battery or open	NOTE: Circuit reference - UPPER HALL SUPPLY RHS - Right side powered luggage compartment lid actuator position sensor power supply circuit short circuit to power, open circuit, high resistance - Right side powered luggage compartment lid actuator failure - Luggage compartment lid control module failure	- Refer to the electrical circuit diagrams and check the right side powered luggage compartment lid actuator position sensor power supply circuit for open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new right side powered luggage compartment lid actuator. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C2005-19	Right Actuator - Circuit current above threshold	NOTE: Circuit reference - RH_SPINDLE_MOTOR_PWR_POS / RH_SPINDLE_COMMON_GND_NEG ■ Powered luggage compartment lid movement blocked ■ Right side powered luggage compartment lid actuator circuit short circuit to ground ■ Right side powered luggage compartment lid actuator failure ■ Luggage compartment lid control module failure	■ Inspect that the luggage compartment lid movement is not inhibited by an obstruction above or inside the luggage compartment. Check the condition of the mechanical linkages/hinges and rectify fault ■ Refer to the electrical circuit diagrams and check the right side powered luggage compartment lid actuator circuit for short circuit to ground. Repair the wiring harness as necessary. Clear the DTCs and retest ■ If fault persists, install a new right side powered luggage compartment lid actuator. Clear the DTCs and retest ■ If fault persists, install a new luggage compartment lid control module
C2005-31	Right Actuator - No signal	NOTE: Circuit reference - RH_HALL_SENSOR_1 / RH_HALL_SENSOR_2 / RH_SPINDLE_HALL_SENSOR_NEG ■ Right side powered luggage compartment lid actuator position sensor circuit(s) short circuit to ground, short circuit to power, open circuit, high resistance ■ Right side powered luggage compartment lid actuator failure ■ Luggage compartment lid control module failure	■ Refer to the electrical circuit diagrams and check the right side powered luggage compartment lid actuator position sensor circuits for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest ■ If fault persists, install a new right side powered luggage compartment lid actuator. Clear the DTCs and retest ■ If fault persists, install a new luggage compartment lid control module
C2006-11	Left Actuator - Circuit short to ground	NOTE: Circuit reference - LH_SPINDLE_MOTOR_PWR_POS / LH_SPINDLE_COMMON_GND_NEG /LH_SPINDLE_HALL_SENSOR_POS ■ Left side powered luggage compartment lid actuator circuit short circuit to ground ■ Left side powered luggage compartment lid actuator failure ■ Luggage compartment lid control module failure	■ Refer to the electrical circuit diagrams and check the left side powered luggage compartment lid actuator circuit for short circuit to ground. Repair the wiring harness as necessary. Clear the DTCs and retest ■ If fault persists, install a new left side powered luggage compartment lid actuator. Clear the DTCs and retest ■ If fault persists, install a new luggage compartment lid control module
C2006-12	Left Actuator - Circuit short to battery	NOTE: Circuit reference - LH_SPINDLE_MOTOR_PWR_POS / LH_SPINDLE_COMMON_GND_NEG ■ Left side powered luggage compartment lid actuator circuit short circuit to power ■ Left side powered luggage compartment lid actuator failure ■ Luggage compartment lid control module failure	■ Refer to the electrical circuit diagrams and check the left side powered luggage compartment lid actuator circuit for short circuit to power. Repair the wiring harness as necessary. Clear the DTCs and retest ■ If fault persists, install a new left side powered luggage compartment lid actuator. Clear the DTCs and retest ■ If fault persists, install a new luggage compartment lid control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C2006-13	Left Actuator - Circuit open	NOTE: Circuit reference - LH_SPINDLE_MOTOR_PWR_POS / LH_SPINDLE_COMMON_GND_NEG - Left side powered luggage compartment lid actuator circuit open circuit, high resistance - Left side powered luggage compartment lid actuator failure - Luggage compartment lid control module failure	- Refer to the electrical circuit diagrams and check the left side powered luggage compartment lid actuator circuit for open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new left side powered luggage compartment lid actuator. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
C2006-15	Left Actuator - Circuit short to battery or open	NOTE: Circuit reference - LH_SPINDLE_HALL_SENSOR_POS - Left side powered luggage compartment lid actuator position sensor power supply circuit short circuit to power, open circuit, high resistance - Left side powered luggage compartment lid actuator failure - Luggage compartment lid control module failure	- Refer to the electrical circuit diagrams and check the left side powered luggage compartment lid actuator position sensor power supply circuit for short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new left side powered luggage compartment lid actuator. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
C2006-19	Left Actuator - Circuit current above threshold	NOTE: Circuit reference - LH_SPINDLE_MOTOR_PWR_POS / LH_SPINDLE_COMMON_GND_NEG - Powered luggage compartment lid movement blocked - Left side powered luggage compartment lid actuator circuit short circuit to ground - Left side powered luggage compartment lid actuator failure - Luggage compartment lid control module failure	- Inspect that the luggage compartment lid movement is not inhibited by an obstruction above or inside the luggage compartment. Check the condition of the mechanical linkages/hinges and rectify fault - Refer to the electrical circuit diagrams and check the left side powered luggage compartment lid actuator circuit for short circuit to ground. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new left side powered luggage compartment lid actuator. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module
C2006-31	Left Actuator - No signal	NOTE: Circuit reference - LH_HALL_SENSOR_1 / LH_HALL_SENSOR_2 / LH_SPINDLE_HALL_SENSOR_NEG - Left side powered luggage compartment lid actuator position sensor circuit(s) short circuit to ground, short circuit to power, open circuit, high resistance - Left side powered luggage compartment lid actuator failure - Luggage compartment lid control module failure	- Refer to the electrical circuit diagrams and check the left side powered luggage compartment lid actuator position sensor circuits for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - If fault persists, install a new left side powered luggage compartment lid actuator. Clear the DTCs and retest - If fault persists, install a new luggage compartment lid control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0010-88	Medium Speed CAN Communication Bus - Bus off	Medium speed CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and test the medium speed CAN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest
U0140-00	Lost Communication With Body Control Module - No sub type information	- Body control module power or ground circuit open circuit, high resistance - Medium speed CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	- Refer to the electrical circuit diagrams and test the body control module power and ground circuits for open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and test the medium speed CAN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest
U0300-00	Internal Control Module Software Incompatibility - No sub type information	Luggage compartment lid control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the luggage compartment lid control module with the latest level software. Clear the DTCs and retest. If the fault persists install a new luggage compartment lid control module
U0401-68	Invalid Data Received from ECM/PCM A - Event information	Luggage compartment lid control module has received invalid data from the engine control module	Using the Jaguar Land Rover approved diagnostic equipment, check the engine control module for related DTCs and refer to the relevant DTC index
U0415-68	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module - Event information	Luggage compartment lid control module has received invalid data for the ABS control module	Using the Jaguar Land Rover approved diagnostic equipment, check the ABS control module for related DTCs and refer to the relevant DTC index
U201A-51	Control Module Main Calibration Data - Not programmed	Luggage compartment lid control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the luggage compartment lid control module with the latest level software. Clear the DTCs and retest. If the fault persists install a new luggage compartment lid control module
U201A-52	Control Module Main Calibration Data - Not activated	Luggage compartment lid control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the luggage compartment lid control module with the latest level software. Clear the DTCs and retest
U2100-00	Initial Configuration Not Complete - No sub type information	Luggage compartment lid control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the luggage compartment lid control module with the latest level software. Clear the DTCs and retest. If the fault persists install a new luggage compartment lid control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2101-00	Control Module Configuration Incompatible - No sub type information	Luggage compartment lid control module is not configured correctly	- Using the Jaguar Land Rover approved diagnostic equipment, check and install the latest relevant level of software to the luggage compartment lid control module - Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary. Clear the DTCs and retest. If the fault persists install a new luggage compartment lid control module
U3000-44	Control Module - Data memory failure	- Luggage compartment lid control module failure - RAM memory corrupted	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If fault persists, install a new luggage compartment lid control module
U3000-45	Control Module - Program memory failure	- Luggage compartment lid control module failure - ROM memory corrupted	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If fault persists, install a new luggage compartment lid control module
U3000-46	Control Module - Calibration/parameter memory failure	- Luggage compartment lid control module failure - Non volatile memory corrupted	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If fault persists, install a new luggage compartment lid control module
U3000-49	Control Module - Internal electronic failure	Luggage compartment lid control module failure	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If fault persists, install a new luggage compartment lid control module
U3000-4B	Control Module - Over temperature	The luggage compartment lid control module has received an ambient temperature value which exceeded 80°C	NOTE: The ambient air temperature value received by the luggage compartment lid control module from the engine control module has exceeded 80°C. This signal is transmitted on CAN. If the value exceeds 80°C the luggage compartment lid control module strategy is to protect the powered luggage compartment lid struts by inhibiting operation - Check if the vehicle has been exposed to very high ambient temperatures, for example in a paint curing oven - Using the Jaguar Land Rover approved diagnostic equipment, check the engine control module for ambient air temperature related DTCs and refer to the relevant DTC index

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U3003-62	Battery Voltage - Signal compare failure	Luggage compartment lid control module voltage differs more than $\pm 2V$ compared to Main ECU Supply Voltage	- Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Main ECU Supply Voltage (0xDD02) - and compare it to battery voltage - Refer to relevant section of workshop manual and battery care requirements. Check battery state of charge and starting/charging system performance - Refer to the electrical circuit diagrams and check the power and ground circuits to the luggage compartment lid control module. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists install a new luggage compartment lid control module