

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC: OCCUPANT CLASSIFICATION SENSOR CONTROL MODULE [OCSCM] [G1577327]

DESCRIPTION AND OPERATION

OCCUPANT CLASSIFICATION SENSOR CONTROL MODULE [OCSCM]

WARNINGS:

- TO AVOID ACCIDENTAL DEPLOYMENT AND POSSIBLE PERSONAL INJURY, THE BACKUP POWER SUPPLY MUST BE DEPLETED BEFORE REPAIRING OR REPLACING ANY AIRBAG Supplementary Restraint System (SRS) COMPONENTS. TO DEplete THE BACKUP POWER SUPPLY ENERGY, DISCONNECT THE BATTERY GROUND CABLE AND WAIT ONE MINUTE. FAILURE TO FOLLOW THIS INSTRUCTION MAY RESULT IN PERSONAL INJURY
- Do not use a multimeter to probe the restraints control module. It is possible for the power from the meter battery to trigger the activation of the airbags. Failure to follow this instruction may result in personal injury

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If a control module or a component is at fault or may be at fault and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval program is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the Jaguar Land Rover approved diagnostic equipment).
- When performing voltage or resistance tests, always use a digital multimeter accurate to three decimal places, and with an up-to-date calibration certificate. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests.
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion.
- If DTCs are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always inspect for loose connections and corroded terminals.
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and complete the recommendations as required.
- It is advisable not to use a mobile phone or to have a mobile phone in close proximity when working on the restraints control module or associated systems.

The table below lists all diagnostic trouble codes (DTCs) that could be set in the occupant classification sensor control module, for additional diagnosis and testing information refer to the relevant diagnosis and testing section. For additional information, refer to: [Airbag Supplementary Restraint System](#) (501-20B Supplementary Restraint System, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B00C0-7B	Passenger Seat Occupant Classification Sensor "A" - Low fluid level	■ Seat incorrectly installed ■ Occupant classification sensor bladder hose loose/detached ■ Occupant classification sensor damaged/leaking	NOTES: ■ If a new occupant classification sensor service kit is installed the new module replacement and programming procedure must be performed. ■ Do not attempt to install individual components from the occupant classification sensor service kit, as they are calibrated to function as a single assembly. ■ Inspect the seat and associated fixings are correctly installed. Rectify installation as required. Clear the DTCs and retest ■ If the fault persists, inspect the integrity of the occupant classification sensor bladder hose routing. Re-attach as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ■ If the fault persists, install a new occupant classification kit and follow the reprogramming procedure. Refer to workshop manual section 510-20B: Supplementary Restraint System - Diagnosis and Testing - Airbag and Safety Belt Pretensioner Supplemental Restraint System - Occupant Classification Sensor Control Module (OCSCM) New Module Replacement And Programming ■ Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Learn Seat Occupant Classification Zero Position. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B00C1-11	Passenger Seat Occupant Classification Sensor "B" - Circuit short to ground	NOTE: Circuit reference BTS / BTS-VREF Seatbelt tension sensor circuit short circuit to ground	NOTE: Seatbelt tension sensor is integrated into the anchor point of the front passenger seatbelt. Refer to the electrical circuit diagrams and inspect the seatbelt tension sensor circuit for short circuit to ground
B00C1-12	Passenger Seat Occupant Classification Sensor "B" - Circuit short to battery	NOTE: Circuit reference IGN / BTS / BTS-VREF / GND Seatbelt tension sensor circuit short circuit to power	NOTE: Seatbelt tension sensor is integrated into the anchor point of the front passenger seatbelt. Refer to the electrical circuit diagrams and inspect the seatbelt tension sensor circuit for short circuit to power
B00C1-13	Passenger Seat Occupant Classification Sensor "B" - Circuit open	NOTE: Circuit reference BTS / BTS-VREF Seatbelt tension sensor circuit open circuit, high resistance	NOTE: Seatbelt tension sensor is integrated into the anchor point of the front passenger seatbelt. Refer to the electrical circuit diagrams and inspect the seatbelt tension sensor circuit for open circuit, high resistance. Repair circuit as required. Clear the DTCs and retest
B00C1-97	Passenger Seat Occupant Classification Sensor "B" - Component or system operation obstructed or blocked	Passenger seatbelt tension sensor internal failure	NOTE: Seatbelt tension sensor is integrated into the anchor point of the front passenger seatbelt. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new seatbelt tension sensor
U0001-81	High Speed CAN Communication Bus - Invalid serial data received	Restraints system fault	Using the Jaguar Land Rover approved diagnostic equipment, check the restraints control module for related DTCs and refer to the relevant Diagnostic Trouble Code(s) (DTC) index
U0001-87	High Speed CAN Communication Bus - Missing message	Missing message from another control module through the high speed Controller Area Network (CAN) bus (powertrain)	Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant <u>DTC</u> index
U0001-88	High Speed CAN Communication Bus - Bus off	High speed <u>CAN</u> bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover approved diagnostic equipment, perform a <u>CAN</u> network integrity test. Refer to the electrical circuit diagrams and inspect the high speed <u>CAN</u> bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0300-00	Internal Control Module Software Incompatibility - No sub type information	- Car configuration file mismatch with vehicle specification - Incorrect occupant classification sensor control module installed	NOTES: - If a new occupant classification sensor service kit is installed the new module replacement and programming procedure must be performed. - Do not attempt to install individual components from the occupant classification sensor service kit, as they are calibrated to function as a single assembly. - Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary - If the fault persists, install a new occupant classification kit and follow the reprogramming procedure. Refer to workshop manual section 510-20B: Supplementary Restraint System - Diagnosis and Testing - Airbag and Safety Belt Pretensioner Supplemental Restraint System - Occupant Classification Sensor Control Module (OCSCM) New Module Replacement And Programming
U2016-51	Control Module Main Software - Not programed	- Occupant classification sensor control module is not configured correctly - Occupant classification sensor control module internal failure	NOTES: - To clear this <u>DTC</u>, the existing module programming procedure must first be performed. - If a new occupant classification sensor service kit is installed the new module replacement and programming procedure must be performed. - Do not attempt to install individual components from the occupant classification sensor service kit, as they are calibrated to function as a single assembly. - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists reprogram the occupant classification sensor control module. Refer to workshop manual section 510-20B: Supplementary Restraint System - Diagnosis and Testing - Airbag and Safety Belt Pretensioner Supplemental Restraint System - Occupant Classification Sensor Control Module (OCSCM) Existing Module Programming - If the fault persists, install a new occupant classification kit and follow the reprogramming procedure. Refer to workshop manual section 510-20B: Supplementary Restraint System - Diagnosis and Testing - Airbag and Safety Belt Pretensioner Supplemental Restraint System - Occupant Classification Sensor Control Module (OCSCM) New Module Replacement And Programming
U201A-51	Control Module Main Calibration Data - Not programed	Occupant classification sensor control module calibration file is not configured correctly	NOTES: - To clear this <u>DTC</u>, the existing module programming procedure must first be performed. - Do not attempt to install individual components from the occupant classification sensor service kit, as they are calibrated to function as a single assembly. - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists reprogram the occupant classification sensor control module. Refer to workshop manual section 510-20B: Supplementary Restraint System - Diagnosis and Testing - Airbag and Safety Belt Pretensioner Supplemental Restraint System - Occupant Classification Sensor Control Module (OCSCM) Existing Module Programming

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U201A-54	Control Module Main Calibration Data - Missing calibration	Occupant classification sensor control module calibration file is not configured correctly	NOTES: - To clear this <u>DTC</u>, the existing module programming procedure must first be performed. - Do not attempt to install individual components from the occupant classification sensor service kit, as they are calibrated to function as a single assembly. - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists reprogram the occupant classification sensor control module. Refer to workshop manual section 510-20B: Supplementary Restraint System - Diagnosis and Testing - Airbag and Safety Belt Pretensioner Supplemental Restraint System - Occupant Classification Sensor Control Module (OCSCM) Existing Module Programming
U3000-49	Control Module - Internal electronic failure	Occupant classification sensor control module internal failure	NOTES: - If a new occupant classification sensor service kit is installed the new module replacement and programming procedure must be performed. - Do not attempt to install individual components from the occupant classification sensor service kit, as they are calibrated to function as a single assembly. - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new occupant classification kit and follow the reprogramming procedure. Refer to workshop manual section 510-20B: Supplementary Restraint System - Diagnosis and Testing - Airbag and Safety Belt Pretensioner Supplemental Restraint System - Occupant Classification Sensor Control Module (OCSCM) New Module Replacement And Programming
U3000-54	Control Module - Missing calibration	Occupant classification sensor configuration error	NOTE: The following pre-conditions are required to run the routine correctly: ignition is switched on, the occupancy seat module has gone through the seat assembly plant calibration, no collision event received from the restraints control module during the current ignition cycle, no faults present in the current ignition cycle, occupancy seat module has settled for 10 seconds, temperature is between 6°C (42°F) and 36°C (97°F), seat is bolted in original installation position Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Learn Seat Occupant Classification Zero Position. Clear the DTCs and retest