

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC:
PARKING ASSIST CONTROL MODULE (PAM) [G2223947]

DESCRIPTION AND OPERATION

PARK ASSIST CONTROL MODULE (PACM)

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If the control module or a component is not to specification and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval program is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the Jaguar Land Rover approved diagnostic equipment).
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests.
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion.
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals.
- Where an 'on demand self-test' is referred to, this can be accessed through the 'diagnostic trouble code monitor' tab on the manufacturers approved diagnostic system.
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and complete the recommendations as required.

The table below lists all diagnostic trouble codes (DTCs) that could be set in the parking assist control module, for additional diagnosis and testing information refer to the relevant diagnosis and testing section. For additional information, refer to: [Parking Aid](#) (413-13 Parking Aid, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B129C-12	Left Front Side Sensor - Circuit short to battery	- Front left side park assist sensor signal circuit short circuit to power - Front left side park assist sensor failure	- Refer to electrical wiring diagrams and check the front bumper harness for damage/corrosion. Check the front left side park assist sensor circuit for short circuit to power. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129C-14	Left Front Side Sensor - Circuit short to ground or open	- Front left side park assist sensor signal circuit short circuit to ground, open circuit, high resistance - Front left side park assist sensor failure	- Refer to electrical wiring diagrams and check the front bumper harness for damage/corrosion. Check the front left side park assist sensor circuit for short circuit to ground, open circuit. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129C-1F	Left Front Side Sensor - Circuit intermittent	- Front left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to electrical wiring diagrams and check the front bumper harness for damage/corrosion. Check the front left side park assist sensor circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B129C-2F	Left Front Side Sensor - Signal erratic	■ Front left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit ■ Front left side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to electrical wiring diagrams and check the front bumper harness for damage/corrosion. Check the front left side park assist sensor circuit for short circuit to ground, short circuit to power, open circuit. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129C-91	Left Front Side Sensor - Parametric	■ Front left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit ■ Front left side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to electrical wiring diagrams and check the front bumper harness for damage/corrosion. Check the front left side park assist sensor circuit for short circuit to ground, short circuit to power, open circuit. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B129C-92	Left Front Side Sensor - Performance or incorrect operation	■ Front left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit ■ Front left side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to electrical wiring diagrams and check the front bumper harness for damage/corrosion. Check the front left side park assist sensor circuit for short circuit to ground, short circuit to power, open circuit. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129C-96	Left Front Side Sensor - Component internal failure	■ Front left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front left side park assist sensor failure	NOTES: ■ This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes ■ This DTC will log if the local ground of the sensor is open circuit ■ Refer to electrical wiring diagrams and check the front bumper harness for damage/corrosion. Check the front left side park assist sensor circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B129D-12	Right Front Side Sensor - Circuit short to battery	- Front right side park assist sensor signal circuit short circuit to power - Front right side park assist sensor failure	- Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right side park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129D-14	Right Front Side Sensor - Circuit short to ground or open	- Front right side park assist sensor signal circuit short circuit to ground, open circuit, high resistance - Front right side park assist sensor failure	- Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right side park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129D-1F	Right Front Side Sensor - Circuit intermittent	- Front right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B129D-2F	Right Front Side Sensor - Signal erratic	■ Front right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front right side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129D-91	Right Front Side Sensor - Parametric	■ Front right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front right side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B129D-92	Right Front Side Sensor - Performance or incorrect operation	- Front right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129D-96	Right Front Side Sensor - Component internal failure	- Front right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right side park assist sensor failure	NOTES: - This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes - This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B129E-73	Enable/Disable Switch - Semi-automatic Advance Parallel Park - Actuator stuck closed	- Park assist switch signal circuit short circuit to ground - Park assist switch stuck active	- Refer to the electrical circuit diagrams and check the park assist switch signal circuit for short circuit to ground. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new touchscreen switchpack as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B129F-11	Function LED - Semi-automatic Advanced Parallel Park - circuit short to ground	■ Park assist switch LED circuit short circuit to ground ■ Park assist switch LED internal failure	■ Refer to the electrical circuit diagrams and check the park assist switch LED circuit for short circuit to ground. Repair the wiring harness as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new touchscreen switchpack as necessary
B129F-12	Function LED - Semi-automatic Advanced Parallel Park - Circuit short to battery	■ Park assist switch LED circuit short circuit to ground ■ Park assist switch LED internal failure	■ Refer to the electrical circuit diagrams and check the park assist switch LED circuit for short circuit to ground. Repair the wiring harness as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new touchscreen switchpack as necessary
B129F-13	Function LED - Semi-automatic Advanced Parallel Park - Circuit open	■ Park assist switch LED circuit open circuit, high resistance ■ Park assist switch LED internal failure	■ Refer to the electrical circuit diagrams and check the park assist switch LED circuit for open circuit, high resistance. Repair the wiring harness as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new touchscreen switchpack as necessary
B1443-12	Left Rear Side Proximity Sensor - Circuit short to battery	■ Rear left side park assist sensor signal circuit short circuit to power ■ Rear left side park assist sensor failure	■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left side park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1443-14	Left Rear Side Proximity Sensor - Circuit short to ground or open	■ Rear left side park assist sensor signal circuit short circuit to ground, open circuit, high resistance ■ Rear left side park assist sensor failure	■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1443-1F	Left Rear Side Proximity Sensor - Circuit intermittent	■ Rear left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1443-2F	Left Rear Side Proximity Sensor - Signal erratic	■ Rear left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1443-91	Left Rear Side Proximity Sensor - Parametric	■ Rear left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1443-92	Left Rear Side Proximity Sensor - Performance or incorrect operation	■ Rear left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1443-96	Left Rear Side Proximity Sensor - Component internal failure	■ Rear left side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left side park assist sensor failure	NOTES: ■ This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes ■ This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1454-12	Right Rear Side Proximity Sensor - Circuit short to battery	■ Rear right side park assist sensor signal circuit short circuit to power ■ Rear right side park assist sensor failure	■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right side park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1454-14	Right Rear Side Proximity Sensor - Circuit short to ground or open	■ Rear right side park assist sensor signal circuit short circuit to ground, open circuit, high resistance ■ Rear right side park assist sensor failure	■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1454-1F	Right Rear Side Proximity Sensor - Circuit intermittent	■ Rear right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1454-2F	Right Rear Side Proximity Sensor - Signal erratic	■ Rear right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1454-91	Right Rear Side Proximity Sensor - Parametric	■ Rear right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1454-92	Right Rear Side Proximity Sensor - Performance or incorrect operation	■ Rear right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right side park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1454-96	Right Rear Side Proximity Sensor - Component internal failure	■ Rear right side park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right side park assist sensor failure	NOTES: ■ This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes ■ This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right side park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B36-12	Right Front Outer Sensor - Circuit short to battery	■ Front right outer park assist sensor signal circuit short circuit to power ■ Front right outer park assist sensor failure	■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right outer park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B36-14	Right Front Outer Sensor - Circuit short to ground or open	■ Front right outer park assist sensor signal circuit short circuit to ground, open circuit, high resistance ■ Front right outer park assist sensor failure	■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right outer park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B36-1F	Right Front Outer Sensor - Circuit intermittent	■ Front right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front right outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B36-2F	Right Front Outer Sensor - Signal erratic	■ Front right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front right outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B36-91	Right Front Outer Sensor - Parametric	■ Front right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front right outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B36-92	Right Front Outer Sensor - Performance or incorrect operation	■ Front right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front right outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B36-96	Right Front Outer Sensor - Component internal failure	- Front right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right outer park assist sensor failure	NOTES: - This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes - This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B38-12	Right Front Inner Sensor - Circuit short to battery	- Front right inner park assist sensor signal circuit short circuit to power - Front right inner park assist sensor failure	- Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right inner park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B38-14	Right Front Inner Sensor - Circuit short to ground or open	- Front right inner park assist sensor signal circuit short circuit to ground, open circuit, high resistance - Front right inner park assist sensor failure	- Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right inner park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment clear, the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B38-1F	Right Front Inner Sensor - Circuit intermittent	- Front right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B38-2F	Right Front Inner Sensor - Signal erratic	- Front right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B38-91	Right Front Inner Sensor - Parametric	- Front right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B38-92	Right Front Inner Sensor - Performance or incorrect operation	- Front right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B38-96	Right Front Inner Sensor - Component internal failure	- Front right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front right inner park assist sensor failure	NOTES: - This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes - This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B40-12	Left Front Outer Sensor - Circuit short to battery	- Front left outer park assist sensor signal circuit short circuit to power - Front left outer park assist sensor failure	- Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left outer park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B40-14	Left Front Outer Sensor - Circuit short to ground or open	- Front left outer park assist sensor signal circuit short circuit to ground, open circuit, high resistance - Front left outer park assist sensor failure	- Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left outer park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B40-1F	Left Front Outer Sensor - Circuit intermittent	- Front left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B40-2F	Left Front Outer Sensor - Signal erratic	- Front left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B40-91	Left Front Outer Sensor - Parametric	- Front left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B40-92	Left Front Outer Sensor - Performance or incorrect operation	- Front left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B40-96	Left Front Outer Sensor - Component internal failure	- Front left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left outer park assist sensor failure	NOTES: - This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes - This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B42-12	Left Front Inner Sensor - Circuit short to battery	- Front left inner park assist sensor signal circuit short circuit to power - Front left inner park assist sensor failure	- Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left inner park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B42-14	Left Front Inner Sensor - Circuit short to ground or open	- Front left inner park assist sensor signal circuit short circuit to ground, open circuit, high resistance - Front left inner park assist sensor failure	- Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left inner park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B42-1F	Left Front Inner Sensor - Circuit intermittent	- Front left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B42-2F	Left Front Inner Sensor - Signal erratic	- Front left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B42-91	Left Front Inner Sensor - Parametric	■ Front left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front left inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B42-92	Left Front Inner Sensor - Performance or incorrect operation	■ Front left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Front left inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B42-96	Left Front Inner Sensor - Component internal failure	- Front left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Front left inner park assist sensor failure	NOTES: - This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes - This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the front bumper harness for damage/corrosion. Check the front left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B44-12	Right Rear Outer Sensor - Circuit short to battery	- Rear right outer park assist sensor signal circuit short circuit to power - Rear right outer park assist sensor failure	- Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right outer park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B44-14	Right Rear Outer Sensor - Circuit short to ground or open	- Rear right outer park assist sensor signal circuit short circuit to ground, open circuit, high resistance - Rear right outer park assist sensor failure	- Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right outer park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B44-1F	Right Rear Outer Sensor - Circuit intermittent	■ Rear right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B44-2F	Right Rear Outer Sensor - Signal erratic	■ Rear right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B44-91	Right Rear Outer Sensor - Parametric	■ Rear right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B44-92	Right Rear Outer Sensor - Performance or incorrect operation	■ Rear right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B44-96	Right Rear Outer Sensor - Component internal failure	■ Rear right outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right outer park assist sensor failure	NOTES: ■ This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes ■ This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B46-12	Right Rear Inner Sensor - Circuit short to battery	■ Rear right inner park assist sensor signal circuit short circuit to power ■ Rear right inner park assist sensor failure	■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right inner park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B46-14	Right Rear Inner Sensor - Circuit short to ground or open	■ Rear right inner park assist sensor signal circuit short circuit to ground, open circuit, high resistance ■ Rear right inner park assist sensor failure	■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right inner park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B46-1F	Right Rear Inner Sensor - Circuit intermittent	■ Rear right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B46-2F	Right Rear Inner Sensor - Signal erratic	■ Rear right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B46-91	Right Rear Inner Sensor - Parametric	▪ Rear right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ▪ Rear right inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ▪ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ▪ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ▪ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B46-92	Right Rear Inner Sensor - Performance or incorrect operation	▪ Rear right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ▪ Rear right inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ▪ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ▪ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ▪ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B46-96	Right Rear Inner Sensor - Component internal failure	■ Rear right inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear right inner park assist sensor failure	NOTES: ■ This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes ■ This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear right inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B48-12	Left Rear Outer Sensor - Circuit short to battery	■ Rear left outer park assist sensor signal circuit short circuit to power ■ Rear left outer park assist sensor failure	■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left outer park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B48-14	Left Rear Outer Sensor - Circuit short to ground or open	■ Rear left outer park assist sensor signal circuit short circuit to ground, open circuit, high resistance ■ Rear left outer park assist sensor failure	■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left outer park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B48-1F	Left Rear Outer Sensor - Circuit intermittent	■ Rear left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B48-2F	Left Rear Outer Sensor - Signal erratic	■ Rear left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B48-91	Left Rear Outer Sensor - Parametric	■ Rear left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B48-92	Left Rear Outer Sensor - Performance or incorrect operation	■ Rear left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left outer park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B48-96	Left Rear Outer Sensor - Component internal failure	- Rear left outer park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Rear left outer park assist sensor failure	NOTES: - This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes - This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left outer park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B50-12	Left Rear Inner Sensor - Circuit short to battery	- Rear left inner park assist sensor signal circuit short circuit to power - Rear left inner park assist sensor failure	- Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left inner park assist sensor signal circuit for short circuit to power. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B50-14	Left Rear Inner Sensor - Circuit short to ground or open	- Rear left inner park assist sensor signal circuit short circuit to ground, open circuit, high resistance - Rear left inner park assist sensor failure	- Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left inner park assist sensor signal circuit for short circuit to ground, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B50-1F	Left Rear Inner Sensor - Circuit intermittent	■ Rear left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B50-2F	Left Rear Inner Sensor - Signal erratic	■ Rear left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B50-91	Left Rear Inner Sensor - Parametric	■ Rear left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B50-92	Left Rear Inner Sensor - Performance or incorrect operation	■ Rear left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance ■ Rear left inner park assist sensor failure	NOTE: This DTC will log if the local ground of the sensor is open circuit ■ Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary ■ Inspect the connector for integrity and damage, then reconnect sensor to confirm connection ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs ■ If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B50-96	Left Rear Inner Sensor - Component internal failure	- Rear left inner park assist sensor signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Rear left inner park assist sensor failure	NOTES: - This DTC was removed at software level GX63-14C090-DM001 and is not supported in the latest software versions and only exists for compatibility purposes - This DTC will log if the local ground of the sensor is open circuit - Refer to the electrical circuit diagrams and check the rear bumper harness for damage/corrosion. Check the rear left inner park assist sensor signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair or install a new wiring harness as necessary - Inspect the connector for integrity and damage, then reconnect sensor to confirm connection - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202) and read the DTCs - If the problem persists remove the sensor at fault from the bumper. Inspect the sensor connector for signs of water ingress/corrosion. Swap the position of the sensor into the position of a fault-free sensor. Clear the DTCs and perform routine - On Demand Self Test (0x0202). If a DTC is set for the new position of the sensor, install a new sensor
B1B54-11	Function LED - Park Aid - Circuit short to ground	- Parking assist switch LED circuit short circuit to ground - Park assist switch LED internal failure	- Refer to the electrical circuit diagrams and check the parking assist switch LED circuit for short circuit to ground. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new touchscreen switchpack as necessary
B1B54-12	Function LED - Park Aid - Circuit short to battery	- Parking assist switch LED circuit short circuit to power - Park assist switch LED internal failure	- Refer to the electrical circuit diagrams and check the parking assist switch LED circuit for short circuit to power. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new touchscreen switchpack as necessary
B1B54-13	Function LED - Park Aid - Circuit open	- Parking assist switch LED circuit open circuit, high resistance - Park assist switch LED internal failure	- Refer to the electrical circuit diagrams and check the parking assist switch LED circuit for open circuit, high resistance. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new touchscreen switchpack as necessary
B1B57-11	Front Sensors Power Circuit - Circuit short to ground	Front parking assist sensors power circuit short circuit to ground	- Refer to the electrical circuit diagrams and check the front parking assist sensors power circuit for short circuit to ground. Repair or install a new wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTC and perform routine - On Demand Self Test (0x0202). If the problem persists, replace the control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1B57-12	Front Sensors Power Circuit - Circuit short to battery	Front parking assist sensors power circuit short circuit to power	- Refer to the electrical circuit diagrams and check the front parking assist sensors power circuit for short circuit to power. Repair or install a new wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTC and perform routine - On Demand Self Test (0x0202). If the problem persists, replace the control module
B1B58-11	Rear Sensors Power Circuit - Circuit short to ground	Rear parking assist sensors power circuit short circuit to ground	- Refer to the electrical circuit diagrams and check the rear parking assist sensors power circuit for short circuit to ground. Repair or install a new wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTC and perform routine - On Demand Self Test (0x0202). If the problem persists, replace the control module
B1B58-12	Rear Sensors Power Circuit - Circuit short to battery	Rear parking assist sensors power circuit short circuit to power	- Refer to the electrical circuit diagrams and check the rear parking assist sensors power circuit for short circuit to power. Repair or install a new wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTC and perform routine - On Demand Self Test (0x0202). If the problem persists, replace the control module
B1C30-73	Disable Switch - Park Aid - Actuator stuck closed	- Parking assist switch signal circuit short circuit to ground - Parking assist switch stuck active	- Refer to the electrical circuit diagrams and check the parking assist switch signal circuit for short circuit to ground. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - On Demand Self Test (0x0202). If the fault persists, install a new touchscreen switchpack as necessary
U0001-81	Vehicle Communication Bus C - Invalid serial data received	Invalid data received from another control module through the high speed CAN bus (chassis)	NOTE: This DTC was removed at software level GX63-14C090-DM001 and is not supported in latest software versions and only exists for compatibility purposes Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0001-82	High Speed CAN Communication Bus - Alive/sequence counter incorrect/not updated	Invalid data received from another control module through the high speed CAN bus	NOTE: This DTC was removed at software level GX63-14C090-DM001 and is not supported in latest software versions and only exists for compatibility purposes Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0001-83	High Speed CAN Communication Bus - Value of signal protection calculation incorrect	Invalid data received from another control module through the high speed CAN bus	NOTE: This DTC was removed at software level GX63-14C090-DM001 and is not supported in latest software versions and only exists for compatibility purposes Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0001-87	High Speed CAN Communication Bus - Missing Message	Missing message from another control module through the high speed CAN bus	NOTE: This DTC was removed at software level GX63-14C090-DM001 and is not supported in latest software versions and only exists for compatibility purposes Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0001-88	High Speed CAN Communication Bus - Bus off	High speed CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: This DTC was removed at software level GX63-14C090-DM001 and is not supported in latest software versions and only exists for compatibility purposes Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0046-81	Vehicle Communication Bus C - Invalid serial data received	Invalid data received from another control module through the high speed CAN bus (chassis)	Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0046-82	Vehicle Communication Bus C - Alive/sequence counter incorrect/not updated	Invalid data received from another control module through the high speed CAN bus (chassis)	Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0046-83	Vehicle Communication Bus C - Value of signal protection calculation incorrect	Invalid data received from another control module through the high speed CAN bus (chassis)	Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0046-86	Vehicle Communication Bus C - Signal Invalid	Invalid data received from another control module through the high speed CAN bus (chassis)	Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0046-87	Vehicle Communication Bus C - Missing message	Missing message from another control module through the high speed CAN bus (chassis)	Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0046-88	Vehicle Communication Bus C – Bus off	High speed CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0300-57	Internal Control Module Software Incompatibility - Invalid/incomplete software component	- Car Configuration file stored in parking assist control module does not match the master Car Configuration file - Master Car Configuration file not being transmitted by master control module	- Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine Car Configuration details - Check the components installed on the vehicle were installed by the factory or a retailer - Install the original component or a new one as required
U0400-83	Invalid Data Received – Value of signal protection calculation incorrect	Invalid data received from another control module through the high speed CAN bus (chassis)	Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0400-86	Invalid Data Received – Signal invalid	Invalid data received from another control module through the high speed CAN bus (chassis)	Using the Jaguar Land Rover approved diagnostic equipment check the snapshot data (0xD020) to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U100B-00	Semi-Automatic Parallel Parking System - No sub type information	Missing/invalid data from the power steering control module	- Check local snapshot data contained in DID 0xDD80 - If DID value is set to 0x02, 0x03, 0x04 use the Jaguar Land Rover approved diagnostic equipment to check steering gear for related DTCs and refer to the relevant DTC index - If DID value is set to 0x06, review the local snapshot data in DID 0xD020 to determine which signal/message is faulty/missing and use the Jaguar Land Rover approved diagnostic equipment to complete a CAN network integrity test - Cycle the ignition off, then on, and check if the DTC is still set. Clear the DTC and retest
U2100-56	Initial Configuration Not Complete - Invalid/incomplete configuration	Car Configuration file mismatch with vehicle specification	NOTE: This DTC was removed at software level GX63-14C090-DM001 and is not supported in latest software versions and only exists for compatibility purposes Using the Jaguar Land Rover approved diagnostic equipment check and update the Car Configuration file as necessary. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2101-56	Control Module Configuration Incompatible - Invalid/incomplete configuration	Car Configuration file mismatch with vehicle specification	NOTE: This DTC was removed at software level GX63-14C090-DM001 and is not supported in latest software versions and only exists for compatibility purposes Using the Jaguar Land Rover approved diagnostic equipment check and update the Car Configuration file as necessary. Clear the DTCs and retest
U2300-54	Central Configuration - Missing calibration	Car Configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs Using the Jaguar Land Rover approved diagnostic equipment check and update the Car Configuration file as necessary. Clear the DTCs and retest
U2300-55	Central Configuration - Not configured	Car Configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs Using the Jaguar Land Rover approved diagnostic equipment check and update the Car Configuration file as necessary. Clear the DTCs and retest
U2300-56	Central Configuration - Invalid/incomplete configuration	Car Configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs Using the Jaguar Land Rover approved diagnostic equipment check and update the Car Configuration file as necessary. Clear the DTCs and retest
U2300-64	Central Configuration - Signal plausibility failure	Car Configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs Using the Jaguar Land Rover approved diagnostic equipment check and update the Car Configuration file as necessary. Clear the DTCs and retest
U3000-47	Control Module - Watchdog/safety MicroController failure	Parking assist control module failure	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs, cycle the ignition and retest. If the fault persists, install a new parking assist control module
U3000-49	Control Module - Internal electronic failure	Parking assist control module failure	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs, cycle the ignition and retest. If the fault persists, install a new parking assist control module

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U3000-55	Control Module - Not configured	Parking assist control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the parking assist control module with the latest level software. If the fault persists, install a new parking assist control module
U3000-56	Control Module - Invalid/incomplete configuration	Parking assist control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the parking assist control module with the latest level software. If the fault persists, install a new parking assist control module
U3000-63	Control Module - Circuit/component protection time-out	Parking assist control module internal circuit protection routine has deactivated the module following detection of repeated parking assist sensor short circuit faults	NOTE: This DTC is only set if the control module has detected persistent parking assist sensor short circuit faults. Make sure that all circuit faults have been resolved before proceeding with the reset short protection routine - Check for related parking assist sensor circuit fault DTCs and make sure all parking assist sensor faults are resolved - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - Reset/Clear Specified Function (Reset Short Protection) (0x040E) - to re-enable the parking assist control module output circuits