

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC: RESTRAINTS CONTROL MODULE (RCM) [GZ010784]

DESCRIPTION AND OPERATION

RESTRAINTS CONTROL MODULE (RCM)

WARNINGS:

- TO AVOID ACCIDENTAL DEPLOYMENT AND POSSIBLE PERSONAL INJURY, THE BACKUP POWER SUPPLY MUST BE DEPLETED BEFORE REPAIRING OR REPLACING ANY AIRBAG SUPPLEMENTAL RESTRAINT SYSTEM (SRS) COMPONENTS. TO DEplete THE BACKUP POWER SUPPLY ENERGY, DISCONNECT THE BATTERY GROUND CABLE AND WAIT ONE MINUTE. FAILURE TO FOLLOW THIS INSTRUCTION MAY RESULT IN PERSONAL INJURY
- Do not use a multimeter to probe the restraints control module. It is possible for the power from the meter battery to trigger the activation of the airbags. Failure to follow this instruction may result in personal injury

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- It is advisable not to use a mobile phone or to have a mobile phone in close proximity when working on the restraints control module or associated systems
- If the control module or a component is not to specification and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval program is in operation, prior to the installation of a new module/component
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the Jaguar Land Rover approved diagnostic equipment)
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals
- Where an 'on demand self-test' is referred to, this can be accessed through the 'diagnostic trouble code monitor' tab on the Jaguar Land Rover approved diagnostic equipment
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and complete the recommendations as required.

The table below lists all diagnostic trouble codes (DTCs) that could be set in the restraints control module, for additional diagnosis and testing information refer to the relevant diagnosis and testing section. For additional information, refer to: [Airbag Supplementary Restraint System](#) (501-20B Supplementary Restraint System, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0001-11	Driver Frontal Stage 1 Deployment Control - Circuit short to ground	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on - Driver airbag (stage 1) connector lever not engaged - Clockspring harness connector fault - Airbag connector(s) damaged - Driver airbag (stage 1) circuit short circuit to ground - Clockspring fault - Harness damage	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Check the lower clockspring harness 8 way connector for security, if loose reconnect. Clear the DTCs and retest - If problem still persists, disconnect and reconnect all connectors. Also test connectors (see above note). Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the driver airbag (stage 1) circuit for short circuit to ground - Check for intermittent shorts to ground within the clockspring by rotating the steering column during the checks - If a wiring fault is detected, repair the wiring as required - If no wiring harness fault exists, using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0001-12	Driver Frontal Stage 1 Deployment Control - Circuit short to battery	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on - Driver airbag (stage 1) connector lever not engaged - Clockspring harness connector fault - Airbag connector(s) damaged - Driver airbag (stage 1) circuit short circuit to power - Clockspring fault - Harness damage	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Check the lower clockspring harness 8 way connector for security, if loose reconnect. Clear the DTCs and retest - If problem still persists, disconnect and reconnect all connectors. Also test connectors (see above note). Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the driver airbag (stage 1) circuit for short circuit to power - Check for intermittent shorts to power within the clockspring by rotating the steering column during the checks - If a wiring fault is detected, repair the wiring as required

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0001-13	Driver Frontal Stage 1 Deployment Control - Circuit open	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on ■ Driver airbag (stage 1) connector lever not engaged ■ Clockspring harness connector fault ■ Airbag connector(s) damaged ■ Driver airbag (stage 1) circuit open circuit, high resistance ■ Clockspring fault ■ Harness damage	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ■ Driver airbag (stage 1) resistance specification should be greater than 1.70 ohms and less than 3.68 ohms at -40°C to 85°C ■ The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ■ Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest ■ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 0 Resistance (0x5B03). If the resistance is too high, check the lower clockspring harness 8 way connector for security, if loose disconnect and reconnect the connector. Clear the DTCs and retest ■ If problem still persists, disconnect and reconnect all connectors. Also test connectors (see above note). Clear the DTCs and retest ■ Refer to the electrical circuit diagrams and check the driver airbag (stage 1) circuit for open circuit, high resistance ■ Check for intermittent open circuit, high resistance faults within the clockspring by rotating the steering column during the checks ■ If a wiring fault is detected, repair the wiring as required ■ If no wiring harness fault exists, using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0001-1A	Driver Frontal Stage 1 Deployment Control - Circuit resistance below threshold	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on ■ Driver airbag (stage 1) connector lever not engaged ■ Airbag connector(s) damaged ■ Clockspring harness connector fault ■ Clockspring fault ■ Driver airbag (stage 1) circuit short circuit between power and ground ■ Harness damage	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ■ A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the connector plunger is engaged ■ Driver airbag (stage 1) resistance specification should be greater than 1.70 ohms and less than 3.68 ohms at -40°C to 85°C ■ The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ■ Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest ■ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 0 Resistance (0x5B03). If the resistance is too low, disconnect and reconnect the driver airbag (stage 1) connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest ■ Check the lower clockspring harness 8 way connector for security, if loose reconnect. Clear the DTCs and retest ■ Check for intermittent short circuits within the clockspring by rotating the steering column during the checks ■ Refer to the electrical circuit diagrams and check the driver (stage1) circuit for short circuit between power and ground. Clear the DTCs and retest. If the fault persists, repair the wiring harness as necessary ■ If a wiring fault is detected, repair the wiring as required ■ If no wiring harness fault exists, using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0001-2B	Driver Frontal Stage 1 Deployment Control - Signal cross coupled	- Driver airbag (stage 1) connector lever not engaged - Clockspring harness connector fault - Airbag connector(s) damaged - Driver airbag (stage 1) circuits short circuit - Clockspring fault - Harness damage	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Check the lower clockspring harness 8 way connector for security, if loose reconnect. Clear the DTCs and retest - If problem still persists, disconnect and reconnect all connectors. Also test connectors (see above note). Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the driver airbag (stage 1) circuit for short circuits to other firing circuits - Check for intermittent short circuits within the clockspring by rotating the steering column during the checks - If a wiring fault is detected, repair the wiring as required
B0001-56	Driver Frontal Stage 1 Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0002-11	Driver Frontal Stage 2 Deployment Control - Circuit short to ground	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on - Driver airbag (stage 2) connector lever not engaged - Clockspring harness connector fault - Airbag connector(s) damaged - Driver airbag (stage 2) circuit short circuit to ground - Clockspring fault - Harness damage	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Check the lower clockspring harness 8 way connector for security, if loose reconnect. Clear the DTCs and retest - If problem still persists, disconnect and reconnect all connectors. Also test connectors (see above note). Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the driver airbag (stage 2) circuit for short circuit to ground - Check for intermittent shorts to ground within the clockspring by rotating the steering column during the checks - If a wiring fault is detected, repair the wiring as required - If no wiring harness fault exists, using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0002-12	Driver Frontal Stage 2 Deployment Control - Circuit short to battery	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on - Driver airbag (stage 2) connector lever not engaged - Clockspring harness connector fault - Airbag connector(s) damaged - Driver airbag (stage 2) circuit short circuit to power - Clockspring fault - Harness damage	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Check the lower clockspring harness 8 way connector for security, if loose reconnect. Clear the DTCs and retest - If problem still persists, disconnect and reconnect all connectors. Also test connectors (see above note). Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the driver airbag (stage 2) circuit for short circuit to power - Check for intermittent shorts to power within the clockspring by rotating the steering column during the checks - If a wiring fault is detected, repair the wiring as required

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0002-13	Driver Frontal Stage 2 Deployment Control - Circuit open	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on ■ Driver airbag (stage 2) connector lever not engaged ■ Clockspring harness connector fault ■ Airbag connector(s) damaged ■ Driver airbag (stage 2) circuit open circuit, high resistance ■ Clockspring fault ■ Harness damage	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ■ Driver airbag (stage 2) resistance specification should be greater than 1.70 ohms and less than 3.68 ohms at -40°C to 85°C ■ The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ■ Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest ■ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 1 Resistance (0x5B04). If the resistance is too high, check the lower clockspring harness 8 way connector for security, if loose disconnect and reconnect the connector. Clear the DTCs and retest ■ If problem still persists, disconnect and reconnect all connectors. Also test connectors (see above note). Clear the DTCs and retest ■ Refer to the electrical circuit diagrams and check the driver airbag (stage 2) circuit for open circuit, high resistance ■ Check for intermittent open circuit, high resistance faults within the clockspring by rotating the steering column during the checks ■ If a wiring fault is detected, repair the wiring as required ■ If no wiring harness fault exists, using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0002-1A	Driver Frontal Stage 2 Deployment Control - Circuit resistance below threshold	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on ■ Driver airbag (stage 2) connector lever not engaged ■ Airbag connector(s) damaged ■ Clockspring harness connector fault ■ Clockspring fault ■ Driver airbag (stage 2) circuit short circuit between power and ground ■ Harness damage	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ■ A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the connector plunger is engaged ■ Driver airbag (stage 2) resistance specification should be greater than 1.70 ohms and less than 3.68 ohms at -40°C to 85°C ■ The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 1 Resistance (0x5B04). If the resistance is too low, disconnect and reconnect the driver airbag (stage 2) connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest ■ Check the lower clockspring harness 8 way connector for security, if loose reconnect. Clear the DTCs and retest ■ Check for intermittent short circuits within the clockspring by rotating the steering column during the checks ■ Refer to the electrical circuit diagrams and check the driver airbag (stage 2) circuit for short circuit between power and ground. Clear the DTCs and retest. If the fault persists, repair the wiring harness as necessary ■ If a wiring fault is detected, repair the wiring as required ■ If no wiring harness fault exists, using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0002-2B	Driver Frontal Stage 2 Deployment Control - Signal cross coupled	NOTE: Airbag warning can take up to 15 seconds to reset when the ignition is switched on - Driver airbag (stage 2) connector lever not engaged - Clockspring harness connector fault - Airbag connector(s) damaged - Driver airbag (stage 2) circuits short circuit - Clockspring fault - Harness damage	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the driver airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Check the lower clockspring harness 8 way connector for security, if loose reconnect. Clear the DTCs and retest - If problem still persists, disconnect and reconnect all connectors. Also test connectors (see above note). Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the driver airbag (stage 2) circuit for short circuits to other firing circuits - Check for intermittent short circuits within the clockspring by rotating the steering column during the checks - If a wiring fault is detected, repair the wiring as required
B0002-56	Driver Frontal Stage 2 Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B0010-11	Passenger Frontal Stage 1 Deployment Control - Circuit short to ground	- Passenger airbag (stage 1) connector lever not engaged - Passenger airbag (stage 1) circuit short to ground	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the passenger airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the passenger airbag (stage 1) circuit for short circuit to ground

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0010-12	Passenger Frontal Stage 1 Deployment Control - Circuit short to battery	- Passenger airbag (stage 1) connector lever not engaged - Passenger airbag (stage 1) circuit short to power	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the passenger airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the passenger airbag (stage 1) circuit for short circuit to power
B0010-13	Passenger Frontal Stage 1 Deployment Control - Circuit open	- Passenger airbag (stage 1) circuit open circuit, high resistance - Passenger airbag (stage 1) connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Passenger airbag (stage 1) resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 3 Resistance (0x5B06). Refer to the electrical circuit diagrams and check the passenger airbag (stage 1) circuit for open circuit, high resistance - Disconnect the passenger airbag (stage 1) connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0010-1A	Passenger Frontal Stage 1 Deployment Control - Circuit resistance below threshold	- Passenger airbag (stage 1) connector plunger not engaged - Passenger airbag (stage 1) connector damaged - Passenger airbag (stage 1) circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Passenger airbag (stage 1) resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 3 Resistance (0x5B06). If the resistance is too low, disconnect and reconnect the passenger airbag (stage 1) connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the passenger airbag (stage 1) connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the passenger airbag (stage 1) circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0010-2B	Passenger Frontal Stage 1 Deployment Control - Signal cross coupled	Passenger airbag (stage 1) circuit short circuit to another restraints circuit	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the passenger airbag (stage 1) circuit for short circuit to another restraints circuit

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0010-56	Passenger Frontal Stage 1 Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B0011-11	Passenger Frontal Stage 2 Deployment Control - Circuit short to ground	- Passenger airbag (stage 2) connector lever not engaged - Passenger airbag (stage 2) circuit short to ground	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the passenger airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the passenger airbag (stage 2) circuit for short circuit to ground
B0011-12	Passenger Frontal Stage 2 Deployment Control - Circuit short to battery	- Passenger airbag (stage 2) connector lever not engaged - Passenger airbag (stage 2) circuit short to power	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the passenger airbag connector(s), the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the passenger airbag (stage 2) circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0011-13	Passenger Frontal Stage 2 Deployment Control - Circuit open	■ Passenger airbag (stage 2) circuit open circuit, high resistance ■ Passenger airbag (stage 2) connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ■ The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ■ Passenger airbag (stage 2) resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C ■ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 4 Resistance (0x5B07). Refer to the electrical circuit diagrams and check the passenger airbag (stage 2) circuit for open circuit, high resistance ■ Disconnect the passenger airbag (stage 2) connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0011-1A	Passenger Frontal Stage 2 Deployment Control - Circuit resistance below threshold	- Passenger airbag (stage 2) connector plunger not engaged - Passenger airbag (stage 2) connector damaged - Passenger airbag (stage 2) circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Passenger airbag (stage 2) resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 4 Resistance (0x5B07). If the resistance is too low, disconnect and reconnect the passenger airbag (stage 2) connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the passenger airbag (stage 2) connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the passenger airbag (stage 2) circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0011-2B	Passenger Frontal Stage 2 Deployment Control - Signal cross coupled	Passenger airbag (stage 2) circuit short circuit to another restraints circuit	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the passenger airbag (stage 2) circuit for short circuit to another restraints circuit

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0011-56	Passenger Frontal Stage 2 Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B0020-11	Left Side Airbag Deployment Control - Circuit short to ground	- Left side airbag connector lever not engaged - Left side airbag (seat) circuit short circuit to ground	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the left side airbag connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the left side airbag (seat) circuit for short circuit to ground - If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation).
B0020-12	Left Side Airbag Deployment Control - Circuit short to battery	- Left side airbag connector lever not engaged - Left side airbag (seat) circuit short circuit to power	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the left side airbag connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the left side airbag (seat) circuit for short circuit to power - If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0020-13	Left Side Airbag Deployment Control - Circuit open	■ Left side airbag (seat) circuit open circuit, high resistance ■ Left side airbag (seat) connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ■ The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ■ Left side airbag (seat) resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C ■ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 5 Resistance (0x5B08). Refer to the electrical circuit diagrams and check the left side airbag (seat) circuit for open circuit, high resistance ■ Disconnect the left side airbag (seat) connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary ■ If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation). ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0020-1A	Left Side Airbag Deployment Control - Circuit resistance below threshold	- Left side airbag (seat) connector plunger not engaged - Left side airbag (seat) connector damaged - Left side airbag (seat) circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Left side airbag (seat) resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 5 Resistance (0x5B08). If the resistance is too low, disconnect and reconnect the left side airbag (seat) connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the left side airbag (seat) connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left side airbag (seat) circuit for short circuit between power and ground - If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation). - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0020-2B	Left Side Airbag Deployment Control - Signal cross coupled	Left side airbag (seat) circuit short circuit to another restraints circuit	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left side airbag (seat) circuit for short circuit to another restraints circuit - If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0020-56	Left Side Airbag Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B0021-11	Left Curtain Deployment Control 1 - Circuit short to ground	- Left side air curtain connector lever not engaged - Left side air curtain circuit short circuit to ground	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the left side air curtain connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the left side air curtain circuit for short circuit to ground
B0021-12	Left Curtain Deployment Control 1 - Circuit short to battery	- Left side air curtain connector lever not engaged - Left side air curtain circuit short circuit to power	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the left side air curtain connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the left side air curtain circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0021-13	Left Curtain Deployment Control 1 - Circuit open	■ Left side air curtain circuit open circuit, high resistance ■ Left side air curtain connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ■ The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ■ Left side air curtain resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C ■ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 6 Resistance (0x5B09). Refer to the electrical circuit diagrams and check the left side air curtain circuit for open circuit, high resistance ■ Disconnect the left side air curtain connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0021-1A	Left Curtain Deployment Control 1 - Circuit resistance below threshold	- Left side air curtain connector plunger not engaged - Left side air curtain connector damaged - Left side air curtain circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Left side air curtain resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 6 Resistance (0x5B09). If the resistance is too low, disconnect and reconnect the left side air curtain connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the left side air curtain connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left side air curtain circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0021-2B	Left Curtain Deployment Control 1 - Signal cross coupled	Left side air curtain circuit short circuit to another restraints circuit	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the left side air curtain circuit for short circuit to another restraints circuit
B0021-56	Left Curtain Deployment Control 1 - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0028-11	Right Side Airbag Deployment Control - Circuit short to ground	- Right side airbag connector lever not engaged - Right side airbag (seat) circuit short circuit to ground	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the right side airbag connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the right side airbag (seat) circuit for short circuit to ground - If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation).
B0028-12	Right Side Airbag Deployment Control - Circuit short to battery	- Right side airbag connector lever not engaged - Right side airbag (seat) circuit short circuit to power	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the right side airbag connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the right side airbag (seat) circuit for short circuit to power - If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0028-13	Right Side Airbag Deployment Control - Circuit open	▪ Right side airbag (seat) circuit open circuit, high resistance ▪ Right side airbag (seat) connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ▪ The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ▪ Right side airbag (seat) resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C ▪ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 7 Resistance (0x5B0A). Refer to the electrical circuit diagrams and check the right side airbag (seat) circuit for open circuit, high resistance ▪ Disconnect the right side airbag (seat) connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary ▪ If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation). ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0028-1A	Right Side Airbag Deployment Control - Circuit resistance below threshold	- Right side airbag (seat) connector plunger not engaged - Right side airbag (seat) connector damaged - Right side airbag (seat) circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Right side airbag (seat) resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 7 Resistance (0x5B0A). If the resistance is too low, disconnect and reconnect the right side airbag (seat) connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the right side airbag (seat) connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right side airbag (seat) circuit for short circuit between power and ground - If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation). - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0028-2B	Right Side Airbag Deployment Control - Signal cross coupled	Right side airbag (seat) circuit short circuit to another restraints circuit	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right side airbag (seat) circuit for short circuit to another restraints circuit - If a harness fault is confirmed, the harness may be repaired with the designated overlay harness repair kit. For additional information, refer to: Wiring Harness Overlay (418-02 Wiring Harnesses, Description and Operation).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0028-56	Right Side Airbag Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B0029-11	Right Curtain Deployment Control 1 - Circuit short to ground	- Right side air curtain connector lever not engaged - Right side air curtain circuit short circuit to ground	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the right side air curtain connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the right side air curtain circuit for short circuit to ground
B0029-12	Right Curtain Deployment Control 1 - Circuit short to battery	- Right side air curtain connector lever not engaged - Right side air curtain circuit short circuit to power	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the right side air curtain connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the right side air curtain circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0029-13	Right Curtain Deployment Control 1 - Circuit open	- Right side air curtain circuit open circuit, high resistance - Right side air curtain connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Right side air curtain resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 8 Resistance (0x5B0B). Refer to the electrical circuit diagrams and check the right side air curtain circuit for open circuit, high resistance - Disconnect the right side air curtain connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0029-1A	Right Curtain Deployment Control 1 - Circuit resistance below threshold	- Right side air curtain connector plunger not engaged - Right side air curtain connector damaged - Right side air curtain circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Right side air curtain resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 8 Resistance (0x5B0B). If the resistance is too low, disconnect and reconnect the right side air curtain connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the right side air curtain connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right side air curtain circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0029-2B	Right Curtain Deployment Control 1 - Signal cross coupled	Right side air curtain circuit short circuit to another restraints circuit	NOTE: The airbag connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the right side air curtain circuit for short circuit to another restraints circuit

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0029-56	Right Curtain Deployment Control 1 - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B0050-11	Driver Seatbelt Sensor - Circuit short to ground	- Driver seatbelt sensor hall switch signal circuit short circuit to ground - Driver seatbelt sensor internal failure	- Refer to the electrical circuit diagrams and check the driver seatbelt sensor hall switch signal circuit for short circuit to ground - If there are no wiring harness faults, check switch circuit in the buckle, replace buckle as required
B0050-12	Driver Seatbelt Sensor - Circuit short to battery	Driver seatbelt sensor hall switch signal circuit short circuit to power	Refer to the electrical circuit diagrams and check the driver seatbelt sensor hall switch signal circuit for short circuit to power
B0050-13	Driver Seatbelt Sensor - Circuit open	- Driver seatbelt sensor hall switch signal circuit open circuit, high resistance - Driver seatbelt sensor internal failure	- Refer to the electrical circuit diagrams and check the driver seatbelt sensor hall switch signal circuit for open circuit, high resistance - If there are no wiring harness faults, check switch circuit in the buckle, replace buckle as required
B0050-1D	Driver Seatbelt Sensor - Circuit current out of range	- Driver seatbelt sensor hall switch signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Driver seatbelt sensor internal failure	- Refer to the electrical circuit diagrams and check the driver seatbelt sensor hall switch signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance - If there are no wiring harness faults, check switch circuit in the buckle, replace buckle as required
B0050-2B	Driver Seatbelt Sensor - Signal cross coupled	Driver seatbelt sensor hall switch signal circuit short circuit to another hall switch circuit	Refer to the electrical circuit diagrams and check the driver seatbelt sensor hall switch signal circuit for short circuit to another hall switch circuit
B0050-56	Driver Seatbelt Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B0052-11	Passenger Seatbelt Sensor - Circuit short to ground	- Passenger seatbelt sensor hall switch signal circuit short circuit to ground - Passenger seatbelt sensor internal failure	- Refer to the electrical circuit diagrams and check the passenger seatbelt sensor hall switch signal circuit for short circuit to ground - If there are no wiring harness faults, check switch circuit in the buckle, replace buckle as required
B0052-12	Passenger Seatbelt Sensor - Circuit short to battery	Passenger seatbelt sensor hall switch signal circuit short circuit to power	Refer to the electrical circuit diagrams and check the passenger seatbelt sensor hall switch signal circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0052-13	Passenger Seatbelt Sensor - Circuit open	- Passenger seatbelt sensor hall switch signal circuit open circuit, high resistance - Passenger seatbelt sensor internal failure	- Refer to the electrical circuit diagrams and check the passenger seatbelt sensor hall switch signal circuit for open circuit, high resistance - If there are no wiring harness faults, check switch circuit in the buckle, replace buckle as required
B0052-1D	Passenger Seatbelt Sensor - Circuit current out of range	- Passenger seatbelt sensor hall switch signal circuit short circuit to ground, short circuit to power, open circuit, high resistance - Passenger seatbelt sensor internal failure	- Refer to the electrical circuit diagrams and check the passenger seatbelt sensor hall switch signal circuit for short circuit to ground, short circuit to power, open circuit, high resistance - If there are no wiring harness faults, check switch circuit in the buckle, replace buckle as required
B0052-2B	Passenger Seatbelt Sensor - Signal cross coupled	Passenger seatbelt sensor hall switch signal circuit short circuit to another hall switch circuit	Refer to the electrical circuit diagrams and check the passenger seatbelt sensor hall switch signal circuit for short circuit to another hall switch circuit
B0052-56	Passenger Seatbelt Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B0082-11	Passenger Seatbelt Load Limiter Deployment Control - Circuit short to ground	- Passenger seatbelt retractor load limiter connector lever not engaged - Passenger seatbelt retractor load limiter circuit short circuit to ground	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the passenger seatbelt retractor load limiter connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the passenger seatbelt retractor load limiter circuit for short circuit to ground
B0082-12	Passenger Seatbelt Load Limiter Deployment Control - Circuit short to battery	- Passenger seatbelt retractor load limiter connector lever not engaged - Passenger seatbelt retractor load limiter circuit short circuit to power	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the passenger seatbelt retractor load limiter connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the passenger seatbelt retractor load limiter circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0082-13	Passenger Seatbelt Load Limiter Deployment Control - Circuit open	▪ Passenger seatbelt retractor load limiter circuit open circuit, high resistance ▪ Passenger seatbelt retractor load limiter connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ▪ The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ▪ Passenger seatbelt retractor load limiter resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C ▪ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 22 Resistance (0x5B3C). Refer to the electrical circuit diagrams and check the passenger seatbelt retractor load limiter circuit for open circuit, high resistance ▪ Disconnect the passenger seatbelt retractor load limiter connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0082-1A	Passenger Seatbelt Load Limiter Deployment Control - Circuit resistance below threshold	- Passenger seatbelt retractor load limiter connector plunger not engaged - Passenger seatbelt retractor load limiter connector damaged - Passenger seatbelt retractor load limiter circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Passenger seatbelt retractor load limiter resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 22 Resistance (0x5B3C). If the resistance is too low, disconnect and reconnect the passenger seatbelt retractor load limiter connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the passenger seatbelt retractor load limiter connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the passenger seatbelt retractor load limiter circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B0082-2B	Passenger Seatbelt Load Limiter Deployment Control - Signal cross coupled	Passenger seatbelt retractor load limiter circuit short circuit to another restraints circuit	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the passenger seatbelt retractor load limiter circuit for short circuit to another restraints circuit

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0082-56	Passenger Seatbelt Load Limiter Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B0090-11	Left Frontal Restraints Sensor - Circuit short to ground	- Front left impact sensor power circuit short circuit to ground - Front left impact sensor circuit short circuit between power and return	- Refer to the electrical circuit diagrams and check the front left impact sensor power circuit (connector A pin 17) for short circuit to ground - Refer to the electrical circuit diagrams and check the front left impact sensor circuit (connector A pins 17 and 18) for short circuit between power and return
B0090-15	Left Frontal Restraints Sensor - Circuit short to battery or open	Front left impact sensor circuit short circuit to power, open circuit, high resistance	Refer to the electrical circuit diagrams and check the front left impact sensor circuit for short circuit to power, open circuit, high resistance
B0090-56	Left Frontal Restraints Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B0090-81	Left Frontal Restraints Sensor - Invalid serial data received	- Front left impact sensor circuit electrical interference - Front left impact sensor internal failure	- Check the front left impact sensor circuit for correct routing. Check for vehicle modifications or non-genuine accessories - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new front left impact sensor
B0090-96	Left Frontal Restraints Sensor - Component internal failure	Front left impact sensor internal failure	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new front left impact sensor
B0092-11	Left Side Restraints Sensor 2 - Circuit short to ground	- Left side impact sensor power circuit short circuit to ground - Left side impact sensor circuit short circuit between power and return	- Refer to the electrical circuit diagrams and check the left side impact sensor power circuit (connector B pin 32) for short circuit to ground - Refer to the electrical circuit diagrams and check the left side impact sensor circuit (connector B pins 31 and 32) for short circuit between power and return
B0092-15	Left Side Restraints Sensor 2 - Circuit short to battery or open	Left side impact sensor circuit short circuit to power, open circuit, high resistance	Refer to the electrical circuit diagrams and check the left side impact sensor circuit for short circuit to power, open circuit, high resistance
B0092-56	Left Side Restraints Sensor 2 - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0092-81	Left Side Restraints Sensor 2 - Invalid serial data received	- Left side impact sensor circuit electrical interference - Left side impact sensor internal failure	- Check the left side impact sensor circuit for correct routing. Check for vehicle modifications or non-genuine accessories - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left side impact sensor
B0092-96	Left Side Restraints Sensor 2 - Component internal failure	Left side impact sensor Internal failure	Install a new Left side impact sensor, clear the DTCs and retest the system
B0095-11	Right Frontal Restraints Sensor - Circuit short to ground	- Front right impact sensor power circuit short circuit to ground - Front right impact sensor circuit short circuit between power and return	- Refer to the electrical circuit diagrams and check the front right impact sensor power circuit (connector A pin 16) for short circuit to ground - Refer to the electrical circuit diagrams and check the front right impact sensor circuit (connector A pins 15 and 16) for short circuit between power and return
B0095-15	Right Frontal Restraints Sensor - Circuit short to battery or open	Front right impact sensor circuit short circuit to power, open circuit, high resistance	Refer to the electrical circuit diagrams and check the front right impact sensor circuit for short circuit to power, open circuit, high resistance
B0095-56	Right Frontal Restraints Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B0095-81	Right Frontal Restraints Sensor - Invalid serial data received	- Front right impact sensor circuit electrical interference - Front right impact sensor internal failure	- Check the front right impact sensor circuit for correct routing. Check for vehicle modifications or non-genuine accessories - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new front right impact sensor
B0095-96	Right Frontal Restraints Sensor - Component internal failure	Front right impact sensor internal failure	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new front right impact sensor
B0097-11	Right Side Restraints Sensor 2 - Circuit short to ground	- Right side impact sensor power circuit short circuit to ground - Right side impact sensor circuit short circuit between power and return	- Refer to the electrical circuit diagrams and check the right side impact sensor power circuit (connector B pin 33) for short circuit to ground - Refer to the electrical circuit diagrams and check the right side impact sensor circuit (connector B pins 33 and 34) for short circuit between power and return
B0097-15	Right Side Restraints Sensor 2 - Circuit short to battery or open	Right side impact sensor circuit short circuit to power, open circuit, high resistance	Refer to the electrical circuit diagrams and check the right side impact sensor circuit for short circuit to power, open circuit, high resistance
B0097-56	Right Side Restraints Sensor 2 - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B0097-81	Right Side Restraints Sensor 2 - Invalid serial data received	▪ Rear right side impact sensor circuit electrical interference ▪ Rear right side impact sensor internal failure	▪ Check the rear right side impact sensor circuit for correct routing. Check for vehicle modifications or non-genuine accessories ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new rear right side impact sensor
B0097-96	Right Side Restraints Sensor 2 - Component internal failure	▪ Rear right side impact sensor internal failure	▪ Install a new rear right side impact sensor, clear the DTCs and retest the system
B00B5-11	Driver Seat Track Position Restraints Sensor - Circuit short to ground	▪ Driver seat position sensor power circuit short circuit to ground ▪ Driver seat position sensor circuit short circuit between power and return	▪ Refer to the electrical circuit diagrams and check the driver seat position sensor power circuit for short circuit to ground ▪ Refer to the electrical circuit diagrams and check the driver seat position sensor circuit for short circuit between power and return
B00B5-12	Driver Seat Track Position Restraints Sensor - Circuit short to battery	▪ Drivers seat position sensor circuit short circuit to power	▪ Refer to the electrical circuit diagrams and check the drivers seat position sensor circuit for short circuit to power
B00B5-13	Driver Seat Track Position Restraints Sensor - Circuit open	▪ Drivers seat position sensor circuit open circuit, high resistance ▪ Drivers seat position sensor internal failure	▪ Refer to the electrical circuit diagrams and check the drivers seat position sensor circuit for open circuit, high resistance. If a wiring fault is detected, repair the wiring as required ▪ Check and install new seat position sensor as required
B00B5-1D	Driver Seat Track Position Restraints Sensor - Circuit current out of range	▪ Driver seat position sensor circuit electrical interference ▪ Driver seat position sensor circuit short circuit to ground, short circuit to power, open circuit, high resistance ▪ Driver seat position sensor internal failure	▪ Check the driver seat position sensor circuit for correct routing. Check for vehicle modifications or non-genuine accessories ▪ Refer to the electrical circuit diagrams and check the driver seat position sensor circuit for short circuit to ground, short circuit to power, open circuit, high resistance ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persist, install a new driver seat position sensor as required
B00B5-2B	Driver Seat Track Position Restraints Sensor - Signal cross coupled	▪ Drivers seat position sensor circuit short circuit to another sensing device	▪ Refer to the electrical circuit diagrams and check the drivers seat position sensor circuit for short circuit to another sensing device
B00B5-56	Driver Seat Track Position Restraints Sensor - Invalid / incomplete configuration	▪ Restraints control module is not configured correctly	▪ Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B00C5-11	Passenger Seat Track Position Restraints Sensor - Circuit short to ground	▪ Passenger seat position sensor circuit short circuit to ground	▪ Refer to the electrical circuit diagrams and check the passenger seat position sensor circuit for short circuit to ground
B00C5-12	Passenger Seat Track Position Restraints Sensor - Circuit short to battery	▪ Passenger seat position sensor circuit short circuit to power	▪ Refer to the electrical circuit diagrams and check the passenger seat position sensor circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B00C5-13	Passenger Seat Track Position Restraints Sensor - Circuit open	Passenger seat position sensor circuit open circuit, high resistance	Refer to the electrical circuit diagrams and check the passenger seat position sensor circuit for open circuit, high resistance
B00C5-1D	Passenger Seat Track Position Restraints Sensor - Circuit current out of range	- Passenger seat position sensor circuit short circuit to ground, short circuit to power, open circuit, high resistance - Passenger seat position sensor internal failure	- Refer to the electrical circuit diagrams and check the passenger seat position sensor circuit for short circuit to ground, short circuit to power, open circuit, high resistance - If there are no wiring harness faults, check and install new seat position sensor as required
B00C5-2B	Passenger Seat Track Position Restraints Sensor - Signal cross coupled	Passenger seat position sensor circuit short circuit to another sensing device	Refer to the electrical circuit diagrams and check the passenger seat position sensor circuit for short circuit to another sensing device
B00C5-56	Passenger Seat Track Position Restraints Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B00D2-01	Restraint System Malfunction Indicator 1 - General electrical failure	A problem with the restraint system warning lamp was reported through the CAN network by the instrument cluster	Check the instrument cluster for relevant DTCs and refer to the DTC index for that module
B00D5-11	Restraint System Passenger Disable Indicator - Circuit short to ground	- Airbag deactivation lamp circuit for short circuit to ground - Overhead console fault	- Refer to the electrical circuit diagrams and check the airbag deactivation lamp circuit for short circuit to ground - If no wiring fault is detected, check the overhead console passenger airbag deactivation lamp circuit for short circuit to ground
B00D5-12	Restraint System Passenger Disable Indicator - Circuit short to battery	- Airbag deactivation lamp circuit short circuit to power - Overhead console fault	- Refer to the electrical circuit diagrams and check the airbag deactivation lamp circuit for short circuit to power - If no wiring fault is detected, check the overhead console passenger airbag deactivation lamp circuit for short circuit to power
B00D5-13	Restraint System Passenger Disable Indicator - Circuit open	- Airbag deactivation lamp circuit open circuit, high resistance - Overhead console fault	- Refer to the electrical circuit diagrams and check the airbag deactivation lamp circuit for open circuit, high resistance - If no wiring fault is detected, check the overhead console passenger airbag deactivation lamp circuit for open circuit, high resistance. If a wiring fault is detected, repair the wiring as required
B00D5-56	Restraint System Passenger Disable Indicator - Invalid / incomplete configuration	- Restraints control module incorrectly installed - Airbag deactivation lamp circuit/connector failure - The indicator device is connected but not configured correctly	- Check the restraints control module is correctly installed - Check the integrity of the airbag deactivation lamp circuit wiring harness and check that harness connectors are correctly seated and not mis-pinned - Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B00DF-95	Passenger Restraints Disable Switch - Incorrect assembly	The switch is connected but not configured correctly	Reconfigure the restraints control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest the system

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1000-11	Right Hood Hinge Deployment Control - Circuit short to ground	- Right side hood latch actuator circuit short circuit to ground - Right side hood latch actuator internal failure	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right side hood latch actuator circuit for short circuit to ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right side hood latch actuator as required
B1000-12	Right Hood Hinge Deployment Control - Circuit short to battery	Right side hood latch actuator circuit short circuit to power	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the right side hood latch actuator circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1000-13	Right Hood Hinge Deployment Control - Circuit open	- Right side hood latch actuator circuit open circuit, high resistance - Right side hood latch actuator connector damaged - Right side hood latch actuator internal failure	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Right side hood latch actuator circuit resistance specification is 1.70 ohms to 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 21 Resistance (0x5B3B). Refer to the electrical circuit diagrams and check the right side hood latch actuator circuit for open circuit, high resistance - Disconnect the side hood latch actuator connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right side hood latch actuator

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1000-1A	Right Hood Hinge Deployment Control - Circuit resistance below threshold	- Right side hood latch actuator connector plunger not engaged - Right side hood latch actuator connector damaged - Right side hood latch actuator circuit short circuit between power and ground - Right side hood latch actuator internal failure	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Right side hood latch actuator resistance specification is 1.70 ohms to 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 21 Resistance (0x5B3B). If the resistance is too low, disconnect and reconnect the right side hood latch actuator connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the right side hood latch actuator connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right side hood latch actuator circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right side hood latch actuator
B1000-2B	Right Hood Hinge Deployment Control - Signal cross coupled	Right side hood latch actuator circuit short circuit to other firing circuits	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the right side hood latch actuator circuit for short circuit to other firing circuits
B1000-56	Right Hood Hinge Deployment Control - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1001-11	Right Hood Deployment Control - Circuit short to ground	Right hood deployment control circuit short circuit to ground	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the right hood deployment control circuit for short circuit to ground
B1001-12	Right Hood Deployment Control - Circuit short to battery	Right hood deployment control circuit short circuit to power	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the right hood deployment control circuit for short circuit to power
B1001-13	Right Hood Deployment Control - Circuit open	- Right hood deployment control circuit open circuit, high resistance - Right hood deployment control connector damaged - Right hood deployment control internal failure	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Right hood deployment control resistance specification is 1.70 ohms to 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 16 Resistance (0x5B36). Refer to the electrical circuit diagrams and check the right hood deployment control circuit for open circuit, high resistance - Disconnect the right hood deployment control connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right hood deployment control

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1001-1A	Right Hood Deployment Control - Circuit resistance below threshold	- Right hood deployment control connector plunger not engaged - Right hood deployment control connector damaged - Right hood deployment control circuit short circuit between power and ground - Right hood deployment control internal failure	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Right hood deployment control resistance specification is 1.70 ohms to 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 16 Resistance (0x5B36). If the resistance is too low, disconnect and reconnect the right hood deployment control connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the right hood deployment control connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the right hood deployment control circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right hood deployment control
B1001-2B	Right Hood Deployment Control - Signal cross coupled	Right hood deployment control circuit short circuit to another restraints circuit	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the right hood deployment control circuit for short circuit to another restraints circuit

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1001-56	Right Hood Deployment Control - Invalid / incomplete configuration	Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary. Clear the DTCs and retest
B1002-11	Left Hood Hinge Deployment Control - Circuit short to ground	- Left side hood latch actuator circuit short circuit to ground - Left side hood latch actuator internal failure	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left side hood latch actuator circuit for short circuit to ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new Left side hood latch actuator as required
B1002-12	Left Hood Hinge Deployment Control - Circuit short to battery	Left side hood latch actuator circuit short circuit to power	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the left side hood latch actuator circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1002-13	Left Hood Hinge Deployment Control - Circuit open	- Left side hood latch actuator circuit open circuit, high resistance - Left side hood latch actuator connector damaged - Left side hood latch actuator internal failure	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Left side hood latch actuator circuit resistance specification is 1.70 ohms to 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 20 Resistance (0x5B3A). Refer to the electrical circuit diagrams and check the left side hood latch actuator circuit for open circuit, high resistance - Disconnect the side hood latch actuator connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left side hood latch actuator

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1002-1A	Left Hood Hinge Deployment Control - Circuit resistance below threshold	- Left side hood latch actuator connector plunger not engaged - Left side hood latch actuator connector damaged - Left side hood latch actuator circuit short circuit between power and ground - Left side hood latch actuator internal failure	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Left side hood latch actuator resistance specification is 1.70 ohms to 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 20 Resistance (0x5B3A). If the resistance is too low, disconnect and reconnect the left side hood latch actuator connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the left side hood latch actuator connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left side hood latch actuator circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left side hood latch actuator
B1002-2B	Left Hood Hinge Deployment Control - Signal cross coupled	Left side hood latch actuator circuit short circuit to other firing circuits	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the left side hood latch actuator circuit for short circuit to other firing circuits
B1002-56	Left Hood Hinge Deployment Control - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1003-11	Left Hood Deployment Control - Circuit short to ground	Left hood deployment control circuit short circuit to ground	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the left hood deployment control circuit for short circuit to ground
B1003-12	Left Hood Deployment Control - Circuit short to battery	Left hood deployment control circuit short circuit to power	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the left hood deployment control circuit for short circuit to power
B1003-13	Left Hood Deployment Control - Circuit open	- Left hood deployment control circuit open circuit, high resistance - Left hood deployment control connector damaged - Left hood deployment control internal failure	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Left hood deployment control resistance specification is 1.70 ohms to 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 15 Resistance (0x5B35). Refer to the electrical circuit diagrams and check the left hood deployment control circuit for open circuit, high resistance - Disconnect the left hood deployment control connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left hood deployment control

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1003-1A	Left Hood Deployment Control - Circuit resistance below threshold	- Left hood deployment control connector plunger not engaged - Left hood deployment control connector damaged - Left hood deployment control circuit short circuit between power and ground - Left hood deployment control internal failure	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Left hood deployment control resistance specification is 1.70 ohms to 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 15 Resistance (0x5B35). If the resistance is too low, disconnect and reconnect the left hood deployment control connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the left hood deployment control connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the left hood deployment control circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left hood deployment control
B1003-2B	Left Hood Deployment Control - Signal cross coupled	Left hood deployment control circuit short circuit to another restraints circuit	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the left hood deployment control circuit for short circuit to another restraints circuit

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1003-56	Left Hood Deployment Control - Invalid / incomplete configuration	Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary. Clear the DTCs and retest
B1193-00	Crash Event Storage Full and Locked - No sub type information	The restraints control module has stored crash events	Check and install a new restraints control module as required
B11A0-11	Left Side Restraints Pressure Sensor - Circuit short to ground	NOTE: Do not apply any compressed air to the sensor when diagnosing - Left impact pressure sensor power circuit short circuit to ground - Left impact pressure sensor circuit short circuit between power and return	- Refer to the electrical circuit diagrams and check the left impact pressure sensor power circuit (connector B pin 19) for short circuit to ground - Refer to the electrical circuit diagrams and check the left impact pressure sensor circuit (connector B pins 19 and 20) for short circuit between power and return
B11A0-15	Left Side Restraints Pressure Sensor - Circuit short to battery or open	NOTE: Do not apply any compressed air to the sensor when diagnosing Left front door side impact sensor circuit short circuit to power, open circuit, high resistance	Refer to the electrical circuit diagrams and check the left front door side impact sensor circuit for short circuit to power, open circuit, high resistance
B11A0-56	Left Side Restraints Pressure Sensor - Invalid / incomplete configuration	NOTE: Do not apply any compressed air to the sensor when diagnosing Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B11A0-81	Left Side Restraints Pressure Sensor - Invalid serial data received	NOTE: Do not apply any compressed air to the sensor when diagnosing - Left impact pressure sensor circuit electrical interference - Left impact pressure sensor internal failure	- Check the left impact pressure sensor circuit for correct routing. Check for vehicle modifications or non-genuine accessories - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left impact pressure sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B11A0-96	Left Side Restraints Pressure Sensor - Component internal failure	NOTE: Do not apply any compressed air to the sensor when diagnosing Left impact pressure sensor internal failure	Install a new left impact pressure sensor, clear the DTCs and retest the system
B11A1-11	Right Side Restraints Pressure Sensor - Circuit short to ground	NOTE: Do not apply any compressed air to the sensor when diagnosing - Right impact pressure sensor power circuit short circuit to ground - Right impact pressure sensor circuit short circuit between power and return	- Refer to the electrical circuit diagrams and check the right impact pressure sensor power circuit (connector B pin 22) for short circuit to ground - Refer to the electrical circuit diagrams and check the right impact pressure sensor circuit (connector B pins 21 and 22) for short circuit between power and return
B11A1-15	Right Side Restraints Pressure Sensor - Circuit short to battery or open	NOTE: Do not apply any compressed air to the sensor when diagnosing Right front door side impact sensor circuit short circuit to power, open circuit, high resistance	Refer to the electrical circuit diagrams and check the right front door side impact sensor circuit for short circuit to power, open circuit, high resistance
B11A1-56	Right Side Restraints Pressure Sensor - Invalid / incomplete configuration	NOTE: Do not apply any compressed air to the sensor when diagnosing Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B11A1-81	Right Side Restraints Pressure Sensor - Invalid serial data received	NOTE: Do not apply any compressed air to the sensor when diagnosing - Right impact pressure sensor circuit electrical interference - Right impact pressure sensor internal failure	- Check the right impact pressure sensor circuit for correct routing. Check for vehicle modifications or non-genuine accessories - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new right impact pressure sensor
B11A1-96	Right Side Restraints Pressure Sensor - Component internal failure	NOTE: Do not apply any compressed air to the sensor when diagnosing Right impact pressure sensor Internal failure	Install a new right impact pressure sensor, clear the DTCs and retest the system
B11D8-11	Restraint Event Notification - Circuit short to ground	Airbag deployed notification circuit short circuit to ground	Refer to the electrical circuit diagrams and check the airbag deployed notification circuit for short circuit to ground

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B11D8-12	Restraint Event Notification - Circuit short to battery	Airbag deployed notification circuit short circuit to power	Refer to the electrical circuit diagrams and check the airbag deployed notification circuit for short circuit to power
B11D8-13	Restraint Event Notification - Circuit open	Airbag deployed notification circuit open circuit, high resistance	Refer to the electrical circuit diagrams and check the airbag deployed notification circuit for open circuit, high resistance
B11D8-68	Restraint Event Notification - Event information	Event information - Left and right hood deployment controls have been activated	The pedestrian impact protection system has deployed. Install new modules and components as required
B1211-11	Driver Seatbelt Retractor Pretensioner Deployment Control - Circuit short to ground	- Driver seatbelt retractor and pretensioner connector lever not engaged - Driver seatbelt retractor and pretensioner circuit short circuit to ground	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the driver seatbelt retractor and pretensioner connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the driver seatbelt retractor and pretensioner circuit for short circuit to ground
B1211-12	Driver Seatbelt Retractor Pretensioner Deployment Control - Circuit short to battery	- Driver seatbelt retractor and pretensioner connector lever not engaged - Driver seatbelt retractor and pretensioner circuit short circuit to power	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the driver seatbelt retractor and pretensioner connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the driver seatbelt retractor and pretensioner circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1211-13	Driver Seatbelt Retractor Pretensioner Deployment Control - Circuit open	▪ Driver seatbelt retractor and pretensioner circuit open circuit, high resistance ▪ Driver seatbelt retractor and pretensioner connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ▪ The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ▪ Driver seatbelt retractor and pretensioner resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C ▪ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 13 Resistance (0x5B10). Refer to the electrical circuit diagrams and check the driver seatbelt retractor and pretensioner circuit for open circuit, high resistance ▪ Disconnect the driver seatbelt retractor and pretensioner connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1211-1A	Driver Seatbelt Retractor Pretensioner Deployment Control - Circuit resistance below threshold	▪ Driver seatbelt retractor and pretensioner connector plunger not engaged ▪ Driver seatbelt retractor and pretensioner connector damaged ▪ Driver seatbelt retractor and pretensioner circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ▪ The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ▪ A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged ▪ Driver seatbelt retractor and pretensioner resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C ▪ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 13 Resistance (0x5B10). If the resistance is too low, disconnect and reconnect the driver seatbelt retractor and pretensioner connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest ▪ Disconnect the driver seatbelt retractor and pretensioner connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary ▪ Refer to the electrical circuit diagrams and check the driver seatbelt retractor and pretensioner circuit for short circuit between power and ground ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B1211-2B	Driver Seatbelt Retractor Pretensioner Deployment Control - Signal cross coupled	▪ Driver seatbelt retractor and pretensioner circuit short circuit to another restraints circuit	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ▪ Refer to the electrical circuit diagrams and check the driver seatbelt retractor and pretensioner circuit for short circuit to another restraints circuit

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1211-56	Driver Seatbelt Retractor Pretensioner Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B1214-11	Passenger Seatbelt Retractor Pretensioner Deployment Control - Circuit short to ground	- Passenger seatbelt retractor and pretensioner connector lever not engaged - Passenger seatbelt retractor and pretensioner circuit short circuit to ground	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the passenger seatbelt retractor and pretensioner connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the passenger seatbelt retractor and pretensioner circuit for short circuit to ground
B1214-12	Passenger Seatbelt Retractor Pretensioner Deployment Control - Circuit short to battery	- Passenger seatbelt retractor and pretensioner connector lever not engaged - Passenger seatbelt retractor and pretensioner circuit short circuit to power	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - Visually inspect the passenger seatbelt retractor and pretensioner connector, the locking plunger should be flush with the housing. If not, push the locking plunger in. Clear the DTCs and retest - Refer to the electrical circuit diagrams and check the passenger seatbelt retractor and pretensioner circuit for short circuit to power

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1214-13	Passenger Seatbelt Retractor Pretensioner Deployment Control - Circuit open	▪ Passenger seatbelt retractor and pretensioner circuit open circuit, high resistance ▪ Passenger seatbelt retractor and pretensioner connector damaged	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: ▪ The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary ▪ Passenger seatbelt retractor and pretensioner resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C ▪ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 14 Resistance (0x5B34). Refer to the electrical circuit diagrams and check the passenger seatbelt retractor and pretensioner circuit for open circuit, high resistance ▪ Disconnect the passenger seatbelt retractor and pretensioner connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary ▪ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1214-1A	Passenger Seatbelt Retractor Pretensioner Deployment Control - Circuit resistance below threshold	- Passenger seatbelt retractor and pretensioner connector plunger not engaged - Passenger seatbelt retractor and pretensioner connector damaged - Passenger seatbelt retractor and pretensioner circuit short circuit between power and ground	WARNING: Do not measure the resistance of a deployable device using any other method than that described below NOTES: - The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary - A shorting bar inside the connector (deployable device side) intentionally creates a short circuit until the wiring harness connector is installed AND the plunger is engaged - Passenger seatbelt retractor and pretensioner resistance specification should be greater than 1.70 ohms and less than 3.28 ohms at -40°C to 85°C - Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Deployment Control 14 Resistance (0x5B34). If the resistance is too low, disconnect and reconnect the passenger seatbelt retractor and pretensioner connector, making sure that the connector plunger is correctly engaged. Clear the DTCs and retest - Disconnect the passenger seatbelt retractor and pretensioner connector and apply light pressure to the connector plunger. If the plunger moves to the engaged position the connector is damaged. Repair the wiring harness as necessary - Refer to the electrical circuit diagrams and check the passenger seatbelt retractor and pretensioner circuit for short circuit between power and ground - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B1214-2B	Passenger Seatbelt Retractor Pretensioner Deployment Control - Signal cross coupled	Passenger seatbelt retractor and pretensioner circuit short circuit to another restraints circuit	NOTE: The deployable device connector has a locking plunger (orange tab) which should only fully lock when the two connectors are securely mated, male to female. If the plunger can move to the locked position easily when not mated (i.e. using reasonable pressure), then this indicates that the connector is damaged. Repair the wiring harness as necessary Refer to the electrical circuit diagrams and check the passenger seatbelt retractor and pretensioner circuit for short circuit to another restraints circuit

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1214-56	Passenger Seatbelt Retractor Pretensioner Deployment Control - Invalid / incomplete configuration	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Restraints control module is not configured correctly - Car configuration file invalid/incomplete configuration	- Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
B1436-11	Left Inner Frontal Impact Classification Sensor - Circuit short to ground	- Inner left impact sensor power circuit short circuit to ground - Inner left impact sensor circuit short circuit between power and return - Inner left impact sensor internal failure	- Refer to the electrical circuit diagrams and check the inner left impact sensor power circuit for short circuit to ground - Refer to the electrical circuit diagrams and check the inner left impact sensor circuit for short circuit between power and return - If no wiring/connector faults are detected, check and install a new inner left impact sensor as required. Clear the DTCs and retest
B1436-15	Left Inner Frontal Impact Classification Sensor - Circuit short to battery or open	Inner left impact sensor circuit short circuit to power, open circuit, high resistance	- Refer to the electrical circuit diagrams and check the inner left impact sensor circuit for short circuit to power, open circuit, high resistance - If a wiring fault is detected, repair or replace as required
B1436-56	Left Inner Frontal Impact Classification Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B1436-81	Left Inner Frontal Impact Classification Sensor - Invalid serial data received	- Inner left impact sensor circuit open circuit, high resistance - Inner left impact sensor internal failure	- Refer to the electrical circuit diagrams and check the inner left impact sensor circuit for open circuit, high resistance. Check that the wiring harness has not been modified in any way - If no wiring faults are detected, check and install a new inner left impact sensor as required. Clear the DTCs and retest
B1436-96	Left Inner Frontal Impact Classification Sensor - Component internal failure	Inner left impact sensor internal failure	Clear the DTCs and retest. If the fault persists, check and install a new inner left impact sensor as required. Clear the DTCs and retest
B1437-11	Right Inner Frontal Impact Classification Sensor - Circuit short to ground	- Inner right impact sensor power circuit short circuit to ground - Inner right impact sensor circuit short circuit between power and return - Inner right impact sensor internal failure	- Refer to the electrical circuit diagrams and check the inner right impact sensor power circuit for short circuit to ground - Refer to the electrical circuit diagrams and check the inner right impact sensor circuit for short circuit between power and return - If no wiring/connector faults are detected, check and install a new inner right impact sensor as required. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1437-15	Right Inner Frontal Impact Classification Sensor - Circuit short to battery or open	Inner right impact sensor circuit short circuit to power, open circuit, high resistance	- Refer to the electrical circuit diagrams and check the inner right impact sensor circuit for short circuit to power, open circuit, high resistance - If a wiring fault is detected, repair or replace as required
B1437-56	Right Inner Frontal Impact Classification Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B1437-81	Right Inner Frontal Impact Classification Sensor - Invalid serial data received	- Inner right impact sensor circuit open circuit, high resistance - Inner right impact sensor internal failure	- Refer to the electrical circuit diagrams and check the inner right impact sensor circuit for open circuit, high resistance. Check that the wiring harness has not been modified in any way - If no wiring faults are detected, check and install a new inner right impact sensor as required. Clear the DTCs and retest
B1437-96	Right Inner Frontal Impact Classification Sensor - Component internal failure	Inner right impact sensor internal failure	Clear the DTCs and retest. If the fault persists, check and install a new inner right impact sensor as required. Clear the DTCs and retest
B1438-11	Left Outer Frontal Impact Classification Sensor - Circuit short to ground	- Outer left impact sensor power circuit short circuit to ground - Outer left impact sensor circuit short circuit between power and return - Outer left impact sensor internal failure	- Refer to the electrical circuit diagrams and check the outer left impact sensor power circuit for short circuit to ground - Refer to the electrical circuit diagrams and check the outer left impact sensor circuit for short circuit between power and return - If no wiring/connector faults are detected, check and install a new outer left impact sensor as required. Clear the DTCs and retest
B1438-15	Left Outer Frontal Impact Classification Sensor - Circuit short to battery or open	Outer left impact sensor circuit short circuit to power, open circuit, high resistance	- Refer to the electrical circuit diagrams and check the outer left impact sensor circuit for short circuit to power, open circuit, high resistance - If a wiring fault is detected, repair or replace as required
B1438-56	Left Outer Frontal Impact Classification Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B1438-81	Left Outer Frontal Impact Classification Sensor - Invalid serial data received	- Outer left impact sensor circuit open circuit, high resistance - Outer left impact sensor internal failure	- Refer to the electrical circuit diagrams and check the outer left impact sensor circuit for open circuit, high resistance. Check that the wiring harness has not been modified in any way - If no wiring faults are detected, check and install a new outer left impact sensor as required. Clear the DTCs and retest
B1438-96	Left Outer Frontal Impact Classification Sensor - Component internal failure	Outer left impact sensor internal failure	Clear the DTCs and retest. If the fault persists, check and install a new outer left impact sensor as required. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1439-11	Right Outer Frontal Impact Classification Sensor - Circuit short to ground	- Outer right impact sensor power circuit short circuit to ground - Outer right impact sensor circuit short circuit between power and return - Outer right impact sensor internal failure	- Refer to the electrical circuit diagrams and check the outer right impact sensor power circuit for short circuit to ground - Refer to the electrical circuit diagrams and check the outer right impact sensor circuit for short circuit between power and return - If no wiring/connector faults are detected, check and install a new outer right impact sensor as required. Clear the DTCs and retest
B1439-15	Right Outer Frontal Impact Classification Sensor - Circuit short to battery or open	Outer right impact sensor circuit short circuit to power, open circuit, high resistance	- Refer to the electrical circuit diagrams and check the outer right impact sensor circuit for short circuit to power, open circuit, high resistance - If a wiring fault is detected, repair or replace as required
B1439-56	Right Outer Frontal Impact Classification Sensor - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, reconfigure the restraints control module with the latest level software
B1439-81	Right Outer Frontal Impact Classification Sensor - Invalid serial data received	- Outer right impact sensor circuit open circuit, high resistance - Outer right impact sensor internal failure	- Refer to the electrical circuit diagrams and check the outer right impact sensor circuit for open circuit, high resistance. Check that the wiring harness has not been modified in any way - If no wiring faults are detected, check and install a new outer right impact sensor as required. Clear the DTCs and retest
B1439-96	Right Outer Frontal Impact Classification Sensor - Component internal failure	Outer right impact sensor internal failure	Clear the DTCs and retest. If the fault persists, check and install a new outer right impact sensor as required. Clear the DTCs and retest
U0001-81	High Speed CAN Communication Bus - Invalid serial data received	Invalid data received from another control module through the high speed CAN bus	Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index. Clear the DTCs and retest
U0001-87	High Speed CAN Communication Bus - Missing message	Missing message from another control module through the high speed CAN bus (powertrain)	Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0001-88	High Speed CAN Communication Bus - Bus off	High speed CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance
U0073-00	Control Module Communication Bus "A" Off - No sub type information	High speed CAN bus (chassis) circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (chassis) circuit for short circuit to ground, short circuit to power, open circuit, high resistance

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0455-56	Invalid Data Received From Restraints Occupant Classification System Module - Invalid / incomplete configuration	- Car configuration file mismatch with vehicle specification - Incorrect passenger seat/occupant classification sensor control module installed	- Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest - Install a new passenger seat/occupant classification sensor control module as necessary
U0455-64	Invalid Data Received From Restraints Occupant Classification System Module - Signal plausibility failure	Occupant classification sensor control module fault	Using the Jaguar Land Rover approved diagnostic equipment, check the occupant classification sensor control module for related DTCs and refer to the relevant DTC index
U0455-92	Invalid Data Received From Restraints Occupant Classification System Module - Performance or incorrect operation	Occupant classification sensor control module fault	Using the Jaguar Land Rover approved diagnostic equipment, check the occupant classification sensor control module for related DTCs and refer to the relevant DTC index
U0455-93	Invalid Data Received From Restraints Occupant Classification System Module - No operation	Occupant classification sensor control module fault	Using the Jaguar Land Rover approved diagnostic equipment, check the occupant classification sensor control module for related DTCs and refer to the relevant DTC index
U0455-95	Invalid Data Received From Restraints Occupant Classification System Module - Incorrect assembly	Occupant classification sensor control module fault	Using the Jaguar Land Rover approved diagnostic equipment, check the occupant classification sensor control module for related DTCs and refer to the relevant DTC index
U1A14-46	CAN Initialization Failure - Calibration / parameter memory failure	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the restraints control module with the latest level software, clear the DTCs and retest. If the fault persists, check and install a new restraints control module as required
U2008-54	Sensor Cluster - Missing calibration	Restraints control module acceleration sensors not calibrated correctly	- Using the Jaguar Land Rover approved diagnostic equipment, perform routine - calibrate acceleration sensor(s) (0x300F). Clear the DTCs and retest - Reconfigure the restraints control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest
U2008-92	Sensor Cluster - Performance or incorrect operation	Restraints control module acceleration sensors calibration routine failure	- Make sure that the restraints control module/vehicle is flat and level. Using the Jaguar Land Rover approved diagnostic equipment, perform routine - calibrate acceleration sensor(s) (0x300F). Clear the DTCs and retest - Reconfigure the restraints control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest
U2016-51	Control Module Main Software - Not programmed	Restraints control module not programed correctly	Reconfigure the restraints control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest
U201A-51	Control Module Main Calibration Data - Not programmed	Restraints control module not programed correctly	Configure the restraints control module using the manufacturer's approved diagnostic system. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U201A-57	Control Module Main Calibration Data - Invalid / incomplete software component	- Car configuration file mismatch with vehicle specification - Model year - Vehicle type	Reconfigure the restraints control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest
U201B-57	Control Module Calibration Data #2 - Invalid / incomplete software component	- Restraints control module not programed correctly - Car configuration file - Model year and/or vehicle type set incorrectly	Reconfigure the restraints control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest
U2023-51	Control Module Network Signal Calibration Data - Not programmed	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the restraints control module with the latest level software
U2100-00	Initial Configuration Not Complete - No sub type information	Restraints control module not correctly configured	Configure the restraints control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest
U2100-56	Initial Configuration Not Complete - Invalid / incomplete configuration	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the restraints control module with the latest level software
U2101-00	Control Module Configuration Incompatible - No sub type information	- Restraints control module is not configured correctly - Car configuration file mismatch with vehicle specification	- Using the Jaguar Land Rover approved diagnostic equipment, re-configure the restraints control module with the latest level software - Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary
U2101-95	Control Module Configuration Incompatible - Incorrect assembly	Car configuration file mismatch with vehicle specification	Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
U2200-00	Control Module Configuration Memory Corrupt - No sub type information	Restraints control module internal failure	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new restraints control module
U2300-54	Central Configuration - Missing calibration	NOTE: This DTC will log with the ignition set to on or with the engine running, if after 25 seconds no car configuration file information, regarding the restraints control module, has been learnt Car configuration file not received	Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2300-55	Central Configuration - Not configured	Car configuration file not received	- Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Reset ECU Central Configuration State/Data To Not Configured (0x0E08). Clear the DTCs and retest - Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
U2300-56	Central Configuration - Invalid / incomplete configuration	Car configuration file not completed	Using the Jaguar Land Rover approved diagnostic equipment, check and update the Car Configuration File (CCF) as required. Clear the DTCs and retest
U3000-00	Control Module - No sub type information	Restraints control module - Internal fault	Clear the DTCs and retest. If fault persists, check and install a new restraints control module as required
U3000-46	Control Module - Calibration / parameter memory failure	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the restraints control module with the latest level software
U3000-49	Control Module - Internal electronic failure	Restraints control module - Internal fault	Clear the DTCs and retest. If fault persists, check and install a new restraints control module as required
U3002-51	Vehicle Identification Number - Not programmed	- Incorrect VIN stored in the restraints control module - Restraints control module not programmed correctly	- Using the Jaguar Land Rover approved diagnostic equipment, perform routine - Learn VIN (0x0404). Clear the DTCs and retest - Reconfigure the restraints control module using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest
U3002-95	Vehicle Identification Number - Incorrect assembly	Restraints control module is not configured correctly	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the restraints control module with the latest level software
U3003-16	Battery Voltage - Circuit voltage below threshold	- Restraints control module power or ground circuit open circuit, high resistance - Battery/charging system fault	- Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Main ECU Supply Voltage (0xDD02). Refer to the electrical circuit diagrams and check the restraints control module power and ground circuits for open circuit, high resistance - Refer to the relevant section of the workshop manual and test the battery and charging system
U3003-17	Battery Voltage - Circuit voltage above threshold	Battery/charging system fault	Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Main ECU Supply Voltage (0xDD02). Refer to the relevant section of the workshop manual and test the battery and charging system
U3003-1F	Battery Voltage - Circuit intermittent	RCM initialization not completed 15 seconds after power-up (Airbag warning indicator will always be ON in this case) due to voltage transients on restraints control module power or ground circuit	Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Main ECU Supply Voltage (0xDD02). Refer to the electrical circuit diagrams and check the restraints control module power and ground circuits for sources of interference, for example from unapproved accessories