

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC: SIDE
OBJECT DETECTION CONTROL MODULE [G2002265]

DESCRIPTION AND OPERATION

SIDE OBJECT DETECTION CONTROL MODULE - LEFT/RIGHT [SODL/SODR]

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If the control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system)
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals
- Where an 'on demand self-test' is referred to, this can be accessed via the 'DTC Monitor' tab on the manufacturers approved diagnostic system
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all diagnostic trouble codes (DTCs) that could be logged in the Side Object Detection Control Module - Left/Right (SODL/SODR), for additional diagnosis and testing information refer to the relevant diagnosis and testing section. For additional information, refer to: [Warning Devices](#) (413-09 Warning Devices, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0001-87	High Speed CAN Communication Bus - Missing message	Missing message from another control module via the high speed CAN bus (comfort)	NOTE: This DTC refers to a CAN bus communications failure, DO NOT replace the side object detection control module Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0001-88	High Speed CAN Communication Bus - Bus off	High speed CAN bus (comfort) circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTES: - This DTC refers to a CAN bus communications failure, DO NOT replace the side object detection control module - To validate the repair, set the ignition to on and wait 30 seconds and check the DTC does not set - Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (comfort) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U0300-00	Internal Control Module Software Incompatibility - No sub type information	- Car configuration file mismatch with vehicle specification - Left/right side object detection control module is not configured correctly - Incorrect left/right side object detection control module installed	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary - Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software - Install a new left/right side object detection control module as necessary
U1000-00	Solid State Driver Protection Active - Driver Disabled - No sub type information	- Left/right side object detection control module is not configured correctly - Left/right side object detection control module internal failure	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software. Clear the DTCs and retest. If the fault persists, install a new left/right side object detection control module as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U1A00-88	Private Communication Network - Bus off	■ Opposite side object detection control module power or ground circuit open circuit, high resistance ■ Private CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTES: ■ This DTC refers to a CAN bus communications failure, DO NOT replace the side object detection control module ■ To validate the repair, set the ignition to on and wait 30 seconds and check the DTC does not set ■ Refer to the electrical circuit diagrams and check the opposite side object detection control module power and ground circuits for open circuit, high resistance ■ Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (comfort) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left and right side object detection control module with the latest level software. Clear the DTCs and retest
U2100-00	Initial Configuration Not Complete - No sub type information	■ Left/right side object detection control module is not configured correctly	NOTE: This DTC refers to a CAN bus communications failure, DO NOT replace the side object detection control module ■ Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software
U2101-00	Control Module Configuration Incompatible - No sub type information	■ Car configuration file mismatch with vehicle specification ■ Left/right side object detection control module is not configured correctly	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs ■ Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest ■ Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software
U3000-44	Control Module - Data memory failure	■ Left/right side object detection control module is not configured correctly ■ Left/right side object detection control module internal failure	■ Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software. Clear the DTCs and retest. If the fault persists, install a new left/right side object detection control module as necessary
U3000-45	Control Module - Program memory failure	■ Car configuration file mismatch with vehicle specification ■ Left/right side object detection control module internal failure	■ Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software. Clear the DTCs and retest. If the fault persists, install a new left/right side object detection control module as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U3000-46	Control Module - Calibration/parameter memory failure	- Left/right side object detection control module is not configured correctly - Left/right side object detection control module internal failure	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software. Clear the DTCs and retest. If the fault persists, install a new left/right side object detection control module as necessary
U3000-48	Control Module - Supervision software failure	- Left/right side object detection control module is not configured correctly - Left/right side object detection control module internal failure	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software. Clear the DTCs and retest. If the fault persists, install a new left/right side object detection control module as necessary
U3000-49	Control Module - Internal electronic failure	- Left/right side object detection control module is not configured correctly - Left/right side object detection control module internal failure	Using the Jaguar Land Rover approved diagnostic equipment, re-configure the left/right side object detection control module with the latest level software. Clear the DTCs and retest. If the fault persists, install a new left/right side object detection control module as necessary
U3000-78	Control Module - Alignment or adjustment incorrect	- Left/right side object detection control module incorrectly installed - Left/right side object detection control module is not configured correctly - Left/right side object detection control module internal failure	NOTE: If the DTC is cleared, a test drive of at least 40 minutes duration is required in order to confirm that the fault is rectified (the DTC will not set again prior to this interval) - Check the left/right side object detection control module for correct installation - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new left/right side object detection control module as necessary