

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC:
STEERING ANGLE SENSOR MODULE [SASM]

[G2057255]

DESCRIPTION AND OPERATION

STEERING ANGLE SENSOR MODULE [SASM]

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle.

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If a control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system).
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests.
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion.
- If DTCs are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals.
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all Diagnostic Trouble Codes (DTCs) that could be logged in the Steering Angle Sensor Module (SASM). For additional diagnosis and testing information, refer to the relevant Diagnosis and Testing section in the workshop manual. For additional information, refer to: [Anti-Lock Control - Stability Assist](#) (206-09 Anti-Lock Control - Stability Assist, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1B00-1C	Steering Angle Sensor - Circuit voltage out of range	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
C1B00-49	Steering Angle Sensor - Internal electronic failure	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
C1B00-61	Steering Angle Sensor - Signal calculation failure	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
C1B00-62	Steering Angle Sensor - Signal compare failure	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
C1B00-64	Steering Angle Sensor - Signal plausibility failure	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1B00-81	Steering Angle Sensor - Invalid serial data received	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
C1B00-85	Steering Angle Sensor - Signal above allowable range	- Steering angle sensor module/clockspring incorrectly aligned - Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information - Check if the steering angle sensor module or the clockspring has been removed and refitted incorrectly - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
C1B00-92	Steering Angle Sensor - Performance or incorrect operation	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
C1B00-96	Steering Angle Sensor - Component internal failure	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
C1B00-97	Steering Angle Sensor - Component or system operation obstructed or blocked	Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0001-88	High Speed CAN Communication Bus - Bus off	High speed CAN bus (chassis) circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the chassis high speed CAN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance
U0300-00	Internal Control Module Software Incompatibility - No sub type information	- Steering angle sensor module power or ground circuit open circuit, high resistance - High speed CAN bus (chassis) circuit short circuit to ground, short circuit to power, open circuit, high resistance - Incorrect steering angle sensor module installed - Steering angle sensor module internal failure	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information - Refer to the electrical circuit diagrams and check the steering angle sensor module power and ground circuits for open circuit, high resistance - Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the chassis high speed CAN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance - Check the correct steering angle sensor module is installed - Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, check and install a new steering angle sensor module as required
U3003-62	Battery Voltage - Signal compare failure	NOTE: Module voltage is more than 2 volts below CAN broadcast voltage for more than 10 seconds Mismatch between the voltage at the steering angle sensor module and the voltage value broadcast on the CAN bus	NOTE: Warning Indicator is not directly controlled by the steering angle sensor module. The steering angle sensor module only stops sending valid information Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Main ECU Supply Voltage (0xDD02). Refer to the electrical circuit diagrams and check the steering angle sensor module power and ground circuits for open circuit, high resistance