

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC:
TELEMATIC CONTROL MODULE [TCU] [G2016419]

DESCRIPTION AND OPERATION

TELEMATIC CONTROL MODULE [TCU]

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle.

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If a control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system).
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests.
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion.
- If DTCs are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals.
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all Diagnostic Trouble Codes (DTCs) that could be logged in the Telematic Control Module (TCU). For additional diagnosis and testing information, refer to the relevant Diagnosis and Testing section in the workshop manual. For additional information, refer to: [Telematics](#) (419-05 Telematics, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10A2-12	Crash Input - Circuit short to battery	NOTE: Circuit reference - CRASH SIGNAL Crash signal circuit short circuit to power	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the crash signal circuit for short circuit to power. Repair the wiring harness as necessary
B10A2-14	Crash Input - Circuit short to ground or open	NOTE: Circuit reference - CRASH SIGNAL Crash signal circuit short circuit to ground, open circuit, high resistance	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the crash signal circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary
B10A2-38	Crash Input - Signal frequency incorrect	NOTE: Circuit reference - CRASH SIGNAL - Crash signal circuit short circuit to another signal circuit - Supplementary restraint system fault	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster - Refer to the electrical circuit diagrams and check the crash signal circuit for short circuit to another signal circuit. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, check the restraints control module for related DTCs and refer to the relevant DTC index
B116D-11	SOS On Call Keypad - Circuit short to ground	NOTE: Circuit reference - E/BCALL SWITCH / BUTTON DIAG OP / BUTTON_IP_COMMON - Telematic switchpack eCall and/or bCall functions inoperative - Telematic switchpack circuit short circuit to ground	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the telematic switchpack circuit for short circuit to ground. Repair the wiring harness as necessary
B116D-12	SOS On Call Keypad - Circuit short to battery	NOTE: Circuit reference - E/BCALL SWITCH / BUTTON_IP_COMMON - Telematic switchpack eCall and/or bCall functions inoperative - Telematic switchpack circuit short circuit to power	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the telematic switchpack circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B116D-13	SOS On Call Keypad - Circuit open	NOTE: Circuit reference - E/BCALL SWITCH / BUTTON_IP_COMMON ■ Telematic switchpack eCall and/or bCall functions inoperative ■ Telematic switchpack circuit open or high resistance	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ Refer to the electrical circuit diagrams and check the telematic switchpack circuit for open circuit or high resistance. Repair the wiring harness as necessary
B116D-97	SOS On Call Keypad - Component or system operation obstructed or blocked	NOTE: Circuit reference - E/BCALL SWITCH / BUTTON_IP_COMMON ■ Telematic switchpack eCall and/or bCall functions inoperative ■ Telematic switchpack switch stuck active ■ Telematic switchpack circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTES: ■ This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ Switch signals are blocked following false or repeated operation ■ Test the operation of the telematic switchpack switches. Install a new telematics switchpack as necessary ■ Refer to the electrical circuit diagrams and check the telematic switchpack circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
B116E-11	SOS On Call Illumination - Circuit short to ground	NOTE: Circuit reference - LED GRD / bCALL ACTIVE IND / bCALL BACKLIGHT SUPP / eCALL ACTIVE IND / eCALL BACKLIGHT SUPP ■ Telematic switchpack backlight inoperative ■ Telematic switchpack illumination circuit short circuit to ground	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ Refer to the electrical circuit diagrams and check the telematic switchpack illumination circuit for short circuit to ground. Repair the wiring harness as necessary
B116E-12	SOS On Call Illumination - Circuit short to battery	NOTE: Circuit reference - LED GRD / bCALL ACTIVE IND / bCALL BACKLIGHT SUPP / eCALL ACTIVE IND / eCALL BACKLIGHT SUPP ■ Telematic switchpack backlight inoperative ■ Telematic switchpack illumination circuit short circuit to power	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ Refer to the electrical circuit diagrams and check the telematic switchpack illumination circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B116E-13	SOS On Call Illumination - Circuit open	NOTE: Circuit reference - LED GRD / bCALL ACTIVE IND / bCALL BACKLIGHT SUPP / eCALL ACTIVE IND / eCALL BACKLIGHT SUPP ■ Telematic switchpack backlight inoperative ■ Telematic switchpack illumination circuit short circuit to power, open circuit, high resistance	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ Refer to the electrical circuit diagrams and check the telematic switchpack illumination circuit for open circuit, high resistance. Repair the wiring harness as necessary
B116F-09	Telematics SIM Card - Component failures	■ Little or no phone functionality and data services ■ Telematic control module failure	■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new telematic control module
B1179-04	Integrated GSM/GPRS Unit - System internal failures	■ Little or no phone functionality and data services ■ Telematic control module internal battery failure	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new telematic control module
B117A-01	Backup Microphone - General electrical failure	NOTE: Circuit reference - MIC I/P - / MIC I/P + / MIC I/P SCN ■ No sound detected by the telematic microphone ■ Telematic microphone circuit short circuit to the telematics speaker circuit	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ Refer to the electrical circuit diagrams and check the telematic microphone circuit for short circuit to the telematics speaker circuit. Repair the wiring harness as necessary
B117A-11	Backup Microphone - Circuit short to ground	NOTE: Circuit reference - MIC I/P - / MIC I/P + / MIC I/P SCN ■ No sounded detected by telematic microphone ■ Telematic microphone circuit short circuit to ground	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ Refer to the electrical circuit diagrams and check the telematic microphone circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B117A-12	Backup Microphone - Circuit short to battery	NOTE: Circuit reference - MIC I/P - / MIC I/P + / MIC I/P SCN - No sound detected by telematics microphone - Telematic microphone circuit short circuit to power	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the telematic microphone circuit for short circuit to power. Repair the wiring harness as necessary
B117A-13	Backup Microphone - Circuit open	NOTE: Circuit reference - MIC I/P - / MIC I/P + / MIC I/P SCN - No sound detected by telematic microphone - Telematic microphone circuit open circuit or high resistance	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the telematic microphone circuit for open circuit or high resistance. Repair the wiring harness as necessary
B119F-11	GPS Antenna - Circuit short to ground	NOTE: Circuit reference - GPS SIG - Poor position accuracy for telematic services - Global positioning system antenna circuit short circuit to ground	NOTES: - This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster - The Telematic Control Module (TCU) may send a message to the monitoring centre when detecting this fault (only when telematic Stolen Vehicle Tracking (SVT) service activated) - Refer to the electrical circuit diagrams and check the global positioning system antenna circuit for short circuit to ground. Repair the wiring harness as necessary
B119F-12	GPS Antenna - Circuit short to battery	NOTE: Circuit reference - GPS SIG - Poor position accuracy for telematic services - Global positioning system antenna circuit short circuit to power	NOTES: - This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster - The Telematic Control Module (TCU) may send a message to the monitoring centre when detecting this fault (only when telematic Stolen Vehicle Tracking (SVT) service activated) - Refer to the electrical circuit diagrams and check the global positioning system antenna circuit for short circuit to power. Repair the wiring harness as necessary
B119F-13	GPS Antenna - Circuit open	NOTE: Circuit reference - GPS SIG - Poor position accuracy for telematic services - Global positioning system antenna circuit open circuit, high resistance	NOTES: - This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster - The Telematic Control Module (TCU) may send a message to the monitoring centre when detecting this fault (only when telematic Stolen Vehicle Tracking (SVT) service activated) - Refer to the electrical circuit diagrams and check the global positioning system antenna circuit for open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B14A9-13	BroadR-Reach Link - Telematics (+) - Circuit open	NOTE: Circuit reference - BR2 POS - Telematics unable to interface with the infotainment system - Telematic ethernet circuit open circuit or high resistance	Refer to the electrical circuit diagrams and check the telematic ethernet circuit for open circuit, high resistance. Repair the wiring harness as necessary. Clear the DTCs and retest
B14A9-64	BroadR-Reach Link - Telematics (+) - Signal Plausibility Failure	NOTE: Circuit reference - BR2 POS - Telematics unable to interface with the infotainment system - Telematic control module internal failure	- Using the Jaguar Land Rover approved diagnostic equipment, check the Infotainment Master Controller (IMC) module for related DTCs and refer to the relevant DTC index - If fault persists install a new telematic control module. If this DTC is still present after the installation of a new telematic control module refer to the Infotainment Master Controller (IMC) module related DTCs. Replacement of the IMC module may be advised
B14AA-13	BroadR-Reach Link - Telematics (-) - Circuit open	NOTE: Circuit reference - BR2 NEG - Telematics unable to interface with the infotainment system - Telematic ethernet circuit open circuit or high resistance	Refer to the electrical circuit diagrams and check the telematic ethernet circuit for open circuit, high resistance. Repair the wiring harness as necessary
B14AA-64	BroadR-Reach Link - Telematics (-) - Signal Plausibility Failure	NOTE: Circuit reference - BR2 NEG - Telematics unable to interface with the infotainment system - Telematic control module internal failure	- Using the Jaguar Land Rover approved diagnostic equipment, check the Infotainment Master Controller (IMC) module for related DTCs and refer to the relevant DTC index - If fault persists install a new telematic control module. If this DTC is still present after the installation of a new telematic control module refer to the Infotainment Master Controller (IMC) module related DTCs. Replacement of the IMC module may be advised
B14B5-11	WiFi Antenna #1 - Circuit Short To Ground	- Poor WiFi performance, little or no WiFi hotspot availability - WiFi antenna circuit short circuit to ground	Refer to electrical circuit diagrams and check the WiFi antenna circuit for short circuit to ground. Repair the wiring harness as necessary
B14B5-12	WiFi Antenna #1 - Circuit Short To Battery	- Poor WiFi performance, little or no WiFi hotspot availability - WiFi antenna circuit short circuit to power	Refer to electrical circuit diagrams and check the WiFi antenna circuit for short circuit to power. Repair the wiring harness as necessary
B14B5-13	WiFi Antenna #1 - Circuit Open	- Poor WiFi performance, little or no WiFi hotspot availability - WiFi antenna circuit open circuit	Refer to electrical circuit diagrams and check the WiFi antenna circuit for open circuit. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A01-01	Speaker #1 - General Electrical Failure	NOTE: Circuit reference - SPEAKER O/P POS / SPEAKER O/P NEG - No sound detected by the telematic microphone - Telematic speaker circuit short circuit to the telematics microphone circuit	Refer to the electrical circuit diagrams and check the telematic speaker circuit for a short circuit to the telematics microphone circuit. Repair the wiring harness as necessary
B1A01-11	Speaker #1 - Circuit short to ground	NOTE: Circuit reference - SPEAKER O/P POS / SPEAKER O/P NEG - Little or no sound when using telematic services - Telematic speaker circuit short circuit to ground	NOTE: NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the telematic speaker circuit for short circuit to ground. Repair the wiring harness as necessary
B1A01-12	Speaker #1 - Circuit short to battery	NOTE: Circuit reference - SPEAKER O/P POS / SPEAKER O/P NEG - Little or no sound when using telematic services - Telematic speaker circuit short circuit to power	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the telematic speaker circuit for short circuit to power. Repair the wiring harness as necessary
B1A01-13	Speaker #1 - Circuit open	NOTE: Circuit reference - SPEAKER O/P POS / SPEAKER O/P NEG - Little or no sound when using telematic services - Telematic speaker circuit open circuit or high resistance	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the telematic speaker circuit for open circuit or high resistance. Repair the wiring harness as necessary
B1A56-11	Antenna - Circuit short to ground	NOTE: Circuit reference - GSM1 SIG - Poor GSM coverage - Poor sound quality sound when using telematic services - Poor or no phone/telematic functionality - GSM antenna circuit short circuit to ground	NOTES: - This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster - The Telematic Control Module (TCU) may send a message to the monitoring centre when detecting this fault (only when telematic Stolen Vehicle Tracking (SVT) service activated) - Refer to the electrical circuit diagrams and check the GSM antenna circuit for short circuit to ground. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1A56-12	Antenna - Circuit short to battery	NOTE: Circuit reference - GSM1 SIG - Poor GSM coverage - Poor sound quality sound when using telematic services - Poor or no phone/telematic functionality - GSM antenna circuit short circuit to power	NOTES: - This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster - The Telematic Control Module (TCU) may send a message to the monitoring centre when detecting this fault (only when telematic Stolen Vehicle Tracking (SVT) service activated) - Refer to the electrical circuit diagrams and check the GSM antenna circuit for short circuit to power. Repair the wiring harness as necessary
B1A56-13	Antenna - Circuit Open	NOTE: Circuit reference - GSM1 SIG - Poor GSM coverage - Poor sound quality sound when using telematic services - Poor or no phone/telematic functionality - GSM antenna circuit open circuit or high resistance	NOTES: - This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster - The Telematic Control Module (TCU) may send a message to the monitoring centre when detecting this fault (only when telematic Stolen Vehicle Tracking (SVT) service activated) - Refer to the electrical circuit diagrams and check the GSM antenna circuit for open circuit or high resistance. Repair the wiring harness as necessary
B1D55-11	Antenna #2- Circuit Short To Ground	NOTE: Circuit reference - GSM2 SIG - Poor internet speeds, especially in low coverage areas - GSM antenna circuit short circuit to ground - GSM antenna circuit short circuit to antenna shield/screen - Incorrect Stolen Vehicle Tracking (SVT) 'Theft Alert' notification through the In Control application	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster - To inspect for a permanent or intermittent fault, using the Jaguar Land Rover approved diagnostic equipment perform the diagnostic routine - On Demand Self Test (0x0202) - If the fault is permanent, refer to the electrical circuit diagrams and inspect the GSM antenna circuit for short circuit to ground. Repair the wiring harness as necessary - If the fault is intermittent, refer to the electrical circuit diagrams and test the GSM antenna circuit for short circuit to antenna shield/screen. Using a multimeter measure the circuit resistance between the GSM antenna cable central pin and the shield/screen at the antenna connector, the nominal resistance of the GSM antenna circuit will be approximately 10,000 Ohms. Then apply pressure to the GSM antenna cable and manipulate the cable at the base of the GSM antenna to test for internal circuit failure. If the circuit resistance is reduced as the cable is manipulated an internal cable failure is confirmed. Replace the GSM antenna as necessary
B1D55-12	Antenna #2- Circuit Short to Battery	NOTE: Circuit reference - GSM2 SIG - Poor internet speeds, especially in low coverage areas - GSM antenna circuit short circuit to power	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster Refer to the electrical circuit diagrams and check the GSM antenna circuit for short circuit to power. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1D55-13	Antenna #2- Circuit open	NOTE: Circuit reference - GSM2 SIG ■ Poor internet speeds, especially in low coverage areas ■ GSM antenna circuit open circuit or high resistance ■ GSM antenna circuit open circuit or high resistance to antenna shield/screen ■ Incorrect Stolen Vehicle Tracking (SVT) 'Theft Alert' notification through the In Control application	NOTE: This DTC will cause the warning "SOS limited functionality" to be displayed on the instrument cluster ■ To inspect for a permanent or intermittent fault, using the Jaguar Land Rover approved diagnostic equipment perform the diagnostic routine - On Demand Self Test (0x0202) ■ If the fault is permanent, refer to the electrical circuit diagrams and check the GSM antenna circuit for open circuit or high resistance. Repair the wiring harness as necessary ■ If the fault is intermittent, refer to the electrical circuit diagrams and test the GSM antenna circuit for open circuit or high resistance to antenna shield/screen. Using a multimeter measure the circuit resistance between the GSM antenna cable central pin and the shield/screen at the antenna connector, the nominal resistance of the GSM antenna circuit will be approximately 10,000 Ohms. Then apply pressure to the GSM antenna cable and manipulate the cable at the base of the GSM antenna to inspect for internal circuit failure. If the circuit resistance is increased or shows an open circuit as the cable is manipulated an internal cable failure is confirmed. Replace the GSM antenna as necessary
P0560-04	System Voltage - System internal failures	NOTE: Circuit reference - V BATT / GND ■ Poor telematic control module functionality ■ Telematic control module power or ground circuit open circuit, high resistance ■ Battery/charging system fault	NOTE: This DTC may cause the warning "SOS not available" to be displayed on the instrument cluster ■ Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - Main ECU Supply Voltage (0xD018). Refer to the electrical circuit diagrams and check the telematic control module power and ground circuits for open circuit, high resistance. Repair the wiring harness as necessary ■ Refer to the relevant section of the workshop manual and test the battery and charging system
U0028-87	Vehicle Communication Bus A - Missing Message	NOTE: Circuit reference - PT CAN HS H / PT CAN HS L ■ Poor telematic control module functionality ■ Missing message from another control module via the high speed CAN bus (powertrain)	■ Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0028-88	Vehicle Communication Bus A - Bus Off	NOTE: Circuit reference - PT CAN HS H / PT CAN HS L ■ Poor telematic control module functionality ■ High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: This DTC will cause the warning "SOS not available" to be displayed on the instrument cluster ■ Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0037-87	Vehicle Communication Bus B - Missing Message	NOTE: Circuit reference - BO CAN HS HI / BO CAN HS LO - Poor telematic control module functionality - Missing message from another control module via the medium speed CAN bus (body)	Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0037-88	Vehicle Communication Bus B - Bus Off	NOTE: Circuit reference - BO CAN HS HI / BO CAN HS LO - Poor telematic control module functionality - Medium speed CAN bus (body) circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the medium speed CAN bus (body) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U0300-00	Internal Control Module Software Incompatibility - No sub type information	- Possibility of poor telematic control module functionality - Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary
U201A-51	Control Module Main Calibration Data - Not programmed	Telematic control module is not configured correctly	NOTE: The Telematic Control Module (TCU) may be sending incorrect messages to the monitoring centre, or sending no information at all, when detecting this fault Using the Jaguar Land Rover approved diagnostic equipment, re-configure the telematic control module with the latest level software
U201A-54	Control Module Main Calibration Data - Missing calibration	Telematic control module is not configured correctly	NOTE: The Telematic Control Module (TCU) may be sending incorrect messages to the monitoring centre, or sending no information at all, when detecting this fault Using the Jaguar Land Rover approved diagnostic equipment, re-configure the telematic control module with the latest level software

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2109-09	Back-up Battery - Component failures	■ Backup battery poor connection or not connected ■ Telematic control unit module internal battery circuit open circuit, high resistance ■ Telematic control unit module internal battery failure	NOTE: Following an emergency call or stolen vehicle tracking alert, a new telematic control unit module internal battery must be installed before this DTC can be cleared ■ Check backup battery for poor connection or not connected ■ Refer to the electrical circuit diagrams and check the telematic control unit module internal battery circuit for open circuit, high resistance. Repair the wiring harness as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and perform routine - Test Internal Backup Battery (0x040C). If the fault persists, install a new telematic control unit module internal battery. Using the Jaguar Land Rover approved diagnostic equipment, reset the non-rechargeable battery power level following the backup battery replacement process
U2109-91	Back-up Battery - Parametric	■ Telematic control unit module internal battery failure	NOTE: The vehicle engine MUST be running to charge the telematic back-up battery. Ignition On will NOT recharge the telematic back-up battery ■ Refer to the relevant section of the workshop manual and check the startup battery condition. If the startup battery charge is low, recharge/ replace the startup battery as necessary ■ Run the vehicle for a minimum of 60 minutes to charge the TCU back-up battery ■ Check the telematic back-up battery voltage. A charged battery will show above 3.3V ■ Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and wait 10 seconds ■ Read DTCs and make sure no warning message is visible on the Instrument Cluster (IC)
U2300-54	Central Configuration - Missing Calibration	■ Car configuration file data not received	■ Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary
U2300-55	Central Configuration - Not Configured	■ Car configuration file mismatch with the vehicle specification ■ Telematic control module is not configured correctly	NOTE: This DTC may cause the warning "SOS not available" to be displayed on the instrument cluster ■ Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary ■ Using the Jaguar Land Rover approved diagnostic equipment, re-configure the telematic control module with the latest level software. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2300-56	Central Configuration - Invalid / Incomplete Configuration	- Car configuration file mismatch with the vehicle specification - Telematic control module is not configured correctly	NOTE: This DTC may cause the warning "SOS not available" to be displayed on the instrument cluster - Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary - Using the Jaguar Land Rover approved diagnostic equipment, re-configure the telematic control module with the latest level software. Clear the DTCs and retest
U2300-64	Central Configuration - Signal Plausibility Failure	Car configuration file mismatch with the vehicle specification	Using the Jaguar Land Rover approved diagnostic equipment, check and update the car configuration file as necessary
U3000-44	Control Module - Data memory failure	- Possibility of poor telematic control module functionality - Telematic control module failure	Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new telematic control module
U3000-49	Control Module - Internal electronic failure	- Possibility of poor telematic control module functionality - Telematic control module internal real time clock or global position system communication failure	NOTE: This DTC may cause the warning "SOS not available" to be displayed on the instrument cluster Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest. If the fault persists, install a new telematic control module