

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX - DTC: TIRE
PRESSURE MONITORING SYSTEM CONTROL
MODULE (TPMSCM) [G2062589]

DESCRIPTION AND OPERATION

TIRE PRESSURE MONITORING SYSTEM CONTROL MODULE (TPMSCM)

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle.

NOTES:

- Guided Diagnostics must be followed and the repair advised by the process completed. Failure to do so may result in the rejection of any warranty claim made.
- If a control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system).
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests.
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion.
- If DTCs are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals.
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all Diagnostic Trouble Codes (DTCs) that could be logged in the Tire Pressure Monitoring System Control Module (TPMSCM). For additional diagnosis and testing information, refer to the relevant Diagnosis and Testing section in the workshop manual. For additional information, refer to: [Tire Pressure Monitoring System](#) (204-04 Wheels and Tires, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B1182-17	Tire Pressure Monitoring System - Circuit voltage above threshold	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Battery/charging system fault	Refer to the relevant section of the workshop manual and test the battery and charging system
B1182-96	Tire Pressure Monitoring System - Component internal failure	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Tire pressure monitoring system control module internal failure	Using the Jaguar Land Rover Approved Diagnostic Equipment, clear the DTCs and retest. If the fault persists, check and install a new tire pressure monitoring system control module as necessary
C1A56-31	Left Front Pressure Sensor and Transmitter Assembly - No signal	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Incorrect wheels/tires installed (without tire pressure sensors - Winter wheels, spare wheel, etc) - Incorrect tire pressure sensor installed - Tire pressure sensor damaged - Tire pressure sensor internal failure or signal corrupted by RF interference	NOTE: Tire pressure sensor wheel position information may be incorrect if the wheels have been swapped during or after the failure event. - Check that the wheels and tires comply with the manufacturer's specification for the vehicle - Check that the correct tire pressure sensor is installed - Check the tire pressure sensor for damage. Install new tire pressure sensor as necessary - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the front left tire pressure sensor fails, check and install a new front left tire pressure sensor as necessary
C1A56-4A	Left Front Tire Pressure Sensor and Transmitter Assembly - Incorrect component installed	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Incorrect front left tire pressure sensor installed	NOTE: There will be no warning indicator/message displayed unless at least two incorrect tire pressure sensors have been installed. - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the front left tire pressure sensor fails, check and install a new front left tire pressure sensor as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1A56-85	Left Front Tire Pressure Sensor and Transmitter Assembly - Signal above allowable range	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Incorrect front left tire pressure sensor installed	NOTE: The DTC is set if a WU that is not capable to measure pressure values in the high range is fitted to the vehicle. - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the front left tire pressure sensor fails, install a new front left tire pressure sensor
C1A56-93	Left Front Tire Pressure Sensor and Transmitter Assembly - No operation	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Incorrect wheel/tire installed (without tire pressure sensor - Winter wheels, spare wheel, etc) - Front left tire pressure sensor damaged - Front left tire pressure sensor internal failure or signal corrupted by RF interference	NOTE: Tire pressure sensor wheel position information may be incorrect if the wheels have been swapped during or after the failure event. - Check that the wheels and tires comply with the manufacturer's specification for the vehicle - Check the front left tire pressure sensor for damage. Install a new front left tire pressure sensor as necessary - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If all tire pressure sensors pass, clear the DTCs and road test the vehicle - If all tire pressure sensors fail, check for sources of RF interference (electronic devices, chargers, non-genuine accessories, etc) - If some tire pressure sensors fail, install new tire pressure sensors as necessary
C1A58-31	Right Front Tire Pressure sensor and Transmitter Assembly - No signal	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Incorrect wheels/tires installed (without tire pressure sensors - Winter wheels, spare wheel, etc) - Incorrect tire pressure sensor installed - Tire pressure sensor damaged - Tire pressure sensor internal failure or signal corrupted by RF interference	NOTE: Tire pressure sensor wheel position information may be incorrect if the wheels have been swapped during or after the failure event. - Check that the wheels and tires comply with the manufacturer's specification for the vehicle - Check that the correct tire pressure sensor is installed - Check the tire pressure sensor for damage. Install new tire pressure sensor as necessary - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the front right tire pressure sensor fails, check and install a new front right tire pressure sensor as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1A58-4A	Right Front Tire Pressure Sensor and Transmitter Assembly - Incorrect component installed	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Incorrect front right tire pressure sensor installed	NOTE: There will be no warning indicator/message displayed unless at least two incorrect tire pressure sensors have been installed. - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the front right tire pressure sensor fails, install a new front right tire pressure sensor
C1A58-85	Right Front Tire Pressure Sensor and Transmitter Assembly - Signal above allowable range	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Incorrect front right tire pressure sensor installed	NOTE: The DTC is set if a WU that is not capable to measure pressure values in the high range is fitted to the vehicle. - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the front right tire pressure sensor fails, install a new front right tire pressure sensor
C1A58-93	Right Front Tire Pressure Sensor and Transmitter Assembly - No operation	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Incorrect wheel/tire installed (without tire pressure sensor - Winter wheels, spare wheel, etc) - Front right tire pressure sensor damaged - Front right tire pressure sensor internal failure or signal corrupted by RF interference	NOTE: Tire pressure sensor wheel position information may be incorrect if the wheels have been swapped during or after the failure event. - Check that the wheels and tires comply with the manufacturer's specification for the vehicle - Check the front right tire pressure sensor for damage. Install a new front right tire pressure sensor as necessary - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If all tire pressure sensors pass, clear the DTCs and road test the vehicle - If all tire pressure sensors fail, check for sources of RF interference (electronic devices, chargers, non-genuine accessories, etc) - If some tire pressure sensors fail, install new tire pressure sensors as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1A60-31	Left Rear Tire Pressure sensor and transmitter Assembly - No signal	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Incorrect wheels/tires installed (without tire pressure sensors - Winter wheels, spare wheel, etc) - Incorrect tire pressure sensor installed - Tire pressure sensor damaged - Tire pressure sensor internal failure or signal corrupted by RF interference	NOTE: Tire pressure sensor wheel position information may be incorrect if the wheels have been swapped during or after the failure event. - Check that the wheels and tires comply with the manufacturer's specification for the vehicle - Check that the correct tire pressure sensor is installed - Check the tire pressure sensor for damage. Install new tire pressure sensor as necessary - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the rear left tire pressure sensor fails, check and install a new rear left tire pressure sensor as necessary
C1A60-4A	Left Rear Tire Pressure Sensor and Transmitter Assembly - Incorrect component installed	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Incorrect rear left tire pressure sensor installed	NOTE: There will be no warning indicator/message displayed unless at least two incorrect tire pressure sensors have been installed. - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the rear left tire pressure sensor fails, install a new rear left tire pressure sensor as necessary
C1A60-85	Left Rear Tire Pressure Sensor and Transmitter Assembly - Signal above allowable range	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Incorrect rear left tire pressure sensor installed	NOTE: The DTC is set if a WU that is not capable to measure pressure values in the high range is fitted to the vehicle. - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the rear left tire pressure sensor fails, install a new rear left tire pressure sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1A60-93	Left Rear Tire Pressure Sensor and Transmitter Assembly - No operation	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Incorrect wheel/tire installed (without tire pressure sensor - Winter wheels, spare wheel, etc) - Rear left tire pressure sensor damaged - Rear left tire pressure sensor internal failure or signal corrupted by RF interference	NOTE: Tire pressure sensor wheel position information may be incorrect if the wheels have been swapped during or after the failure event. - Check that the wheels and tires comply with the manufacturer's specification for the vehicle - Check the rear left tire pressure sensor for damage. Install a new rear left tire pressure sensor as necessary - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If all tire pressure sensors pass, clear the DTCs and road test the vehicle - If all tire pressure sensors fail, check for sources of RF interference (electronic devices, chargers, non-genuine accessories, etc) - If some tire pressure sensors fail, install new tire pressure sensors as necessary
C1A62-31	Right Rear Tire Pressure Sensor and Transmitter Assembly - No signal	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Incorrect wheels/tires installed (without tire pressure sensors - Winter wheels, spare wheel, etc) - Incorrect tire pressure sensor installed - Tire pressure sensor damaged - Tire pressure sensor internal failure or signal corrupted by RF interference	NOTE: Tire pressure sensor wheel position information may be incorrect if the wheels have been swapped during or after the failure event. - Check that the wheels and tires comply with the manufacturer's specification for the vehicle - Check that the correct tire pressure sensor is installed - Check the tire pressure sensor for damage. Install new tire pressure sensor as necessary - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the rear right tire pressure sensor fails, check and install a new rear right tire pressure sensor
C1A62-4A	Right Rear Tire Pressure Sensor and Transmitter Assembly - Incorrect component installed	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Incorrect rear right tire pressure sensor installed	NOTE: There will be no warning indicator/message displayed unless at least two incorrect tire pressure sensors have been installed. - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the rear right tire pressure sensor fails, install a new rear right tire pressure sensor

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
C1A62-85	Right Rear Tire Pressure Sensor and Transmitter Assembly - Signal above allowable range	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Incorrect rear right tire pressure sensor installed	NOTE: The DTC is set if a WU that is not capable to measure pressure values in the high range is fitted to the vehicle. - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If the rear right tire pressure sensor fails, install a new rear right tire pressure sensor
C1A62-93	Right Rear Tire Pressure Sensor and Transmitter Assembly - No operation	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Incorrect wheel/tire installed (without tire pressure sensor - Winter wheels, spare wheel, etc) - Rear right tire pressure sensor damaged - Rear right tire pressure sensor internal failure or signal corrupted by RF interference	NOTE: Tire pressure sensor wheel position information may be incorrect if the wheels have been swapped during or after the failure event. - Check that the wheels and tires comply with the manufacturer's specification for the vehicle - Check the rear right tire pressure sensor for damage. Install a new rear right tire pressure sensor as necessary - Using the Jaguar Land Rover Approved Diagnostic Equipment, perform routine - Tire Pressure Monitoring Tire Pressure Sensor Test - If all tire pressure sensors pass, clear the DTCs and road test the vehicle - If all tire pressure sensors fail, check for sources of RF interference (electronic devices, chargers, non-genuine accessories, etc) - If some tire pressure sensors fail, install new tire pressure sensors as necessary
C1D18-00	Wheel Localisation Failed - No sub type information	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues - Low pressure in one or more road tires - One or more incorrect tire pressure sensors installed - Missing/invalid data from the anti-lock brake system control module	NOTE: There will be no warning indicator/message displayed unless at least two incorrect tire pressure sensors have been installed. - With the ignition set to on, adjust all the road tire pressures to the manufacturer's recommended pressure values - Using the Jaguar Land Rover Approved Diagnostic Equipment, check for tire pressure sensor related DTCs and perform the relevant corrective actions - Using the Jaguar Land Rover Approved Diagnostic Equipment, check the anti-lock brake system control module for related DTCs and refer to the relevant DTC index

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0001-81	High Speed CAN Communication Bus - Invalid serial data received	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Invalid data received from another control module via the high speed CAN bus	Using the Jaguar Land Rover Approved Diagnostic Equipment, check the anti-lock brake system control module for related DTCs and refer to the relevant DTC index
U0001-86	High Speed CAN Communication Bus - Signal invalid	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Invalid signal received from another control module via the high speed CAN bus	Using the Jaguar Land Rover Approved Diagnostic Equipment, check the snapshot data to determine the invalid signal source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0001-87	High Speed CAN Communication Bus - Missing message	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Missing message from another control module via the high speed CAN bus	Using the Jaguar Land Rover Approved Diagnostic Equipment, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0001-88	High Speed CAN Communication Bus - Bus off	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues High speed CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover Approved Diagnostic Equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0300-00	Internal Control Module Software Incompatibility - No sub type information	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Tire pressure monitoring system control module is not configured correctly	Using the Jaguar Land Rover Approved Diagnostic Equipment, re-configure the tire pressure monitoring system control module with the latest level software
U2300-54	Central Configuration - Missing calibration	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs. Using the Jaguar Land Rover Approved Diagnostic Equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest
U2300-55	Central Configuration - Not configured	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs. Using the Jaguar Land Rover Approved Diagnostic Equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest
U2300-56	Central Configuration - Invalid/incomplete configuration	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs. Using the Jaguar Land Rover Approved Diagnostic Equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2300-64	Central Configuration - Signal plausibility failure	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues ■ Tire pressure monitoring system control module is not configured correctly ■ Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs. ■ Using the Jaguar Land Rover Approved Diagnostic Equipment, re-configure the tire pressure monitoring system control module with the latest level software ■ Using the Jaguar Land Rover Approved Diagnostic Equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest
U3000-51	Control Module - Not programmed	NOTE: When the ignition is switched on, if the warning indicator flashes for 75 seconds then remains illuminated a system fault is present, if the warning indicator does not flash but remains illuminated, check for tyre pressure issues ■ Tire pressure monitoring system control module is not configured correctly	■ Using the Jaguar Land Rover Approved Diagnostic Equipment, re-configure the tire pressure monitoring system control module with the latest level software