

GENERAL INFORMATION

DIAGNOSTIC TROUBLE CODE INDEX: INTEGRATED
CONTROL PANEL - DTC: [ICP] [G2018747]

DESCRIPTION AND OPERATION

INTEGRATED CONTROL PANEL [ICP]

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle

NOTES:

- If the control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system)
- When performing voltage or resistance tests, always use a digital multimeter that has the resolution ability to view 3 decimal places. For example, on the 2 volts range can measure 1mV or 2 K Ohm range can measure 1 Ohm. When testing resistance always take the resistance of the digital multimeter leads into account
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals
- Where an 'on demand self-test' is referred to, this can be accessed via the 'diagnostic trouble code monitor' tab on the manufacturers approved diagnostic system
- Check JLR claims submission system for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all diagnostic trouble codes (DTCs) that could be logged in the integrated control panel, for additional diagnosis and testing information refer to the relevant diagnosis and testing section. For additional information, refer to: (415-00 Information and Entertainment System - General Information)

[Information and Entertainment System](#) (Diagnosis and Testing),
[Cellular Phone](#) (Diagnosis and Testing),
[Navigation System](#) (Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B101F-14	Eject Switch - Circuit short to ground or open	- Fascia panel eject switch circuit short circuit to ground, open circuit, high resistance - Switch failure	- Refer to the electrical circuit diagrams and check the fascia panel eject switch circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - If fault persists, check and install new fascia panel eject switch. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B101F-24	Eject Switch - Signal stuck high	- Fascia panel eject switch stuck - If the switch is pressed for longer than 1 minute, the switch is deemed to be malfunctioning - Switch failure	- Check the operation of the fascia panel eject switch and rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - If fault persists, check and install a new fascia panel eject switch as required
B1022-03	Audio On/Off Switch - FM (Frequency Modulated) / PWM (Pulse Width Modulated) Failures	- Volume control switch illumination circuit failure - Switch failure	- Refer to the electrical circuit diagrams and check the volume control switch illumination circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - If fault persists, check and install new volume control switch. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B1022-14	Audio On/Off Switch - Circuit short to ground or open	- Volume control switch circuit short circuit to ground, open circuit, high resistance - Switch fault	- Refer to the electrical circuit diagrams and check the volume control switch circuit for short circuit to ground, open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - If fault persists, check and install new volume control switch. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
B1022-24	Audio On/Off Switch - Signal stuck high	- Volume control switch stuck - If the switch is pressed for longer than 1 minute, the switch is deemed to be malfunctioning - Switch failure	- Check the operation of the volume control switch and rectify as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - If fault persists, check and install a new volume control switch as required
U0055-82	Vehicle communication bus D - Alive/sequence counter incorrect/not updated	Invalid data received from another control module via the high speed CAN bus (comfort)	Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0055-87	Vehicle communication bus D - Missing message	Missing message from another control module via the medium speed CAN bus (body)	Using the Jaguar Land Rover approved diagnostic equipment, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0055-88	Vehicle communication bus D - Bus off	Medium speed CAN bus (body) circuit - Short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the medium speed CAN bus (body) circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0300-00	Internal Control Module Software Incompatibility - No sub type information	- Invalid message received from another module via CAN circuit - Incorrect module connected to CAN network	- Check the module connections for correct fitment, security, and serviceability. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTC and retest - Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the medium speed CAN bus circuits for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U1A00-87	Private communication network - Missing message	- Reduced touch screen functionality - Unexpected data has been received via the private CAN network - Private CAN network failure	- Refer to the electrical circuit diagrams and check the power and ground connections to the module. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, complete a CAN network integrity test. Refer to the electrical circuit diagrams and check the CAN network. Repair the wiring harness as necessary - Using the Jaguar Land Rover approved diagnostic equipment, identify the module(s) responsible for the erroneous CAN signals. Check these modules for related DTCs and refer to the relevant DTC index
U1A00-88	Private communication network - Bus off	Private CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the Jaguar Land Rover approved diagnostic equipment, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the private CAN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary
U2002-24	Switch - Signal stuck high	- Switch(s) stuck or continually pressed by customer - Integrated control panel failure	- Ensure no buttons are inadvertently being pressed. Using the Jaguar Land Rover approved diagnostic equipment, clear DTC and re-check, if DTC is still present suspect integrated control panel - Check and install a new integrated control panel as required
U2010-98	Switch Illumination - Component or system over temperature	- Control switch illumination has been disabled due to control module overheat - Integrated control panel failure	- Check for possible causes of the integrated control panel overheating. Check that the integrated control panel ventilation is not obstructed. Using the Jaguar Land Rover approved diagnostic equipment, check for internal electronic failure related DTCs and rectify as necessary. Allow the system to cool, clear the DTCs and check/monitor system for reoccurrence - If fault persists, check and install a new integrated control panel. Clear the DTCs and retest
U2105-03	Switch Pack Signal "A" - FM (Frequency Modulated) / PWM (Pulse Width Modulated) Failures	- Touch screen switchpack illumination circuit failure - Touch screen switchpack failure	- Refer to the electrical circuit diagrams and check the touch screen switchpack illumination circuit for short circuit to ground, short circuit to power, open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - If fault persists, check and install new touch screen switchpack. Clear the DTCs and retest
U2105-11	Switch Pack Signal "A" - Circuit short to ground	- Touch screen switchpack resistor ladder input circuit short circuit to ground - Touch screen switchpack failure	- Refer to the electrical circuit diagrams and check the touch screen switchpack resistor ladder input circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest - If fault persists, check and install new touch screen switchpack. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2105-13	Switch Pack Signal "A" - Circuit open	■ Touch screen switchpack circuit open circuit, high resistance ■ Touch screen switchpack failure	■ Refer to the electrical circuit diagrams and check the touch screen switchpack circuit between the integrated control panel and the touch screen switchpack for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ■ If fault persists, check and install new touch screen switchpack. Clear the DTCs and retest
U2105-29	Switch Pack Signal "A" - Signal invalid	■ Switchpack softkey held in (pressed by external object in contact with softkey) ■ Switchpack softkeys sticking or jammed ■ Touch screen switchpack failure	NOTE: NOTE: This DTC can be caused by pressing three buttons simultaneously ■ Check that no objects are pressing on the switchpack softkeys ■ Check for dirt or other contamination of switchpack softkeys and clean as necessary. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ■ If softkey operation cannot be resolved by external cleaning, check and install a new touch screen switchpack. Clear the DTCs and retest
U2105-2A	Switch Pack Signal "A" - Signal stuck in range	■ Switchpack softkey held in (pressed by external object in contact with softkey) ■ Switchpack softkey sticking or jammed ■ Touch screen switchpack failure	■ Check that no objects are pressing on the switchpack softkeys ■ Check for dirt or other contamination of switchpack/softkeys and clean as necessary. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ■ If softkey operation cannot be resolved by external cleaning, check and install a new touch screen switchpack. Clear the DTCs and retest
U2105-4A	Switch Pack Signal "A" - Incorrect component installed	■ The serial number of the touch screen switchpack does not match the serial number stored in the master module	■ Check the serial number of the touch screen switchpack is valid (as installed at the factory) ■ Check and install a new touch screen switchpack as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
U2105-54	Switch Pack Signal "A" - Missing calibration	■ Touch screen switchpack incorrect configuration ■ Touch screen switchpack failure	■ Reconfigure the touch screen switchpack using the Jaguar Land Rover approved diagnostic equipment, clear the DTC and retest ■ If fault persists, check and install a new touch screen switchpack. Clear the DTCs and retest
U2106-11	Switch Pack Signal "B" - Circuit short to ground	■ Touch screen switchpack resistor ladder input circuit short circuit to ground ■ Touch screen switchpack failure	■ Refer to the electrical circuit diagrams and check the touch screen switchpack resistor ladder input circuit for short circuit to ground. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ■ If fault persists, check and install new touch screen switchpack. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U2106-13	Switch Pack Signal "B" - Circuit open	■ Touch screen switchpack circuits open circuit, high resistance ■ Touch screen switchpack failure	■ Refer to the electrical circuit diagrams and check the touch screen switchpack circuits between the integrated control panel and the touch screen switchpack for open circuit, high resistance. Repair the wiring harness as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ■ If fault persists, check and install new touch screen switchpack. Clear the DTCs and retest
U2106-29	Switch Pack Signal "B" - Signal invalid	■ Switchpack softkeys held in (pressed by external object in contact with softkey) ■ Switchpack softkeys sticking or jammed ■ Touch screen switchpack failure	NOTE: NOTE: This DTC can be caused by pressing three buttons simultaneously ■ Check that no objects are pressing on the switchpack softkeys ■ Check for dirt or other contamination of switchpack/softkeys and clean as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ■ If softkey operation cannot be resolved by external cleaning, check and install a new touch screen switchpack. Clear the DTCs and retest
U2106-2A	Switch Pack Signal "B" - Signal stuck in range	■ Switchpack softkeys held in (pressed by external object in contact with softkey) ■ Switchpack softkeys sticking or jammed ■ Touch screen switchpack failure	■ Check that no objects are pressing on the switchpack softkeys ■ Check for dirt or other contamination of switchpack/softkeys and clean as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest ■ If softkey operation cannot be resolved by external cleaning, check and install a new touch screen switchpack. Clear the DTCs and retest
U2106-4A	Switch Pack Signal "B" - Incorrect component installed	■ The serial number of the touch screen switchpack does not match the serial number stored in the master module	■ Check the serial number of the touch screen switchpack is valid (as installed at the factory) ■ Check and install a new touch screen switchpack as necessary. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
U2106-54	Switch Pack Signal "B" - Missing calibration	■ Touch screen switchpack - Configuration incorrect ■ Touch screen switchpack failure	■ Reconfigure the touch screen switchpack using the Jaguar Land Rover approved diagnostic equipment. Clear the DTCs and retest ■ If fault persists, check and install a new touch screen switchpack. Using the Jaguar Land Rover approved diagnostic equipment, clear the DTCs and retest
U2300-54	Central configuration - Missing calibration	■ Car configuration file mismatch with vehicle specification	■ Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest
U2300-55	Central configuration - Not configured	■ Car configuration file mismatch with vehicle specification	■ Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest
U2300-56	Central Configuration - Invalid / incomplete configuration	■ Car configuration file mismatch with vehicle specification	■ Using the Jaguar Land Rover approved diagnostic equipment, check and up-date the car configuration file as necessary. Clear the DTCs and retest

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U3000-41	Control Module - General checksum failure	Checksum error, internal module failure	Using the Jaguar Land Rover approved diagnostic equipment, clear DTC and re-test. If DTC remains suspect the integrated control panel. Check and install a new integrated control panel as required. Refer to the warranty policy and procedures manual if a module is suspect
U3000-96	Control Module - Component internal failure	Integrated control panel internal failure	Using the Jaguar Land Rover approved diagnostic equipment, clear DTC and retest. If fault persists, check and install a new integrated control panel as required
U3003-62	Battery Voltage - Signal compare failure	Mismatch between the voltage at the integrated control panel and the voltage value broadcast on the CAN bus	Using the Jaguar Land Rover approved diagnostic equipment, check datalogger signal - ECU Power Supply Voltage (0xD11f) - and compare it to battery voltage. Refer to the electrical circuit diagrams and check the integrated control panel power and ground circuits for open circuit, high resistance