05FIQ-01

PROBLEM SYMPTOMS TABLE

HINT:

- Before performing verification listed in the table below, check the fuse and relay.
- Methods used to verify the cause of the problem are listed in order of probability in the verification column.

Display function

Symptom	Verification	See page
Pressing PWR switch does not turn on system.	1. "PRESSING POWER SWITCH DOES NOT TURN ON	05-66
	THE SYSTEM"	
	2. Power source circuit (radio and navigation assy)	05–1 <mark>0</mark> 2
	3. Replace radio and navigation assy	(1)
	1. "BLACK SCREEN (NO IMAGE APPEARS ON NAV-	05–67
	IGATION AND AUDIO SCREEN)"	
Black screen (no image appears on navigation and audio screen).	2. Dimmer signal circuit	05–111
	3. Power source circuit (radio and navigation assy)	05–102
	4. Replace radio and navigation assy	(1)
	1. "ILLUMINATION FOR PANEL SWITCH DOES NOT	05-68
Illumination for panel switch does not come on with TAIL switch	COME ON WITH TAIL SWITCH ON"	
on.	2. Dimmer signal circuit	05–111
	3. Replace radio and navigation assy	(1)
	1. "DISPLAY DOES NOT DIM (NIGHT SCREEN) WITH	05-69
Display does not dim (night screen) with TAIL switch on.	TAIL SWITCH ON"	
Display does not dim (night screen) with TAIL switch on.	2. Dimmer signal circuit	05–111
	3. Replace radio and navigation assy	(1)
Dower does not turn off (the corean remains on)	Power source circuit (radio and navigation assy)	05-102
Power does not turn off (the screen remains on).	2. Replace radio and navigation assy	(1)
Panel switch does not function.	1. "PANEL SWITCH DOES NOT FUNCTION"	05-71
	1. "TOUCH PANEL SWITCH DOES NOT FUNCTION"	05-71
Touch panel switch does not function.	2. Power source circuit (radio and navigation assy)	05-102
	3. Replace radio and navigation assy	(1)
	1. "DISPLAY PANEL DOES NOT OPEN, TILT, OR TILTS	05-72
Display panel dags not onen tilt av tilta imprenent	IMPROPERLY"	
Display panel does not open, tilt, or tilts improperly.	2. Power source circuit (radio and navigation assy)	05-102
	3. Replace radio and navigation assy	(1)
Carana in distanted	Power source circuit (radio and navigation assy)	05-1 <mark>0</mark> 2
Screen is distorted.	2. Replace radio and navigation assy	(1)
Screen flicker or color distortion.	1. "SCREEN FLICKER OR COLOR DISTORTION"	05-73
	2. Power source circuit (radio and navigation assy)	05-102
	3. Replace radio and navigation assy	(1)

Audio function

Symptom	Verification	See page
No sound can be heard from speakers (audio is mute).	1. "NO SOUND CAN BE HEARD FROM THE SPEAK-	05-75
	ERS (AUDIO IS MUTE)"	
	2. Speaker circuit	05-113
	3. Power source circuit (radio and navigation assy)	05–1 <mark>0</mark> 2
	4. Replace radio and navigation assy	(1)
Radio broadcast cannot be received (poor reception).	1. "RADIO BROADCAST CANNOT BE RECEIVER	05-76
	(POOR RECEPTIONS)"	
	2. Power source circuit (auto antenna control relay)	05-1 <mark>0</mark> 4
	3. Auto antenna control relay signal circuit	05-11 6
	4. Replace antenna assy	(3)
	5. Replace radio and navigation assy	(1)

CD cannot be inserted/played or CD is ejected right after insertion.	"CD CANNOT BE INSERTED/PLAYED OR CD IS EJECTED RIGHT AFTER INSERTION"	05–78
	Power source circuit (radio and navigation assy)	05–1 <mark>0</mark> 2
	Replace radio and navigation assy	(1)
CD cannot be ejected.	1. "CD CANNOT BE EJECTED"	05-80
	Power source circuit (radio and navigation assy)	05–1 <mark>0</mark> 2
	3. Replace radio and navigation assy	(1)
Abnormal noise occurs.	1. "ABNORMAL NOISE OCCURS"	05-81
	2. Power source circuit (radio and navigation assy)	05–1 <mark>0</mark> 2
	3. Replace radio and navigation assy	(1)
20	1. "CD SOUND SKIPS"	05-82
CD sound skips.	Power source circuit (radio and navigation assy) Replace radio and navigation assy "CD SOUND SKIPS" Replace radio and navigation assy	(1)
Poor sound quality in all modes (low volume).	1. "POOR SOUND QUALITY IN ALL MODES (LOW VOL-	05–84
	UME)"	
	2. Power source circuit (radio and navigation assy)	05-1 <mark>0</mark> 2
	3. Replace radio and navigation assy	(1)

Navigation function

Symptom	Verification	See page
Map disc cannot be inserted.	1. "MAP DISC CANNOT BE INSERTED"	05-85
	2. Power source circuit (radio and navigation assy)	05-1 <mark>0</mark> 2
	3. Replace radio and navigation assy	(1)
Map disc cannot be ejected.	1. "MAP DISC CANNOT BE EJECTED"	05-86
	2. Power source circuit (radio and navigation assy)	05-1 <mark>0</mark> 2
	3. Replace radio and navigation assy	(1)
Vehicle position mark deviates greatly.	1. "VEHICLE POSITION MARK DEVIATES GREATLY"	05-87
	2. Replace GPS antenna assy	(2)
	3. Replace radio and navigation assy	(1)
Cursor or map rotates when vehicle is stopped.	1. "CURSOR OR MAP ROTATES WHEN VEHICLE IS	05-89
	STOPPED"	
	2. Replace radio and navigation assy	(1)
	1. "VEHICLE POSITION MARK IS NOT UPDATED"	05–90
Vehicle position mark is not updated.	2. Replace map disc	-
	3. Replace radio and navigation assy	(1)
	1. "CURRENT POSITION DISPLAY DOES NOT AP-	05–91
Current position display does not appear.	PEAR"	
	2. Replace map disc	-
	3. Replace radio and navigation assy	(1)
GPS mark does not displayed.	1. "GPS MARK IS NOT DISPLAYED"	05-92
	2. Replace GPS antenna assy	(2)
	3. Replace radio and navigation assy	(1)
Voice guidance does not function.	1. "VOICE GUIDANCE DOES NOT FUNCTION"	05-94
	2. Speaker circuit	05-11 <mark>3</mark>
	3. Replace map disc	-
	4. Replace radio and navigation assy	(1)
	1. "MAP DISPLAY INCOMPLETE"	05-97
Map display incomplete.	2. Replace map disc	_
	3. Replace radio and navigation assy	(1)
Route cannot be calculated.	1. "ROUTE CANNOT BE CALCULATED"	05-98
	2. Replace map disc	_
	3. Replace radio and navigation assy	(1)

- (1): See pub. No. RM915E, page 67-4.
- (2): See pub. No. RM915E, page 67-17.
- (3): See pub. No. RM915E, page 67-14.