
# CD SOUND SKIPS

#### INSPECTION PROCEDURE

### 1 DISC CLEANING



- (a) Disk cleaning
  - (1) If the disk gets dirty, clean the disk by wiping the surface from the center to outside in the radial directions with a soft cloth.

#### NOTICE:

Do not use a conventional record cleaner or anti-static preservative.

Standard: malfunction disappear.

ок

**DISC DIRTY** 

NG

## 2 REPLACE CD WITH ANOTHER AND RECHECK

- (a) Replace the CD with another and recheck.
  - (1) Check the installation condition of the radio receiver assembly.

Standard: malfunction disappear.

OK > CD FAULTY

NG

## 3 CHECK WHEN THIS HAPPENS

- (a) Check then this happens.
  - Check that in what condition (place) noise occurs.

Standard: Driving on the bumpy road.

OK Go to step 5

NG

# 4 | COMPARE IT WITH ANOTHER CAR OF SAME MODEL

- (a) Compare it with another vehicle of the same model.
  - (1) Compare with the vehicle of the same type which does not have a trouble to see if there is any difference in the condition of trouble occurrence.

Standard: No difference found.

OK SETTING

NG

## 5 CHECK OF RADIO RECEIVER ASSEMBLY INSTALLATION

- (a) Check of radio receiver assembly installation.
  - (1) Check the installation condition of the radio receiver assembly.

Standard: Installed properly.

NG INSTALL THE RADIO RECEIVER ASSEMBLY PROPERLY

OK

## 6 DID THE TEMPERATURE IN THE CABIN CHANGE RAPIDLY?

- (a) Did the temperature in the cabin change rapidly?
  - (1) Check whether or not the rapid temperature change occurred in the cabin.

Standard: The rapid temperature change occurred.

Reference:

The rapid temperature change creates condensation inside the CD player, which may disable playing CD.

OK CONDENSATION DUE TO TEMPERATURE CHANGE(LEAVE IT AS IT IS FOR A WHILE BEFORE USING)

NG

**CHECK AND REPLACE RADIO RECEIVER ASSY**