05620_01

CD SOUND SKIPS

INSPECTION PROCEDURE

- 1 REPLACE CD WITH ANOTHER AND RECHECK
- (a) Replace the CD with normal one and check it the same trouble occurs again.
 - Check the installation condition of the radio receiver assembly.

Standard: The operation returns to be normal.

OK CD FAULTY

NG

2 CHECK WHEN THIS HAPPENS

- (a) Check when this happens.
 - Check that in what condition (place) sound skips.

Cause: Driving on the bumpy road.

OK Go to step 4

NG

3 COMPARE IT WITH ANOTHER CAR OF SAME MODEL

- (a) Compare it with another vehicle of the same model.
 - (1) Compare with the vehicle of the same type which does not have a trouble to see if there is any difference in the condition of trouble occurrence.

Standard: No difference found.

OK SETTING

NG

4 CHECK OF RADIO RECEIVER ASSEMBLY INSTALLATION

- (a) Check of the radio receiver assembly installation.
 - (1) Check the installation condition of the radio receiver assembly.

Standard: Installed properly.

NG INSTALL THE RADIO RECEIVER ASSEMBLY PROPERLY

OK


5 DID THE TEMPERATURE IN THE CABIN CHANGE RAPIDLY?

- (a) Did the temperature in the cabin change rapidly?
 - (1) Check whether or not rapid temperature change occurred in the cabin.

Cause: Rapid temp. change.

Reference:

Rapid temperature change my cause condensation inside the CD player, which may affect its normal operation



NG

CHECK AND REPLACE RADIO RECEIVER ASSY