

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 67503

A general cargo ship that is carrying general cargo and/or container cargo

Vessel Name:	MANTA FATMA
IMO Number:	9604809
DOC Company:	Manta Denizcilik Nakliyat ve Ticaret Ltd Sti
Place of Inspection:	Turkey, Derince
Name of Inspector:	Fatih Gunes
Inspection Completion Date:	10/7/2025 12:00:00 AM
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

Number of Findings: 11

Section 2: Certification and Personal Management

2.1 Is the latest Class Survey Status available and are all statutory certificates listed in the Class Survey Status valid, and is the vessel free of condition of class or significant recommendations? (M)

Findings: As per the latest class survey status the vessel have one class condition.

Section 3: Navigation

3.18 Can the master and watch-keeping officer demonstrate a familiarity with the use of ECDIS? (V)

Findings: The officer was not familiar with company SCAMIN procedures and the the scamin selection menu in the ECDIS.

Section 4: ISM System

4.42 Are the lifebuoys, related equipment, and pyrotechnics in good working order? (V)

Findings: One LTA unit was observed to be trigger not connected to the rocket and at the transportation mode.

Section 6: Ship's Structure

6.4 Are the access points to cargo holds, ballast tanks, and void spaces including vertical ladders, spiral ladders, rungs, stations, and platforms being maintained and in good order? (V)

Findings: The first two rungs of the fore peak tank access ladders were observed to be wasted more than 25% of the original thickness.

Section 9A: Hatch Cover and Lifting Appliances

9A.5 Are the drain holes of coaming clean, the inboard coaming faces free from any vertical rust staining and are the non-return valves in good condition? (V)

Findings: Two drain valves non return valves on the No. 5 hold were observed to be frozen in open condition and no blank caps available.

9A.20 Is the machinery of the cargo crane, including controls in the operator's cab inspected, tested, and maintained as per manufacturer's recommendations? (V)

Findings: The No.4 cargo crane window viper was observed to be missing.

Section 10: Mooring Operations

10.5 Is there a procedure for testing the winch brake rendering setting and is it being tested regularly? (V & M)

Findings: The vessel completed the mooring winch rendering tests but the markings on the spindles were not correctly marked as no reference point marking for spindles were available .

10.18 Are the windlasses, anchors, locking bars and cables in good order, operating effectively and is their maintenance incorporated in the plan maintenance system? (V)

Findings: The port-side anchor winch stripper bar was observed to be bent.

Section 13: Machinery Space

13.19 Are engine exhausts and other hot surfaces effectively shielded against oil spray and are flanges and connections of flammable liquid pipelines adequately protected with guards and spray tape? (V)

Findings: No.1 auxiliary engine exhaust piping was observed to be with exposed section and the temperature was measured 250c at the exposed section. This was rectified before inspector left the vessel.

Section 14: General Appearance - Hull and Superstructure

14.1 Is the ship's hull clean, free of significant corrosion, extensive coating breakdown and marine growth? (V)

Findings: The port-side hull on the way of No.1 and No.5 ballast tanks were observed to be poor condition as the more than 20% of the area was coating break down and hard rusted.

14.5 Are all the watertight doors, weathertight doors, portholes, and wheelhouse windows maintained in good order? (V)

Findings: The engine control room, fire station and the air condition room fire does have observed with holding back arrangements and imo signs were missing.

Vessel's Master Name

EGE DONMEZ

Vessel's Master Email Address

mantafatma@skyfile.com

- ☒ By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:

A handwritten signature in black ink, appearing to be 'EGE DONMEZ', written over a horizontal line.

Inspector Name

Fatih Gunes

Inspector's Signature:

A handwritten signature in black ink, appearing to be 'FATIH GUNES', written over a horizontal line.

CONTACT US

If you're interested and would like to know more, get in touch with our team today.

 www.rightship.com

 dryinspections@rightship.com

 RightShip

MELBOURNE

 Level 8/ 550 Bourke Street,
Melbourne VIC 3000,
Australia

 +61 3 8686 5750

LONDON

 4th Floor, 6 Dowgate Hill,
London EC4R 2SU, United
Kingdom

 +44 203 872 5900

SINGAPORE

 20 Cecil Street, PLUS,
#13-06
Singapore 049705

 +65 3138 3855

HOUSTON

 Suite 140 14141
Southwest Freeway,
Sugar Land TX 77478,
United States of America

 +1 832 770 8200

MALTA

 The Tower, 3rd Floor,
Fortunato Mizzi Street,
Ir-Rabat Għawdex
VCT 2517, Malta