

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 72635

Vessel Type:	A bulk carrier that is carrying solid bulk cargo
Vessel Name:	STAR ASPIRATION
IMO Number:	9458767
DOC Company:	Charterwell Maritime SA
Place of Inspection:	Maputo
Name of Inspector:	Werner Van Der Merwe
Inspection Completion Date	02/May/2026
Operational Variant:	

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and responses to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

Number of Findings: 9

Inspected Item	Response	Finding description
4.2 Has a safety officer been appointed and adequately trained, onboard safety meetings held regularly and acknowledged by the vessel's manager, with feedback provided where necessary, and are safety inspections of the main deck, machinery space, accommodation and forecastle store conducted at regular intervals in accordance with the company's procedures, and are health, safety, and environmental hazards effectively identified? (V)	No	Safety inspections of the main deck, machinery spaces, accommodation, and forecastle store were not conducted at regular intervals, as no company procedure was in place for carrying out safety area inspections.
4.23 Has a sample of foam compound, applicable to both fixed and portable systems, been sent for regular testing and is evidence of satisfactory results available? (M)	No	Two 20 L containers of 3% AFFF compound stored at the upper deck entrance to the engine room were found to be stored on their side within the storage box, with evidence of leakage. Approximately half of one container and one-third of the second container had leaked, with an estimated 1–1.5 litres of foam compound accumulated within the foam applicator storage box.
5.25 Are the ballast pumping systems, including their associated instruments, controls, valves, pipework, and the control panel (including pressure gauges, draft gauges, and the remote control system), in good working order and is there recorded evidence of regular inspection? (V)	No	Tank level readings on the ballast system control computer were found to be inaccurate for the following tanks: topside tanks No. 1 port, No. 2 port, No. 4 starboard, and No. 5 starboard, as well as double bottom ballast water tanks No. 1 starboard, No. 2 port, and No. 3 starboard. In addition, the forward, midship, and aft draft and trim sensors were also providing incorrect readings.
9A.2 Is there a procedure in place for the safe operation and inspection of hatch covers and, has the	No	The Master and Chief Officer had completed generic hatch cover training for side-rolling hatch covers; however, neither had completed

Master/Chief Officer received appropriate training in hatch cover inspection and maintenance? (V)		type-specific training for the hatch covers fitted onboard the vessel. In addition, no training material was available onboard to supplement generic training with type-specific information relevant to the installed hatch covers.
9A.9 Are the side and cross-joint rubber seals in good condition? (V)	No	The hatch cover rubber on the starboard hatch cover at the aft end of No. 7 hold was found to have a permanent deformation of approximately 14 mm, extending across the full width of the hatch cover. In addition, the starboard side longitudinal rubber seals of the hatch cover were also found to have permanent deformation of approximately 14 to 16 mm. The No. 6 hatch cover rubber on the starboard side, forward/aft section, was found with the outboard edge of the rubber being pushed out of the retaining channel by approximately 20 mm, extending for approximately 8 metres from aft end towards the forward section of the hatch cover.
9A.22 Are the loose gears of lifting appliances clearly marked and are the certificates of the loose gears available and traceable on board? (V)	No	Three 16-ton chain blocks and various wire slings of differing safe working loads (SWLs) located in the engine room workshop were found without any corresponding test certificates available onboard.
10.4 Do mooring lines and mooring tails comply with industry guidelines and are they in good order? (M&V)	No	Two coils of mooring lines stored forward in the bosun's store were not secured on pallets and were found stowed directly on the deck.
14.2 Are the following permanent markings on the ship's hull, where applicable, plainly visible and painted in a contrasting colour? - The vessel's name - Port of registry - Load lines - Draft marks - Thruster warnings - Tug push points - IMO number - Bulbous bow mark (V)	No	The forward draft marks on the port bow were not clearly visible from approximately 11 meters to the waterline. The visibility of the draft marks was poor due to faded and eroded paint, rust staining, corrosion, and general wear of the hull surface.
15.9 Has the vessel's manager developed a policy and procedure addressing violence and harassment, including sexual harassment, bullying, and sexual assault, are the requirements of this policy being disseminated to the crew in their native language, and, are the crew familiar with the complaint procedure and how to report a complaint? (V)	No	The policy and procedure had not been disseminated to the crew in their native language.

Vessel's Master Name

Capt. M. FURKAN TEKIN

Vessel's Master Email Address

master.star.aspiration@gtships.com

☒ **By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.**

Vessel's Master Signature:



Inspector Name

Werner Van Der Merwe

Inspector's Signature:

A handwritten signature in black ink, consisting of a series of loops and a long horizontal stroke extending to the right, positioned above a solid horizontal line.