

RightShip Ship Inspection Program

List of Findings

RightShip Ship Inspection Report - 72698

Vessel Type:	A bulk carrier that is carrying grain cargo
Vessel Name:	CIHAN
IMO Number:	9622174
DOC Company:	Manta Denizcilik Nakliyat ve Ticaret Ltd Sti
Place of Inspection:	Dongjiakou
Name of Inspector:	Chunfeng He
Inspection Completion Date	14/Apr/2026
Operational Variant:	A bulk carrier that is carrying grain cargo-The cargo spaces had been fumigated at least once in the last 12 months

This is a list of Findings made during my inspection of your vessel, completed today. As the scope and scale of the inspection has been limited by time and operational constraints, this does not necessarily constitute a comprehensive list of all Findings on board.

A copy of this list together with a detailed inspection report will be submitted to RightShip, who will liaise directly with your owners / managers in due course. The following Findings should not be considered as a final or comprehensive list and RightShip reserves the right to add to or amend these Findings. If RightShip adds to or amends the list of Findings, they will advise the owner/ship's manager.

When RightShip reviews the inspection report, the vessel's manager and Master will be given the opportunity to provide comments and response to each Finding on the list.

This list of Findings does not constitute any warranty of the fitness or suitability of the vessel. Thank you for the cooperation and hospitality accorded to me by yourself and your crew.

Number of Findings: 16

Inspected Item	Response	Finding description
3.10 Is navigation equipment in good order? (V)	No	The performance monitor for the X-band radar was tested during inspection; however, no arcs—either one or two—as described in the operating manual were displayed on the radar screen. The magnetron for this radar was replaced by the ship's crew on 03 Apr 2026, and its accumulated operating hours are 243.4.
3.26 Is the Global Navigation Satellite System (GNSS) set to the correct Geodetic Datum, and are officers aware of the errors and alarms associated with GNSS? (V)	No	The antenna positions for both GPS receivers were not set up according to their physical positions; instead, the default value of zero was retained.
4.6 Is entry into and rescue from enclosed space training undertaken and are regular drills conducted? (V)	No	There was no scenario involving the rescue of a person from the cargo hold, including access to and retrieval from that space, in the ship's enclosed space entry and rescue drill.
4.7 Are procedures in place for the control of hot work, are they incorporated in the safety management system and is there documented evidence of compliance? (M)	No	The hot work permits outside the designated spaces were not reviewed prior to commencement by the vessel's management company.
4.13 Is a completed IMSBC/BLU Code ship/shore safety checklist for loading and unloading dry bulk carriers available and are the requirements of the checklist complied with? (M)	No	The ship–shore safety checklists did not include a stevedore familiarization section covering emergency procedures, nor did they verify compliance with cargo hold entry procedures at least once per watch.
4.38 Has the vessel been provided with ship-specific fire safety and SOLAS training manuals and operational booklets? (V)	No	The SOLAS training manual in the crew's smoking room was inspected and found to include the launching procedures for both the open-type lifeboat and the free-fall lifeboat; the ship's actual lifeboat is of the free-fall type.

Inspected Item	Response	Finding description
4.44 Does the vessel manager have documented procedures in place to control stevedore activities onboard by identifying potential hazards and implementing appropriate mitigation measures? (V)	No	1. There were no documented procedures in place to control stevedore activities onboard by identifying potential hazards and implementing appropriate mitigation measures. 2. All the access hatches to cargo holds Nos. 1 to 7 were signed and secured, but not padlocked, while the ship was discharging at this port.
5.19 Has a Garbage Management Plan been provided and is the Garbage Record Book (GRB) being correctly maintained? (V)	No	Two garbage drums filled with food waste were located in the meat room together with the ship's provisions. Such a location was not registered in the garbage management plan.
9A.2 Is there a procedure in place for the safe operation and inspection of hatch covers and, has the Master/Chief Officer received appropriate training in hatch cover inspection and maintenance? (V)	No	There was no a procedure and ensure that the clearance measurements of hatch cover components are carried out regularly every six months.
9A.12 Are the cross-joint seal retaining channels and the cross-joint compression bar straight, free of corrosion and damage, and are the channel supports and brackets in good condition? (V)	No	The seal-retaining channel plates and water-channel plates on the cross joints of hatch covers Nos. 1, 2, 3, 5, 6, and 7 were corroded, and worn and broken sections were observed on the upper water-channel plates.
10.4 Do mooring lines and mooring tails comply with industry guidelines and are they in good order? (M&V)	No	The mooring ropes were stowed directly on deck: one on cross deck H6/7, one on cross deck H1/2, and one on the fore deck.
10.5 Is there a procedure for testing the winch brake rendering setting and is it being tested regularly? (M&V)	No	The rendering points were marked on the fixed bracket of the winch brake, not on the screw rod, so that the marks would remain stationary regardless of changes in the tension of the mooring winch brake on all mooring winches onboard.
13.26 Is the workshop clean and tidy, and are the engine room workshop tools' protective guards, shields, and emergency stops in good condition? (V)	No	1. A 6 mm gap was measured between the tool rest and the grinding wheel on the grinder in the engine room workshop. 2. Cracks were observed at four locations on the welding machine cables in the workshop.
13.39 Is the main and emergency switchboard earth fault monitoring equipment operational with no earthing faults indicated? (V)	No	A low insulation resistance of 1 MΩ was observed on the ship's 440 V system at the switchboard in the engine control room.
14.2 Are the following permanent markings on the ship's hull, where applicable, plainly visible and painted in a contrasting colour? - The vessel's name - Port of registry - Load lines - Draft marks - Thruster warnings - Tug push points - IMO number - Bulbous bow mark (V)	No	The draft marks on the starboard bow between 14.3 m and 15.1 m, as well as those on the starboard stern between 13.7 m and 14.4 m, were rusted and not readable.
14.10 Are portable and fixed cargo lights used for illumination of cargo holds inspected regularly and maintained in good condition? (V)	No	The lamp holders and shades of the portable cargo lights are made of aluminum, which is conductive; therefore, they do not isolate crew members from electrical shock hazards, and the voltage at the ship's sockets is 220 V AC.

Vessel's Master NameSEVKI YANIK

Vessel's Master Email Addresscihan@skyfile.com

☒ By signing the list of Findings, I confirm a closing meeting has taken place and the inspector has informed me that, where not already transmitted, the list of Findings will be sent via internet email once connectivity is restored.

Vessel's Master Signature:



Inspector NameChunfeng He

Inspector's Signature:

