

PDK_STM_cmos28FDSOI_RF_mmW_6U1x_2T8x_LB Known Problems and Solutions

- This document is listing the known problems of the DK 1.2 and proposes solutions whenever they are available.
 - The Design Kit new features are described in the release notes document.
- Compliancy with ERC_MG_KIT@3.0-01
 - The following error is displayed in Virtuoso when STECCK is loaded after the Design-Kit:
 - ERROR: Invalid calibre version
 - \o current version: v2018.2 24.18
 - \o required version: 2017.3 29.23
 - \o -> calibre version for ERC verification flow is not OK. Expected version: 2017.3 29.23
 - You can safely ignore this error message.

■ Mosfet Matching:

The extraction of parameters (xpos/ypos) flattens the layout hierarchy during LVS. If matching simulations are not required, the switch "Do not extract XPOS/YPOS" is available to disable the extraction of such parameters if needed.

■ Monte-Carlo simulations:

- With ELDO ams>15.4 and DATAFLOW=1, a syntax problem in mc extract exists.
 - In order to ensure good Monte Carlo analysis results:
 - Don't use mc extract (as mcavg, mcstd etc.) in the same line, break down in several lines.
 Ex with DATAFLOW=1 (in MC Analysis Definition form / MC Advanced Output):
 - Syntax NOT TO BE USED
 - .EXTRACT mc label=Adids abs(sqrt(m*w*l)*(1e6)*100*mcstd(extract_intern_dids)/mcavg (extract_intern_ids))
 - .EXTRACT mc label=sigma_dioi abs(100*mcstd(extract_intern_dids)/mcavg(extract_intern_ids)

Syntax TO USE

- .EXTRACT mc LABEL=STD_extract_intern_dids mcstd(extract_intern_dids)
- .EXTRACT mc LABEL=AVG_extract_intern_ids mcavg(extract_intern_ids)
- .EXTRACT LABEL=Adids2
 abs(sqrt(m*w*l)*(1e6)*100*EXTRACT(STD_extract_intern_dids)/EXTRACT(AVG_extract_intern_ids))

- .EXTRACT label=sigma_dioi2 abs(100*EXTRACT(STD_extract_intern_dids)/ EXTRACT(AVG_extract_intern_ids))
- or set DATAFLOW=0 in MC Analysis Definition form / MC Advanced Output
- Nota bene: in ams 16.1 release, this compact syntax won't be allowed and it will lead to warning message: Warning 1053: COMMAND .EXTRACT: ADIDS is ignored. An .EXTRACT MC cannot contain multiple functions.
- Selection of statistical variations (global process and/or local mismatch)
 - The selection of the statistical variations involved during a monte-carlo analysis MUST be done using the following features of the models:
 - Use the stat corner for involving Global Process variations
 - Set the <family>_dev (ex: rvt_dev, eg_dev) parameters to 1 for involving Local Mismatch variations

The ArtistKit Setup Corners GUI helps you doing these selections

- Set the GLOBAL VARIATIONS to stat for all or some device families
- Set the LOCAL VARIATIONS to monte-carlo for all or some device families
- The selection of the statistical variations MUST NOT be done using the montecarlo analysis definitions of the simulators. So please do not use the following simulator statements:
 - Spectre
 - In stand-alone, always set the variations=all flag on the montecarlo analysis statement. Per default only process variations are involved.
 - From ADE-XL, in *Monte-Carlo* form, always keep the *Statistical Variations* field to **All** value



- Hspice
 - In stand-alone, do not use the .VARIATION Block Control Options and the Ignore_Global_Variation, Ignore_Local_Variations associated otpions.
 - From ADE-XL, in Monte-Carlo form, always keep the Statistical Variations field to All value (same as Spectre)
- Eldo
 - In stand-alone netlist, never set the VARY argument on the .MC command. Per default all statistical variations are involved.
 - From ADE-L, in *Choosing Analyses* **mc** form, always keep the *Apply Variations Using* field to **Both Device/Lot** value.



• From ADE-XL, in Monte Carlo form, always keep the Statistical Variations field to All value (same as spectre simulator).

Summary table

Simulator statistical variation selection	Corner Model settings	Matching model settings	Global contributions (process)	Local contributions (mismatch)
All	TT, SS, SFA,, USER (any corner except statmotherfab)	<family>_dev = 0 or mismatch = 0</family>	Worst-Case Corner	None
All	TT, SS, SFA,, USER (any corner except statmotherfab)	<family>_dev = 1 and mismatch = 1</family>	None	All
All	STATMOTHERFAB	<family>_dev = 0 or mismatch = 0</family>	All	None
All	STATMOTHERFAB	<family>_dev = 1 and mismatch = 1</family>	All	All

■ RF-MOS:

- o Number of gate fingers (n) parameter cannot be parameterized.
- DC Annotation on segmented simulation level takes into account a single transistor instance.
- o MOS RF devices are not supported within Cadence LDE flow yet.
- The "Add Labels (partial layout XL)" option in PLS GUI is only working with analog MOS, not with RF MOS

Other simulation items:

- Poly resistors: Inaccurate non-linearity modeling when sbar (series stripes) >1.
 - Workaround:
 - Use series resistors in schematic
 - Run Post-Layout Simulation for a correct modeling
- o LF noise corners in post-layout :
 - Models: SG and EG MOS transistors
 - The corners defined for the LF noise do not take into account the variation reduction due to the multiplicity of the devices in post-layout simulation because LVS cannot extract the mult instance parameter
- o Modeling inaccuracy of EGRVT PFET capacitances :

- Models: egpfet_acc, egvpfet_acc
- EG/EGV RVT PFET models do not simulate the Cg-ds capacitances around the threshold voltage inside the modeling accuracy tolerance of 5%.

Saturation current of RPO mosfets :

- The modeling of the RPO mosfets for the I/O applications are performed in the design-kit through the association of the mosfets accurate models with the corresponding unsalicided resistance (sblkndres/sblkpdres) models
- The correlation between the simulation and the measurement shows an under-estimation of the saturation current by 7%.

Wpe default values :

- Models: pfet_acc, eglvtnfet_acc, eglvtvnfet_acc, egpfet_acc, egvpfet_acc, pfet_rf, eglvtnfet_rf, eglvtvnfet_rf, pfet_rfseg, eglvtnfet_rfseg, eglvtvnfet_rfseg
- The default value of the models in pre-layout assumes no WPE effect whereas the P-cell adds Nwell layer at the minimum DRM distance.

o Modeling inaccuracy of LOD effect:

- Models: egnfet_acc, egvnfet_acc, eglvtpfet_acc, eglvtvpfet_acc, eglvtpfet_rf, eglvtvpfet_rf, eglvtpfet_rfseg, eglvtvpfet_rfseg
 - The models under-estimate the linear and saturation currents by 5% at small SA and SB values (<0.4um) for narrow-short devices (W<0.3um, L< 0.5 um)
- Models: eglvtnfet_acc, eglvtvnfet_acc, eglvtnfet_rf, eglvtvnfet_rf, , eglvtnfet_rfseg, eglvtvnfet_rfseg, egpfet_acc, egvpfet_acc
 - Inaccurate stress STI modeling when nf>1 in pre-layout mode for large L. Please use post-layout simulation to recover accuracy

Leakage in CMIM16acc :

- Models: cmim16acc, cmim16acc_acc, cmim16acc_sh, cmim16acc sh acc, cmim16acc 2p, cmim16acc 2p acc
 - The minimum leakage in CMIM16acc device is wrongly setup. We recommend to use the typical and maximum values

ESD models:

- Models: esdnfet_nova, esdegnfet_nova, esdvnpn_eg_nova, esdvpnp_eg_nova, esdndsx_eg_nova, esdvnpn_nova, esdvpnp_nova, esdndsx_nova, esdnfet, esdegnfet, esdvnpn_eg, esdvpnp_eg, esdndsx_eg, esdvnpn, esdvpnp, esdndsx
 - Non-veriloga models are dedicated to SST simulation using Spectre or GoldenGate only. Veriloga models are strongly recommended for other simulators and other simulation analysis.
 - The SOA is implemented for the non-Verilog-a models

o ESD Diodes:

- Models: esdvnpn_eg_va, esdvpnp_eg_va, esdvnpn_va, esdvpnp_va, esdndsx_va
 - Models were historically developed for ESD diodes PCELLs
 - Reference layouts for diodes are now the ones from ESDKIT library and ESD models are optimized for best describing diodes with these layouts.

 Diodes layouts have diverged from PCELLs, and there might now be a miscorrelation between models and PCELLs for ESD behaviour.

o ESD Low Cap:

- Models: esd_lowcap
 - In AC signals, voltage dependence of capacitance is not accurately modeled. Model to measurement error is overestimated, by up to 40% at 1V.
 - Current is underestimated in Spectre / Hspice versus Eldo, especially for low temperature.
- ESD Ultra Low Cap EG:
 - Current is underestimated in spectre and hspice vs eldo, especially for low temperatures
- O Inductors and Varactors :
 - R(\$freq) expression is not considered during transient simulation with spectre. Issue has been reported to Cadence (CCR1769638).
- VNPN Bipolar:
 - Collector current oscillates around the correct behavior (reproduced with AFS and ADS) at high frequency (F > 1 GHz).
- o SG & EG Varactors:
 - Access resistance is overestimated at lower frequency in AFS and ADS.
 Support of voltage dependent resistors is missing in these simulators.
- Ageing models are available in Eldo, Hspice and Spectre :
 - Ageing models for xa –hspice are not provided in this PDK
- Due to R3 implementation issue in Goldengate, flicker noise for discrete resistors is 10% under-estimated (Golden Gate 4.10.0). This issue has been reported to Keysight
- Missing parameters in DCOP Back-Annotation with GoldenGate for utsoi 2.20 models (egnfet acc,lvtnfet rf):
 - –Id, -Is, -Ig, -Vdsat_marg, -vdsat, -vth_drive, -FT, -Dtsh
- Minor problems identified during hspice soa validation :
 - With hcdgated/esdndsx_eg, NF1 rule is not properly detected.
 - With eglvt fet family, possible bad detection on MO4 rule, further analysis on-going
 - With rvt pfet_rf NF1 rule is not properly detected.

Calibre DRC:

- MTFlex run cannot start with LSF (whereas it does in MT with LSF) or when CI was launched from Virtuoso (whereas it does when directly launched from a terminal).
 - Workaround: Set this environment variable (supported by any Calibre release) as follows: CALIBRE_CI_REMOTE_COMMAND_USE_BASH 1
- PVS DRC is not supported in this PDK release
- LVS:

- When defining mconbot == mcontop == (3 or 5) with shielded MOM capacitor, the psub pin is considered as NWELL, and so is the same as shap.
 - To achieve correct LVS, connection of psub to shap is required
- Lvsres devices on M1, M2 or M3 are not extracted for PEX flows over esd devices (ie, under MKR_esd_local or ESDIMP_dg or ESD;CDM or ESD;HBM layers).
- Transistors: nfing comparison (when enabled) is not working when parallel reduction if disabled (HD tickets #83421, #8359)

General PEX:

 Please note that stack description for PEX tools (StarRCXT and QuantusQRC) is not fully aligned on DRM description regarding passivation layers above Alucap (AP). This is considered negligible for common PEX applications. EMAG tools (Momentum, EMX) are fully aligned on DRM description in order to provide the best-in-class accuracy for electromagnetic simulations of RF structures.

■ QRC:

- The following warnings are expected during QRC extraction and can be ignored:
 - WARNING (CAPGEN-41475): Via layer 'V1FILL' resistance value is <= 0.
 - Ignoring via definition in p2lvsfile, via will be shorted
 - WARNING (CAPGEN-41475): Via layer 'V2FILL' resistance value is <= 0.
 - Ignoring via definition in p2lvsfile, via will be shorted
 - · ...

■ EMX:

- With default settings, performing EM simulations on a MOM topology is not accurate, since there are many fingers of metal which have a theoretical rectangular shape, which is not the real life in process (shapes non manhattan, OPC and so on ...).
- o It is not possible to define a conformal layer in the proc file.
 - Workaround: Conformal layer are approximated by a planar layers in the proc files.
 - For the cmim description, an equivalent dielectric mim layer thickness is re-computed and defined in the proc file.
- Description of resistivity of M1 & Mx layers are not fully aligned with latest DRM values. It is considered negligible.


■ EMIR:

 Ipeak values in EMIR tools (Totem, Voltus, CustomSimRA) are not aligned with latest 28FDSOI Design-Rule Manual


■ Virtuoso Library:

Update PCell issue when changing ctkrev to previous version 1_0_RF. Reopening 1_0_RF designs is working properly and updating to 1_1_RF ctkrev is also correct. But when changing back to previous 1_0_RF version, there is a pcell eval failed error with following message: "Pcell does not exist in version "1_0_rf".


- Workaround: force ctkrev device parameter in CIW (or with a skill script) to 1_0_RF.
- Some warnings and errors are displayed in CIW during Virtuoso due to a setup issue with AFS simulator. They can be ignored.
 - WARNING (ADE-5033): Cannot find the environment variable 'ignoreToLoadComponentsString' for tool 'afs.envOpts'.
 - Its internal default value will be used.
 - WARNING (ADE-5034): Unable to access the default environment variables in the simulator's
 - global .cdsenv file ('<your_install_dir>/tools/dfll/etc/tools/afs/.cdsenv')
 - because the file is missing or out-of-date. Till this problem exists, internal
 - default values will be used for these environment variables during this session.
 - *WARNING* envGetVal: Could not find variable 'nport_default_passivity'
 - in tool[.partition] 'afs.opts'.
 - ERROR (ADE-5007): Variable 'nport_default_passivity': Invalid value specified. Value should be a string.
- Multiplicity is not working with VXL for EDMOS
- In order to avoid unexpected netlisting issues due to a known Virtuoso limitation, the change of device name in symbol property and in Find&Replace is not allowed anymore.
 - Work-around: Use the dedicated "Schematic Cell Replacement" utility available from Right-Click Mouse on schematic
- Standard vias 's' are not available when TAFKit is loaded in the environment. By default, via constraint group is "VirtuosoDefaultSetup" (same as wire) then available vias are:



Available vias are now the following ones:



- CreateVia seems to give bad number of contacts with large spacing of arrays (example DRM rule 2x51d). This is the correct behavior of Virtuoso.
 - If you select the property of the via, then "Edit Cut Pattern" > "Manual Edit", you will see the description of the array of via.



- In this example, matrix 7x7 is requested, but due to DRM rule spacing of large array of via (example 2x51d), 2 columns of via are removed from the matrix.
- For all resistors, in order to remap the old parameter 'm' (multiplicity) on 'pbar' (parallel stripes), both parameters 'ser' and 'pbar' can be at the same time more than 1 only in schematic views. Then if you create a layout using the command "Generate all from source", as the pcell cannot support 'ser' and 'pbar' both more than 1, the pcell is drawn with "pbar=1"
 - The parameters 'ser' and 'pbar' should be both more than 1 only when you migrate a previous design with a multiplicity different than 1. With a new instance, we strongly recommend to have one of 'ser' or 'pbar' equal to 1
- Gate spacing has no effect on computation of source and drain areas (as/ad)
 - Workaround: Designer can modify the as/ad values according to its design using "Drain/Source Contact Selection = user" or rely on Post-Layout Extraction
- When opening an old design in DK 2.7 or 2.7.a, some pcells could change: it is possible that your original design is not preserved. This is due to the change of pcell code from MGEN (DK 2.5 and before) to skill (DK from 2.7).
 - Workaround: If you need to preserve your design, run the procedure UpdatePcell with ctkrev version 2.5.
- Layers unsupported in metal stack still have type "cut" in order to keep the cutsizes in the layer map table. In this way we are able to streamOut existing designs containing these eventual layers, but some warnings can appear during streamOut.
- Some width and area rules are not respected on devices. Here is the list of rules which could be flash on some devices :
 - NGATE.B.1, NGATE.B.3, NW.EN.2, NW.EX.1, PWB.W.1, FD_GEN.5, PLDDSOI.B.2, NLDDSOI.B.3, HSSOI.W.1, HSSOI.EN.1.2, HSSOI.EN.4.1, GRB_BH03, GRB_PH03, GRB_BV03, GRB_CV03, GRB_XW03, GRB_LW03, GRB_BF01, GRB_BF03, GRB_BN03, GRB_BP03, GRB_MY01, GRB_MY03, GRB_N301, GRB_NW01, GRB_NW03, GR51, GR51a, GR101a, GR101aa, GRLVT10_noNW, GRLVT10_NW, GRRVT10_noNW, GRRVT10_NW, GR351a, GR250, GR251a, GR260a, GREG11a, GREG21, GREG30, GREG34, GREG260, GR3T02, GR3T18, GR3T18b, GR501a, GR501aSE, GR501d, HSSOI.A.1, HSSOI.EX.11, EGLVT.EX.2
 - Workaround: Designers have to extend those layers or simply connect the device in metal to remove the corresponding rule.
- Some width and area rules are not respected on techfile vias. Here is the list of rules waived per default standards vias :
 - GRB_BH03, GRB_PH03, GRB_BF01, GRB_BF03, GRB_BN03, GRB_BP03, GRB_MY01, GRB_MY03, GRB_NW01, GRB_NW03, GR51, GR51a, GR101a, GR101aa, GR351a, GR250, GR251a, GR209_or, GR2x01a_B1, GR2x01a_B2, GR8x01a_IA, GR8x00b_IB, GR8x01a_IB, GR999aa_BP, GR999aa_NW, GR999aa_VV, GR999aa_RX, GR999aa_PC, GR999aa_M1, GR999aa_M2, GR999aa_M3, GR999aa_M4, GR999aa_M5, GR999aa_M6, GR999aa_B1, GR999aa_B2, GR999aa_IA, GR999aa_IB, GR999aa_LB, GR999aa_CA, GR999aa_V1, GR999aa_V1BAR, GR999aa_V1LRG, GR999aa_V2, GR999aa_V2BAR, GR999aa_V2LRG, GR999aa_V3, GR999aa_V3BAR, GR999aa_V3LRG, GR999aa_V4LRG, GR999aa_V5, GR999aa_V5, GR999aa_V5LRG, GR999aa_W0, GR999aa_W1, GR999aa_XA, GR999aa_YZ, GRGUARDEDG, GR501a,

GR501aSE, GR501d, GR601a_M2, GR601aSE_M2, GR601a_M3, GR601aSE_M3, GR601a_M4, GR601aSE_M4, GR601a_M5, GR601aSE_M5, GR601a_M6, GR601aSE_M6, ID.IP.2, PWB.W.1, LUP.D.1.2, FC44S.R.2, PLDDSOI.B.2, NLDDSOI.B.3, HYBRID.A.1, HYBRID.R.1, DTPC.R.2, ID.MPW.1, ID.BEOL.1, ST_268b_FD, EMET.DEN.1, EMET.DEN.2, EMET.DEN.3, EMET.DEN.4, EMET.DEN.5, EMET.DEN.6, EMET.DEN.7, EMET.DEN.8, EMET.DEN.9, EMET.DEN.10, EMET.DEN.11, EMET.DEN.12, RX.DEN.1, PC.DEN.1, M1.DEN.1, M2.DEN.1, M3.DEN.1, M4.DEN.1, M5.DEN.1, M6.DEN.1, B1.DEN.1, IA.DEN.1, IB.DEN.1, LB.DEN.1, DV.DEN.1

- Workaround: Designers have to stretch all requested layers.
- For mosfet core with small gate length, the DRC requires poly dummies on both side of the gate, rule (ST_105_or). But dummies are not automatic activated by callbacks.
 - Workaround: Designers have to activate the parameter "ACLV PC fill" with option Both. The Pcell will draw PC dummies on both side of the gate.
- Egncap/Egpcap: When designer selects "Default" button, capacitance value depletion is reset to nil
 - Workaround: value is re-computed when some other parameters are changed
- Automatic routing with VSR does not respect the minimum MLAST enclosure on W0 (rule ST_2x60_or).
 - The rule 2x60f, with smaller enclosures, is used instead.
 - The issue is confirmed by Cadence, we are waiting for the CCR resolution.
 - Workaround: Modify the enclosure with via options.
- Warning during EM/IR TOTEM simulation
 - The following warnings still appears during TOTEM simulation:
 - WARNING(TEC-126): Missing Via definition between metal layer: IA and HKBOTMIMD!
 - WARNING(TEC-126): Missing Via definition between metal layer: HKBOTMIMD and HKTOPMIMD!
 - Indeed, these vias are not present in the EM techfiles and the connectivity is assumed by LVS.
 - So there is no issue during the simulation, these warnings can be waived and they will be discussed with ANSYS for removal.
- Due to a limitation in Virtuoso, Fluid guardrings drawn with wrap mode around mos fets are not DRC clean.
 - GRSE3, GR352, GR352a, GREG207, NLDDSOI.B.1.2, NLDDSOI.B.2, PLDDGO2.B.1.1, PLDDGO2.B.1.2, HSSOI.D.12
 - Workaround: Use path or rectangle modes.
- Some rules are not respected on techfile vias, they are considered as fixed in design :
 - GRB_BF03, GRB_NW03, GR51, GR51a, GR101a, GR101aa, GR351a, GR251a, GRCABAR.R.1, GR204_or, GR209_or, GR2x01a_B1, GR2x01a_B2, GR2x51d_W0, GR2x93_W0BAR, GR2x51d_W1, GR2x93_W1BAR, GR8x01a_IA, GR8x01a_IB, GR501a, GR501aSE, GR501d, GR551_V1LRGd, GR553q2_V1, GR551_V2LRGd, GR553q2_V2, GR551_V3LRGd, GR553q2_V3, GR551_V4LRGd, GR553q2_V4, GR551_V5LRGd, GR553q2_V5, GR601a_M2,

GR601aSE_M2, GR601a_M3, GR601aSE_M3, GR601a_M4, GR601aSE_M4, GR601a_M5, GR601aSE_M5, GR601a_M6, GR601aSE_M6, ID.IP.2, ID.MPW.1, LUP.D.1.2, RX.DEN.1, PC.DEN.1, M1.DEN.1, M2.DEN.1, M3.DEN.1, M4.DEN.1, M5.DEN.1, M6.DEN.1, B1.DEN.1, B2.DEN.1, IA.DEN.1, IB.DEN.1, LB.DEN.1, DV.DEN.1, EMET.DEN.6, EMET.DEN.7, FC.R.2.V1, FC.R.2.V2, FC.R.2.V3, FC.R.2.V4, FC.R.2.V5, FC.R.2.W0, FC.R.2.W1, ST_8x93_YZ, ST_8bx93, ST_LB93, FDSOI.R.1, PLDDSOI.B.2, NLDDSOI.B.3, HYBRID.A.1, HYBRID.R.1, DTPC.R.2, ID.BEOL.1, CA.EX.1, ST_268b_FD, ST_B_BN03, ST_B_BN07, ST_B_BP03, ST_B_BH03, ST_B_PH03

- Workaround: stretch all requested layers.
- Routing done with techfile is not always DRC clean.
 - Workaround: Run DRC as soon as possible. Automatic routing is different from a run to another, so you can run several times.
- All mos types: fets, sram, ED, RF, esd: Parameters ps and pd cannot be parametrized
- List of known DRC violations in pcells. Most of these violation can be cleaned during design integration :

Device	DRC error	configuration
hlvtnfet_b		
hlvtnfetnp		
hlvtnfet		
hlvtpfet_b		
hlvtpfet		1 finger , small length , pc dummies and CA with 96nm
hlvtpfettw	ST_102_or	<pre><gatespacing 114nm<="" =<="" pre=""></gatespacing></pre>
lvtnfet_b		
lvtnfetnp		
lvtnfet		PC enclosed area for small size of device and when top
lvtpfet_b	GR101b	and bottom gate contacts.
lvtpfet		
lvtpfettw		
nfet_b		
nfet		
nfettw		
pfet_b		
pfetnp		
pfet		
egnexti		
	FDSOI.R.1	
	GR3T18	
egpext	GR3T18b	
	NWED.EN.1	

	-	1
egpfet		
egpfet_b		
egpfetnp		
egvlvtnfet		
egvlvtnfetnp		
egvlvtnfet_b		
eglvtpspfet_b		
eglvtnfet_b		
eglvtnfetnp		
egvpfet		
egvpfet_b		
egvpfetnp		
egvnfettw		
egvnfet		
egvnfet_b	GREG207	
esdlvtnfet_fdsoi	B_OP03	
	SB729a	
esdlvtpfet_fdsoi	B OP03	
	SB729a	
esdpfet_fdsoi	B_OP03	
	SB729a	
esdnfet_fdsoi	B_OP03	
	SB729a	
esdvpnp	604d_{M2-M3}	
esdvnpn	604e_{M2-M3}	
esdndsx	GR604d_{M2-M3}	
	GR604e_{M2-M3}	
	GR504c1/c2/c3	
	GR504d	
	GR504e	
esdndsx_eg	GR604c1/c2/c3_{M	
esdvnpn_eg	2-M3}	
esdvpnp_eg	GR604d{M2-M3}	
	GR604e{M2-M3}	
	I_DUM.DEN.2.2_{M	
ind_hq_6U1x_2T8x_LB	2-M6/IA}	
	I_DUM.DEN.4.2_IB	
	I_DUM.DEN.2.2_{M	
ind_lohq_6U1x_2T8x_LB	2-M6/IA}	
	I_DUM.DEN.2_{M2-	
	M6/IA/IB}	
	I_DUM.DEN.2_{M2-	default
ind Joha high next Cliff.	M6IA/IB}	
ind_lohq_high_perf_6U1x_	I_DUM.DEN.2.2_{M	
2T8x_LB	2-M6/IA}	
	I_DUM.DEN.4.2_IB	
	I_DUM.DEN.2.2_{M	
inddif_hq_6U1x_2T8x_LB	2-M6/IA}	
	I_DUM.DEN.4.2_IB	
		I .

	I_DUM.DEN.2.2_{M	
inddif_lohq_6U1x_2T8x_LB	2-M6/IA}	
	I_DUM.DEN.2_{M2-	
	M6/IA/IB}	
	I_DUM.DEN.2_{M2-	
inddif loba bigh porf 611	M6IA/IB}	
inddif_lohq_high_perf_6U 1x_2T8x_LB	I_DUM.DEN.2.2_{M	
1X_210X_EB	2-M6/IA}	
	I_DUM.DEN.4.2_IB	
	2x61	Top metal connection=7
cmom_5U1x_2T8x_LB_sh	2x60	
cmom_5U1x_2T8x_LB_2p	555j	
	611	
cmom_6U1x_2T8x_LB_sh		
cmom_6U1x_2T8x_LB_wo_		
via_sh	MOM.D.5.or	
cmom_6U1x_2U2x_2T8x_L		
B_sh		
cmom_6U1x_2U2x_2T8x_L		
B_wo_via_sh		
mesh	GR8x60a_YX	

Contact Information

<This section contains information on how the users can contact the provider. If link to an application is given for example, CAD HelpDesk, guiding steps should be provided for selecting the relevant category.>

For more information about this product/IP/Library or any problems or suggestions, please contact **HELPDESK** (http://col2.cro.st.com/helpdesk).

Non-ST users, please contact the respective Customer Support.



Please Read Carefully:

Information in this document is provided solely in connection with ST products. STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, modifications or improvements, to this document, and the products and services described herein at any time, without notice.

All ST products are sold pursuant to ST's terms and conditions of sale.

Purchasers are solely responsible for the choice, selection and use of the ST products and services described herein, and ST assumes no liability whatsoever relating to the choice, selection or use of the ST products and services described herein.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted under this document. If any part of this document refers to any third party products or services it shall not be deemed a license grant by ST for the use of such third party products or services, or any intellectual property contained therein or considered as a warranty covering the use in any manner whatsoever of such third party products or services or any intellectual property contained therein.

UNLESS OTHERWISE SET FORTH IN ST'S TERMS AND CONDITIONS OF SALE ST DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY WITH RESPECT TO THE USE AND/OR SALE OF ST PRODUCTS INCLUDING WITHOUT LIMITATION IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE (AND THEIR EQUIVALENTS UNDER THE LAWS OF ANY JURISDICTION), OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

UNLESS EXPRESSLY APPROVED IN WRITING BY TWO AUTHORIZED ST REPRESENTATIVES, ST PRODUCTS ARE NOT RECOMMENDED, AUTHORIZED OR WARRANTED FOR USE IN MILITARY, AIR CRAFT, SPACE, LIFE SAVING, OR LIFE SUSTAINING APPLICATIONS, NOR IN PRODUCTS OR SYSTEMS WHERE FAILURE OR MALFUNCTION MAY RESULT IN PERSONAL INJURY, DEATH, OR SEVERE PROPERTY OR ENVIRONMENTAL DAMAGE. ST PRODUCTS WHICH ARE NOT SPECIFIED AS "AUTOMOTIVE GRADE" MAY ONLY BE USED IN AUTOMOTIVE APPLICATIONS AT USER'S OWN RISK.

Resale of ST products with provisions different from the statements and/or technical features set forth in this document shall immediately void any warranty granted by ST for the ST product or service described herein and shall not create or extend in any manner whatsoever, any liability of ST.

ST and the ST logo are trademarks or registered trademarks of ST in various countries.

Information in this document supersedes and replaces all information previously supplied.

The ST logo is a registered trademark of STMicroelectronics. All other names are the property of their respective owners.

© 10/18/18 STMicroelectronics - All rights reserved

STMicroelectronics group of companies

Australia - Belgium - Brazil - Canada - China - Czech Republic - Finland - France - Germany - Hong Kong - India - Israel - Italy - Japan - Malaysia - Malta - Morocco - Philippines - Singapore - Spain - Sweden - Switzerland - United Kingdom - United States of America

www.st.com