

(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 <u>Model Answer</u> Page No: 1 of 24

Important Instruction to examiners:

- 1) The answers should be examined by key words and not as word-to-word as given in the model answer scheme.
- 2) The model answer and the answer written by candidate may vary but the examiner may try to assess the understanding level of the candidate.
- 3) The language errors such as grammatical, spelling errors should not be given more importance.(Not applicable for subject English and Communication Skills)
- 4) While assessing figures, examiner may give credit for principle components indicated in a figure. The figures drawn by candidate and model answer may vary. The examiner may give credit for any equivalent figure drawn.
- 5) Credits may be given step wise for numerical problems. In some cases, the assumed constant values may vary and there may be some difference in the candidate's answers and model answer.
- 6) In case some questions credit may be given by judgment on part of examiner of relevant answer based on candidate understands.
- 7) For programming language papers, credit may be given to any other program based on equivalent concept.

Q.1 A Attempt any three of the following

12 Marks

a) Enlist any four parts of 3-Phase induction Motor and state the function of each listed.

(Any four parts are expected each parts 1 Mark)

S.No	Parts of 3-Ph Induction	Function
	Motor	
1	Stator Frame	Supports the stator core, protects inner parts
2	Stator Core	Stator winding is housed in slots of stator core which
		provides low reluctance path for rotating magnetic field
3	Stator Winding	Provides rotating magnetic field when supply is given
4	Rotor Core	Rotor conductor is housed in slots of rotor core which
		provides low reluctance path for rotating magnetic field
5	Rotor Conductor	To produce rotor current
6	Slip-rings in case slip ring I.M	Connect 3-Ph rheostat to the rotor circuit via brushes
7	Brushes in case slip ring I.M	To provide connection between external rheostat to rotor
		circuit through Slip-ring
8	Shaft	Supports the rotor structure.
9	Cooling Fan	Air circulation and cooling.
10	Air inlet & outlet	Air circulation and cooling
11	Terminal Box	To provide connection to external circuit
12	Foundation	Supports the whole structure of 3-Ph induction motor



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Answer


Subject Code: 12144 <u>Model Answer</u> Page No: 2 of 24

b) State any four applications for each of 3 phase squirrel cage induction motor & 3- Ph slip ring Induction Motor.

(1/2 marks to each applications of each motor)

S.No	Types Of Induction Motor	Applications (Any Four Applications
		expected)
1	3 phase squirrel cage induction motor	Water Pumps, Tube wells, Lathes Machine,
		Line shaft, Circular-saws, Grinders, Polishers,
		Wood Planners, Compressors, Laundry
		washing machines, fans, and Blowers.
2	3 phase Slip Ring induction motor	Line Shafts, Lifts, Pumps, Generators, winding
		machine, Auxiliary fans, Smoke exhausters,
		Printing presses, Elevators and compressors.

c) Practically if D.C series motor has to be supplied with 1- phase A.C. What modification and refinements will on DC series Motor? (Figure- 2 Marks & Explanation 2 Marks)



or Equivalent fig

The D.C series motor can be run on A.C supply also, but the following modifications will be done when D.C series motor works on A.C. Supply.

- 1. The armature & field core are made up of laminated nature to reduce eddy current losses.

 The Laminations are of silicon steel stampings.
- 2. The power factor of the motor can be improved by,
 - ➤ If possible motor is run at low frequency or



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Subject Code: 12144 <u>Model Answer</u> Page No: 3 of 24

- ➤ Field is wound with fewer turns than an equivalent DC motor and increase pole area to reduce reluctance.
- And operating the iron at low flux density & at high permeability
- And by keeping small air gap.
- 3) The sparking of brushes (Armature reaction) will be minimized by compensating winding which is embedded in the pole faces.

If the compensating winding is short circuit on itself as shown in above figure, a motor is said to be inductively compensated.

d) Discuss the advantages of rotating field type alternator.

(Any four Point Expected each point 1 Marks)

Following Advantages of rotating field type alternator:

Various advantages of rotating field can be stated as,

- 1) The generation level of a.c. voltage may be higher as 11 KV to 33 KV. This gets induced in the armature. For stationary armature large space can be provided to accommodate large number of conductors and the insulations.
- 2) It is always better to protect high voltage winding from the centrifugal forces caused due to the rotation. So high voltage armature is generally kept stationary. This avoids the interaction of mechanical and electrical stresses.
- 3) It is easier to collect larger currents at very high voltage from a stationary member than from the slip ring and brush assembly. The voltage required to be supplied to the field is very low (110 V to 220 V d.c.) and hence can be easily supplied with the help of slip ring and brush assembly by keeping it rotating.
- 4) Due to low voltage level on the field side, the insulation required is less and hence field system has very low inertia. It is always better to rotate low inertia system than high inertia, as efforts required to rotate low inertia system are always less.
- 5) Rotating field makes the overall construction very simple. With simple, robust mechanical construction and low inertia of rotor, it can be driven at high speeds. So greater output can obtain from an alternator of given size.



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Angrees

Subject Code: 12144 <u>Model Answer</u> Page No: 4 of 24

- 6) If field is rotating, to excite it be external d.c. supply two slip rings are enough. Once each for positive and negative terminals. As against this, in three phase rotating armature the minimum number of slip rings required are three and can not be easily insulated due to high voltage levels.
- 7) The ventilation arrangement for high voltage side can be improved if it is kept stationary.
- 8) Rotating field is comparatively light and can run with high speed.

Q.1 B Attempt any One of the following

6 Marks

a) Does the speed of the synchronous motor change when loaded? If not explain how the motor takes load.


The speed of synchronous motor never changes when it is loaded, due to interlocking between stator & rotor magnetic fields. ----- (3 Marks)


Explanation:-

When motor gets loaded, the back emf E_b vector shifts backward due to load angle α .

b) Discuss fully the synchronous impedance method to calculate voltage regulation of an alternator. Explain why this method is considered as a pessimistic method.

Figure: or Equivalent fig (2 Marks)







(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Subject Code: 12144 <u>Model Answer</u> Page No: 5 of 24

The procedural steps for synchronous impedance method are as follows: -- (2 Marks)

- 1) The Open Circuit Characteristics OCC is plotted from open circuit test
- 2) Short Circuit characteristics is plotted from short circuit test:

Short circuit characteristics are straight line through origin. Both characteristics plotted for common field current base. Consider field current If and the corresponding OC voltage E_1 . During short circuit, at the same field current, the whole E_1 is being used to circulate the short circuit current in armature I_{sc} .

3) The synchronous impedance Zs can be calculated as,

$$E_1 = I_{SC} Z_S \to Z_S = \frac{E_{1OCC}}{I_{SC}}$$

4) By performing resistance test, Effective armature resistance, Ra can be calculated Synchronous reactance can be calculated as

$$X_S = \sqrt{Z_S^2 - R_a^2}$$

5) The regulation of the alternator at a particular load condition can be calculated as, the generated EMF; E₀ can be calculated as,

$$E_0 = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi + I_a X_S)^2}$$

The % regulation =
$$\frac{E0-V}{V} \times 100$$

Why this method is considered as a pessimistic method: ----- (2 Marks)

This is indirect method of calculating % regulation, this method assume that the synchronous impedance or reactance is a constant quantity. Actually it is not true, Calculated synchronous impedance or reactance is to large. So regulation obtain by this method is much higher than direct load test method, So it is called the pessimistic method.

Q.2 Attempt any Two of the following

16 Marks

a) Given Data:

3-Ph, 440V, 50Hz induction Motor, Pole = 4 T_f = 150 N-m Resistance R_2/Ph = 0.025 Ω Reactance X_2/Ph = 0.15 Ω N= 1440 RPM



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER - 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 6 of 24

$$N_{S} = \frac{120f}{4} = \frac{120 \times 50}{4}$$
 $N_{S} = 1500 \ RPM$ (1 Mark)

 $\therefore Slip \ at \ Full \ load \ ie \ Sf = \frac{N_{S} - N}{N_{S}} = \frac{1500 - 1440}{1500}$

i) Speed at max.torque condition:

Condition for MaximumTorque, $R_2 = S X_2$

$$S = \frac{0.025}{0.15} = Slip \ at \ max. torque$$

$$S = 0.1667$$

N =Speed at, S = 0.1667 (Max. torque Slip)

$$N = N_s (1-S) = 1500 \times (1-0.1667)$$

 $N = 1250 RPM$ (1 Mark)

ii) We Know,
$$\frac{T_{full}}{T_{\text{max}}} = \frac{2a S_f}{a^2 + S_f^2}, \text{ Where } a = \frac{R_2}{X_2} = 0.1667$$

$$= \frac{2 (0.1667) (0.04)}{(0.1667)^2 + (0.04)^2}$$

$$= \frac{0.01334}{0.02939}$$

$$= \frac{T_{full}}{T_{\text{max}}} = 0.4539$$

$$T_{\text{max}} = \frac{150}{0.4539} = 330.47 \text{ N} - m$$
(1 Mark)

iii) Max. torque condition for Slip Ring $I.M = R_2 + r = S X_2$

Where r = External rotor resistan ce inserted per ph

At Start
$$S = 1$$

 $R_2 + r = X_2$
 $r = X_2 - R_2 = 0.15 - 0.025$
 $r = 0.125 \Omega / Ph$ ------ (2 Mark)



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 <u>Model Answer</u> Page No: 7 of 24

b) Given Data:

3-Ph, 4 Pole, Delta Connected, V=230 Volt, f=50 Hz Input P=10 KWSpeed N=1440 RPM Stator Losses = 0.6 KW P.f. = 0.8 lag

Windage / Mech. Losses = 0.8 KW

a) The current in each phase

Power I/p =
$$\sqrt{3} V_1 I_1 Cos \phi$$
 (1 Mark)
 $10 \times 10^3 = \sqrt{3} \times 230 \times I_1 \times 0.8$

Current in each phase
$$(I_1/ph) = \frac{31.37}{\sqrt{3}} = 18.11 A$$
 ----- (1 Mark)

b) :: Slip
$$S_f = \frac{N_S - N}{N_S} = \frac{1500 - 1440}{1500}$$

$$S_f = 0.04 \ or \ 4 \%$$
 ------ (1 Mark)

c) Rotor $I/P = Stator\ Input - Stator\ Losses$

$$= 10000-600$$

Rotor Copper losses = S (Rotor I/P)

$$= 0.04 \times 9400$$

$$= 376$$
 watts

d) Gross Rotor Output = (1 - S) Rotor input

Gross Rotor Output =
$$(1-0.04)$$
 (9400)

$$\therefore Net Motor \ o/p = Gross \ Rotor \ O/P - Mech \ losses$$

$$= 9042 - 800 \ W \qquad \qquad (1 \ Mark)$$

$$= 8224 \ W$$




(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Subject Code: 12144 <u>Model Answer</u> Page No: 8 of 24

c) Draw and explain the phasor diagram of a synchronous motor operating at a) Lagging Power factor b) Leading Power factor

Phasor Diagram: (Each Phasor Diagram 2 Mark & Each Explanation 2 Marks)



a) Ref. Figure No. 1 For Lagging Power Factor:

For a particular constant load condition, if the excitation is kept low i.e. under excited condition, so E_b will be less than supply voltage 'V' synchronous motor will run with lagging power factor or worked as inductive load.

b) Ref. Figure No. 2 For Leading Power Factor:

Now, if the excitation is increased i.e. over excited condition, so E_b will be more than supply voltage 'V' synchronous motor will run with leading power factor or worked as condenser.



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Q.3 Attempt any Four of the following

Subject Code: 12144

16 Marks

Page No: 9 of 24


a) Discuss why single phase induction motors is not self starting motor. (4 Marks)

- When single phase AC supply is given to main winding it produces alternating flux.
- According to double field revolving theory, alternating flux can be represented by two opposite rotating flux of half magnitude.
- These oppositely rotating flux induce current in rotor & there interaction produces two opposite torque hence the net torque is Zero and the rotor remains standstill.
- ➤ Hence Single-phase induction motor is not self starting. **OR**

When single phase A.C supply is applied across the single phase stator winding, an alternating field is produced. The axis of this field is stationary in horizontal direction. The alternating field will induce an emf in the rotor conductors by transformer action. Since the rotor has closed circuit, current will flow through the rotor conductors. Due to induced emf and current in the rotor conductors the force experienced by the upper conductors of the rotor will be downward and the force experienced by the lower conductors of the rotor will be upward. The two sets of force will cancel each other and the rotor will experience no torque. Therefore single phase motors are not self starting.

b) Draw the wiring diagram of squirrel cage induction motor with Star-Delta Starter.

(4 Mark)



or Equivalent fig




(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 10 of 24

c) Draw torque Slip Characteristics of 3-Ph Induction Motor. State effect of change of rotor resistance on it. (Figure-2 Marks & Effect- 2 Marks)



or Equivalent fig

Effect of variation of Rotor Resistance on the Torque-Slip Characteristics:

- 1. Starting torque increases with increases in value of rotor resistance.
- 2. Maximum torque remains constant and is independent of the value of rotor resistance.
- 3. The Slip at which maximum torque occurs varies with the variation of rotor resistance.
- 4. Maximum torque is developed at starting when rotor resistance is equal to the standstill rotor reactance i.e. when R_2 is equal to X_{20}
- 5. Torque is maximum when the rotor reactance $X_2 = (SX_{20})$ is equal to the rotor resistance R_2 .

d) What is hunting? State effect of it on operation of synchronous motor.

(Difination-2 Marks & Effect- 2 Marks)

When a synchronous motor is used for driving a varying load, it produces hunting effect. When there is sudden increase in the load, the load angle is suddenly increased as the rotor is pulled backwards w.r.t. the stator field. If the load is suddenly decreased, then the rotor is immediately pulled up to a new load angle. But in this process the rotor overshoots and again pulled back. In this way, the rotor starts oscillating about its new position of equilibrium. **This is** called as hunting or phase swinging.



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Subject Code: 12144 Model Answer Page No: 11 of 24

Effects of hunting:-

Hunting produces oscillations of the rotor of synchronous motor .If the time period of these oscillations happens to be equal to the natural time period of the machine than mechanical resonance is set up the amplitude of these oscillations is built up to a large value and may throw the machine out of synchronism.

e) List any four types of 1-Ph induction motor. Write down any one application for each.

(Each type of 1-Ph I.M- 1/2 each and any one application of motor 1/2 Mark each)

S.No	Types of 1-Ph Induction Motor (Any Four)	Applications (Any one expected)
1	Split phase Resistance start motors:	Washing Machine, Fans, Blowers,
		Domestic Refrigerator, Centrifugal Pump,
		Small electrical Tools
2	Split phase capacitor motor	Fans, Blowers, Grander, Drilling Machine,
		Washing Machine, Refrigerator, Air
		conditioner, Domestic Water Pumps,
		Compressor, conveyors
3	Permanent split single value capacitor motor	Fans, Blowers, Grander, Drilling Machine,
		Washing Machine, Refrigerator, Air
		conditioner, Domestic Water Pumps,
4	Two value capacitor motor	Fans, Blowers, Grander, Drilling Machine,
		Washing Machine, Refrigerator, Air
		conditioner, Domestic Water Pumps,
5	Single value capacitor starts motor	Fans, Blowers, Grander, Drilling Machine,
		Washing Machine, Refrigerator, Air
		conditioner, Domestic Water Pumps,
6	Shaded pole motor	Recording Instruments, Record Player,
		Gramophones, toy Motors, Hair dryers,
		Photo copy machine, Advertizing display



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 12 of 24

Q.4 A) Attempt any Three of the following

12 Marks


a) State any four points of comparison between squirrel-cage and slip ring induction motor.


(Any four points expected each point- 1 Mark)

S.No.	Squirrel Cage Induction Motor	Slip Ring Induction Motor
1	Construction :-	
	Simple and robust	Complicated and bulkily
2	Starting Torque :-	
	Poor	Higher
3	Operating Efficiency :-	
	Better	Lower
4	Applications :-	
	For driving some how constant load	For driving heavy load where high starting
	eg. Lathe Machine, Workshop	torque is required eg. Lift, Crane, Elevators,
	Machine and water pump	conveyor belts etc
5	Limitation :-	
	Low Starting torque external	Frequent maintenance is essential. low
	resistance cannot be connected ,speed	efficiency P.f. more costly
	control is difficult	

b) Explain the principle of working of capacitor start capacitor run induction motor.

(Figure- 2 Mark & Explanation- 2 Mark)





or Equivalent fig

In these motors one capacitor is connected in series with the auxiliary winding. There is no centrifugal switch. Thus this winding along with the capacitor remains energized for both starting and running conditions. Capacitor used serves the purpose of obtaining necessary phase displacement at the time of starting and also improves the power factor of the motor



Subject Code: 12144

(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

c) Explain why rotor speed of 3 phases Induction never catches the speed of Stator flux.

(4 3 4 . 1 .)

Page No: 13 of 24

The working principle of three phase induction motor is based on relative motion between rotating magnetic field and rotor conductors i.e $(N_S - N)$, According to Lenz's law rotor will try to catch the synchronous speed of rotating magnetic field to oppose the 'cause producing it'. But rotor never succeeds due to frictional losses.

If rotor catches the synchronous speed of rotating magnetic field, $(N_S$ - N) i.e is relative motion will be zero and rotor stops to rotate. ${\bf OR}$

Relative motion between rotor conductors and rotating magnetic field induces rotor currents. Interaction of rotor current of stator flux produces torque on rotor which means that relative motion of rotor is the cause of rotation of rotor. In No-load condition, due to friction of windage rotor has to produce a small torque to overcome frictional force and thus rotor speed never catches synchronous speed

d) Explain the term armature reaction in relation to 3-Phase alternator & discuss the effect of load power factor on armature reaction.

Armature Reaction: - (1 Mark)

When the armature conductors carry current they produce their own flux this flux affects the main pole flux. Due to the change in flux the terminal voltage available at the load conditions will be different. The effect of armature flux on pole flux is called as armature reaction.

The effect of armature reaction depends upon power factor the load:

- 1) For Resistive load or unity P.f.:- In this case the armature flux crosses the main flux. This Effect is called 'Cross magnetizing effect. Due to this, the main flux will be distributed and terminal voltage drops ie $V_T \setminus E$.-----(1 Mark)



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

3) For leading P.f. or capacitive load: - In this case the armature flux assists the main flux. This Effect is called as Strong magnetizing and due to this ,the main flux will be stronger & terminal voltage increases ie $V_T \setminus E$.-----(1 Mark)

Q.4 B) Attempt any One of the following

6 Marks

a) Is it possible to change the direction of rotation of shaded-pole type single phase Induction?

(6-Marks)

The Shaded pole motor generally has a definite direction of rotation which cannot be reversed. However, if such reversal is essential, it can by achieved by providing two shading coils, one on each end of every pole. Then by open circuiting one set of shading coils and short circuiting the other set, desired direction of rotation can be achieved.

b) Derive e.m.f equation of 3-Ph alternator considering chording factor and distribution factor.

Let, P = no. of rotor poles. $\phi = Flux$ per pole Z = Number of stator conductors

N =Speed in rpm

$$\therefore turns \ per \ phase \ (Tph) = \frac{Z_{Ph}}{2}$$

:. Frequency of induced emf is

f = Cycles per rotation x rotation per sec

$$\therefore = \frac{P}{2} \times \frac{N}{60}$$

$$\therefore f = \frac{PN}{120} \qquad (1 \text{ Marks})$$

Consider one rotation of rotor then change in flux linkage is,

 $d\phi = P$. ϕ Time required for one rotation is,

$$\therefore dt = \frac{1}{n} = \frac{1}{(N/60)} = \frac{60}{N} - - - - - - - Sec.$$
 (1 Marks)



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 15 of 24

By faradays law of Electromagnetic induction

$$\therefore Average\ emf\ per\ conductor = \frac{d\phi}{dt}$$

$$\therefore E_{\text{ave}} / \text{Conductor} = \frac{P.\phi}{(N/60)}$$

$$\therefore \text{ E}_{\text{ave}}/\text{ Conductor} = \frac{P \times \phi \times N}{60} - - - - - - - Volt - - - - - (1 \text{ Marks})$$

$$\therefore E_{ave} / turn = 2 E_{ave} / Conductor \frac{P \times \phi \times N}{60} ------Volt$$

$$\therefore E_{\text{ave}} / \text{turn} = 2 \frac{P \times \phi \times N}{60} - - - - - - Volt$$

$$\therefore \qquad = \frac{4P\phi N}{120} ------Volt$$

$$\therefore = 4(\frac{PN}{120}) \phi$$

$$\therefore E_{\text{ave}} / \text{turn} = 4 f \phi \therefore (f = \frac{P N}{120})$$

 $\therefore E_{ave} / Phs = E_{ave} / x \text{ Number of turns per phase}$

= 4
$$f \phi \times T_{Ph}$$
 ------ (1 Marks)

RMS Value per phase is given by,

$$E_{ph} = E_{ph}$$
 (ave) x Form Factor
= $4 f \phi \times T_{Ph} \times 1.11$ ------ (1 Marks)

$$E_{ph} = 4.44 \ f. \phi. T_{Ph}$$

It is for full pitched concentrated winding. If winding is distributed & short pitched then

$$\mathsf{E}_{\mathsf{Ph}} = 4.44 \ f \ \phi. T_{\mathit{Ph}}. kd.kc$$
 ------ (1 Marks)

Kc = coil span factor or chording factor

Kd = Distribution factor



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 16 of 24

Q.5 A) Attempt any Two of the following

16 Marks

a) Given Data:

3Ph, 6 Pole, 50 Hz I.M Full load Slip = 3.5 % Stator Losses 1700 watts

Torque at shaft i.e Gross Torque = $153 \text{ N-m} = T_g$ Mechanical Losses = 575 watt

Where
$$N_s = \frac{120 f}{P} = \frac{120 \times 50}{6} = 1000 RPM$$
 ----- (1 Marks)

Full Load Speed = Ns (1-S),

Full Load Speed = 1000 (1-0.035)

Full Load Speed = 965 RPM ----- (1 Marks)

1) Gross Rotor Output = $2 \pi N T_g$ (Where, N in RPS)

$$=2\times3.142\times\frac{965}{60}\times153$$

Net Motor output = Gross Rotor output - mech. Losses

Net Motor output = 14888.35 Watts----- (1 Marks)

2) Rotor Input =
$$\frac{Gross\ Rotor\ output}{(1-S)}$$
 ------ (1 Marks)

Rotor Input =
$$\frac{15463.35}{(1-0.035)}$$
 = 16024.2 *Watts*

Rotor Copper Losses = $S \times Rotor$ Input

Rotor Copper Losses = 0.035×16024.2

Rotor Copper Losses = 560.847 *Watts* ------ (1 Marks)

3) Net Motor Input = *Rotor Input + Stator Losses*

Net Motor Input = 16024.2 + 1700 Watts

Net Motor Input = 17724.2 *Watts* ----- (1 Marks)



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 17 of 24

$$\% \ \eta = \frac{Net \ Motor \ output}{Net \ Motor \ Input} \times 100$$

$$\% \ \eta = \frac{14888.35}{17724.2} \times 100$$


$$\%$$
 $\eta = 84 \%$ ------ (1 Marks)

b) Given Data:

3-Ph, 400V, P = 125 KVA Ra = 0.15 ohm

Field current (A)	0	10	20	30	40	50	60
Open circuit emf (V)	0	140	250	340	400	460	520
Open circuit V per Phase		80.8	144.3	196.3	230.9	256.6	300

Note: In Graph Scale may be different: ----- (2Mark)





(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 18 of 24

Phase Resistance, $R_a = 0.15$ ohm

Phase Voltage V=
$$\frac{400}{\sqrt{3}}$$
 = 230.90 *volts* ----- (1/2Mark)

Full load Line current
$$I = I_a = \frac{125 \times 10^3}{\sqrt{3} \times 440} = 180.42A$$
 ----- (1/2Mark)

From OCC and SCC:-

∴ Synchronous impedance per phase =
$$Zs = \frac{O.C \ Voltage/\ ph}{S.C \ Current/\ ph} = \frac{144.3}{180.42}$$

:. Synchronous impedance per phase = $Zs = 0.8\Omega$ ----- (1/2Mark)

Synchronous reactance,
$$X_S = \sqrt{Z_S^2 - R_a^2} = \sqrt{0.8^2 - 0.15^2} = 0.7858 \ \Omega$$
 ----- (1/2Mark)

i) 0.8 Lagging Power Factor;

No. load emf
$$E_0 = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi + I_a X_s)^2}$$
 ------(1Mark)

No. load emf
$$E_0 = \sqrt{(230.9 \times 0.8 + 180.42 \times 0.15)^2 + (230.9 \times 0.6 + 180.42 \times 180.42 \times 0.7858)^2}$$

No. load emf
$$E_0 = \sqrt{(2211.783)^2 + (280.31)^2}$$

No. load emf $E_0 = 351.32 \, Volt$

Re gulation =
$$\frac{E_0 - V_T}{V_T} \times 100 = 230.9 \times 100$$

ii) 0.707 leading Power Factor;

No. load emf
$$E_0 = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi + I_a X_s)^2}$$

No. load emf
$$E_0 = \sqrt{(230.9 \times 0.707 + 180.42 \times 0.15)^2 + (230.9 \times 0.707 + 180.42 \times 0.7858)^2}$$

(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 **Model Answer** Page No: 19 of 24

No. load emf
$$E_0 = \sqrt{(190.31)^2 + (21.47)^2}$$

No. load emf $E_0 = 191.52$ Volt

Re gulation =
$$\frac{E_0 - V_T}{V_T} \times 100 = \frac{191.52 - 230.9}{230.9} \times 100$$

% Regulation = -17.05 % ----- (1Mark)

iii) Unity Power Factor;

No. load emf
$$E_0 = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi + I_a X_s)^2}$$

No. load emf
$$E_0 = \sqrt{(230.9 \times 1 + 180.42 \times 0.15)^2 + (180.42 \times 0.7858)^2}$$

No. load emf
$$E_0 = \sqrt{(257.96)^2 + (141.77)^2}$$

No. load emf $E_0 = 294.35$ Volt

Re gulation =
$$\frac{E_0 - V_T}{V_T} \times 100 = \frac{294.35 - 230.9}{230.9} \times 100$$

% Regulation = 27.48 % ----- (1Mark)

- Derive equivalent circuit diagram of 3-ph Induction motor. State the terms used in it. c)
 - > Terms used in equivalent circuit diagram of 3-Ph induction motor all the quantities are per phase quantities.
 - **Stator Side:** i) V_1 = Input Voltage to Stator ii) I_1 = Total Stator current
 - iii) I_0 = No load stator current
- iv) I_C = Working component of I_0
- v) I_{μ} = Magnetizing component of I_0 vi) I_2 = Rotor current referred to stator side
- vii) E_1 = Self induced emf at standstill in stator
- viii) R₁= Stator Resistance
- ix) X_1 = Stator Reactance Standstill
- **Rotor Side :** i) $I_2 = Rotor Current$


- ii) $R_2 = Rotor Resistance$
- iii) $X_2 = \text{Rotor Reactance at standstill}$ iv) $E_2 = \text{Mutual induced emf in Rotor at standstill}$
- v) R_L = Mech. Load Representative
- vi) S = % Slip




(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION Model Answer

Subject Code: 12144 Model Answer Page No: 20 of 24



Each remaining steps 1 Mark Each





(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 21 of 24

Q.6 Attempt any Four of the following

16 Marks

a) Derive the condition for maximum torque under running condition.

Note: The student can follow for different method of derivation also

Let us consider the equation of torque,

$$T = \frac{K \phi S E_2 R_2}{R_2^2 + S^2 X^2}$$
 (1 Mark)

Condition of maximum torque can be found out by taking derivative of torque equation w.r.t. Slip and equating it to zero. For the simplicity of derivation, let us put $\frac{1}{T} = M$

$$M = \frac{R_{2}^{2} + S^{2} X_{2}^{2}}{K \phi S E_{2} R_{2}}$$

$$M = \frac{R_{2}^{2}}{K \phi S E_{2} R_{2}} + \frac{S^{2} X_{2}^{2}}{K \phi S E_{2} R_{2}}$$

$$M = \frac{R_{2}}{K \phi S E_{2}} + \frac{S X^{2}}{K \phi S E_{2} R_{2}}$$

$$M = \frac{R_{2}}{K \phi S E_{2}} + \frac{S X^{2}}{K \phi E_{2} R_{2}}$$

$$\frac{d(M)}{dS} = \frac{d}{dS} \left[\frac{R_{2}}{K \phi S E_{2}} + \frac{S X_{2}^{2}}{K \phi E_{2} R_{2}} \right] = 0$$

$$-\frac{R_{2}}{K \phi S^{2} E_{2}} + \frac{X_{2}^{2}}{K \phi E_{2} R_{2}} = 0$$

$$\frac{X_{2}^{2}}{K \phi E_{2} R_{2}} = \frac{R_{2}}{K \phi S^{2} E_{2}}$$

$$\frac{S^{2} X_{2}^{2}}{K \phi E_{2} R_{2}} = \frac{R_{2}^{2}}{K \phi S^{2} E_{2}}$$

$$S^2 X_2^2 = R_2^2$$

$$\therefore R_2 = S X_2$$
------(1Mark

This is the condition for maximum torque of 3-Ph induction motor under running




(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 22 of 24

b) Explain in brief how the direction of induction motor change with circuit can diagram.

(Figure – 2 Marks & Explanation-2 Marks)



Direction of 3-Ph induction motor can be changed by changing any 2 phases of stator supply as shown in figure for this reversing switch is used. **OR**

The direction of rotation of three phase induction motor can be changed by changing its phase sequence

c) Given Data:

 $N = 700 \ RPM$ Slip = 4% P = ? (if f = 60Hz & 50 Hz) Actual Speed $N_r = ?$ As speed is 700 rpm is synchronous speed must be greater than 700 RPM

$$Ns = \frac{120 f}{P}$$

Where f = Supply frequency P = No. of pole

Number of poles must be even integrate

When Frequency f = 60 Hz Number of pole:

$$P = 10 Nos pole for f = 60Hz$$
 ----- (1/2 Mark)



(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 Model Answer Page No: 23 of 24

When Frequency f = 50 Hz Number of pole:

$$N_{s} = \frac{120 \ f}{p}$$
 (1/2 Mark)

If P = 8

 $N_{s} = \frac{120 \times 50}{8}$ $N_{s} = 750 RPM$
 $P = 8 \ Nos \ pole \ for \ f = 50 Hz$ (1/2 Mark)

Actual Speed:

d) What is induction generator? Under what condition induction motor will acts as Induction generator? What will be the value of slip in case of induction generator?

Induction generator:

(2 Mark)

When rotor of induction motor runs faster than synchronous speed, induction motor runs as generator and called as induction generator. It converts mechanical energy it receives from the shaft into electrical energy which is released by stator. However, for creating its own magnetic field, it absorbs reactive power Q from the lime to which it is connected. The reactive power is supplied by a capacitor bank connected at the induction generator output terminals.

Under condition induction motor will acts as Induction generator: When rotor speed is greater than synchronous speed than induction motor will acts as Induction generator (1 Mark)

What will be the value of slip in case of induction generator: Slip will be negative (1 Mark)




(Autonomous) (ISO/IEC-27001-2005 Certified)

SUMMER – 13 EXAMINATION

Subject Code: 12144 <u>Model Answer</u> Page No: 24 of 24

e) Explain the principle of operation of linear induction motor.

(Figure- 2 Marks & Principle – 2 Marks)



In a sector IM, if sector is made flat and squirrel cage winding is brought to it we get linear I.M. In practice instead of a flat squirrel cage winding, aluminum or copper or iron plate is used as rotor.

The flat stator produces a flux that moves in a straight line from its one end to other at a linear synchronous speed given by $Vs=2\ wf$

Where, Vs = linear synchronous speed in m/sec

w = width of one pitch in m.

f = supply frequency (Hz)

The speed does not depends on number of poles but only on the poles pitch and supply frequency. As the flux move linearly it drags the rotor plate along with it in same direction. However in much practical application the rotor is stationary while stator moves.

END	
	/