Cooling Unit Fault Diagnosis Report

Report no.	DG-261114-003	Customer	مصنع تجريبي
Location	العاشر من رمضان	Visit date	2026-11-14
Technician / Engineer	tech1		

Visit summary

3	2	1
Units inspected	Repaired	Follow-up needed

#	Unit	Alarms	Result	Status
1	Blue e S/N 1234567 خط التعبئة 1	A02 A07	Temperature sensor (NTC) or its connection	**Repaired**
2	Blue e خط التعبئة 2	A02	Low refrigerant charge (leak)	**Follow-up needed**
3	Blue e خط التعبئة 3	A15	Temperature sensor (NTC) or its connection	**Repaired**

Unit 1

Model	Blue e
Part number	SK 3304.500
Serial number	1234567
Line / location	خط التعبئة 1

Alarms displayed

Code	Meaning
A02	Enclosure temperature too high
A07	Evaporator coil (low refrigerant or sensor)

Inspection result

Temperature sensor (NTC) or its connection

Recommended actions

1. Measuring sensor resistance against the reference table
2. Inspecting the connector and sensor mounting
3. Replacing the sensor if required

Visit outcome

Status	**Repaired during the visit**
Work carried out	تم الفحص وتحديد العطل: تلف حساس حرارة. تم استبدال الحساس.

Unit 2

Model	Blue e
Part number	SK 3304.500
Line / location	خط التعبئة 2

Alarms displayed

Code	Meaning
A02	Enclosure temperature too high

Measurements

Phase currents (A)	4.1 / 4.3 / 4.0
Phase imbalance	7%

Inspection result

Low refrigerant charge (leak)

Recommended actions

1. Locating and repairing the leak before recharging
2. Evacuating the circuit and recharging by weight per the nameplate
3. Verifying performance after one hour of operation

Refrigerant circuit work is carried out by a qualified refrigeration technician.

Visit outcome

Status	**Not repaired during the visit**

Required for the next visit	فني تبريد إلصالح التسريب وشحن الغاز

Unit 3

Model	Blue e
Part number	SK 3304.500
Line / location	خط التعبئة 3

Alarms displayed

Code	Meaning
A15	Condensate sensor

Inspection result

Temperature sensor (NTC) or its connection

Recommended actions

1. Measuring sensor resistance against the reference table
2. Inspecting the connector and sensor mounting
3. Replacing the sensor if required

Visit outcome

Status	**Repaired during the visit**

The results in this report are based on the field inspection at the time of the visit.

Technician / Engineer: name and signature

Customer representative: name and signature