

This is sample data provided for CALIBER purposes only	ONE POINT LESSON (OPL)	OPL No: OPL-GA-1201A-02 Sheet 1 of 1
--	-------------------------------	--

OPL Title	Bearing Oil Bath Level & Greasing	Discipline	Mechanical
Equipment	GA-1201A - HEXANE FEED PUMP	Area / Unit	1200 - HEXANE FEED SYSTEM
Related Interlock	SEQ-1201 (SIL 1)	P&ID; Ref	TJC-LLD-PID-1201

Classification:	☒ Basic Knowledge	☐ Improvement	☐ Trouble Case	Aspect: P-Q-C-D- S -M-E
-----------------	---	--------------------------------------	---------------------------------------	--------------------------------

1. PURPOSE / OBJECTIVE

This One Point Lesson explains **bearing oil bath level & greasing** for GA-1201A (HEXANE FEED PUMP) in the HEXANE FEED SYSTEM. Maintain oil bath at the centre of the sight glass with ISO VG 68. Both over-fill and under-fill overheat the bearing. The lesson gives operators and technicians the key knowledge and the correct step-by-step method so the task is done safely, correctly and consistently every time.

2. SAFETY PRECAUTIONS

Hazard note: this equipment is **HIGH CRITICAL** handling **n-Hexane** at up to 16 barg / 80 degC. Observe the following before and during the task:

- Apply LOTO (Lock-Out Tag-Out) and prove zero energy before starting work.
- Isolate, depressurise, drain and purge the equipment; obtain a valid work permit.
- Wear the correct PPE: coverall, safety shoes, gloves, goggles and hearing protection.
- Beware of stored mechanical energy (springs, rotating inertia) and pinch points.
- Use certified lifting gear and correct manual-handling technique for heavy parts.

3. TOOLS & MATERIALS REQUIRED

- Standard mechanical hand tools & calibrated torque wrench
- LOTO padlocks and permit
- Laser/dial alignment kit (as applicable)
- Feeler gauges, dial indicator, seal/bearing pullers
- Correct spare parts and gaskets per the BOM
- Lifting gear and slings (certified)

4. DETAILED PROCEDURE / STEPS

Step	Action	Check / Acceptance
1	Stop pump, isolate electrically (LOTO) before any lube work	Isolation & LOTO verified
2	Check the oil sight-glass level sits at the middle mark	Parts match BOM / spec
3	Top-up with ISO VG 68 only - never mix grades	Torque / clearance to spec
4	Inspect the constant-level oiler bottle and refill	No leak / smooth operation
5	Record oil condition (colour/water) on the weekly lube route sheet	Record in equipment history

5. COMMON PROBLEMS & TROUBLESHOOTING

Symptom	Likely Cause	Action
Hexane leak observed at GA-1201A seal gland during operation, seal dr.	API Plan 11 flush orifice RO-1201 partially plugged causing seal face.	Replaced JC T2100 mechanical seal cartridge, cleaned flush orifice, v.
GA-1201A tripped on VSHH-1201 high vibration 7.4 mm/s	Angular misalignment 0.12 mm/100mm after foundation settlement	Laser re-aligned pump/motor, re-shimmed motor feet, vibration back to.
Bearing DE noisy with rising temperature TI-1201 trend	Outer race spalling on DE bearing due to prolonged misalignment	Renewed DE bearing 7310 BECBM, flushed housing, refilled ISO VG 68

6. KEY LEARNING POINTS

- Maintain oil bath at the centre of the sight glass with ISO VG 68. Both over-fill and under-fill overheat the bearing.
- Respect the interlock SEQ-1201: e.g. PSL-1201 trips at < 0.5 barg - never defeat it without a permit.
- Always cross-check the Datasheet limits and the P&ID; TJC-LLD-PID-1201 before working on GA-1201A.
- Record the work in the equipment history so the Knowledge Hub stays the single source of truth.

Prepared by	Reviewed by (Supervisor)	Approved by (Manager)	Date of Sharing
Panel Operator / Technician	Wahyu Setiadi (EMP-1113)	Arya Wibisono (EMP-0912)	Thursday, 26 March 2026

Notes: Cross-ref tag GA-1201A across Datasheet, GA, P&ID, Interlock and Maintenance History.