SB-LWS-2025-11 Rev. B - Pitch bearing bolt re-torque

Service bulletin issued by Litware Wind Systems on 2026-09-04.

Field	Value
Bulletin number	SB-LWS-2025-11
Revision	B
Issue date	2026-09-04
Category	Mandatory
Applies to	LT-32 turbines, all variants (M30 10.9 pitch bearing bolts, 72 per blade bearing, 216 per turbine)
Compliance	At the next 12-month service
Supersedes	SB-LWS-2025-11 Rev. A of 2025-10-06

REVISION B: This revision supersedes SB-LWS-2025-11 Rev. A. The re-torque value changes from 1,450 Nm to 1,380 Nm.

1. Reason

Laboratory tests on bolts re-torqued according to Rev. A showed that 1,450 Nm combined with the factory-lubricated washers overloads the M30 bolts. Rev. B lowers the re-torque value and introduces a lubricated washer kit.

2. Instructions

1. Stop the turbine, lock the rotor and isolate the pitch system.
2. Use a hydraulic torque wrench calibrated within the last 12 months (accuracy +/- 3 %).
3. Fit the lubricated washer kit LWS-P-60477 under the nuts where washers are damaged or missing.
4. Re-torque 100 % of the pitch bearing bolts to 1,380 Nm in the cross pattern of the bolt map, blade by blade.
5. Mark each bolt with a paint line after re-torque.
6. Replace any bolt that turns more than 30 degrees before reaching the torque.

3. Records

Record the turbine, blade, torque wrench serial number and the bolts that turned on the re-torque form and return it to Litware Wind Systems within 60 days.

Summary of changes

Item	Rev. A (2025-10-06)	Rev. B (2026-09-04)
Re-torque value	1,450 Nm	1,380 Nm
Washers	factory washers	lubricated washer kit LWS-P-60477 where needed
Bolt turned during re-torque	report above 60 degrees	replace above 30 degrees