

Incident Report — Pump P-204

Incident No : INC-2023-04-17
Equipment : P-204
Date : 2023-04-17
Detected at : 6.2 mm/s (shutdown band)

Event

Pump P-204 tripped on high vibration at 6.2 mm/s. Bearing failure confirmed on strip-down. A minor seal weep was noted prior to the trip, consistent with the pump's seal-related trip history.

Root Cause

Lubrication interval exceeded. Grease had degraded past service limit, raising bearing housing temperature before failure.

Corrective Action

Revised preventive maintenance schedule from 2000 hrs to 1500 hrs.
Added bearing housing temperature to the daily operator round.