Google Store — Hardware Quality Assurance Audit Report

Component Audit Reference: QA-AUD-2026-DISP904 | **Classification**: Confidential / Internal Operations

Target Device:	Pixel 11 Pro 256GB Obsidian (SKU-PX11P-256-OBS)	**Audit Period:**	August 1 – August 25, 2026
Assembly Facility:	Foxconn / Compal Precision Electronics (Tainan Plant)	**Destination DC:**	Tilburg Central DC (NL-TILBURG-01)
Inspected Lot:	Super Actua OLED Display (Sub-lot DISP-P11-904)	**Batch Volume:**	50,000 Display Assemblies

1. Executive Summary & Audit Scope

This factory acceptance quality audit evaluates 50,000 Super Actua OLED display assemblies manufactured for Google Pixel 11 Pro (SKU-PX11P-256-OBS) at the Tainan assembly plant between August 1 and August 25, 2026. All manufactured consignments were dispatched to European Central Distribution in Tilburg, Netherlands (NL-TILBURG-01) to support launch preorder fulfillment across Spain, France, Germany, Italy, and the United Kingdom.

2. Assembly Line Testing Methodology & Automated Test Equipment (ATE)

Factory automated test equipment (ATE) evaluates display luminance uniformity, color accuracy (Delta E < 1.0), touch digitizer responsiveness, and pulse-width modulation (PWM) duty cycles across five brightness regimes (100%, 75%, 50%, 25%, and 10%). Standard factory gate acceptance criteria permit a maximum component failure rate of 1.5% across tested samples prior to containerized air freight dispatch.

3. Micro-Flicker Anomaly & Calibration Variance

During secondary quality inspection at the factory gate, display sub-lot DISP-P11-904 exhibited an initial variance in high-frequency PWM driver pulse stability below 30% display brightness. While automated factory testing initially registered a minor variance of 1.2%, subsequent European field repair center intake records from B2X Frankfurt and CTDI Madrid have reported a verified customer defect rate of 9.6% on European preorder units.

Preliminary Root Cause: Component lot DISP-P11-904 utilized a secondary batch of power-management integrated circuits (PMIC) with tighter impedance tolerances, resulting in pulse timing drift under low-light operating temperatures.

Google Store — Hardware Quality Assurance Audit Report (Cont.)

Section 4: Factory Gate Testing vs. European DC Intake Reconciliation

The following table reconciles factory gate test measurements against verified intake defect rates recorded at European authorized service centers (B2X Frankfurt and CTDI Madrid) across display sub-lots:

Component Lot ID	Assembly Line	Factory ATE Variance	European DC Verified Defect Rate	Discrepancy Status
DISP-P11-901	Line A-1	0.4%	0.6%	CONFIRMED_NOMINAL
DISP-P11-902	Line A-2	0.5%	0.7%	CONFIRMED_NOMINAL
DISP-P11-903	Line B-1	0.8%	1.1%	CONFIRMED_NOMINAL
DISP-P11-904	**Line B-3**	**1.2%**	**9.6% (Critical Mismatch)**	**FLAGGED_CRITICAL_VARIANCE**
DISP-P11-905	Line C-1	0.6%	0.8%	CONFIRMED_NOMINAL

5. Recommended Remediation & Containment Actions

Based on the 8.4% calibration variance between factory gate testing (1.2%) and European verified service intake (9.6%), the Quality Engineering team mandates the following immediate actions:

• **Immediate Inventory Quarantine**: Quarantine all remaining unallocated factory inventory of display sub-lot DISP-P11-904 at the Tainan facility.
• **Cross-Source RMA Reconciliation**: Reconcile European customer warranty return tickets (RMA-2026-0401 through RMA-2026-0410) with factory serial number manifests to confirm affected units.
• **Firmware Mitigation Deployment**: Accelerate the rollout of firmware OTA patch OT-P11-26.2 to recalibrate the PWM duty cycle for low-luminance thresholds.
• **Proactive Customer Service Recovery**: Issue €50 Google Store promotional vouchers alongside expedited warranty device replacements for affected European preorder customers.

6. Audit Sign-Off & Approvals

Lead Quality Auditor:	Dr. H. Chen, Senior Director of Hardware QA	Signature:	[VERIFIED DIGITAL SIGNATURE]
European Operations Lead:	Google Store Hardware Operations Manager	Date:	September 18, 2026