I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged I have read and understand the above and acknowledge receipt of an estimate



Terms: Cash unless arrangements are made prior to authorization. Vehicles left after repair is completed may be subjected to a \$85.00 per day storage charge.

All Americal

846 Harri San Francis (415) 9

ALL AMERICAN AUTOMOTIVE 846 HARRISON STREET SAN FRANCISCO CA 24107 415-957-1170

8627

6:12 PM

Terminal ID: 01557188 7/18/17

UID: 719913590618 REF #: 2233 BATCH #: 394 AUTH #: 78289D AMOUNT \$2956.76

\$2956.76 APPROVED

TC - 94784E281F4F8778 CUSTOMER COPY

2003 Volkswagen EuroVan MV

VIN: WV3AB47004H001830

Engine: V6 2.8L, 2792cc, DOHC, GAS, FI

Trans:

Odom: 29929 Color: White Mfg. Date:

License #

Unit#

ned

Vehicle Prob	lems F	Requests for Service	Services Performed	Hrs	Qty	17(000 1	Res I	74
Customer stat	es that: smog	inspection		//	17	g - wa ve		
Labor Serv New	rice - California SSC	Emission Inspection B	H Emission Certificate	1.00	1.00	130,00 8.25	-78.30	51.70 8.25
engine per noted brok P1151 for l	formance test. e EVAP line to	Scan fuel management purge valve under vehic and code P1476 Leak de	light on perform strategy based management system. Inspection the causing vehicle to have code etection pump malfunction. Replace	4.50		145.00	<u> </u>	652.50
New	GASOLINE	Gasoline			1.00	30.00 13	29 64	30.00
New	7D0201995G				1.00	88.80	-1001	88.80
New	B7080-16908				1.00	58.98		58.98
New	7D0906271A		ction Pump		1.00	347.36	(347.36
New	7D0906515	Vapor Ven	· · · · · · · · · · · · · · · · · · ·		1.00	182.00		182.00
ustomer stat	es that: regula	r service needed				X THE TANK		
change e lube susp change o check for adjust al check ou check tire service b	ngine oil pension il filter fluid leaks I fluids tside bulbs es/belts/hoses	naintenance service		1.50		145.00		217.50
Labor Serv	ice - Parts Sol	d BH				145.00		0.00
New	WASHER FL	UID Windsheild	f washer fluid		1.00	6.69		6.69
New	WK8307	Fuel Filter	- Mann+Hummel		1.00	26.40		26,40
New	CU1738	Cabin Air F	Filter - Mann+Hummel		1,00	29.53		29,53
New	HU7197X	Oil Filter -	Mann+Hummel		1.00	18.56		18.56
New	31100-76949	Motor Oil S	Synthoil 5W-40 - 5 Ltr		1.00	58.20		58.20
nspection not	te that: vehicle	needs rear brakes		int digital	Worth the	do La pune	poper serious pour reco	t (Allere III
Labor Service - Rear brake labor * remove wheel assy * inspect hydraulics * renew friction material * check drum/rotor * test drive BH				1.50		145.00		217,50
New	BC		solvent cleaner		1.00	8.67		8.67
New	N1010-32350		Set-Rear - With Shims		1.00	110.65		110.65
New	N1000-12565	56 Brake Disc	-Rear		2.00	78.88		157.76
Labor Serv brake lines vehicle Bh	with required		cylinder & clean reservoir * flush all tion if equipted. * Road test	0.50		145.00		72.50
New	BF	Brake fluid			2.00	4.70		9.40
Sustomer stat	es that: install	customer suppled rea	r view mirrrow camera		0 100	N III = X		
Labor Service - install back up camera BH				3.50		145.00		507.50
			The second secon					