Service Report

General Information

Report No.	SR-2026-01893
Service Date	2026-10-07 (1405/07/15 SH)
Next Service Due	2027-04-07 (1406/01/18 SH)
Customer	Ironwood Machinery Works
Address	Sample Industrial Park, 3rd Street, No. 12
Technician	Sample Technician C

Machine

Description	Screw air compressor
Manufacturer	Quanta
Model	QSC-75
Serial No.	QN-75-20418
Operating Hours	12,480
Location	Production hall 2, compressed-air station

Reported Problem

Output pressure drops under full load and the oil temperature rises to 105 °C. The unit tripped several times on the high-temperature alarm.

Root Cause

The oil filter and air/oil separator were clogged because their service interval had been exceeded. The cooler fins were also blocked with dust.

Actions Performed

No.	Action	Hours
1	Drained oil and replaced the oil filter	1.5
2	Replaced the air/oil separator	2
3	Cleaned the cooler with dry air and a gentle wash	1
4	60-minute full-load test with temperature and pressure logging	1.5

Parts Used

All values in rials.

No.	Code	Part	Qty	Unit price	Amount
1	OF-75-A	Oil filter	1	4,250,000	4,250,000
2	AOS-75-B	Air/oil separator	1	18,600,000	18,600,000

No.	Code	Part	Qty	Unit price	Amount
3	LUB-46-20	Compressor oil (litre)	20	1,350,000	27,000,000
4	GSK-75-K	Gasket kit	1	1,980,000	1,980,000

Cost Summary

All values in rials.

Parts total	51,830,000
Labor	21,000,000 (6.0 × 3,500,000)
Subtotal	72,830,000
VAT 10 %	7,283,000
Total payable	**80,113,000**

In words: eighty million one hundred thirteen thousand rials

Recommendation

Inspect the intake air filter and oil every 2,000 hours. Clean the cooler every three months. Check the belt and the inlet valve at the next service.

Serviced by
Sample Technician C

Signature

Accepted by (customer)
Customer representative

Signature

Fictional sample document generated for demonstration. All names and values are invented.