

Table of Contents

[LegalDefTopic](#)

[ReadMe_V8_30_00_uflx.1.02](#)

[ReadMe_V8_30_00_uflx.1.03](#)

[ReadMe_V8_30_00_uflx.1.04](#)

[ReadMe_V8_30_00_uflx.1.05](#)

[ReadMe_V8_30_00_uflx.1.06](#)

[ReadMe_V8_30_00_uflx.1.07](#)

[ReadMe_V8_30_00_uflx.1.08](#)

[ReadMe_V8_30_00_uflx.1.09](#)

[ReadMe_V8_30_00_uflx.1.10](#)

[ReadMe_V8_30_00_uflx.1.11](#)

[ReadMe_V8_30_00_uflx.1.12](#)

[ReadMe_V8_30_00_uflx.1.13](#)

[ReadMe_V8_30_00_uflx.1.14](#)

[ReadMe_V8_30_00_uflx.1.15](#)

[ReadMe_V8_30_00_uflx.1.16](#)

[ReadMe_V8_30_00_uflx.1.17](#)

[ReadMe_V8_30_00_uflx.1.18](#)

[ReadMe_V8_30_00_uflx.1.19](#)

[ReadMe_V8_30_00_uflx.1.20](#)

[ReadMe_V8_30_00_uflx.1.21](#)

[ReadMe_V8_30_00_uflx.1.22](#)

[ReadMe_V8_30_00_uflx.1.23](#)

[ReadMe_V8_30_00_uflx.1.24](#)

[ReadMe_V8_30_00_uflx.1.25](#)

[ReadMe_V8_30_00_uflx.1.26](#)

[ReadMe_V8_30_00_uflx.1.27](#)

[ReadMe_V8_30_00_uflx.1.28](#)

[ReadMe_V8_30_00_uflx.1.29](#)

[ReadMe_V8_30_00_uflx.1.30](#)
[ReadMe_V8_30_00_uflx.1.31](#)
[ReadMe_V8_30_00_uflx.1.32](#)
[RelNotesCurDefTopic](#)

LegalDefTopic

	
---	---

Legal Notices

Legal Notices

The legal notices are as follows:

- | | |
|---|--|
| • | Copyright |
| • | Restricted Rights Legend |
| • | Credits and Trademarks |
| • | End User License Agreement |
| • | Software License Agreement |

Copyright

2014 Teradyne, Inc. All rights reserved.

The material in this document is subject to change without notice. Teradyne, Inc. assumes no responsibility for any errors which may appear in this document. This document contains trade secrets and confidential information, and is furnished pursuant to a license to the user from

Teradyne, Inc. Use or reproduction of this document is restricted under the terms of the license. This material cannot be reproduced, viewed, or uploaded without the express and written permission of Teradyne.

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to the restrictions as set forth in paragraph (b)(3)(B) of the Rights of Technical Data and Computer Software clause in DAR 7-104.9(a).

Credits and Trademarks

Teradyne is a registered trademark and FLEX, microFLEX, UltraFLEX, J750, IP750, IG-XL, DataTool, IMAGE, BBAC, TurboAC, UltraPin800, UltraWave, UVS256, Background DSP, Sync-Link, Signature Receive, and RA/Plus are trademarks of Teradyne, Inc in the U.S. and other countries. Microsoft, ActiveX, Excel, IntelliSense, MS-DOS, Visual Basic, Visual Studio, Windows, and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and other countries. Pogo is a registered trademark of Everett Charles Technologies. FLEXnet, FLEXnet Publisher, and InstallShield are registered trademarks of Flexera Software, Inc. Adobe, Acrobat, and Acrobat Reader are either registered trademarks or trademarks of Adobe Systems, Inc. in the United States and/or other countries. Sun, Solaris, and Java are either registered trademarks or trademarks of Oracle and/or its affiliates. UNIX is a registered trademark of The Open Group. Allegro is a registered trademark of Cadence Design Systems, Inc. Mate-N-Lok is a trademark of Tyco Electronics Corporation. FastScan is a trademark of Mentor Graphics Corp. TetraMAX is a registered trademark of Synopsys, Inc. Encounter is a trademark of Cadence Design Systems, Inc. HyperTransport is a trademark of the HyperTransport Technology Consortium. FlexIO is a trademark of Rambus, Inc. Blu-ray is a trademark of the Blu-ray Disc Association. HDMI and High-Definition Multimedia Interface are trademarks or registered trademarks of HDMI Licensing LLC. Dolby, Dolby Digital, and Dolby True HD are trademarks of Dolby Laboratories. TMDS is a trademark of Silicon Image, Inc. HDCP is a trademark or registered trademark of Digital Content Protection LLC. PCI-SIG, PCIe, and PCI Express are registered trademarks of PCI-SIG. Solidworks is a registered trademark of Dassault Systmes SolidWorks Corporation. TORX is a registered trademark of Acument Global Technologies, Inc. Symantec is a trademark of Symantec Corporation. ZigBee is a trademark of the ZigBee Alliance. minibend is a registered trademark of Astrolab, Inc. MIPI and SLIMbus are registered trademarks of the MIPI Alliance. Bluetooth is a registered trademark of the Bluetooth SIG, Inc. cdma2000 is a registered trademark of the Telecommunications Industry Association (TIA-USA). WiBro is a registered trademark of the Telecommunications Technology Association. WiMAX is a registered certification mark and registered service mark of the WiMAX Forum. VNC is a registered trademark of RealVNC Ltd. in the U.S. and in other countries. PhotoMOS is a registered trademark of Panasonic Corporation. Styrofoam is a trademark of The Dow Chemical Company. All other trademarks are property of their respective owners.

Teradyne, Inc.

600 Riverpark Drive

North Reading, Massachusetts 01864

End User License Agreement

Copyright 1997-2014 Teradyne, Inc. All Rights Reserved

Inclusion of a copyright notice does not imply that this software has been published.

This software is the trade secret information of Teradyne, Inc.

Use of this software is only in accordance with the Software License Agreement from Teradyne, Inc.

Software License Agreement

Upon the execution of this License Agreement in duplicate by the undersigned ("Customer"), subject to Teradyne's acceptance, Teradyne, Inc. grants to Customer, under the terms and conditions set forth herein, the non-exclusive and non-transferable right to use standard Teradyne Software and related documentation furnished by Teradyne.

1. Customer and its consolidated subsidiaries have the right to use Teradyne Software only with the specific system or systems for which it is authorized (designated by serial number or other designation acceptable to Teradyne), except for a temporary emergency due to equipment malfunction. Customer's rights in Teradyne Software and Software Documentation are user's rights only, and all title and ownership rights in them remain with Teradyne (or the supplier to Teradyne). Customer acknowledges that the Teradyne Software and related documentation contain trade secret and proprietary information of Teradyne, and agrees not to disclose it to any third parties, using the same degree of care as with its own materials of a similar nature. No additional copies of Teradyne Software or related documentation will be made by Customer except for archival or emergency backup purposes, or for use only on authorized systems by its operators who have agreed to observe these restrictions. Any such copy must contain the copyright or proprietary notice as furnished with the original. Customer agrees to allow Teradyne to monitor compliance with these conditions in a manner which does not interfere with normal business operations.

2. If a warranty applies to any item of Teradyne Software, the duration of the warranty will be one year from the date of delivery. Teradyne's warranty is that the Software will function in accordance with the description contained in the Software Documentation. If Customer notifies Teradyne within the warranty period that it suspects an error in the program logic of the Teradyne Software, Teradyne shall use its best efforts to confirm the existence of such error. If the error is confirmed, Teradyne shall undertake, at no charge to Customer, sufficient efforts as it determines necessary to: (i) apply a temporary correction; or (ii) develop an emergency bypass if the System is inoperable. If Teradyne determines that neither (i) nor (ii) is practical, then Teradyne may satisfy its warranty obligations by returning any license fee paid in exchange for return of the Software. If Teradyne reasonably determines that no such error exists, Customer agrees to pay Teradyne for its services at Teradyne standard charges, including reasonable travel and living expenses. This warranty extends

to the original Customer only, and applies only to the then current unaltered form of the Teradyne Software. This paragraph states the full warranty obligation for Software prepared by Teradyne. TERADYNE MAKES NO OTHER WARRANTIES OR REPRESENTATIONS, EXPRESS OR IMPLIED, IN FACT OR IN LAW, INCLUDING THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. IN NO EVENT WILL TERADYNE BE LIABLE FOR INCIDENTAL, SPECIAL OR CONSEQUENTIAL PENALTIES OR DAMAGES, INCLUDING LOST PROFITS, OR PENALTIES AND/OR DAMAGES FOR DELAY IN DELIVERY OR FAILURE TO GIVE NOTICE OF DELAY, EVEN IF TERADYNE HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. CUSTOMER AGREES THAT ANY LIABILITY OF TERADYNE HEREUNDER FOR DAMAGES, REGARDLESS OF THE FORM OF ACTION, SHALL NOT EXCEED THE LICENSE CHARGES PAID BY CUSTOMER FOR THE PARTICULAR SOFTWARE INVOLVED.

3. This License Agreement also governs any updates or enhancements to Teradyne Software furnished by Teradyne. This License Agreement continues in effect until terminated by ninety (90) days written notice from either party. Such termination will not affect Customer's rights with respect to Teradyne Software furnished prior to the termination date. In addition, Teradyne can terminate Customer's rights to use Teradyne Software for any material failure to perform Customer's obligations under this License which is not remedied within thirty (30) days of written notice, or failure to pay any fees related to Teradyne Software, or Customer's ceasing to do business or becoming bankrupt. If Teradyne terminates for such cause, Customer agrees to return all Teradyne Software and Software Documentation including any copies or partial copies. After termination of this License Agreement for any reason the obligation of Paragraph 1 will continue for all Teradyne Software furnished prior to the termination date.

4. License fees for Software shall be at the prices prevailing at the time the order is received. Except as modified herein, terms shall be the Standard Teradyne Terms and Conditions, incorporated herein by reference, at the time the order is received.

5. Any change to this License Agreement must be in writing, signed by both parties. Interpretation of this License Agreement will be governed by the laws of the Commonwealth of Massachusetts. When a separate Software License exists or is required, such as for specific programs, source code, or third party software, the terms of that License will govern and this License Agreement will not apply.

	
---	---

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.02

	
---	---

[IG-XL V8.30.00 Release Notes](#) : Installing IG-XL V8.30.00

Installing IG-XL V8.30.00
Installing IG-XL
To install IG-XL V8.30.00:

- | | |
|----|---|
| 1. | Disable any antivirus software running on the computer that you are using for installation. |
|----|---|
- [See DSP PC Installation Changes in V8.30.00](#) for information regarding an issue with firewall settings.
- | | |
|----|---|
| 2. | Navigate to the folder that contains the installation files. If you are installing from the distribution disc, this is the \IG-XL folder. |
|----|---|
- | | |
|----|--|
| 3. | Run Setup.exe and accept all defaults. |
|----|--|

[If you are not logged in using an account with Administrator privileges, right click Setup.exe and select Run as administrator.](#)

[If you do not have Microsoft SQL Server installed, Setup launches installation for SQL Server 2008 Express SP1:](#)

[Once the SQL Server installation completes, IG-XL Setup continues automatically.](#)

[If you do not have Java Runtime Environment \(JRE\) 1.6.0_21 installed, Setup installs it before installing IG-XL. If you have an earlier version of JRE, Setup upgrades it to version 1.6.0_21 and maintains your settings.](#)

[IG-XL requires Microsoft’s .NET Framework V4.0. If the .NET Framework V4.0 or later is not already installed on your computer, IG-XL Setup installs it. To do this, IG-XL Setup starts a separate](#)

installation program. Do not interrupt, cancel, or bypass this installation. Once the .NET installation completes, IG-XL Setup continues.

4. Restart the antivirus software on the computer that you used for installation.
5. Reboot your installation computer before using IG-XL.

Directory for Installation

By default, the installation procedure uses \Program Files\Teradyne\IG-XL (or Program Files (x86)) as the installation directory. You should accept this default.

If you install several versions of IG-XL, use this directory for all versions. This is particularly important because all versions share the same calibration database, which is located at IG-XL\Cal. Installing all versions of IG-XL in the recommended folder means you do not need to recalibrate the test system when you switch versions. This is because the new version can use the same calibration database. If you install the versions in different locations (for example, on different hard drives) the versions cannot share the calibration database, and you must recalibrate after switching versions.

Install IG-XL only in the Program Files (x86) folder on the drive you choose. For example, to install IG-XL on drive C:, install it in C:\Program Files (x86). Installing IG-XL in a different folder may prevent the IG-XL ribbon from loading when you are loading a test program.

Uninstalling IG-XL

To remove IG-XL entirely:

1. From the Windows Start Menu, select Settings>Control Panel>Add/Remove Programs.
2. In the Add/Remove Programs dialog box, click the version of IG-XL that you want to remove.

If you have multiple versions installed, each version is listed separately.

3. Click Change/Remove.
4. Follow the prompts to complete the uninstallation.
5. If you have multiple versions of IG-XL installed on this computer and you have removed the current version, switch to a version that you want to make current.

Installing IG-XL Patches

IG-XL patches contain functionality that was not available at the time of the original release, including bug fixes.

To apply a patch, run the software installer. Patch installers are cumulative and install all files for that patch and earlier patches.

Patches are specific to one version of IG-XL. Before you install a patch, make sure that the version you want to modify is the current version.

Note that all patches are removed when you reinstall or uninstall the base IG-XL software. If a patch fails to uninstall, remove and reinstall the base software to clear the patch.

For more information on patches, see the Version Selector Plus manual. Version Selector Plus installs in a separate item on the Windows Start menu. To view the manual, start Version Selector Plus, then click Help.

Installing Virus Protection

Teradyne recommends that you install and use virus protection on all test systems. For information on Teradyne’s Virus Protection Policy, see “Virus Protection” in the IG-XL Administration and Licensing section of Help.

ReadMe_V8_30_00_uflx.1.03

<

>

IG-XL V8.30.00 Release Notes : Getting Assistance in eKnowledge

Getting Assistance in eKnowledge

Teradyne’s eKnowledge portal is a primary source of Teradyne product support and information. If you have questions about Teradyne products, search eKnowledge before calling Teradyne Support. eKnowledge is available at <http://support.teradyne.com>.

To log in to eKnowledge, you must have a user name and password. Obtain these from Teradyne’s Semiconductor Test Field Support.

eKnowledge includes additional information, including:

Product Alerts	Contains late-breaking documentation, such as notifications of and workarounds for software and hardware issues.
Centers of Excellence	Contains additional information on test and test issues, such as Applications Notes.

Copies of IG-XL online documentation, IG-XL Help, are available in eKnowledge. You can view Help in either of the following ways:

- View IG-XL Help online in eKnowledge. On the eKnowledge Home page, click IG-XL Help under Support Links (lower left of the page). This brings up a list of IG-XL Help versions. Click a version, and that version of IG-XL Help comes up in an on-line viewer.
- View the HTML Help version of IG-XL Help as installed with IG-XL on your own PC. (This is stored in one ZIP file.)

To locate and download IG-XL Help files in eKnowledge:

1.
- In the search box at the top of the eKnowledge Home page, enter “IG-XL Help” and click SEARCH.

eKnowledge displays a list of documents that contain your keywords. Results are sorted by relevance, with the most-likely matches at the top of the list.

2.
- View the file:

- a.
- To view the file in your browser, click the manual title. Note that IG-XL Help files are large and take some time to display.
- b.
- To save a file on your local computer, right-click the manual title and select Save Target As. Your browser asks you to supply a folder and filename.

To view IG-XL Help once you have saved the ZIP file to your local computer:

1.
- Extract all files from the ZIP.

You can extract the files into the same folder in which you stored the ZIP file. Avoid extracting files to your desktop.

 Note:

IG-XL Help files must be run on your local computer. They do not open over a network.

2.
- Double-click any .chm file (denoted by a yellow question mark icon) to launch IG-XL Help:

	DatalogSupportInternal.dll	4/3/2012 3:39 AM	Application extens...	7 KB
	DataLogViewer.exe	4/3/2012 4:23 AM	Application	264 KB
	DataTool.chm	4/9/2012 9:05 AM	Compiled HTML ...	2,370 KB
	DataTool.xla	4/3/2012 4:23 AM	Microsoft Office E...	3,419 KB
	DatatoolExternalUtility.dll	4/3/2012 6:16 AM	Application extens...	145 KB

.chm File in Windows Explorer

IG-XL Help starts and displays help for the topic you selected.

3.
- Use the Table of Contents pane at the left of the Help browser window to navigate to the topic you want to view.

For more information, see “Using IG-XL Help” in the IG-XL Help doc set.

<		>	
	2015 Teradyne, Inc. All rights reserved.		

ReadMe_V8_30_00_uflx.1.04

<	>
--------------------------------------	--------------------------------------

[IG-XL V8.30.00 Release Notes](#) : General Notes on V8.30.00

General Notes on V8.30.00

General notes on this release include the following:

- | | |
|---|---|
| • | System Requirements |
| • | Patches Included in This Release |
| • | Licensing for IG-XL V8.30.00 |
| • | Operating System for DSP PCs |
| • | DSP PC Installation Changes in V8.30.00 |
| • | Version Selector Plus |
| • | Uninstalling Inactive Versions of IG-XL |
| • | Installing ESA for IG-XL V8.30.00 (ESA 4.5) |
| • | Using Remote Desktop |
| • | Microsoft Service Pack and Hotfix Policy |

- [Configuration Used to Test This Release](#)

	
---	---

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.05

<

>

[IG-XL V8.30.00 Release Notes](#) : [General Notes on V8.30.00](#) : [System Requirements](#)

System Requirements

IG-XL V8.30.00 requires certain hardware and software to operate properly. This topic describes the following system requirements:

- [IG-XL Online Requirements](#)
- [IG-XL Offline Requirements](#)
- [IG-XL Support for Excel](#)
- [Datalog SDK](#)

For information on Windows and computer support of IG-XL versions, consult [Teradyne IG-XL Tester Computer, Windows and Office Support Table](#) in eKnowledge.
Note that IG-XL no longer supports Windows XP in either online or offline environments as of V8.30.00.

IG-XL Online Requirements

IG-XL V8.30.00 has been successfully tested on the following configuration:

- [Tera1 Tester Computer](#)
- [Microsoft Windows 7 x64 SP1](#)
- [Microsoft Office 2010 x86 \(32-bit\) SP2](#)

For a DSP PC, see Operating System for DSP PCs.

Administrator privilege is required for installation.

IG-XL Offline Requirements

- | | |
|---|--|
| • | 2.8 GHz Pentium 4 processor (2 GHz Core Duo recommended) |
| • | At least 4 GB of RAM |
| • | At least 6 GB of free hard disk space |
| • | DVD drive if using DVD to install IG-XL (IG-XL is also available for download from eKnowledge) |
| • | Display capable of 1024x768 pixel resolution (1280x1024 recommended) |
| • | Windows 7 Enterprise 64-bit edition or Windows 7 Professional 64-bit edition |
| • | Microsoft Excel 2010 (32-bit) SP2 |
| • | Administrator privilege (for installation only) |

IG-XL Support for Excel

IG-XL V8.30.00 requires Microsoft Excel 2010. Earlier and later versions are not supported.

Datalog SDK

The Datalog DSK requires Visual Studio 2010 or later.

ReadMe_V8_30_00_uflx.1.07



[IG-XL V8.30.00 Release Notes](#) : [General Notes on V8.30.00](#) : [Licensing for IG-XL V8.30.00](#)

Licensing for IG-XL V8.30.00

Note the following for 8.30.00:

- [Make sure that your licenses support your current instrumentation and the current version of IG-XL. For more information, see the following section in IG-XL Help: IG-XL Administration and Licensing>IG-XL Licensing.](#)
- [Self Service Licensing \(SSL\) is now available and provides responsive, immediate, and streamlined software license management for all IG-XL users. SSL is available for all versions of IG-XL on all IG-XL based platforms, and it is the preferred method of obtaining and administering IG-XL licenses.](#)

The components of SSL are:

- [Self Service Licensing \(SSL\) software that you install on your machine \(required on any machine that is running IG-XL or hosting floating licenses for other machines running IG-XL\)](#)
- [License Activation Utility to activate, return, transfer, and upgrade licenses](#)
- [Teradyne Self Service Licensing Portal to manage licenses across the fleet](#)

[SSL replaces the older style certificate based licenses.](#)

<		>	
	2015 Teradyne, Inc. All rights reserved.		

ReadMe_V8_30_00_uflx.1.08

<	>
-----------------	-----------------

[IG-XL V8.30.00 Release Notes](#) : [General Notes on V8.30.00](#) : Operating System for DSP PCs

Operating System for DSP PCs

All DSP PCs in an UltraFLEX test system should have the same operating system configuration, including the same Service Pack level. While there are currently no known problems with OS mismatches, using the same configuration minimizes the potential for future problems. Note the following:

- The operating system (OS) for the DSP PC may differ from the tester computer OS.
- Embedded Signal Analyzer (ESA) 4.5 requires the use of the third generation or newer UltraFLEX DSP PCs.

<	>
-----------------	-----------------

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.09

<

>

[IG-XL V8.30.00 Release Notes](#) : [General Notes on V8.30.00](#) : DSP PC Installation Changes in V8.30.00

DSP PC Installation Changes in V8.30.00

In V8.30.00, IG-XL changes the way the host/tester computer communicates with the DSP computers in the test system. This change allows faster transfer of DSP data and shortens test times for processing-intensive tests.

The firewall settings on the tester’s host computer must be as follows:

- Deny all incoming traffic from the Internet to IG-XL.
- Permit incoming and outgoing traffic from all clients (local, ttdsppc0, ttdsppc1) for TCP port 135 (this is port-level exception).

Note: If for some reason you fail to make this change until after IG-XL is installed, the installation process may report errors, but the installation does not fail. It is safe to ignore the errors.

- Permit incoming and outgoing traffic from all clients (local, ttdsppc0, ttdsppc1) to the TCP all ports for IG-XL (this is application-specific exception).

How you create an exception in the firewall depends on which firewall software is running on your host computer and how your organization chooses to deploy these settings.

If you are using Windows Firewall on the tester’s host computer, you can use these commands:

- To establish a firewall exception for DCOM port 135, use the following command:

```
netsh advfirewall firewall add rule dir=in name="DCOM"  
program=%systemroot%\system32\svchost.exe service=rpcss action=allow protocol=TCP  
localport=135
```

2.

To establish a firewall exception for IG-XL, use the following command:

```
netsh advfirewall firewall add rule dir=out name ="IGXL" program=C:\Program Files (x86)\Microsoft Office\Office14\EXCEL.EXE action=allow protocol=TCP localport=any
```

For IG-XL, the incoming ports are allocated dynamically, like outgoing ports. Teradyne recommends an application-specific rule rather than a port-centric approach.

If you use third-party firewall software instead of Windows Firewall, you need to configure your firewall to reflect the settings detailed above.

☒ **Note:**

None of the above charges need to happen on the DSP PC. The DSP PCs have already been preconfigured for these communication settings.

ReadMe_V8_30_00_uflx.1.10

<	>
-----------------	-----------------

IG-XL V8.30.00 Release Notes : [General Notes on V8.30.00](#) : Version Selector Plus

Version Selector Plus

Version Selector Plus (VS+) is not distributed with IG-XL. This allows more frequent updates to VS+. For each release of IG-XL, the installation checks whether the version of any VS+ already installed is lower than the minimum version required for the version of IG-XL being installed. If it is lower, the installation removes the Start menu item and the files for the installed VS+. It replaces the Start menu item with a web page explaining the VS+ installation and upgrade. The web page contains a link to eKnowledge to let you install or upgrade VS+. Click the link to begin the installation. To follow the link, you must log into eKnowledge.

This process ensures that the VS+ you have installed always supports the version of IG-XL you have installed.

IG-XL V8.30.00 requires Version Selector Plus V52.0 or later.

<	>
-----------------	-----------------

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.11

<	>
-----------------	-----------------

IG-XL V8.30.00 Release Notes : [General Notes on V8.30.00](#) : Uninstalling Inactive Versions of IG-XL

Uninstalling Inactive Versions of IG-XL

You can have multiple version of IG-XL installed at the same time. One is the active version and the others are inactive. You can use [Version Selector Plus \(VS+\)](#) to switch among versions.

Under releases before IG-XL V8.00.00, uninstalling an inactive IG-XL release affects the active release, requiring you to use VS+ to make the active release fully functional again.

In IG-XL V8.00.00 and later, uninstalling an inactive V8.00 or later version does not affect the active release and therefore does not require the use of VS+. Note the following:

- | | |
|--|---|
| | <ul style="list-style-type: none">If the active version is V8.00 or later, and the inactive version is V8.00 or later, uninstalling the inactive version does not affect the active version. |
| | <ul style="list-style-type: none">If the active version is V8.00 or later, and the inactive version is earlier than V8.00, uninstalling the inactive version affects the active version, and you must use VS+ to reactivate the active version. |

<	>
-----------------	-----------------

ReadMe_V8_30_00_uflx.1.12

	
---	---

[IG-XL V8.30.00 Release Notes](#) : [General Notes on V8.30.00](#) : Installing ESA for IG-XL V8.30.00 (ESA 4.5)

Installing ESA for IG-XL V8.30.00 (ESA 4.5)

Embedded Signal Analyzer (ESA) Toolkit 4.5 is required for ESA operations in IG-XL V8.30.00. The ESA Toolkit file, along with a PDF file with the instructions for installing ESA, can be found in [eKnowledge](#), which is available at <http://support.teradyne.com>. On the eKnowledge, home page, click View Your COEs under Center of Excellence, and select ESA Toolkit from the COE list.

ESA Toolkit can take some time to download, so start the download well before the time you want to install ESA.

The following information summarizes installation for ESA 4.5. For more information, see "Installing the V4.5 ESA Toolkit," available for download from eKnowledge.

System Requirements

To use ESA 4.5, the tester computer must meet the following minimum requirements:

- | | |
|---|--|
| • | Teradyne supplied Tera1 Tester Computer or newer |
| • | 6GB of free hard disk space |
| • | Microsoft Windows 7 x64 SP1 |
| • | Microsoft Excel 2010 x86 (32 bit) SP2 |
| • | Administrator privilege (for installation only) |

Note the following:

- ESA 4.5 requires third generation or newer UltraFLEX DSP PCs.
-
- To install ESA 4.5, turn off any antivirus software.

 Note:

Earlier versions of the DSP PC lack the prerequisites required to run VSA-B V17.22. Therefore, Teradyne cannot guarantee the functionality and performance of ESA software on those DSP PCs. If a DSP PC does not meet minimum requirements, the ESA installer issues this warning:
The DSP Computers installed on this tester do not meet the minimum system requirements. Click "OK" to stop installation. Click "Ignore" to continue with the installation. Note that Teradyne cannot guarantee the performance and functionality of ESA if the minimum system requirements are not met.

DSP PC Physical Memory and Maximum VSA Instances

Minimum system requirements for this version have increased due to requirements for Keysight Technologies 89600 VSA Software. For VSA-B V17.22, which is used for ESA 4.5, the maximum number of instances that can be created on a DSP PC is limited by the amount of physical memory (RAM) available. This is due to the large footprint of VSA-B instances.
Note the following:

- The concrete physical memory per VSA instance consumed is VSA standard and test setup dependent.
-
- On average, 1 GB of physical memory can support eight VSA instances.
-
- ESA 4.5 only supports memory configurations of third generation or newer UltraFLEX DSP PCs. DSP PCs with other memory configurations do not support ESA 4.5.

Licensing for ESA 4.5

IG-XL supports multiple versions of the ESA Toolkit software. The following table maps versions of IG-XL to versions of ESA Toolkit and VSA.

IG-XL Versions Mapped to ESA and VSA		
IG-XL Version	ESA Version	VSA Version
7.10.00	2.51 (replaces 2.50)	8.00
7.30.00	2.51 (replaces 2.50)	10.02

7.40.00	2.51 (replaces 2.50)	11.21
8.00.00	3.01 (replaces 3.00)	12.00
8.10.00	3.5	14.22
8.10.10	3.6	14.22
8.10.11	3.6	14.22
8.10.12	3.6	14.22
8.10.14	3.61	14.22
8.14.00 P1	3.63	14.22
8.20.00	3.63	14.22
8.20.00 P1	4.0	17.22
8.30.00	4.5	17.22

As the table shows, ESA Toolkit 2.5 has been replaced by 2.51, and ESA Toolkit 3.0 has been replaced by 3.01.

☑ Note:

ESA Toolkit 3.6 and later are incompatible with the previously released ESA Toolkit 2.5 and 3.0. Version switching between IG-XL versions will fail using the older ESA Toolkits. Therefore, installing ESA Toolkit 3.6 and later automatically updates older installed ESA versions to 2.51 or 3.01. If you need several versions of ESA Toolkit, install ESA Toolkits chronologically, installing the oldest versions first and ESA Toolkit 3.6 or later last.

Versions of ESA Toolkit before 3.5 (2.51 and 3.01, which include VSA 12.00 or lower) use VSA-A licenses. VSA-A licenses are specified in the environment variable AGILEVSA2_LICENSE_FILE. VSA-A Agilent license files are located in the tester computer folder C:\Windows\vsa\licenses.

ESA Toolkit 3.6 and later include versions of VSA that use VSA-B licenses. (ESA Toolkit 3.6 uses VSA 14.22, and ESA Toolkit 4.0 and 4.5 use VSA 17.22.) Keysight Technologies Licensing is controlled by a license manager. Installation of VSA 17.22 installs the following new programs:

- Agilent Host Processor Platform
- ACCL Licensing
- Agilent License Manager
- Agilent Translator Framework

To obtain a license from Keysight Technologies, you must have the following information from the tester computer:

- Host Name

- MAC address

Note: If you already have an VSA-A license, obtaining the VSA-B license is free.

If the current machine already has a VSA-A based installation, you should be able to obtain the MAC address and Host Name using LMTOOLS. Do the following:

1. [Navigate to](#) Start>All Programs>Agilent 89600 License Support>LMTOOLS.

2. [Click the System Settings tab.](#)

The [Host Name](#) is found in the Computer/Hostname, field, and the MAC address is found in the Ethernet Address field.

3. [As an alternative, open a command line window and type in](#) ipconfig /all.

In the [command window](#), the [Host Name](#) is found under Host Name, and the MAC address is found under Physical Address.

4. [Contact Teradyne to obtain VSA-B license files based on the MAC address and Host Name.](#)

5. [Once you obtain the files, copy them to](#) C:\Windows\vas\licenses on the Host PC. Perform this step before installing ESA Toolkit 4.5.

For more information, see “Installing the V4.5 ESA Toolkit.”

Replacing the Tester Computer or DSP Computer

If you must replace the tester computer or a DSP PC, uninstall all ESA Toolkits, starting with the newest version. If ESA Toolkit 2.51, 3.01, and 3.5 are all active on the system, you must uninstall ESA Toolkit 3.5 first, followed by 3.01, and then 2.51 last.

Once you install the new computer, reinstall ESA Toolkits as described in “Installing the V4.5 ESA Toolkit.”

Note that you must request a new VSA-B license from Teradyne as the Host ID will be different on a new host machine. Follow the same sequence, as described in the installation guide to retrieve the

VSA-B license. By going through the install procedure (as already stated, you must place the VSA-B license files in the appropriate directory before ESA 3.6 and later installation), the correct VSA-B license file will be copied to the DSP PCs. You should not have to manually intervene on the DSP PCs.

Verifying ESA 4.5 Installation

You can run the Verify Installation function from About IG-XL to verify that IG-XL and ESA Toolkit 4.5 are installed correctly. The Verify Installation of About IG-XL takes longer when ESA is installed because it verifies both the ESA installation and the IG-XL installation.

Additional Notes on ESA 4.5 Installation

Note the following on installing ESA 4.5:

- To access DSP PCs, you must use VNC. If your tester computer does not have RealVNC or UltraVNC installed, you must install UltraVNC:

<http://sourceforge.net/projects/ultravnc/>

- Tester computers and DSP PCs require Windows Internet Explorer version IE8 or higher.

- Before installing ESA Toolkit 4.5, ensure that IG-XL V8.30.00 or later is installed and is the active version of IG-XL. If IG-XL V8.30.00 or later is not installed, install it. If V8.30.00 or later is installed but another version of IG-XL is active, use Version Selector Plus to switch IG-XL version to V8.30.00 or later.

- Version Selector Plus V51.00.00 or higher is required for version switching between ESA Toolkits to work properly. To install VS+, go to the following in eKnowledge:

https://ebusiness.teradyne.com/eknowledge/urlredirect/VersionSelectorPlusInstall.exe?dDocName=P_030439&filename=VersionSelectorPlusInstall.exe

- Windows 7 installations of ESA do not support version switching below IG-XL V8.10.10.

- For VSA-B macro importing and exporting, one of the following must be installed on the tester computer to avoid possible issues:

- Visual C# 2010 Express (free):

<http://www.microsoft.com/visualstudio/en-us/products/2010-editions/visual-csharp-express>

- [Microsoft Windows SDK for Windows 7 and .NET Framework 4:](#)

<http://www.microsoft.com/download/en/details.aspx?id=8279>

You can uncheck everything but the .NET Development item in Installation Options to reduce the size of and time required for installation.

- [Manual installation of VSA17.22 is the workaround in cases where automatic installation of 4.5 fails. In rare cases, that too may not work. The workaround in those cases is to uninstall VSA14 from add/remove program to get ESA 4.5 to work.](#)
- [Test programs using ESA 4.5 with IG-XL 8.30 can see a time increase when running either of the following during OnProgramValidated:](#)

[Demod.Instances.ApplySettings](#)

[Demod.Instances.Item\(instanceName\).ApplySettings](#)

This increase is due to a change that makes VSA instance setups inside [.ApplySettings](#) be synchronous procedures when operating on the tester computer. The time increase depends on the number of Demod instances defined and the types of VSA standards tested. You can observe this increase by noting the time of the Validation Completed Successfully indicator in the bottom left corner of the DataTool window. For example, the ESA training program includes nine Demod instances, including VSA measurement types of Digital Demod, GSM, W-CDMA, and Vector mode for the corresponding nine VSA instance setups on the tester computer. Running this program with [.ApplySettings](#) inside OnProgramValidated in 8.30 results in a validation time of 57 seconds, an increase of 76%.

- [If you only have a Teradyne Modulation Base Bundle \(Rev B\) \(that is, the ESA basic license\) and your test program attempts to access the 802.11ac feature, you may not see a licensing error for 802.11ac during the ESA based test program run. This is because 802.11n \(which is covered by the ESA base license\) shares the same demodulator with 802.11ac \(which requires an ESA advanced license\). VSA will try to set up measurements as close as possible based on the license enabled feature \(802.11n, in this case\).](#)
- [VSA behavior changed after version 14, including VSA 17.22 that ESA 4.0 and 4.5 supported. A Demod test that uses a VSA setup file with more traces defined can lead to a significant performance overhead. To achieve a better performance, optimize VSA setup files used in an ESA test program to minimize the traces defined there. To do this, remove unused traces or set them to a "No Data" state to improve run-time performance.](#)

For more information, see ["Installing the V4.5 ESA Toolkit."](#)

<	>	
	2015 Teradyne, Inc. All rights reserved.	

ReadMe_V8_30_00_uflx.1.13

	
---	---

[IG-XL V8.30.00 Release Notes](#) : [General Notes on V8.30.00](#) : Using Remote Desktop

Using Remote Desktop

IG-XL users working online can connect to remote test systems using Microsoft's Remote Desktop software.

Remote Desktop in Windows 7 works significantly differently from the way it worked in earlier versions of Windows. In particular, the Remote Desktop Connection (RDC) under Windows 7 does not terminate an existing local session when another user remotely logs in using RDC. Instead, RDC preserves the local session and puts it in the disconnected state.

This change in handling local and remote sessions can create problems if more than one person is logged on to the tester computer. For example, one user may be running IG-XL while another user is installing IG-XL. Or both users may be running IG-XL simultaneously.

A possible alternative to Remote Desktop, VNC, can also be used to make connections when running IG-XL remotely online. Teradyne includes VNC on all tester computers.

Note:

Do not use Remote Desktop to connect to DSP PCs. Use VNC only.

	
---	---

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.14

<

>

IG-XL V8.30.00 Release Notes : [General Notes on V8.30.00](#) : Microsoft Service Pack and Hotfix Policy

Microsoft Service Pack and Hotfix Policy

Teradyne’s policy on Microsoft hotfixes, also known as QFE (Quick Fix Engineering) or LDRs (Limited Distribution Releases), and security updates, and Microsoft service packs is as follows:

- The release notes for each IG-XL version describe the minimum Windows service pack and Microsoft Excel and Office software required for that release. These requirements are set based on how the release was developed and tested. Higher service pack versions will be supported by Teradyne. Lower service pack versions are not supported.
- Teradyne does not qualify every IG-XL release against every Microsoft hotfix or all combinations of hotfixes.
- Each month, Teradyne updates its quality assurance (QA) IG-XL testing configuration to the latest Microsoft hotfixes. Teradyne tests newer patches and releases against the latest testing configuration. (See [Microsoft Security Patch Testing](#) below.) In the rare event that we find an issue with a hotfix, we publish a Product Support Bulletin (PSB) with instructions for dealing with the issue.
- If a customer installs a Microsoft hotfix and experiences a problem, Teradyne will investigate and provide advice to the customer. The advice may be to remove the hotfix, to use a workaround, or an IG-XL patch (if the IG-XL release is the most current one).

Microsoft Security Patch Testing

Microsoft frequently releases security patches (also known as “security updates”). These patches can sometimes affect products or tools that are used to build or run IG-XL. The Teradyne Patch

Management Group (PMG), with help from both IG-XL Software Engineering and IG-XL Release Engineering, identifies potentially disruptive patches. These patches are tested before they are released into the Teradyne community. Testing is done by IG-XL Release Engineering and QA AutoTest, and problems encountered are escalated to IG-XL Software Engineering.

An isolated build environment is created consisting of a build machine and optionally multiple accelerator machines. A project with passing builds and stable AutoTest results using the standard “unpatched” production configuration is also identified. The source code baseline from that build and the build’s AutoTest results become our standards for testing a patch.

A patch to be tested is identified. It is installed on all required build machines, and an On-Demand build is performed using the known good source code baseline.

If the build fails, then build failures are analyzed by Release Engineering and escalated to Software Engineering. Software Engineering determines if any IG-XL code changes should be made to allow IG-XL to be compatible with the patch. All further work on testing this patch is suspended pending a decision from Software Engineering.

If the build passes, the kit is sent to AutoTest. The patch is installed on all required AutoTest machines, and regression tests are performed. The results are compared to the unpatched results. If differences occur between patched and unpatched results, AutoTest will analyze the differences and then escalate any issues to Software Engineering. As a result, changes may be made to AutoTest or IG-XL product code or both.

When QA AutoTest and Software Engineering agree that the results are stable with the patch installed, then the patch is approved and can be released for deployment.

ReadMe_V8_30_00_uflx.1.15

<

>

IG-XL V8.30.00 Release Notes : [General Notes on V8.30.00](#) : Configuration Used to Test This Release

Configuration Used to Test This Release

The following list provides details of the test system computer configuration this release has been tested against. The list includes:

- [MS service packs and hot fixes installed on QA CPUs](#)
- [CPU types \(Tera1\)](#)
- [DSP types \(2009, UltraDSP1\)](#)
- [Antivirus information](#)
- [VNC software](#)
- [Visual Studio versions and patches installed](#)

System information for \\TUFLX19:
Uptime: 2 days 16 hours 35 minutes 45 seconds
Kernel version: Windows Embedded Standard, Multiprocessor Free
Product type: Professional
Product version: 6.1
Service pack: 0
Kernel build number: 7601
Registered organization: Microsoft

Registered owner: Microsoft

IE version: 8.0000

System root: C:\Windows

Processors: 8

Processor speed: 3.2 GHz

Processor type: Intel(R) Xeon(R) CPU E5-2643 0 @

Physical memory: 11920 MB

Video driver: NVIDIA NVS 300

Installed HotFix

n/a Internet Explorer - 0

Applications:

AX88772 1.00.0000

ActivePerl 5.8.9 Build 827 5.8.827

ActiveState Komodo IDE 5.2.4 5.2.4

Adobe AIR 14.0.0.178

Adobe AIR 14.0.0.178

Adobe Flash Player 15 ActiveX 15.0.0.152

Adobe Reader X (10.1.12) 10.1.12

Adobe Refresh Manager 1.8.0

Agilent 89600 License Support

Agilent License Manager 4.5.17814.10823

Agilent Translator Framework 2.0.60

CCleaner (remove only)

CRT-71 1.00.0000

Cadence Allegro Free Physical Viewers 16.3 16.3.0

Compatibility Pack for the 2007 Office system 12.0.6612.1000

Configuration Manager Client 4.00.6468.2000

Crystal Reports for Visual Studio 12.51.0.240

Data Dynamics ActiveBar Version 3.0 3.0

Definition Update for Microsoft Office 2010 (KB982726) 32-Bit Edition

Dotfuscator Software Services - Community Edition 5.0.2300.0

Drivers_TCIT_TCIJ_amd64 1.0.0001

GDR 3077 for SQL Server Database Services 2005 ENU (KB960089) 9.2.3077

GDR 3077 for SQL Server Tools and Workstation Components 2005 ENU (KB960089) 9.2.3077

GSKit8 SSL 32-bit 8.0.50.10

Hotfix for Microsoft .NET Framework 4 Client Profile (KB982638) 1

Hotfix for Microsoft Office 2010 (KB2880541) 32-Bit Edition

Hotfix for Microsoft Visual Studio 2010 Premium - ENU (KB2542054) 1

IBM Installation Manager

IBM Lotus Sametime Connect 8.5.1 8.51.10219

IBM Rational ClearCase

Imca Systems FlyTreeX ActiveX v2.08 (Site License)

Java Auto Updater 2.0.2.4

Java(TM) 6 Update 21 6.0.210

LeakDiag 1.25 1.25.28.2201

MaintenanceWizards 1.09.01 Templates 1.06.01

MaintenanceWizards 1.09.02 Templates 1.06.01

Matrox Graphics Software (remove only)

Microsoft .NET Compact Framework 1.0 SP3 Developer 1.0.4292

Microsoft .NET Compact Framework 2.0 2.0.5238

Microsoft .NET Framework 4 Multi-Targeting Pack 4.0.30319

Microsoft ASP.NET MVC 2 2.0.50217.0

Microsoft ASP.NET MVC 2 - Visual Studio 2010 Tools 2.0.50217.0

Microsoft Application Error Reporting 12.0.6012.5000

Microsoft Chart Controls for Microsoft .NET Framework 3.5 3.5.0.0

Microsoft Device Emulator version 1.0 - ENU 1.0.50727.42

Microsoft Document Explorer 2005 8.0.50727.42

Microsoft Document Explorer 2005

Microsoft Excel 2010 14.0.7015.1000

Microsoft Office 2007 Service Pack 3 (SP3)

Microsoft Office 2010 Primary Interop Assemblies 14.0.4763.1150

Microsoft Office Excel 2010 14.0.7015.1000

Microsoft Office Excel MUI (English) 2007 12.0.6612.1000

Microsoft Office Excel MUI (English) 2010 14.0.7015.1000

Microsoft Office File Validation Add-In 14.0.5130.5003

Microsoft Office Outlook MUI (English) 2007 12.0.6612.1000

Microsoft Office PowerPoint MUI (English) 2007 12.0.6612.1000

Microsoft Office Proof (English) 2007 12.0.6612.1000

Microsoft Office Proof (English) 2010 14.0.7015.1000

Microsoft Office Proof (French) 2007 12.0.6612.1000

Microsoft Office Proof (French) 2010 14.0.7015.1000

Microsoft Office Proof (Spanish) 2007 12.0.6612.1000

Microsoft Office Proof (Spanish) 2010 14.0.7015.1000

Microsoft Office Proofing (English) 2007 12.0.4518.1014

Microsoft Office Proofing (English) 2010 14.0.7015.1000

Microsoft Office Proofing Tools 2007 Service Pack 3 (SP3)
Microsoft Office Proofing Tools 2007 Service Pack 3 (SP3)
Microsoft Office Proofing Tools 2007 Service Pack 3 (SP3)
Microsoft Office Shared MUI (English) 2007 12.0.6612.1000
Microsoft Office Shared MUI (English) 2010 14.0.7015.1000
Microsoft Office Shared Setup Metadata MUI (English) 2007 12.0.6612.1000
Microsoft Office Shared Setup Metadata MUI (English) 2010 14.0.7015.1000
Microsoft Office Standard 2007 12.0.4518.1014
Microsoft Office Standard 2007 12.0.4518.1014
Microsoft Office Standard Edition 2003 11.0.5614.0
Microsoft Office Word MUI (English) 2007 12.0.6612.1000
Microsoft SQL Server 2005
Microsoft SQL Server 2005 Express Edition (SQLEXPRESS) 9.2.3042.00
Microsoft SQL Server 2005 Mobile [ENU] Developer Tools 3.0.0.0
Microsoft SQL Server 2005 Tools Express Edition 9.2.3042.00
Microsoft SQL Server 2008 Browser 10.1.2531.0
Microsoft SQL Server 2008 R2 Data-Tier Application Framework 10.50.1447.4
Microsoft SQL Server 2008 R2 Data-Tier Application Project 10.50.1447.4
Microsoft SQL Server 2008 R2 Management Objects 10.50.1447.4
Microsoft SQL Server 2008 R2 Transact-SQL Language Service 10.50.1447.4
Microsoft SQL Server Compact 3.5 SP2 ENU 3.5.8080.0
Microsoft SQL Server Database Publishing Wizard 1.4 10.1.2512.8
Microsoft SQL Server Desktop Engine 8.00.760
Microsoft SQL Server Setup Support Files (English) 9.00.3042.00
Microsoft SQL Server System CLR Types 10.50.1447.4
Microsoft Silverlight 4.0.60310.0
Microsoft Silverlight 3 SDK 3.0.40818.0
Microsoft Sync Framework SDK v1.0 SP1 1.0.3010.0
Microsoft Visual C++ 2005 Redistributable 8.0.59193
Microsoft Visual C++ 2005 Redistributable 8.0.56336
Microsoft Visual C++ 2005 Redistributable 8.0.61001
Microsoft Visual C++ 2008 Redistributable - x86 9.0.30729.17 9.0.30729
Microsoft Visual C++ 2008 Redistributable - x86 9.0.30729.4148 9.0.30729.4148
Microsoft Visual C++ 2008 Redistributable - x86 9.0.30729.4974 9.0.30729.4974
Microsoft Visual C++ 2008 Redistributable - x86 9.0.30729.6161 9.0.30729.6161
Microsoft Visual C++ 2010 x86 Redistributable - 10.0.40219 10.0.40219
Microsoft Visual C++ 2010 x86 Runtime - 10.0.30319 10.0.30319
Microsoft Visual F# 2.0 Runtime 10.0.30319

Microsoft Visual J# 2.0 Redistributable Package 2.0.50727
Microsoft Visual J# 2.0 Redistributable Package
Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU 8.0.50728
Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU
Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU Service Pack 1 (KB926601) 1
Microsoft Visual Studio 2005 Tools for Office Runtime 8.0.50727.42
Microsoft Visual Studio 2005 Tools for Office Runtime
Microsoft Visual Studio 2010 ADO.NET Entity Framework Tools 10.0.30319
Microsoft Visual Studio 2010 Premium - ENU 10.0.30319
Microsoft Visual Studio 2010 Premium - ENU 10.0.30319
Microsoft Visual Studio 2010 SharePoint Developer Tools 10.0.30319
Microsoft Visual Studio 6.0 Professional Edition
Microsoft Visual Studio Macro Tools 9.0.30729
Microsoft Visual Studio Macro Tools 9.0.30729
Microsoft Web Publishing Wizard 1.53
NI Authentication 2.0 2.0.220.0
NI Certificates Deployment Support 1.02.49152
NI DN 2.0 SP1 installer 2.11.49152
NI EulaDepot 3.0.408
NI GMP Windows 32-bit Installer 11.0.0 11.0.22.0
NI Help Assistant 1.0.11
NI Help Configuration Utility for VS2010 9.1.00154
NI I/O Trace API LV2010 3.0.36.0
NI I/O Trace API LV2011 3.0.36.0
NI I/O Trace API LV86 3.0.36.0
NI I/O Trace API LV90 3.0.36.0
NI IO Trace 3.0.0 3.0.768
NI LabVIEW 2009 SP1 Run-Time Engine Web Services 9.0.234.0
NI LabVIEW 2011 Real-Time Error Dialog 11.0.248.0
NI LabVIEW Real-Time NBFifo 9.0.319.0
NI LabVIEW Run-Time Engine 2009 SP1 9.0.1077.0
NI LabVIEW Run-Time Engine Interop 2009 9.0.149.0
NI LabVIEW Web Server for Run-Time Engine 9.0.185.0
NI LabWindows/CVI 2010 Analysis Library 10.0.0360
NI LabWindows/CVI 2010 Network Variable Library 10.0.0360
NI LabWindows/CVI 2010 TDM Streaming Library 10.0.0360
NI LabWindows/CVI Run-Time Engine 2010 10.0.0360

[NI License Manager 3.6.85](#)
[NI Logos 5.2.1 5.2.28.0](#)
[NI Logos XT Support 5.2.24.0](#)
[NI MAX Remote Configuration Installer 5.0 5.00.49153](#)
[NI MDF Support 3.0.408](#)
[NI MXS 5.0.0 5.00.49153](#)
[NI MXS 5.0.0f1 for LabVIEW Real-Time 5.00.49153](#)
[NI Math Kernel Libraries 1.0.28.0](#)
[NI Math Kernel Libraries 1.0.25.0](#)
[NI Measurement & Automation Explorer 5.0.0 5.00.49153](#)
[NI Measurement Studio Common .NET Assemblies for .NET 2.0 9.1.00159](#)
[NI Measurement Studio Common .NET Assemblies for .NET 3.5 9.1.00159](#)
[NI Measurement Studio Common .NET Assemblies for .NET 4.0 9.1.00159](#)
[NI Measurement Studio GPIB Support for VS2005 9.0.00157](#)
[NI Measurement Studio GPIB Support for VS2008 9.0.00157](#)
[NI Measurement Studio GPIB Support for VS2010 9.0.00157](#)
[NI Measurement Studio MAX Configuration Support for VS2005 8.9.00111](#)
[NI Measurement Studio MAX Configuration Support for VS2008 8.9.00111](#)
[NI Measurement Studio VISA Support for VS2005 9.0.00156](#)
[NI Measurement Studio VISA Support for VS2008 9.0.00156](#)
[NI Measurement Studio VISA Support for VS2010 9.0.00156](#)
[NI MetaSuite Installer 3.0.408](#)
[NI Microsoft Silverlight Wrapper 4.0.307](#)
[NI Network Browser 5.0.0 5.0.293.0](#)
[NI Network Discovery 5.0 5.00.49152](#)
[NI Network Discovery 5.0 for LabVIEW Real-Time 5.00.49152](#)
[NI PXI Platform Framework 1.5.0 1.50.49152](#)
[NI PXI Platform Framework 1.5.0 for Phar Lap ETS 1.50.49152](#)
[NI PXI Platform Services 2.6.2 2.62.49152](#)
[NI PXI Platform Services 2.6.2 Configuration Support 2.62.49152](#)
[NI PXI Platform Services 2.6.2 Expert 2.62.49152](#)
[NI PXI Platform Services 2.6.2 Expert for LabVIEW Real-Time 2.62.49152](#)
[NI PXI Platform Services 2.6.2 for LabVIEW Real-Time 2.62.49152](#)
[NI PXI SystemAPI Expert 2.6.2 2.62.49152](#)
[NI Portable Configuration 5.0.0 5.00.49152](#)
[NI Real-Time Device Manager 1.01.49152](#)
[NI Registration Wizard 1.3.87.0](#)
[NI Remote PXI Provider for MAX 5.0.0 5.00.49152](#)

NI Remote Provider for MAX 5.0.0 5.00.49153
NI SSL Support 11.0.221.0
NI Software Provider for MAX 5.0.0 5.00.49152
NI System API RT 5.0.0 5.0.336.0
NI System API Web-Service 32-bit 5.0.0 5.0.310.0
NI System API Windows 32-bit 5.0.0 5.0.312.0
NI System Configuration Runtime 5.0.0 5.0.362.0
NI System Web Server 2.0 11.0.214.0
NI System Web Server Base 2.0 2.0.220.0
NI TDMS 2.2.8.0
NI Trace Engine 11.0.213.0
NI Uninstaller 3.0.408
NI Update Service 2.0 2.0.270.0
NI VC2005MSMs x86 8.04.0
NI VC2008MSMs x86 9.0.301
NI VC2010MSMs x86 10.0.001
NI Visual C++ 2010 Redistributable Package 10.01.49152
NI Xalan Delay Load 1.10.1 1.10.46.0
NI Xerces Delay Load 2.7.3 2.7.180.0
NI mDNS Responder 1.6 for LabVIEW Real-Time 1.60.49155
NI mDNS Responder 1.6.0 1.60.49155
NI-488.2 3.0 3.00.49152
NI-488.2 3.0 Development Support 3.00.49152
NI-488.2 3.0 for LabVIEW Real-Time 3.00.49152
NI-488.2 Provider for MAX version 3.0 3.00.49152
NI-APAL 2.0 Error Files 2.00.49152
NI-DIM 1.12.0f0 1.120.49152
NI-DIM 1.12.0f0 for Phar Lap ETS 1.120.49152
NI-MDBG 1.11.0f0 1.110.49152
NI-MDBG 1.11.0f0 for Phar Lap ETS 1.110.49152
NI-MXDF 1.12.0f0 1.120.49152
NI-MXDF 1.12.0f0 for Phar Lap ETS 1.120.49152
NI-Mesa 10.0.14.0
NI-ORB 1.10.0f0 1.100.49152
NI-ORB 1.10.0f0 for Phar Lap ETS 1.100.49152
NI-PAL 2.7.0f0 10.80.49152
NI-PAL 2.7.0f0 for Phar Lap ETS 10.80.49152
NI-RPC 4.2.2f0 4.22.49152

[NI-RPC 4.2.2f0 for Phar Lap ETS 4.22.49152](#)
[NI-VISA 5.1.0 for LabVIEW Real-Time 5.10.49152](#)
[NI-VISA 5.1.1 5.11.49152](#)
[NI-VISA 5.1.1 MAX Provider 5.11.49152](#)
[NI-VISA Runtime 5.1.1 5.11.49152](#)
[NVIDIA Stereoscopic 3D Driver 7.17.13.1135](#)
[National Instruments Software](#)
[Procedure Authoring Tool 3.03 Schema 3.0](#)
[Reflection Suite for the Enterprise 7.50](#)
[Reset NI Config 5.0.0 5.0.146.0](#)
[Rohde & Schwarz NRP USB Driver v2.50.0 2.50.0](#)
[Rohde & Schwarz NRP-Toolkit V2.2.0 2.2.0](#)
[Rohde & Schwarz Visa Plugin 1.4.0.3](#)
[SEDana](#)
[Security Update for CAPICOM \(KB931906\) 2.1.0.2](#)
[Security Update for CAPICOM \(KB931906\) 2.1.0.2](#)
[Security Update for Microsoft Excel 2010 \(KB2910902\) 32-Bit Edition](#)
[Security Update for Microsoft Office 2007 suites \(KB2760415\) 32-Bit Edition](#)
[Security Update for Microsoft Office 2010 \(KB2553154\) 32-Bit Edition](#)
[Security Update for Microsoft Office 2010 \(KB2553284\) 32-Bit Edition](#)
[Security Update for Microsoft Office 2010 \(KB2687423\) 32-Bit Edition](#)
[Security Update for Microsoft Office 2010 \(KB2767915\) 32-Bit Edition](#)
[Security Update for Microsoft Office 2010 \(KB2826023\) 32-Bit Edition](#)
[Security Update for Microsoft Office 2010 \(KB2850016\) 32-Bit Edition](#)
[Security Update for Microsoft Office 2010 \(KB2878284\) 32-Bit Edition](#)
[Security Update for Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU \(KB2251481\) 3](#)
[Security Update for Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU \(KB2538218\) 2](#)
[Security Update for Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU \(KB2548826\) 4](#)
[Security Update for Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU \(KB937061\) 1](#)
[Security Update for Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU \(KB973673\) 1](#)
[Security Update for Microsoft Visual Studio 2010 Premium - ENU \(KB2644980\) 1](#)
[Security Update for Microsoft Visual Studio Macro Tools \(KB2669970\) 1](#)
[Self Service Licensing 3.0.5](#)

[Service Pack 2 for Microsoft Office 2010 \(KB2687455\) 32-Bit Edition](#)

[Spread 7](#)

[Teradyne Devel Tools](#)

[Teradyne ESA Toolkit 4.0 4.0](#)

[Teradyne File Monitor 2.02.0000](#)

[Teradyne IG-XL V8.00.01_uflx 8.00.01](#)

[Teradyne IG-XL V8.00.01_uflx\(P4\) 1.0.0](#)

[Teradyne IG-XL V8.10.11_uflx 8.10.11](#)

[Teradyne IG-XL V8.10.12_uflx 8.10.12](#)

[Teradyne IG-XL V8.10.12_uflx\(P302\) 1.0.0](#)

[Teradyne IG-XL V8.20.00_uflx 8.20.00](#)

[Teradyne IG-XL V8.20.00_uflx\(P104\) 1.0.0](#)

[Teradyne IG-XL V8.30.00_uflx 8.30.00](#)

[Teradyne Internal Use Send \(TCIJ\) 1.2 1.2](#)

[Teradyne Maintenance Wizards 1.09.04 1.09.04](#)

[Teradyne VersionSelector Plus 51.00.0000](#)

[Test Process Manager 3.16 Schema 1..](#)

[UltraVnc 1.0.9.6](#)

[Update for Microsoft Filter Pack 2.0 \(KB2837594\) 32-Bit Edition](#)

[Update for Microsoft Filter Pack 2.0 \(KB2837594\) 32-Bit Edition](#)

[Update for Microsoft InfoPath 2010 \(KB2817369\) 32-Bit Edition](#)

[Update for Microsoft Office 2007 Help for Common Features \(KB963673\)](#)

[Update for Microsoft Office 2007 suites \(KB2767849\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2589298\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2589352\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2589352\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2589375\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2597087\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2760598\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2760598\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2760631\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2794737\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2850079\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2850079\) 32-Bit Edition](#)

[Update for Microsoft Office 2010 \(KB2878225\) 32-Bit Edition](#)

[Update for Microsoft Office Excel 2007 Help \(KB963678\)](#)

[Update for Microsoft Office Outlook 2007 \(KB2687404\) 32-Bit Edition](#)

[Update for Microsoft Office Outlook 2007 Help \(KB963677\)](#)

[Update for Microsoft Office Powerpoint 2007 Help \(KB963669\)](#)
[Update for Microsoft Office Script Editor Help \(KB963671\)](#)
[Update for Microsoft Office Word 2007 Help \(KB963665\)](#)
[Update for Microsoft OneNote 2010 \(KB2837595\) 32-Bit Edition](#)
[Update for Microsoft SharePoint Workspace 2010 \(KB2760601\) 32-Bit Edition](#)
[Update for Microsoft Visual Studio 2005 Team Edition for Software Developers - ENU \(KB932232\) 1](#)
[VISA Shared Components 64-Bit](#)
[Visual Studio 2010 Tools for SQL Server Compact 3.5 SP2 ENU 4.0.8080.0](#)
[WaveWizard 2.1.51 2.1.51](#)
[WebEx Recorder and Player 2.9.1700](#)
[microsoft.vs6 1.00.0000](#)

<	>	
	2015 Teradyne, Inc. All rights reserved.	

ReadMe_V8_30_00_uflx.1.16

<	>
-----------------	-----------------

[IG-XL V8.30.00 Release Notes](#) : What's New in V8.30.00

What's New in V8.30.00

IG-XL V8.30.00 contains changes and updates in the following areas (differences are relative to IG-XL V8.20.00):

- | | |
|---|--|
| • | New Tester Options |
| • | New IG-XL Capabilities |
| • | Checkers |
| • | General Enhancements |

<	>
-----------------	-----------------

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.17

<	>
-----------------	-----------------

[IG-XL V8.30.00 Release Notes : What’s New in V8.30.00 : New Tester Options](#)

New Tester Options

High Performance Memory 4.5G and 8.5G Instrument Boards

The HPM-XIO 4.5G instrument (947-245-50) can test devices with data rates up to 4.56544 Gbps, such as GDDR3 SGRAM or DDR4 SDRAM.

The HPM-XIO 8.5G instrument (947-245-52) can test high-end graphics memory devices with data rates up to 8.56544 Gbps, such as GDDR5.

The HPM 4.5G and HPM 8.5G instrument boards support a different MOSC frequency range, which results in slightly different timing specifications. For more information, see the HPM Hardware Specifications and the HPM Timing topic in the HPM Theory of Operation section.

Support for UltraDSP1 Computers with Dual CPUs

IG-XL V8.30.00 now supports UltraDSP1 computers in a dual CPU configuration. Earlier releases supported only a single CPU.

<	>
-----------------	-----------------

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.18

<	>
-----------------	-----------------

IG-XL V8.30.00 Release Notes : [What’s New in V8.30.00](#) : New IG-XL Capabilities

New IG-XL Capabilities

New capabilities in IG-XL V8.30.00 include:

- [Embedded Signal Analyzer \(ESA\) Enhancements](#)
- [System Validation Checker Utility](#)

Embedded Signal Analyzer (ESA) Enhancements

V8.30.00 includes a new version of ESA, ESA 4.5, for UltraWave 12G and UltraWave24. This version of ESA includes the following enhancements and changes:

- [Wireless Standards \(SRC and REC\)](#)
 - [802.11ac MU-MIMO 2x2](#)
 - [802.11p](#)
 - [802.11n \(100 ns RC Window\)](#)
- [Updated to work in Windows 7](#)
- [Support for DSP As Called Architecture in 8.30](#)

System Validation Checker Utility

System Validation Check inspects your current software and hardware environment and reports on whether your environment meets the minimum requirements for the release of IG-XL you are running (see [System Requirements](#)). It writes the configuration and pass/fail status to a text file. This can help you to ensure that your test program runs on a test system that fully supports the resources and IG-XL version your test program expects to find.

You can call this utility as a:

• [Stand-alone graphical utility](#)

• [Command-line text-only utility](#)

• [VBT method](#)

This answers Case 389997.

ReadMe_V8_30_00_uflx.1.19



IG-XL V8.30.00 Release Notes : What's New in V8.30.00 : Checkers

Checkers

Checkers Warn of BIOS Configuration Mismatch

Beginning in V8.30.00, the Maintenance User Interface (MUI) marks BIOS configuration mismatches on Tera1 and DSP computers as an invalid result. If the checker detects that the BIOS configuration does not match Teradyne's recommended setup, the MUI shows the "Invalid" icon (a question mark on a yellow square) in the test tree. The checker writes a warning message to the message window and to the Messages file. The message is similar to the following:

PCIT Quick Check Warnings:

```
%TestType_START Starting CIT_BIOS_Test at 8:22:55 AM
```

```
%WARNING WARNING: IG-XL performance and/or functionality may be affected by the following noncomplying BIOS settings on the system.
```

```
%WARNING WARNING: Mismatched BIOS setting: [BIOS::PCI Configuration] Memory Mapped I/O above 4GB=0 Memory Mapped I/O above 4GB=1 %TestType_END
```

```
**** INVALID**** PCIT_BIOS_Test at 8:22:57 AM
```

In previous releases, the test appeared with the "Passed" icon (a green check mark) in the test tree even if warnings were recorded to the message window and the Messages file.

For details, see the product support bulletin titled [Tera1 BIOS Checker and UltraDSP1 Reported Results Will Be Different in IG-XL 8.30.00](#).

This answers Case 402305.



	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.20

<	>
-----------------	-----------------

IG-XL V8.30.00 Release Notes : [What’s New in V8.30.00](#) : General Enhancements

General Enhancements

This version of IG-XL includes the following general enhancements:

- | | |
|---|--|
| • | DSP Throughput Enhancement |
| • | DSP New Features |
| • | Flow Table Enhancements |
| • | MiniFlow Enhancements |
| • | Limit Sets For Specifying Test Limits |
| • | Bin Tables Can Use Test Instances and Site Variables |
| • | Retest Option for Program Execution |
| • | Pattern Compiler Time Domain Switch Keywords for Digital Instruments |
| • | LMC Syntax Enhancements |
| • | VBT Language Enhancements |

DSP Throughput Enhancement

IG-XL V8.30.00 provides enhanced DSP throughput. No change is needed to existing DSP programs or procedures to take advantage of the enhanced throughput.

- IG-XL now supports multiple DSP processes per site, to speed processing.
- IG-XL now ensures that results that are needed sooner are processed sooner. It is not necessary for the user to arrange the order of the flow to have results ready when needed.
- The DSP computer now delivers results back to the tester computer as soon as they are ready, permitting faster processing on the tester computer.
- The UltraDSP1 computer can populate a second CPU, giving double the number of logical cores and DSP threads and providing more DSP computation bandwidth.

DSP New Features

The following are other new DSP features:

- OnDSPGlobalVariableReset exec interpose function

Provides consistent DSP global variable initialization

This answers Case IDs 400374 and 401647.

- New methods .Ceiling and .Floor

This answers Case ID 391912.

Flow Table Enhancements

The following features have been added to the Flow Table sheet:

- More complex looping opcodes are now supported. In addition to loop n, the flow table now supports these loop structures: For/Next, While/EndWhile, and Do/Until. These loop opcodes, unlike loop, are site-aware.
- The flow table now supports the Break and Continue opcodes for loop exit and MaxLoopCount to avoid infinite loops.

- The flow table lets you turn on outlining, which enables grouping controls for loop blocks and condition blocks. The Outline command is on the right-click context menu. Grouping controls for Use-Limit blocks are always enabled.
- The Pass/Fail Flag columns have become Pass/Fail Action columns. In addition to setting a flag based on the test result, you can now set a site variable, call a subflow, or use the new Break or Continue opcode.
- You can override the Result setting Fail-stop using a run option. Fail-stop causes a failing test to stop execution, even if Do All is enabled. In some cases, you want to override the Fail-stop and allow execution to continue. The Override Fail-stop option lets you do this.
- You can force execution to stop on an error or alarm, even if Do All is enabled. The VBT statement is `TheExec.Flow.ForceStopOnError`.
- The Enable column supports compound logical expressions using ! (not), && (and), and || (or). The entire expression must evaluate to True for the row to be executed.
- A new run option causes IG-XL to check for duplicate test names at run time. It checks the names specified in the TName column of the flow table.
- You can enforce explicit declaration of flags and flow variables in the flow table. This is equivalent to Option Explicit in a VBA module. By default, if a flag or flow variable does not exist when you first use it, it is created. If you enable explicit declaration, using a flag or flow variable that has not been explicitly created generates a validation error. The VBT statement `TheExec.Flow.ExplicitlyDeclareFlagsAndVars` enables this check.
- When using deferred limits checking, you can defer writing any comments in a test (`TheExec.Datalog.WriteComment`) until the limits are evaluated. By default, comments are written when `.WriteComment` is executed. To change the default, use `TheExec.Datalog.WriteCommentDeferralEnabled`.
- Flow table opcodes that create or set flags or variables can now take a comma-separated list in addition to a single item.

- You can turn on row grouping in a large Flow Table sheet.

When a Flow Table sheet has more than 4000 rows, grouping for test and Use-Limits rows is turned off by default for faster loading. When editing a large Flow Table sheet, it can be useful to enable row grouping. The new method TheExec.GroupActiveFlowSheet turns on row grouping for the currently active Flow Table sheet.

This answers Case 374860.

MiniFlow Enhancements

The following features have been added to the MiniFlow tool in TDE:

- The DR button on the MiniFlow toolbar lets you display or hide the reasons that a step is not executed.
- The +- button on the MiniFlow toolbar lets you enable or disable row grouping for tests, loops, and branches.
- Using the MiniFlow Run Options pane, you do not need to click Apply when changing the drop-down or checkbox controls for flow flags, do all, simulate, and assume.

Limit Sets For Specifying Test Limits

IG-XL now supports limit sets. A limit set, allows you to specify all the limits that are to be used by tests in the program. Limit sets include the following features:

- Alternative way to specify limits, but they cannot be used with "Limit In the Flow" (Use-Limits)
- Supports multiple limit sets per flow
 - Allows for reuse of flows in different jobs
 - Active Limit set can be changed during run time without revalidation
 - Allows changes of limit values without test program modification. New limit files (new sets) can be loaded at any time.
 - Supports test program modularity: A single job can use one or more limit set files

- If the active limit set does not have a limit for your test it will result in a run-time error.

- Limit Set Files are tab delimited text files that you can edit in Excel.

- File can be generated from existing use model (VBT, limits in Flow) using “Auto-Create” mode.

- Supports all flow table features

- Support all kinds of limits (parametric, functional template, PPMU template).

Bin Tables Can Use Test Instances and Site Variables

The Bin Table sheet can now directly use test instance results and site variable values as binning criteria. In previous releases, you must set a flag based on a test result and then use the flag in the bin table. You can now directly use a test instance result, thereby simplifying the bin table logic. Using site variables permits the use of bin tables for parametric tests. Site variable criteria can use the equality and relational operators.

A new VBT statement, `TheExec.Flow.UntestedInstanceResult`, lets you specify how the bin table should treat untested instances.

Retest Option for Program Execution

You can now retest a part during program execution without causing the device count to increment. The Run Options window has a Retest button. There is an equivalent new VBT method, `TheExec.RunOptions.Retest`. Retest reruns the job on the selected sites. Retest information is written to the datalog output and to the STDF file.

This answers Case 382613.

Pattern Compiler Time Domain Switch Keywords for Digital Instruments

V8.30.00 includes two new keywords for the pattern compiler -`time_domain` switch used with digital instruments (HSDM, HSDMQ, or HSD4G.). You can now use one of these keywords, instead of the time domain name:

- **tlSystem**: Assign a pattern to the default System time domain in a multiple time domain pin map.
- **tlBestFit**: Assign a pattern to the best fit time domain in a multiple time domain pin map. This option allows you to override a nondefault time domain name in the ATP file.

This answers [Case 394867](#) and [Case 395602](#).

[UltraPin1600 Quad High Speed Receive Timing Mode](#)

[IG-XL V8.30.00](#) adds the QuadHiSpeedRcv timing mode on the Time Sets (Basic), Time Sets, and Edge Sets sheets. Use this mode to ensure that strobe events on 2X pins always fire when running at speeds greater than 1500 Mbps in quad mode on the UltraPin1600. For more information, see [Validation Error for UltraPin1600 Test Programs Operation Above 1500 Mbps](#) and "Programming Quad High Speed Receive Timing Mode" in the UltraFLEX Instruments>UltraPin1600 Digital Instrument>UltraPin1600 Programming>UltraPin1600 DataTool Programming section.

[LMC Syntax Enhancements](#)

[Logical MicroCode syntax now includes the](#) `CtrReserveTwoAlu` function that reserves a counter of the specified type and assigns that counter to physical counters from both ALU groups. This feature first appeared in IG-XL V8.20.00. For more information, see [Logical MicroCode \(LMC\)>Logical MicroCode Syntax Reference>Control Functions>CtrReserveTwoAlu](#) in IG-XL Help.

This answers [Case 404374](#).

[VBT Language Enhancements](#)

VBT includes the following new statements. For descriptions, see the individual entries in the [VBT Syntax Reference](#) in the UltraFLEX User Manuals.

- [For datalogging:](#)

- [TheExec.Datalog.WriteCommentDeferralEnabled](#)

- [For DSPWave objects:](#)

- [DSPWave.Ceiling](#)

- [DSPWave.Done](#)

- [DSPWave.Floor](#)

This answers [Case ID 391912](#).

- [For DSPWave hardware:](#)

- [TheHdw.DSP.DspWaveUpsyncThreshold](#)

- For Executive Flow:

- [TheExec.Flow.ExplicitlyDeclareFlagsAndVars](#)

- [TheExec.Flow.ForceStopOnError](#)

- [TheExec.Flow.Limits.CurrentLimitSet](#)

- [TheExec.Flow.Limits.Key](#)

- [TheExec.Flow.Limits.LimitSetFilePath](#)

- [TheExec.Flow.Limits.LimitSetsInFile](#)

- [TheExec.Flow.Limits.Load](#)

- [TheExec.Flow.Limits.LoadedLimitSetFiles](#)

- [TheExec.Flow.Limits.UnloadAll](#)

- [TheExec.Flow.MaxLoopCount](#)

- [TheExec.Flow.UntestedInstanceResult](#)

- [TheExec.GroupActiveFlowSheet](#)

- [IFlowLimitsInfo.GetLimits](#)

- [IFlowLimitsInfo.GetLowCompareSigns](#)

- For Executive RunOptions:

- [TheExec.RunOptions.CheckDuplicateTestName](#)

- [TheExec.RunOptions.CTProfiler](#)

- [TheExec.RunOptions.OverrideFailStop](#)

- [TheExec.RunOptions.Retest](#)

- For other Executive functions:

- [TheExec.TestProgramAudit](#)

- For UltraPin1600:

- [TheHdw.Digital.Pins.Timing.SrcSyncDataDelay](#)

- [TheHdw.Digital.Timing.FullPAClockFrequencyRange](#)

- For Patterns:

- [TheHdw.Patterns.UseFlowLimits](#)

- For the Pin Parametric Measurement Unit (PPMU):

- [TheHdw.PPMU.UseFlowLimits](#)

- For Protocol Aware:

- [TheHdw.Protocol.Ports\(PortList\).Item.EngineNames](#)

- [TheHdw.Protocol.Ports\(PortList\).Item.MemorySize](#)

- [TheHdw.Protocol.Ports\(PortList\).Item.MemorySize.TotalFreeMemory](#)

- [TheHdw.Protocol.Ports\(PortList\).Item.MemorySize.TotalUsedMemory](#)

- [TheHdw.Protocol.Ports\(PortList\).Item.MemorySize.UsedPermanentMemory](#)

- [TheHdw.Protocol.Ports\(PortList\).Item.MemorySize.UsedTemporaryMemory](#)

- [TheHdw.Protocol.Ports\(PortList\).Item.Modules.Item.Size](#)

- For computer information:

- [TheHdw.Computer.OperatingSystemEdition](#)

- [TheHdw.Computer.OSProcessorType](#)

- [TheHdw.Computer.ProcessingBits](#)

- [TheHdw.DSP.Computers.Item.OperatingSystemEdition](#)

- [TheHdw.DSP.Computers.Item.OSProcessorModel](#)

- [TheHdw.DSP.Computers.Item.OSProcessorType](#)

- [TheHdw.DSP.Computers.Item.ProcessingBits](#)

- [tl_WriteCurrentConfigToSTDF](#)

These are related to the System Validity Checker tool.

- For VSA demodulation:

- [Demod.RuntimeMemoryHeadroom](#)

- [Demod.Instances.Item.ValidTraceTimeout](#)

This release also includes the following enhancements to this VBT syntax:

- [The VBT method](#) TheHdw.MTO.LoadScrambleMem includes a new optional parameter, muxRootSrcStr, that allows you to create a list of multiplexer selections from the available X, Y, or Z address bits for the address scrambler memory's root source multiplexers.
- [The VBT methods](#) TheHdw.Protocol.Ports.ModuleFiles.Load and TheHdw.Protocol.Ports.Modules.IsRecording include a new optional parameter, FieldValuesAreUniform, that allows you to broadcast the same field payload data to all sites. When the PA transaction payload data is the same for all sites, setting this parameter to True reduces PA module loading time. Note that this option does not support merged engines.
- [The VBT methods](#) TheHdw.Protocol.Ports.HaltWait and TheHdw.Protocol.Ports.IdleWait include a new optional parameter, AllowConcurrency, that determines whether to allow a concurrent test subflow to execute while waiting for the halt or idle timeout on a PA engine.



ReadMe_V8_30_00_uflx.1.21

<	>
-----------------	-----------------

[IG-XL V8.30.00 Release Notes](#) : Migrating to IG-XL V8.30.00

Migrating to IG-XL V8.30.00

This section describes changes in IG-XL that may affect the behavior or results of your test program. This includes changes in the following areas:

- | | |
|---|--|
| • | General Changes to IG-XL |
| • | Digital |
| • | DSP |
| • | IG-XL Tools |

This section describes migration from IG-XL V8.20.00 to V8.30.00. If you are migrating from an IG-XL release before V8.20.00, check the release notes for previous releases.

<	>
-----------------	-----------------

ReadMe_V8_30_00_uflx.1.22

<

>

[IG-XL V8.30.00 Release Notes](#) : [Migrating to IG-XL V8.30.00](#) : [General Changes to IG-XL](#)

General Changes to IG-XL

This version of IG-XL includes the following general changes:

- [System Requirements Changes](#)

System Requirements Changes

Introduced in: V8.30.00

Minimum system requirements have changed. As of V8.30.00, IG-XL no longer supports:

- [Windows XP on the tester computer or on offline workstations. The minimum requirement for this version of IG-XL is Windows 7 64-bit with Service Pack 1. If you have workstations or tester computers running Windows XP, upgrade them to Windows 7 before you install this version of IG-XL.](#)

[IG-XL V8.30.00](#) does support [Windows XP on older DSP Computers](#). See [Operating System for DSP PCs](#) for additional requirements.

- [Hewlett-Packard Z800 as tester computer. The minimum tester computer requirement for this version of IG-XL is a Tera1. If you have test systems using Z800s as host computers, contact Teradyne for upgrade options.](#)

- [Microsoft Office Excel 2003. IG-XL requires Excel 2010. If you are using Excel 2003, upgrade to Excel 2010 before you install IG-XL. 8.30.00 or later](#)

See [System Requirements](#) for more information on hardware and software requirements.

<		>	
	2015 Teradyne, Inc. All rights reserved.		

ReadMe_V8_30_00_uflx.1.23

<	>
-----------------	-----------------

IG-XL V8.30.00 Release Notes : Migrating to IG-XL V8.30.00 : Digital

Digital

Maximum Period Limits for Twin Strobe Timesets on HPM 8.0G and 8.5G Instruments

Introduced in: V8.30.00

For timesets containing twin strobe pins, the maximum period is limited to 500 ps on HPM 8.0G XIO (974-245-32) and HPM 8.0G XIO JI (974-245-38) instruments. On the HPM 8.5G XIO (974-245-52) instrument, the limit is 438.073 ps. Specifying values outside these limits produces errors at validation and at run time.

Validation Error for UltraPin1600 Test Programs Operation Above 1500 Mbps

Introduced in: V8.30.00

IG-XL returns a validation error on UltraPin1600 test programs that have these conditions:

- | | |
|---|--|
| • | Quad timing mode operation |
| • | Timeset period less than 1.33 ns (that is, a speed greater than 1500 Mbps) |
| • | 2X pin setup for output or I/O pins |
| • | Any compare mode used except Off |

If you encounter this error, you must switch to the new Quad High Speed Receive timing mode (QuadHiSpeedRcv) on the Time Sets (Basic), Time Sets, and Edge Sets sheets. This mode ensures that strobe events on 2X pins always fire when running at speeds greater than 1500 Mbps in quad mode on the UltraPin1600.

When using this mode, however, you can program only one time set per sheet and one edge set per sheet and use only machine resolution. Contact the Teradyne Applications team if these

restrictions are not suitable for your particular test program requirements.

<		>	
	2015 Teradyne, Inc. All rights reserved.		

ReadMe_V8_30_00_uflx.1.24



IG-XL V8.30.00 Release Notes : Migrating to IG-XL V8.30.00 : DSP

DSP

Support for Interpreter Mode Has Been Removed

Support for the DSP Interpreter Mode has been removed from IG-XL V8.30.00. This legacy mode of DSP procedure execution was replaced in 2004 with the higher performance “translator mode” of execution. Translator mode was made the default in 2007 with IG-XL V6.00.00, and several new features, such as DSP custom libraries and globally accessible variables, have been developed with support only in translator mode. The legacy interpreter mode had been retained because some customers might have preferred to continue using it, since it was once the default. Also, local static variables did not work as well in translator mode, so customers might have kept using interpreter mode to use local statics.

However, local static variables have been deprecated for several years now and are not recommended. (Globally accessible variables are the recommended alternative.) Given all the changes, we have discontinued support for interpreter mode. This means that Teradyne and all of our customers can benefit from a simpler system which is easier to maintain and develop new features for.

Since the default mode is translator mode, any customer still using interpreter mode would have to be setting it using the hidden language `TheHdw.DSP.VBUseModel = tlDSP_ByteCode_Interpreter`. If this statement does not appear in your test program, then you are not using interpreter mode and this change does not affect you.

If this statement is executed in your test program, IG-XL returns a run-time error. The error notifies you of the change and describes what to do:

Support for DSP Interpreter Mode has been removed from IG-XL. Please remove the use of the `VBUseModel` language from your test program. Doing so will mean your program will run in the default Translator Mode, which has performance and other benefits. Most test programs will run without errors in translator mode, but it's possible some programs may encounter intermittent

problems if they use local static variables within DSP Procedures. You should remove any such variables. If the variables are needed, you can achieve the same functionality using Globally Accessible Variables, a more robust and easier to use solution. See "Globally accessible variables, DSP" in IG-XL Help for more information. Support for local static variables in translator mode is not being changed at this time, and you are free to continue using them.

DspProcedure Test Element Can Cause Error

You may see errors in test programs that contain test procedures with DspProcedure test elements immediately followed by Limits test elements fetching the DspProcedure results. The error shown is:

FLO:0043 : Test_Instance_Name

Test procedures are a deprecated feature, and Teradyne recommends customers upgrade test programs to use all-VBT tests.

A workaround is available for customers who want to continue running test programs using DspProcedure test elements. A program will execute correctly as long as the DSP procedure has finished and sent the result to the tester computer. Therefore, you can add a Wait test element between the DspProcedure test element and the test element that checks the result of the DspProcedure (likely a Limits or VBT test element). The time required to wait depends on how long the test procedure takes. You should experiment to determine the time required to make a test pass reliably.

Incorrect Initialization of DSP Globally Accessible Variables Causes Error

IG-XL V8.30.00 introduces a new exec interpose function, OnDSPGlobalVariableReset. This function is called when DSP globally accessible variables are reset, such as when the VBA Stop (Reset) button is pressed. It is also called at the start of the first job run or of the first job run after a revalidation. This permits initializing the variables.

If the job requires globally accessible variables, they should be initialized in the OnDSPGlobalVariableReset function.

Globally accessible variables can be accessed only during the job run or from this function. As of V8.30.00, initializing the variables in OnProgramLoaded or OnProgramValidated returns a run-time error. Any initialization of DSP globally accessible variables in these other functions must be moved to OnDSPGlobalVariableReset. You can access the variables in OnProgramStarted, which is part of the job run.

For a workbook created before V8.30.00, you must add the OnDSPGlobalVariableReset() function to the Exec_IP_Module, using the existing exec interpose functions as a model. The easiest way is to open a new program and copy the function to your Exec_IP_Module.



	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.25

<	>
-----------------	-----------------

IG-XL V8.30.00 Release Notes : Migrating to IG-XL V8.30.00 : IG-XL Tools

IG-XL Tools

This version of IG-XL includes the following IG-XL tools changes:

- | | |
|---|---|
| • | Undefined Variable for Bin or Sort Number Causes Validation Error |
| • | Flags Have Global Scope in Flow Tables |
| • | Using a Flag Multiple Times in a Cell Returns Validation Error |
| • | Test Missing Limits Assigns Device to Error Bin |
| • | Validation Error for Macro Not in "VBT" Module But Used as "VBT" Test |

Undefined Variable for Bin or Sort Number Causes Validation Error

Introduced in: V8.30.00

A flow or site variable must be defined in the flow table before it can be used as a bin or sort number in the table. If the variable is undefined in the flow table, a validation error is returned. In previous releases of IG-XL, an undefined variable used for a bin or sort number returns a run-time error, but not a validation error.

This change affects any program that defines a site variable in VBT and then uses the site variable for a bin or sort number in the flow table. In previous releases, this use is permitted. As of IG-XL V8.30.00, the site variable must be defined in the flow table before you use it as a bin or sort number in the flow table.

This answers Case 394934.

Flags Have Global Scope in Flow Tables

Introduced in: V8.30.00

All flags created in a job's Flow Table sheets have global scope.

In previous releases of IG-XL, a flag is associated with the first Flow Table sheet encountered during validation that defines the flag. At runtime, if the Flow Table is not in the call stack, an error is generated. Note that previous releases of IG-XL help do not accurately describe this scoping. As of V8.30.00, subflows that refer to the same named flag will read from and write to the same flag at runtime. For workbooks that implement program modularity, it is important to ensure that named flags that are intended to be unique to one subflow are in fact unique throughout the job. If a flag happens to be the same as in another subflow, both subflows use the same flag.

Using a Flag Multiple Times in a Cell Returns Validation Error

Introduced in: V8.30.00

Certain columns on a Flow Table sheet can take a comma-separated list of flags. For example, the Action Pass and Fail columns can contain multiple flags, and the flag- opcodes can take a list of flags as a parameter.

As of V8.30.00, if the same flag name appears more than once in a list of flags, a validation occurs. This release also officially supports the use of a list of flags.

In previous releases of IG-XL, using the same flag name more than once in a list does not return a validation error. The use of a flag list is not officially supported before V8.30.00.

This change is beneficial, because repeating a flag name in a list is usually unintentional, often the result of a cut-and-paste mistake.

Test Missing Limits Assigns Device to Error Bin

Introduced in: V8.30.00

If a VBT test specifies `forceresults:=tlForceFlow` (that is, the limits are in the flow or a limit set), but the limits are not in a Use-Limit row or limit set for the test, then the test returns a run-time error, and the devices being tested are assigned to the error bin.

In previous releases of IG-XL, a test that is missing limits causes the device to fail, but if the test's Result column is not set to Fail, the device is not binned out. This can lead to bad parts passing.

Validation Error for Macro Not in "VBT" Module But Used as "VBT" Test

Introduced in: V8.30.00

On a Test Instances sheet, if the Type column specifies VBT, the valid names for Name are public functions in modules beginning with "VBT." IN V8.30.00 and later, if a public macro not in a "VBT" module is used in the Name column for a VBT test, IG-XL returns a validation error.

In previous releases of IG-XL, a macro not in a "VBT" module but used as a VBT test does not return a validation error.

This answers Case 389633.

<	>	
	2015 Teradyne, Inc. All rights reserved.	

ReadMe_V8_30_00_uflx.1.26

<

>

IG-XL V8.30.00 Release Notes : Bugs Fixed in V8.30.00

Bugs Fixed in V8.30.00

The following table lists bugs fixed in IG-XL V8.30.00.

Bugs Fixed in IG-XL V8.30.00		
Project	Case ID	Description
About IG-XL	389436	After installation of IG-XL V8.10.12, Verify Installation gives error messages
About IG-XL	390257	Verify Installation gives "Microsoft Excel has Stopped Working" error
Data Collection	365676, 388045	Run button unresponsive because of shared .dlex file
Data Collection	394509	Datalog server crashes with test program with MPR enabled
Data Manager	392687	Validation error does not provide any details when open in ASCII
Data Tools		TheExec.Tools(tool).ShowPin(pin) with an illegal pin name does not cause a validation error
DataTool	382535	Value in grayed-out cells of Time Sets sheet causes validation error
DataTool	392793, 396039	Channel Map entry for DCTime is case-sensitive
DataTool	385431	Excel 2010 fails to import 64K-row Flow Table sheet

DataTool	389375, 392240	Select All (Ctrl+A) on a DataTool sheet causes IG-XL to crash
DCVI	403823	IG-XL crashes when DCVI settings are modified in TDE during capture setup
Documentation	378594	Java error when switching IG-XL versions
Documentation	392792	UltraVI80 help not descriptive for hardware averaging
Documentation	396721	Help for UltraPin1600 source synchronous programming is insufficient
Documentation	397184	Documentation unclear for coding DCVIGateHiZ on UltraVI80
Documentation	397261	Help error describing UltraFLEX DSSC for 2X pins
Documentation	397666	Help does not describe if UltraWave12G and 24 ports are AC coupled
Documentation	398295	IG-XL Help UltraPin1600 DigCap specification is out of alignment
Documentation	399151	UltraVS256 DIB Design Guide missing four channel group limitation
Documentation	399578	Help for LastPass/LastFail in IF opcode is confusing
Documentation	400373	IG-XL Help for ClearFail command is inadequate
Documentation	401957	UltraWave24 DIB Design Guidelines incorrect
Documentation	401957	UltraWave24 DIB Design Guidelines inaccurate for DIB Access
Documentation	402560	Run Option flag = "Check Duplicate Test Numbers" does not work
Documentation	403650	Help omits that set_msb opcode is required
DSP		Opening a second workbook causes Excel to crash
DSP	376964	DSPWave .Select without .Copy causes memory leak
DSSC		When MoveMode is set to IIM and no DSP PC exists the capture data is not moved to the host PC
DSSC	382426	ElementLite returns same data when there are two active sites
DSSC	387135	DSSC Parallel Capture Error
DSSC	397119	Unclear error message for incorrect DigCap assignment in UltraPin1600 quad mode

DSSC, UltraVI80	374764	DSSC Capture pattern errors make HRAM Display close test program
ESA Toolkit	375562	LTE 8.9 VSA demodulator properties window is missing
ESA Toolkit	377626	Need better error message when LTE license is not installed
ESA Toolkit	399154	Problem initializing VSA with more than eight worker threads and eight sites
ESA Toolkit	399155	Improve error message when VSA fails to initialize
Flow	385588	Pass/Fail Flag performs incorrectly in Flow Table
Flow	398937	Undefined flag error when two subflows contain flags with same name
HSD	381580	IG-XL validation fails with 256 level sheets, error says 256 supported
IG-XL General	402784	Characterization window becomes hidden while running a shmoo plot
Logical Micro Code	404374	CtrRelease does not release LMC Address Counter TwoALU flag
MiniFlow	406331	Trying to open instance from MiniFlow does not open selected test
OpenProgram	404456	Program load times excessive when Excel is not the active window
Operator Interface	389190	Load file for operator interface runs wrong flow sheet
Pattern Library	403610	UltraPAC80 default signal change error at pattern start
Pattern Tool	379637	PatternTool takes very long to open a pattern
Pattern Tool	379921	Learn mode fails with an nWire error
Pattern Tool	387528	"Invalid list member" error when opening PatternTool at breakpoint
Pattern Tool	388551	PatternTool does not align scan vectors in dual mode as even/odd
Pattern Tool	394717	PatternTool crashes on saving a file after scan pins are removed
PatternTool	388089	PatternTool cannot save pattern file after deleting DigSrc/Cap group

PPMU	388529	Mixing UltraPin and UltraPAC80 pins returns error message at .Read method
Production Controls	390144	Performance issue for operator interface SetWaferXY method
Protocol Aware	391865	IG-XL does not unload previously loaded Protocol Aware modules after channel map change and test program revalidation
Protocol Aware	392235	Time Sets sheet validation does not fail with invalid PA timing programmed
Protocol Aware	393035	TheHdw.Protocol.Ports.ModuleFiles.Load does not check for uniform channel assignment across sites, which results in test failures
Protocol Aware nWire	389787	PatternTool unable to read Protocol Aware module names for all microcodes in pattern
Protocol Definition Editor	388191	Protocol Definition Editor assigns Booleans instead of Doubles for MaxWaitUntilTimeout and MaxHoldUntilTimeout settings
SB6G	374485	TheHdw.Serial.Pins.Timing.Jitter.Insertion.Amplitude.Value does not set the correct amplitude value in SB6G hardware
TDE	387685	TDE cannot open at breakpoint when using run option Debug Loop
TDE	387757	Export function on Smith Display causes TDE to crash
UltraPAC	388637	UltraPAC Src/Capture bandwidth license limitations not enforced properly
UltraSerial10G	381815	IG-XL returns error when setting the UltraSerial10G sample rate before capture
UltraSerial10G	393256	UltraSerial10G drive-only site copy allowed on only one pair of sites
UltraVI80	369057	Multiple merged UltraVI80 channels show mode alarms offline
UltraVI80	396097	Programming UltraVI80 nominal bandwidth causes errors if all sites failed
UltraVS256	399152	UltraVS256 current limit incorrect in IG-XL Help
UltraWave 12G	380770	Excessive UltraWave 12G SMEM loading latency

UltraWave24	400672	Excessive memory use in UltraWave24 LoadSettingsConnect
UltraWave24	400672	Excessive memory used in caching LoadSettingsConnect
UltraWave24	403977	Unable to obtain UltraWave24 AWG license at 160 MHz
UltraWave24	406386	UltraWave24 Receiver licensing enforces wrong number of Receivers
UltraWave24	406387	UltraWave24 AWG licensing enforces wrong number of AWGs
Waveform Display	379638	Waveform Display does not plot actual mode when first selected

Run button unresponsive because of shared .dlex file

Case ID

365676, 388045

Facts

Found Release: IG-XL V7.30.00_P8

Project: Data Collection

Fix

This is fixed in V8.30.00.

When the .dlex file, which stores DataCollect settings, was shared by two users, the settings for the wrong user were applied. Settings for the correct user are now applied.

DSPWave .Select without .Copy causes memory leak

Case ID

376964

Facts

Found Release: IG-XL V8.00.01_P8

Project: DSP

Fix

This is fixed in V8.30.00.

In previous releases, it was recommended to use a .Copy with a .Select to avoid the memory leak. As of V8.30.00, it is no longer necessary to use a .Copy. The .Select by itself does not cause a memory leak.

PatternTool takes very long to open a pattern

Case ID

379637

Facts

Found Release: IG-XL V8.00.01_P6

Project: PatternTool

Fix

This is fixed in IG-XL V8.30.00.

Pass/Fail Flag performs incorrectly in Flow Table

Case ID

385588

Facts

Found Release: IG-XL V8.00.01_P8

Project: Flow

Fix

This is fixed in IG-XL V8.30.00, which provides enhanced Step Action Pass/Fail columns that replace the Flag Pass/Fail columns.

Time Sets sheet validation does not fail with invalid PA timing programmed

Case ID

392235

Facts

Found Release: IG-XL V8.20.00FQ

Project: Protocol Aware

Symptoms

You can program a PA timeset to a period value that is lower than 1/137.5MHz, and IG-XL allows the test program to pass validation when it should fail. The maximum data rate for PA pins in non-2X mode is 275Mbps, which means the PA clock rate is limited to 137.5MHz when creating a clock using the RTN pin format.

Fix

This is fixed in IG-XL V8.30.00.

Validation error does not provide any details when open in ASCII

Case ID

392687

Facts

Found Release: IG-XL V8.10.12

Project: Data Manager

Symptoms

When a workbook is open in ASCII, a validation error does not appear on the Errors sheet pointing to where the error occurs.

Fix

This is fixed in IG-XL V8.30.00.

UltraWave24 DIB Design Guidelines inaccurate for DIB Access

Case ID

401957

Facts

Found Release: IG-XL V8.20.00_uflx

Project: Documentation

Symptoms

DIB Design Guidelines for the Sidewalk 4 pads for UltraWave24 say that the DIB access connection can only be connected to the RefCLK outputs.

Fix

This is fixed in IG-XL Help V8.30.00. The DIB access output signal description now reads:

Use this signal to connect one of the DUT_CLK outputs to another instrument through the DIB. You can also use this signal for continuity connections.

IG-XL returns error when setting the UltraSerial10G sample rate before capture

Case ID

381815

Facts

Found Release: IG-XL V8.10.00

Project: UltraSerial10G

Fix

This is fixed in V8.30.00.

DSSC Capture pattern errors make HRAM Display close test program

Case ID

374764

Facts

Found Release: IG-XL V8.10.00

Project: DSSC, UltraVI80

Symptoms

If you reburst a DSSC pattern from the HRAM Display and the pattern generates errors, the workbook closes and the HRAM Display becomes unresponsive. This happens only on a test system.

Fix

This is fixed in V8.30.00.

Help does not describe if UltraWave12G and 24 ports are AC coupled

Case ID

397666

Facts

Found Release: IG-XL V8.20.00

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. Added information on coupling for the UltraWave 12G and UltraWave24 instruments in the Hardware Specifications.

IG-XL Help UltraPin1600 DigCap specification is out of alignment

Case ID

398295

Facts

Found Release: IG-XL V8.10.14

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. Fixed misaligned specifications in DSSC Capture for the UltraPin1600.

IG-XL validation fails with 256 level sheets, error says 256 supported

Case ID

381580

Facts

Found Release: IG-XL V8.00.01

Project: HSD

Fix

This is fixed in V8.30.00. Error message now states that 255 level sets supported.

ElementLite returns same data when there are two active sites

Case ID

382426

Facts

Found Release: IG-XL V8.00.01_P6

Project: DSP

Fix

This is fixed in V8.30.00.

DSSC Parallel Capture Error

Case ID

387135

Facts

Found Release: IG-XL V8.00.01_P6

Project: DSSC

Symptoms

DSSC reports an error when you try to capture signals from two sites at the same time if the two sites use different channels on the same board. This happens in parallel mode only; the tests pass in serial mode.

Fix

This is fixed in IG-XL V8.30.00. An address conflict between channel groups has been resolved.

Export function on Smith Display causes TDE to crash

Case ID

387757

Facts

Found Release: IG-XL V8.00.01_P7

Project: TDE

Fix

This is fixed in IG-XL V8.30.00. A third-party component has been updated.

When MoveMode is set to IIM and no DSP PC exists the capture data is not moved to the host PC

Facts

Found Release: IG-XL V8.20.00

Project: DSSC

Fix

This is expected behavior. The VBT Reference entry for TheHdw.DSSC.MoveMode has been changed so it now properly describes the behavior of the property.

TheHdw.Protocol.Ports.ModuleFiles.Load does not check for uniform channel assignment across sites, which results in test failures

Case ID

393035

Facts

Found Release: IG-XL V8.10.11_P1

Project: Protocol Aware

Symptoms

When the FieldValuesAreUniform parameter is enabled on the VBT method

TheHdw.Protocol.Ports.ModuleFiles.Load, IG-XL does not load the relative channel assignments for an nWire engine correctly across sites. For instance, on the JTAG protocol, IG-XL assigns TDI to channel 0 on one engine and channel 9 (relative channel 1) on another engine. This results in test failures.

Fix

This is fixed in IG-XL V8.30.00.

PatternTool crashes on saving a file after scan pins are removed

Case ID

394717

Facts

Found Release: IG-XL V8.10.14

Project: PatternTool

Fix

This is fixed in IG-XL V8.30.00. PatternTool does not support scan pin deletion. You must delete the scan pin from the .atp file and recompile it. PatternTool now gives an error if you try to delete a bus that contains a scan pin.

UltraVI80 help not descriptive for hardware averaging

Case ID

392792

Facts

Found Release: IG-XL V8.10.11

Project: Documentation

Fix

This has been updated in IG-XL Help V8.30.00. The hardware averaging descriptions for UltraVI80's DCVI and DCDiffMeter are now more descriptive and accurate.

Run Option flag = "Check Duplicate Test Numbers" does not work

Case ID

402560

Facts

Found Release: IG-XL V8.10.14

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. The following warning has been added to the VBT Reference entry in IG-XL Help for UltraFLEX and FLEX:

This option checks only test numbers that are set using the TNum column on the Flow Table sheet.

It does not check test numbers set using the VBT statement

TheExec.Sites.Site(SiteNum).TestNumber.

Improve error message when VSA fails to initialize

Case ID

399155

Facts

Found Release: IG-XL V8.20.00

Project: ESA Toolkit

Fix

This is fixed in V8.30.00.

Load file for operator interface runs wrong flow sheet

Case ID

389190

Facts

Found Release: IG-XL V8.10.11

Project: Operator Interface

Fix

This is fixed in IG-XL V8.30.00. The problem was caused when the test program did not contain the job specified in the load file. The same problem occurred if the test program did not contain the specified channel map. IG-XL V8.30.00 returns an error and stops the program run if the job does not contain the specified job or channel map.

LTE 8.9 VSA demodulator properties window is missing

Case ID

375562

Facts

Found Release: IG-XL V8.00.01

Project: ESA V4 Toolkit Installer

Fix

This is fixed in V8.30.00.

TDE cannot open at breakpoint when using run option Debug Loop

Case ID

387685

Facts

Found Release: IG-XL V8.10.11

Project: DataTool

Fix

This is fixed in IG-XL V8.30.00.

UltraPAC Src/Capture bandwidth license limitations not enforced properly

Case ID

388637

Facts

Found Release: IG-XL V8.10.11_P1

Project: UltraPAC80

Fix

This is fixed in V8.30.00. Licenses for UltraPAC are now properly enforced.

Bitmap Tool shows displaced and extra bits

Case ID

391911

Facts

Found Release: IG-XL V8.10.12

Project: BitMap Tool

Fix

This is fixed in IG-XL V8.30.00.

Waveform Display does not plot actual mode when first selected

Case ID

379638

Facts

Found Release: IG-XL V8.00.01_P6

Project: Waveform Display

Fix

This is fixed in IG-XL V8.30.00. Waveform Display now automatically changes the zoom factor if the pixel width is too small to display the data.

Mixing UltraPin and UltraPAC80 pins returns error message at .Read method

Case ID

388529

Facts

Found Release: IG-XL V8.10.11_P1

Project: PPMU Driver

Fix

This is fixed in V8.30.00.

PatternTool does not align scan vectors in dual mode as even/odd

Case ID

388551

Facts

Found Release: IG-XL V8.10.00

Project: PatternTool

Fix

This is fixed in IG-XL V8.30.00. For a pattern in dual with scan chains, PatternTool outlines the major and minor vectors.

Verify Installation gives "Microsoft Excel has Stopped Working" error

Case ID

390257

Facts

Found Release: IG-XL V8.10.12_uflx

Project: About IG-XL

Symptoms

Running About IG-XL>Verify Installation produces the following error message: "Microsoft Excel has Stopped Working." If you click Close the program, the Verify Installation completes.

Fix

This is fixed in IG-XL V8.30.00.

Undefined flag error when two subflows contain flags with same name

Case ID

398937

Facts

Found Release: IG-XL V8.10.12_P1

Project: Flow

Fix

This is fixed in IG-XL V8.30.00.

IG-XL Help for ClearFail command is inadequate

Case ID

400373

Facts

Found Release: IG-XL V8.10.11_P1

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. The following statement has been included in the help for TheHdw.Digital.Patgen.ClearFail:

The HSD1000, UltraPin800, and UltraPin1600 instruments clear fails from a block of eight channels to achieve optimal performance. As a result, when clearing one channel (for instance, pin0, which is assigned to channel 0), IG-XL also clears the next seven channels (pin1 through pin7 assuming they are assigned to channels 1 through 7 in sequential order).

Need better error message when LTE license is not installed

Case ID

377626

Facts

Found Release: IG-XL V8.10.00

Project: ESA V3 Toolkit

Fix

This is fixed in V8.30.00.

Learn mode fails with an nWire error

Case ID

379921

Facts

Found Release: IG-XL V8.10.00

Project: PatternTool

Fix

This is fixed in IG-XL V8.30.00. Learn mode has been improved. This defect is not related to nWire.

"Invalid list member" error when opening PatternTool at breakpoint

Case ID

387528

Facts

Found Release: IG-XL V8.10.90

Project: PatternTool

Fix

This is fixed in IG-XL V8.30.00.

After installation of IG-XL V8.10.12, Verify Installation gives error messages

Case ID

389436

Facts

Found Release: IG-XL V8.10.12_uflx

Project: About IG-XL

Fix

This is fixed in IG-XL V8.30.00. A delay of one second has been included after verifying the Excel object.

TheHdw.Serial.Pins.Timing.Jitter.Insertion.Amplitude.Value does not set the correct amplitude value in SB6G hardware

Case ID

374485

Facts

Found Release: IG-XL V8.00.01_P6

Project: SB6G

Operating System: Windows XP

Fix

This is fixed in V8.30.00.

Excessive memory used in caching LoadSettingsConnect

Case ID

400672

Facts

Found Release: IG-XL V8.20.00_uflx

Project: UltraWave24

Fix

This is fixed in IG-XL V8.30.00.

Excel 2010 fails to import 64K-row Flow Table sheet

Case ID

385431

Facts

Found Release: IG-XL V8.10.11

Project: DataTool

Fix

This is fixed in IG-XL V8.30.00.

PatternTool cannot save pattern file after deleting DigSrc/Cap group

Case ID

388089

Facts

Found Release: IG-XL V8.10.11_P1

Project: PatternTool

Fix

This is fixed in IG-XL V8.30.00.

IG-XL does not unload previously loaded Protocol Aware modules after channel map change and test program revalidation

Case ID

391865

Facts

Found Release: IG-XL V8.10.11_P1

Project: Protocol Aware

Fix

This is fixed in IG-XL V8.30.00.

Help error describing UltraFLEX DSSC for 2X pins

Case ID

397261

Facts

Found Release: IG-XL V8.10.12

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. Channel numbers and allowable count of capture bits are now correct.

Multiple merged UltraVI80 channels show mode alarms offline

Case ID

369057

Facts

Found Release: IG-XL V8.00.01_P5

Project: UltraVI80

Fix

This is fixed in V8.30.00.

PatternTool unable to read Protocol Aware module names for all microcodes in pattern

Case ID

389787

Facts

Found Release: IG-XL V8.10.11_P1

Project: Protocol Aware nWire

Fix

This is fixed in IG-XL V8.30.00.

Excessive UltraWave 12G SMEM loading latency

Case ID

380770

Facts

Found Release: IG-XL V8.00.01

Project: UltraWave 12G Source

Fix

This is fixed for V8.30.00.

Protocol Definition Editor assigns Booleans instead of Doubles for MaxWaitUntilTimeout and MaxHoldUntilTimeout settings

Case ID

388191

Facts

Found Release: IG-XL V8.10.11_P1

Project: Protocol Definition Editor

Fix

This is fixed in IG-XL V8.30.00.

UltraVS256 current limit incorrect in IG-XL Help

Case ID

399152

Facts

Found Release: IG-XL V8.20.00

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. Changed "2 A" to "2.8 A" and "500 mA" to "800 mA" (twice).

UltraSerial10G drive-only site copy allowed on only one pair of sites

Case ID

393256

Facts

Found Release: IG-XL V8.10.11_P1

Project: UltraSerial10G

Fix

This is fixed in V8.30.00.

Datalog server crashes with test program with MPR enabled

Case ID

394509

Facts

Found Release: IG-XL V8.00.01

Project: Data Collection

Fix

This is fixed in V8.30.00.

Channel Map entry for DCTime is case-sensitive

Case ID

396039, 392793

Facts

Found Release: IG-XL V8.10.12_uflx

Project: DCTime

Fix

This is resolved in IG-XL V8.30.00. The Channel Map sheet now automatically adjusts the case of your entry as you type.

Problem initializing VSA with more than eight worker threads and eight sites

Case ID

399154

Facts

Found Release: IG-XL V8.20.00

Project: ESA Toolkit

Fix

This is fixed in V8.30.00.

Programming UltraVI80 nominal bandwidth causes errors if all sites failed

Case ID

396097

Facts

Found Release: IG-XL V8.10.12_P0.0

Project: UltraVI80

Fix

This is fixed in V8.30.00. Programming the nominal bandwidth no longer causes errors if all sites have failed.

Value in grayed-out cells of Time Sets sheet causes validation error

Case ID

382535

Facts

Found Release: IG-XL V8.10.00

Project: DataTool

Fix

This is fixed in IG-XL V8.30.00. If a cell is grayed out and therefore disabled, a value in the cell no longer causes a validation error.

Select All (Ctrl+A) on a DataTool sheet causes IG-XL to crash

Case ID

389375, 392240

Facts

Found Release: IG-XL V8.10.11_P1

Project: DataTool

Fix

This is fixed in IG-XL V8.30.00.

Performance issue for operator interface SetWaferXY method

Case ID

390144

Facts

Found Release: IG-XL V8.10.11

Project: Production Controls

Fix

This is fixed in IG-XL V8.30.00.

TheExec.Tools(tool).ShowPin(pin) with an illegal pin name does not cause a validation error

Facts

Found Release: IG-XL V8.20.00

Project: Data Tools

Fix

This is fixed in IG-XL V8.30.00. If the pin name contains illegal characters, a validation error results.

A blank pin name does not cause an error.

Unclear error message for incorrect DigCap assignment in UltraPin1600 quad mode

Case ID

397119

Facts

Found Release: IG-XL V8.10.12

Project: DSSC

Symptoms

If you try to assign too many channels to a parallel DSSC group using UltraPin1600 in Quad Mode, IG-XL returns an unclear and misleading error.

Fix

This is fixed in IG-XL V8.30.00. The error message now correctly describes the problem.

Java error when switching IG-XL versions

Case ID

378594

Facts

Found Release: IG-XL V7.30.00_P10

Project: Documentation

Symptoms

IG-XL and its Java based tools do not support version 7 of the Java Runtime Environment (JRE).

Oracle's JRE updater automatically removes version 6 after it installs version 7. This can cause IG-XL tools to display errors or warnings.

Fix

This is fixed in IG-XL V8.30.00. Application Support Bulletin "Java Error when Switching IG-XL Versions" details the problem, lists the required versions of JRE for each active IG-XL platform, and describes a way to maintain the required version of Java.

Excessive memory use in UltraWave24 LoadSettingsConnect

Case ID

400672

Facts

Found Release: IG-XL V8.20.00

Project: UltraWave24

Fix

This is fixed in IG-XL V8.30.00.

Documentation unclear for coding DCVIGateHiZ on UltraVI80

Case ID

397184

Facts

Found Release: IG-XL V8.10.14_P1

Project: Documentation

Fix

This is fixed in IG-XL Help V8.30.00. The explanation in Help of gating off HiZ instead of using V=0 V is clearer. A table is now included noting the syntax for each action, and a note has been added stating that gate off HiZ is available only on UltraVI80.

Help for UltraPin1600 source synchronous programming is insufficient

Case ID

396721

Facts

Found Release: IG-XL V8.10.11

Project: Documentation

Fix

This is fixed in IG-XL Help V8.30.00. Changes are as follows.

- Noted that the Voh pin level is the input clock trigger level for source synchronous clock programming in single ended mode, and the Vod pin level is the input clock trigger level for source synchronous clock programming in differential mode in UltraPin1600 DataTool Programming>Programming Pin Levels.
- Added new "Source Synchronous Pin Levels Sheet" topic to UltraPin1600 Source Synchronous Clock Programming>Source Synchronous Levels and Timing Programming:

UltraVS256 DIB Design Guide missing four channel group limitation

Case ID

399151

Facts

Found Release: IG-XL V8.20.00_uflx

Project: Documentation

Fix

This is fixed in IG-XL Help V8.30.00. Help now notes that a group of four adjacent UltraVS256 channels has a maximum current of 2.8 A and that IG-XL decreases the current level automatically if the programmed current exceeds this limit. This addition is in UltraFLEX DIB Design

Guidelines>UVS256 DIB Design Guidelines>UVS256 Channel Selection Guidelines>Assigning UVS256 Channels.

Help for LastPass/LastFail in IF opcode is confusing

Case ID

399578

Facts

Found Release: IG-XL V8.20.00_uflx

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. Help now emphasizes that LastPass/LastFail evaluates to False if the test is not executed.

Unable to obtain UltraWave24 AWG license at 160 MHz

Case ID

403977

Facts

Found Release: IG-XL V8.20.00_uflx

Project: UltraWave24

Fix

This is fixed in IG-XL V8.30.00. The license check now uses 200 MHz as the threshold for taking the high bandwidth AWG license. This is down from 400 MHz.

UltraPAC80 default signal change error at pattern start

Case ID

403610

Facts

Found Release: IG-XL V8.20.00_uflx

Project: Pattern Library

Fix

This is fixed in IG-XL V8.30.00.

Help omits that set_msb opcode is required

Case ID

403650

Facts

Found Release: IG-XL V8.20.00_uflx

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. Help now includes a statement that you must call set_msb at least once before the first set.

UltraWave24 DIB Design Guidelines incorrect

Case ID

401957

Facts

Found Release: IG-XL V8.20.00_uflx

Project: Documentation

Fix

This is fixed in IG-XL V8.30.00. The DIB access output signal description in Help now reads: "Use this signal to connect one of the DUT_CLK outputs to another instrument through the DIB. You can also use this signal for continuity connections."

IG-XL crashes when DCVI settings are modified in TDE during capture setup

Case ID

403823

Facts

Found Release: IG-XL V8.30.00 (Prerelease), V8.10.xx

Project: DCVI

Symptoms

Crash when DCVI is configured for capture, settings are modified in TDE, then pattern is started.

Fix

This fixed in IG-XL V8.30.00.

CtrRelease does not release LMC Address Counter TwoALU flag

Case ID

404374

Facts

Found Release: IG-XL V8.20.00_uflx

Project: Logical Micro Code (LMC)

Symptoms

When an address counter is reserved using the CtrReserveTwoAlu() function and then released using either CtrRelease(thisCounter) or CtrRelease(), a subsequent use of that same name still has the TwoALU attribute.

Fix

This is fixed in IG-XL V8.30.00. The TwoALU aspect of the counter wasn't being reset when the counter was released. It is now.

Program load times excessive when Excel is not the active window

Case ID

404456

Facts

Found Release: IG-XL V8.10.11

Project: OpenProgram

Symptoms

When Excel 2010 does not have the focus in Windows, loading a test program can take many times longer than the program takes to load when Excel has the focus.

Fix

This is fixed in IG-XL V8.30.00, V8.20.00, and V8.10.11_P108. This is a known issue with Excel 2010.

IG-XL's bin folder includes xlactivateapp.dll, which is called when starting Excel 2010. This prevents Excel from losing focus and loading the workbook slowly.

Opening a second workbook causes Excel to crash

Facts

Found Release: IG-XL V8.10.14, IG-XL V8.20.00

Project: DSP

Symptoms

Error "Excel process might have been terminated by the user"

Fix

This is fixed in IG-XL V8.30.00. You are now able to open a second workbook.

Characterization window becomes hidden while running a shmoo plot

Case ID

402784

Facts

Found Release: IG-XL V8.20.00

Project: IG-XL General

Symptoms

During a shmoo plot, focus goes to DataTool (Excel) and hides either the Characterization panel or the Visual Basic window, or both.

Fix

This is fixed in IG-XL V8.30.00 as follows:

- DataTool (Excel) no longer grabs focus when test program execution is trapped at a VBA breakpoint.
- During a shmoo plot, DataTool takes focus and Characterization studio drops to background. This is expected behavior.

Trying to open instance from MiniFlow does not open selected test

Case ID

406331

Facts

Found Release: IG-XL V8.30.00 Prerelease

Project: MiniFlow

Symptoms

When using MiniFlow, right-clicking a test and selecting Edit>Instance does not always open the selected test.

Fix

This is fixed in the shipping version of IG-XL V8.30.00.

UltraWave24 Receiver licensing enforces wrong number of Receivers

Case ID

406386

Facts

Found Release: IG-XL V8.30.00 Prerelease

Project: UltraWave24

Symptoms

Validation reports that licensing is insufficient for the number of UltraWave24 Receivers used.

Fix

This is fixed in the shipping version of IG-XL V8.30.00. License checking verifies the correct number of UltraWave24 Receivers.

UltraWave24 AWG licensing enforces wrong number of AWGs

Case ID

406387

Facts

Found Release: IG-XL V8.30.00 Prerelease

Project: UltraWave24

Symptoms

Validation reports that licensing is insufficient for the number of UltraWave24 AWGs used.

Fix

This is fixed in the shipping version of IG-XL V8.30.00. License checking verifies the correct number of UltraWave24 AWGs.

< >		
	2015 Teradyne, Inc. All rights reserved.	

ReadMe_V8_30_00_uflx.1.27

<	>
-----------------	-----------------

IG-XL V8.30.00 Release Notes : Known Issues

Known Issues

This section describes the known issues in IG-XL V8.30.00 in the following categories:

- | | |
|---|-------------------------|
| • | AC Instrumentation |
| • | Digital Instrumentation |
| • | DSP |
| • | Software Tools |
| • | Operating Environment |

<	>
-----------------	-----------------

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.28

<	>
-----------------	-----------------

[IG-XL V8.30.00 Release Notes](#) : [Known Issues](#) : AC Instrumentation

AC Instrumentation

UltraWave External Field Calibration Crashes

While running UltraWave External Field Calibration (Power Transfer and VNA), data is written to the NVRAM on the instrument. During the NVRAM writing process, an intermittent error occurs that causes the calibration to crash.

Workaround: Do not run UltraWave VNA calibration in 8.30.00. Version switch to 8.10.00 to run UltraWave External calibration. Calibration data is valid between the versions.

A fix for this issue is planned in a future version of IG-XL.

UltraWave Error in Concurrent Test

If an UltraWave24 VNA instrument is used in a concurrent test flow, IG-XL may return an error of the form:

error MWVna : 00xx : No results found for "VNA_sig1" at "pin abc"

No workaround is available to prevent this error other than to use the UltraWave24 VNA instrument in a serial test flow.

A fix for this issue is planned in a future version of IG-XL.

<	>
-----------------	-----------------

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.29

<	>
-----------------	-----------------

[IG-XL V8.30.00 Release Notes](#) : [Known Issues](#) : Digital Instrumentation

Digital Instrumentation

Crash when Loading or Bursting Dual 2X Pattern with KeepAlive

Loading or bursting a pattern set that uses a keepalive module that was unloaded and loaded again can cause an internal error and crash. This can happen if the keepalive module was loaded in a prior job run, unloaded after the previous run, and loaded again for the current run. Unloading and reloading causes IG-XL to create a different keepalive object for the reloaded module, but the pattern set refers to the original keepalive object. The crash occurs when Pattern Loader tries to follow the stale pointer to the original object.

As a workaround, do either of the following:

- | | |
|--|--|
| | <ul style="list-style-type: none">Do not unload the keepalive module |
| | <ul style="list-style-type: none">Unload all loaded patterns, as this forces IG-XL to clean up stale references and to create new objects and new references |

A fix for this issue is planned for a future version of IG-XL.

<	>
-----------------	-----------------

ReadMe_V8_30_00_uflx.1.30

<	>
-----------------	-----------------

[IG-XL V8.30.00 Release Notes](#) : [Known Issues](#) : DSP

DSP

DSP PC Error

When running checkers, you may see the following error:

DSP:0173 : The installation verification failed for the library demoddsp.dll on DSP PC. The function SelfCheck implemented in the library returned the error code Error: hr (80004005). Re-installing the library might be required.

This error can occur if VSA is not installed properly. Please re-install VSA.

A clearer error message is planned for a future release of IG-XL.

<	>
-----------------	-----------------

	2015 Teradyne, Inc. All rights reserved.	
--	--	--

ReadMe_V8_30_00_uflx.1.31



[IG-XL V8.30.00 Release Notes](#) : [Known Issues](#) : Software Tools

Software Tools

Merging time domain into pin group raises error

On a Pin Map sheet, a time domain can be defined right after a pin group. If you merge the time domain into the pin group by deleting the time domain name, the row with the pin group name shows up with a red background and the error message "Illegal value in cell." Validation succeeds but does not clear the error.

A fix for this issue is planned for a future release of IG-XL.

Summary report has memory leak

If you try to generate a large amount of summary data after every run of a test program, there is a possibility of a memory increase for the datalog server process. This can lead to an "Out Of Memory" error. Therefore, generate a summary only infrequently, not at the end of every run.

A fix for this issue is planned for a future release of IG-XL.

Deletion in group followed by Undo corrupts DataTool sheet

DataTool sheets frequently group consecutive rows into a single item that can be collapsed or expanded. For example, on the Pin Map sheet, rows are grouped into pin groups and time domains; on the Levels sheet, the levels for each pin form a group.

If you expand the last group on the sheet, then delete one or more of the last rows in the group, and then execute Undo, the Undo does not always restore the group to its pre-deletion state. The Undo may cause the other existing rows to be corrupted or deleted. In some case, IG-XL may hang. This problem was identified in IG-XL V7.40.00. A fix for this issue is planned for a future release of IG-XL.

TrackTestTime add-in causes second Save query when exiting DataTool

A TrackTestTime.xla add-in is available from Teradyne applications. If a test program uses the .xla, you are queried twice about saving the file when you exit from DataTool. The first pop-up query is from IG-XL; the second is from Excel.

This occurs only under Excel 2010.

The work-around is as follows:

1. [Open the Visual Basic editor \(Alt+F11\).](#)
2. [In the Project Explorer, locate the](#) TrackTestTime.xla.
3. [Expand](#) Microsoft Excel Objects.
4. [Open](#) ThisWorksheet.
5. [Locate the function](#) Workbook_BeforeClose().
6. [Add this statement to the end of the function:](#)

[ActiveWorkbook.Saved = True](#)

[A fix for this issue is planned for the next release of the TrackTestTime add-in.](#)

[TheExec.VariableValue spec parameter requires an underscore](#)

[The VBT property](#) TheExec.VariableValue returns the current value of the specific spec. As documented, the spec parameter must be preceded by an underscore: for example, `_low_freq`. In releases before IG-XL V7.10.00, this requirement is enforced, and a spec name without a leading underscore returns an error. In V7.10.00, as a consequence of another change, this check was removed. In V8.00.00, the check was restored. As a result, a program that runs under V7.10.00 through V7.40.00 may return an error under V8.00.00 and later.

[In IG-XL V8.00.01 P2 and later, the leading underscore on the spec name is no longer enforced.](#)

[Note that use of](#) TheExec.VariableValue is not recommended, especially for production. Syntax for accessing spec values is available at TheExec.Specs in the VBT Syntax Reference.

[VNC connection settings required for IG-XL tools](#)

[If you are running IG-XL on a system that you are accessing through VNC, you must set certain VNC settings to ensure that certain aspects of the IG-XL tools function correctly.](#)

- [You must enable](#) Capture Alpha-Blending on the VNC server. This is required for the tooltips and other alpha-blending that the tools use, such as the "Needs refresh" window in PatternTool, HRAM Display, and Waveform Display.

- [You must disable clipboard transfer. Check](#) Disable clipboard transfer in the VNC viewer settings. This lets you use the PatternTool cut, copy, and paste operations, and other operations that use cut, copy, and paste, such as creating a new subroutine.

This issue was identified in IG-XL V8.00.00. Setting VNC correctly lets you use the tools features mentioned here without errors.

Windows 7 install window issue

Using the Windows 7 installer, if you minimize the install window and give focus to other windows, the install window is displayed when the install is complete. However, it is in the top left corner of the screen with only a small part visible.

The issue is associated with the Microsoft Windows Installer (MSI).

This issue only occurs when you minimize the install dialog window. If you bring the install dialog window to the background by giving the focus to another Windows dialog window, there is no issue with dialog positioning.

PatternTool launched from Pattern Control Display may not show pattern correctly

The Pattern Control Display (PCD) includes a control that allows you to launch PatternTool and view the current pattern in PatternTool. In some cases, however, patterns may not display correctly.

If you attempt to launch a pattern from the PCD, PatternTool will come up with the display empty if:

- The folder path in the PCD includes a space
- The selected pattern module in the PCD has an empty pattern path

A fix for this issue is planned for a future release of IG-XL.

PatternTool Crashes with refresh_subr Opcode and Relative Addressing

If your pattern uses the refresh_subr opcode with relative addressing, such as .+3 ("three vectors after the current vector"), and the location of the destination vector is greater than 1024, you may see the following behavior:

- Scrolling down through the pattern can cause PatternTool to crash.
- Reverse-compiling patterns can produce errors.
- In the reverse-compiled pattern, refresh_subr opcode is replaced the with the stop_subr opcode and an incorrect destination.

- A reverse-compiled pattern may not compile.

A fix for this issue is planned for IG-XL V9.00.00.

Datalogging duplicate test numbers in concurrent test

TNum values may be datalogged incorrectly during concurrent testing if:

- Subflows are burst concurrently and

- A test on a subflow leaves the TNum value blank on the Flow Table sheet, letting IG-XL automatically calculate the TNum value.

When running subflows concurrently, therefore, you should assign a TNum value for all tests on a Flow Table sheet that will be run concurrently. This avoids a risk of datalogging duplicate test number values.

A fix for this issue is planned for a future release of IG-XL.

“Document not saved” message with .xlsm workbook

This problem has been encountered in a small number of cases and occurs only under Windows 7 and Microsoft Excel 2010.

Using File>Save or Save As multiple times with a workbook with the .xlsm extension can cause a “Document not saved” error. If this error occurs, you lose any changes that you have made to your test program since the last successful save.

This is an issue with the way in which the Microsoft Excel 2010 VBA compiler handles static variables. Teradyne is awaiting a resolution from Microsoft.

If you encounter this problem with an .xlsm workbook, the current workaround is not to continue to work with it in .xlsm format. After terminating the processes, you can open the workbook again and immediately save it as an .xls file or as ASCII files. Then exit and proceed to work with the workbook in the new format.

A fix for this issue is planned for a future release of IG-XL.

Run buttons stop working after change that requires revalidation

The Run and Debug Run buttons in DataTool and the Run button in the Run Options dialog box may become unresponsive if you click Run (not Validate) after you make a change that requires revalidating the test program. The test program validates, but it does not run. After this, clicking any of the Run buttons does not run the test program.

After the Run buttons become inactive:

- **Enabling** Detailed test time profile from Run Options may reactivate the Run buttons. When you disable this option, the buttons become inactive again.

- Reloading the test program always enables the Run buttons.
- You can run your test program using the VBT method TheExec.RunTestProgram in the Immediate Window when the Run buttons are inactive.
- You can select a row in the Flow sheet, right-click that row, and select Run to cursor when the Run buttons are inactive.

When this condition occurs, IG-XL returns an error in the Output Window and the Datalog Window. As a workaround, move the following line from the OnProgramValidated interpose function to the OnValidationStart interpose function in your test program:

```
ActiveWorkbook.Worksheets("Home").Activate
```

This resolves the issue.

A fix for this issue is planned for a future release of IG-XL.

PatternTool stops working after inserting pins and data and then performing Replicate

In very specific circumstances, PatternTool stops working if you insert new pins into a pattern, paste data into the pattern, select vectors, and then replicate the vectors. This happens only when there are exactly 512 pins in the pattern, before you insert more pins.

The workaround is to save the pattern after inserting the pins and the data. You can then select and replicate vectors.

This issue was identified in IG-XL V8.00.00. A fix is planned for a future release of IG-XL.

		
	2015 Teradyne, Inc. All rights reserved.	

ReadMe_V8_30_00_uflx.1.32



IG-XL V8.30.00 Release Notes : Known Issues : Operating Environment

Operating Environment

Mouse scroll wheel does not work in VB Editor

In the VB Editor, the mouse’s scroll wheel has no effect. This is a problem with Microsoft’s IntelliPoint driver, version 5.xx. As a workaround, you can install a third-party scroll wheel enabler, such as FreeWheel or VBScroll (<http://www.gasanov.net/VBScroll.asp>). See <http://support.microsoft.com/?id=837910> for Microsoft’s suggested solutions for this problem.

SEDana installation issue

When you install a newer version of IG-XL, the installer also upgrades SEDana to a more recent version on your system. During this upgrade, an issue can occur that causes the new version of SEDana not to be installed correctly.

When upgrading IG-XL, the installer does the following:

1.

Uninstall the earlier version of SEDana if earlier version is older than the SEDana version being installed with IG-XL. (If the IG-XL version being installed uses the same version of SEDana, the older version of SEDana is not uninstalled.)
2.

Install the more recent version of SEDana.

So, for example, you are upgrading IG-XL from V8.00.01 to V8.10.10. In this case, the installer uninstalls SEDana version 3.6f and installs version 3.7e, which is supported by IG-XL 8.10.10. If you upgrade IG-XL and SEDana from local or network drive where you have write access to the installation package folder, SEDana will upgrade successfully. However, if you perform the upgrade installation from network drive where you do not have write access to installation package folder, the SEDana installation will not be successful. In this case, the

installer will uninstall the older version of SEDana, but it will not install the newer version. The result will be that you will not have any version of SEDana installed on your system.

When performing an upgrade to IG-XL and SEDana, therefore, make sure to download the IG-XL installation package to a local drive or server to which you have write access.

Lower screen resolution cannot display some dialog boxes

Teradyne recommends using a minimum screen resolution of 1024 by 768 (XGA) or higher when running IG-XL. You can use lower resolutions, such as 800 by 600, but such lower resolutions can create a problem. Some IG-XL dialog boxes, such as DataCollect Setup, are large and cannot be resized. At lower resolutions, these dialogs cannot fit within the screen, so that you cannot access some of their buttons. This can be an issue especially when accessing IG-XL remotely.

The workaround is to use the higher, supported screen resolution. If desired, you can use a vision-assist feature such as the Windows Magnifier.

When using Remote Desktop Connection, open the Options part of the window and go to the Display tab. Move the slider all the way to the right to **Large** to have the Full Screen used.

This relates to Case 364539.

Failure to update .NET Framework

Successful installation of IG-XL requires installation of the proper version of the Microsoft .NET Framework. If you are installing multiple versions of IG-XL, each installation may install a different version of .NET Framework.

For example, you do the following:

- | | |
|----|--|
| 1. | Install 8.20.00. The installation installs .NET Framework 4.0 on your PC. |
| 2. | Install 8.00.01. The installation installs .NET Framework 3.5 and the update for .NET Framework SP2. |

In this case everything should install correctly.

Uninstalling IG-XL also uninstalls the corresponding version of .NET Framework. For example, you do the following:

- | | |
|----|---|
| 1. | Uninstall all .NET Framework from the PC. |
| 2. | Install IG-XL V8.00.01. The installation installs .NET Framework 3.5 and the update for .NET Framework SP2. |

In this case everything should install correctly.

However, a problem can occur with the following sequence:

- | | |
|----|---|
| 1. | Uninstall all .NET Framework from the PC. |
| 2. | Install 8.00.01. |

First, installation installs .NET Framework 3.5. If installation is disturbed (either the installation is stopped before completion or .NET Framework is installed improperly), then installation of the update for .NET Framework 3.0 SP2 fails.

The failure occurs because update of .NET framework 3.0 SP2 needs a base version of .NET Framework to exist on the PC. Since the 3.5 version is not installed, an error is returned.

If the update for .NET framework 3.0 SP2 fails, do not continue the installation. Instead, click No to stop the installation and reinstall the IG-XL Setup. This installs .NET Framework 3.5, and the update of 3.0 SP2 should install correctly.

Failure installing previous version of IG-XL

If you have IG-XL V8.20.00 installed and attempt to install a previous version of IG-XL, such as V8.10.11, installation may seem to fail.

When you install an earlier version of IG-XL, the installer first unregisters the existing active version (V8.20.00, in this case). As part of unregistration, the following file is executed:

C:\Program Files (x86)\Teradyne\IG-XL\8.20.00_uflx\bin\igxlregbin.exe\unregserver

Execution of this unregistration file for IG-XL V8.20.00 typically takes 20 to 30 minutes and may take up to 2 or 3 hours. The lengthy execution time makes it appear that the installation process is hung.

This issue occurs when using Symantec version SEP 12.1.1.

The workaround for this issue is to install Symantec version SEP 12.1.4.

RelNotesCurDefTopic

<	>
---	---

IG-XL V8.30.00 Release Notes

IG-XL V8.30.00 Release Notes

These notes describe the updates, bug fixes, and known bugs in IG-XL V8.30.00 as of Thursday, January 22, 2015 (012215). This document includes changes and updates for V8.30.00.

This document includes the following sections:

- | | |
|---|--|
| • | Installing IG-XL V8.30.00 |
| • | Getting Assistance in eKnowledge |
| • | General Notes on V8.30.00 |
| • | What’s New in V8.30.00 |
| • | Migrating to IG-XL V8.30.00 |
| • | Bugs Fixed in V8.30.00 |
| • | Known Issues |

Release Notes from previous versions of IG-XL for UltraFLEX are also available. See [IG-XL Release Notes>Previous Release Notes in IG-XL Help](#).

<		>	
	2015 Teradyne, Inc. All rights reserved.		