Assignment 5: Control Charts for Attributes

- 1. A process is controlled with a fraction nonconforming control chart with three-sigma limits, n = 100, UCL = 0.161, center line = 0.080, and LCL = 0.
 - (a) Find the equivalent control chart for the number nonconforming.

$$CL = n\bar{p} = 100 \times 0.08 = 8$$

$$UCL = n\bar{p} + 3\sqrt{n\bar{p}(1-\bar{p})} = 100 \times 0.08 + 3\sqrt{100 \times 0.08 \times 0.92} = 16.139$$

$$LCL = n\bar{p} - 3\sqrt{n\bar{p}(1-\bar{p})} = 100 \times 0.08 - 3\sqrt{100 \times 0.08 \times 0.92} = -0.139$$

$$\therefore \text{ For the } np \text{ chart: } UCL = 16.139, \ CL = 8, \ LCL = 0 \text{ } \#$$

(b) Use the Poisson approximation to the binomial to find the probability of a type I error.

$$\begin{split} X &\equiv \text{the number of nonconforming} \\ X \sim Bin(n=100,p=0.08) \ \approx \ X \sim Poi(\lambda=8) \\ \alpha &= P\left(type\ I\ error\right) = 1 - P\left(X \leq 16.14\right) \\ &= 1 - \sum_{i=0}^{16.14} \frac{e^{-8}\ 8^x}{x!} \\ &= 1 - 0.9963 \\ &= 0.0037\ _{\#} \end{split}$$

(c) Use the Normal approximation to find the probability of a type II error if the process fraction nonconforming shifts to 0.2.

$$\begin{split} \beta &= P \left(type \ II \ error \right) = P \left(0 < \hat{p} < 0.161 \mid p = 0.2 \right) \\ &= \Phi \left(\frac{16.139 - 0.2}{\sqrt{\frac{0.08 \times 0.92}{100}}} \right) - \Phi \left(\frac{0 - 20}{\sqrt{\frac{0.08 \times 0.92}{100}}} \right) \\ &= \Phi (-1.44) - \Phi (-7.37) \\ &= 0.0749 \ _{\text{\#}} \end{split}$$

(d) What is the probability of detecting the shift in part (c) by at least the fourth sample after the shift?

$$P\left(detect\ the\ shift\ at\ least\ 4th\ sample\right) = 1 - P\left(no\ detect\ at\ first\ 4\ sample\right)$$

$$= 1 - \beta^4$$

$$= 1 - (0.0749)^4$$

$$= 0.99996\ _{\#}$$

- 2. A process is being controlled with a fraction nonconforming control chart. The process average has been shown to be 0.07. Three-sigma control limits are used, and the procedure calls for taking daily samples of 400 items.
 - (a) Calculate the upper and lower control limits.

$$CL = \bar{p} = 0.07$$

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1 - \bar{p})}{n}} = 0.07 + 3\sqrt{\frac{0.07 \times 0.93}{400}} = 0.108$$

$$LCL = \bar{p} - 3\sqrt{\frac{\bar{p}(1 - \bar{p})}{n}} = 0.07 - 3\sqrt{\frac{0.07 \times 0.93}{400}} = 0.032$$

$$\therefore \text{ For the } p \text{ chart: } UCL = 0.108, \ CL = 0.07, \ LCL = 0.032 \text{ } \#$$

(b) If the process average should suddenly shift to 0.10, what is the probability that the shift would be detected on the first subsequent sample?

$$\begin{split} 1-\beta &= P \left(detect \ on \ 1st \ sample \right) \\ &= 1-P(0.032 < \hat{p} < 0.108 \mid p = 0.1) \\ &= 1-\Phi \left(\frac{0.108-0.1}{\sqrt{\frac{0.1\times0.9}{400}}} \right) + \Phi \left(\frac{0.032-0.1}{\sqrt{\frac{0.1\times0.9}{400}}} \right) \\ &= 1-\Phi(0.53) + \Phi(-4.53) \\ &= 0.298 \ {\rm \#} \end{split}$$

(c) What is the probability that the shift in part (b) would be detect on the first or second sample taken after the shift?

$$P\left(detect\ on\ 1st\ or\ 2nd\ sample\right) = P\left(detect\ 1st\ sample\right) + P\left(detect\ 2nd\ sample\right)$$

$$= (1-\beta) + \beta(1-\beta)$$

$$= 0.298 + (1-0.298) \times 0.298$$

$$= 0.507\ _{\#}$$

- 3. In designing a fraction nonconforming chart with center line at p = 0.20 and three-sigma control limits, what is the sample size required to yield a positive lower control limit? What is the value of n necessary to give a probability of 0.50 of detecting a shift in the process to 0.26?
 - The sample size that required to yield LCL:

- \therefore The sample size that required is greater than 36 $_{\scriptscriptstyle \#}$
- The value of n necessary to give a probability of 0.50 to detect a shift to 0.26:

$$\Rightarrow 0.26 - 0.2 = 3\sqrt{\frac{0.2 \times 0.8}{n}}$$
$$\Rightarrow \left(\frac{0.06}{3}\right)^2 = \frac{0.16}{n}$$
$$\Rightarrow n = 0.16 \times \frac{9}{0.0036} = 400$$

 \therefore The value of n that necessary is 400 $_{\#}$