P0668、P0669

Description of fault diagnosis codes
P0668-11：SRC low for ECU temperature sensor
P0669-12：SRC high for ECU temperature sensor
Detection tools
1 Multimeter and diagnostic apparatus
Possible causes
• ECU damages
Description of circuit diagram
ECU temperature sensor is integrated in electronic control unit (ECU). The fault code indicates that the signal circuit voltage of control module internal temperature sensor is less than calibrated min. value or max. value.

Troubleshooting procedures		
Step 1	General inspection.	
		1 Check the fuse for damage. 2 Check battery capacity. 3 Check if there is any damage, bad contact, aging and looseness phenomenon on harness plug of engine control module and main relay. 4 Check whether the result is normal?
		No → Repair or replace the faulted parts.
Yes ↓		
Step 2	Check fault codes.	
		1 Connect the fault diagnosis instrument to diagnosis interface. 2 Turn the ignition switch to ON position. 3 Diagnose the engine control system with diagnostic apparatus. 4 If there is any fault code except for P0668-11/P0669-12?
		Yes → Refer to: DTC Summary List (EU5).
No ↓		
Step 3	Using fault diagnosis instrument to confirm whether the fault code is stored again.	
		1 Connect the fault diagnosis instrument to diagnosis interface. 2 Turn the ignition switch to OFF. 3 Clear the troubleshooting code. 4 Start the engine and idle for at least 5 minutes. 5 Again to the control system to read the fault code to confirm the system error-free code output. 6 Check whether the result is normal?
		No → Replace engine control module.
Next ↓		
Step 4	Complete the check and confirm whether the system works normally nor not.	