P2263

Description of fault diagnosis codes		
P2263-84：PCR negative governor deviation below limit		
P26E4-11：PCR positive governor deviation above limit		
Detection tools		
1 Multimeter and diagnostic apparatus		
Possible causes		
• Harness or connector fault • Air filter fault • Turbocharger fault • Inlet air leak • Exhaust leak • Fault in boost pressure temperature sensor		
Troubleshooting procedures		
Step 1	Check the air filter.	
		1 Check whether the air filter is blocked. 2 Check whether the result is normal?
		Yes → Repair or replace the faulted parts.
No ↓		
Step 2	Check the air inlet pipe.	
		1 Check whether the air inlet pipe is blocked. 2 Check whether the result is normal?
		No → Repair or replace the faulted parts.
Yes ↓		
Step 3	Check the exhaust leakage.	
		1 Check whether the exhaust pipe is leaking. 2 Check whether the result is normal?
		No → Repair or replace the faulted parts.
Yes ↓		
Step 4	Check the boost pressure and temperature sensor.	
		1 Check the boost pressure and temperature sensor. 2 Check whether the result is normal?
		No → Replace the boost pressure temperature sensor.
Yes ↓		

Step 5	Check the turbocharger.	
		1 Check whether the turbocharger is damaged. 2 Check whether the result is normal?
		No → Replace the turbocharger.
Yes ↓		
Step 6	Check fault codes.	
		1 Connect the fault diagnosis instrument to diagnosis interface. 2 Turn the ignition switch to ON position. 3 Diagnose the engine control system with diagnostic apparatus. 4 Is there any other fault code except for P2263?
		Yes → Reference: DTC Summary List (EU5).
Next ↓		
Step 7	Complete the check and confirm whether the system works normally nor not.	