3012 Jasper Blvd

After Action Review

Prepared by: Captain Shane Himes, Engine Company 501-A

ATTITUDES TO FOSTER
(AFTER ACTION REPORT (AAR) MPFD SOP 201.07)

The AAR is not to be used to assign fault and responsibility but an opportunity to learn from our mistakes. Each person should feel that they are free from ridicule or harassment when voicing what they saw and did at the incident. The IC should use positive reinforcement to address less than expected behavior. Likewise, responders should not ridicule command decisions. Each person should realize that actions and decisions on an emergency scene are made with the best of intentions. However, mistakes may happen and can be avoided in the future by conducting AARs on a regular basis. The practice of conducting AARs will further our experience in a positive way. It will help everyone learn from everyone else's mistakes and add to their knowledge base by reviewing the advantages they saw and did at an emergency scene.

Weather

At 1800 2/22/2025

- Partly Cloudy
- Temperature: 52°F
- Winds: 7 mph SE
- Humidity: 57%
- Precipitation: 0%


3008 SC-703
Sullivan's Island, South Carolina
View on Google Maps
https://www.google.com/intl/en-US_US/help/terms_maps.html
Keyboard shortcuts
© 2025 Google
Terms
Report a problem




TRASH
U2 831205




703
Jasper Blvd
Middle St
Middle St
Station 31 St
Middle St
Middle St
Keyboard shortcuts
Map Data ©2025 Imagery ©2025 Airbus,


703
RS504
T1002
E1201
E501
Jasper Blvd
L503
E502
E503
Middle St

ARRIVAL	COMPANY	ASSIGNMENT	DUTIES (OFFENSIVE)	DUTIES (DEFENSIVE)
18:10:07	E1201	1st Engine	300’ 1.75” (Yellow), Charlie (EXT)	2.5”?, Delta (EXT)
18:10:08	E501	1st/2nd Engine	Initiated Command, 300’ 1.75” (Red), Alpha (DIV1), Established Water Supply (Jasper/30)	2.5”, Alpha (EXT), Overhaul 1.75” (White) Alpha (DIV2ROOF)
18:11:05	TW1002	1st Aerial	Split Crew, Search, Alpha (DIV1), Deployed 1.75” (Blue)	Elevated Master Stream Alpha/Delta
18:13:12	C1201	1st Chief	Incident Command, Charlie	Incident Command
18:14:45	BC508	2nd Chief	Safety, Charlie	Safety/Interior
18:15:20	BC1006	3rd Chief	Alpha	Alpha
18:19:32	E503	4th Engine	300’ 1.75” (Yellow) Charlie (DIV2/EXT)	
18:20:37	E502	3rd Engine	Initated RIT, Alpha, 250’ 1.75” (Blue), Alpha (DIV2/3)	250’ 1.75”, (Blue) Alpha (DIV2/3)
18:21:56	RS504	1st Rescue	Split, Overhaul, Alpha (DIV1/3)	1.75” (Red), Bravo (EXT) Split, Overhaul, Alpha (DIV2/3)
18:24:43	L503	2nd Aerial		Assisted E501 with 1.75” (White)
18:41:48	E505	5th Engine		Assisted Water Supply to TW1002, 1.75”?, Charlie (EXT), Overhaul (DIV1/2)

Engine 1201

1st Arriving Engine Company

Engine 501

1st/2nd Arriving Engine Company

Tower 1002

1st Arriving Ladder Company

Chief 1201

1st Arriving Chief Officer

Battalion 508

2nd Arriving Chief Officer

Battalion 1006

3rd Arriving Chief Officer

Engine 502

2nd/3rd Arriving Engine Company

Engine 503

4th Arriving Engine Company

Rescue 504

1st Arriving Rescue Company

Ladder 503

2nd Arriving Ladder Company

Engine 505

5th Arriving Engine Company

Engine 116

6th Arriving Engine Company









1. WHAT WAS OUR MISSION?

- Had we planned for this event?
- Were there any gaps in our planning?

2. WHAT WENT WELL?

- Did we have the resources for conducting this event?
- Did we do all we could to make this a successful operation?

3. WHAT COULD HAVE GONE BETTER?

- Did we see any unsafe behaviors?
- Did our training prepare us?

4. WHAT MIGHT WE HAVE DONE DIFFERENTLY?

- **If you ran the same incident today what would be done differently?**

5. WHO NEEDS TO KNOW?

First 30 Minutes

18:03:26	WIRELSS CALL, CALLER STATING FIRE
18:08:43	E501 SEES SMOKE OVER THE BEN SAWYER REQ 3 ENGINES AND A LADDER
18:10:05	E501 REQ TO SHUT DOWN JASPER FOR HOSE
18:10:07	E1201 At Scene, HEAVY SMOKE SHOWING
18:10:08	E501 At Scene, ELEVATED 2 STORY RESD SMOKE FROM GARAGE B/C SIDE, STRETCHING LINES WITH SIFD, E501 HAS CMD
18:11:05	TW1002 1ST DUE AERIAL
18:11:19	ANIMALS TRAPPED INSIDE PER CMD
18:12:48	E501 MAKING ENTRY, A SIDE
18:13:12	C1201 At Scene, HEAVY FIRE AT REAR
18:13:56	E1201 CHARGING YELLOW ATTACK LINE
18:14:45	BC508 At Scene, ASSUMING SAFETY
18:14:56	E501 HAS WATER ON FIRE, DIVISION 1
18:15:20	BC1006 At Scene
18:19:32	E503 At Scene, 4TH DUE ENGINE
18:19:49	E501 FIRE KNOCKED DOWN DIVISION 1
18:20:37	E502 At Scene, 3RD DUE ENGINE
18:20:49	SAFETY HEAVY FIRE DIV 3 POSS THE ATTIC
18:21:32	SAFETY NEXT ARRIVING UNIT TO ASSUME RIT
18:21:56	RS504 At Scene, 1ST DUE RESCUE
18:23:43	***13 MIN TIME STAMP***
18:24:16	E501 BULK OF FIRE KNOCKED DOWN, HITTING HOT SPOTS
18:24:42	CHARGING THE BLUE LINE
18:24:43	L503 At Scene, 2ND DUE AERIAL
18:24:57	E502 ENTRY Xs 3
18:25:16	BC1006 DIV 1 CLEARED
18:26:25	SAFETY STILL HAS FIRE DIV 3 B/C CORNER
18:26:41	BC1006 HEAVY FIRE A/B CORNER ALSO
18:27:01	HEAVY FIRE INSIDE HAS EXT INTO CEILING
18:27:51	SAFETY FIRE IS SELF VENTING B/C CORNER DIV 3
18:28:16	BC504 SEND NEXT 2 CLOSEST ENGINES
18:30:19	***20 MIN TIME STAMP***
18:32:36	RS504 CREW IS ON DIV 2, SAFETY ADV FOR E502 CREW TO MOVE TO DIV 2
18:35:05	SAFETY STARTING EXT ATTACK FROM DIV 3
18:35:16	E1201 HEAVY FIRE THRU ROOF A SIDE
18:36:43	SAFETY RECOMMENDS PULLING EVERYONE OUT
18:37:42	EVAC TONES DROPPED
18:41:11	****30 MIN TIME STAMP***

After the first 30 minutes

18:41:11	****30 MIN TIME STAMP***
18:41:48	E505 At Scene, 5TH DUE ENGINE
18:47:18	SAFETY STRUCTURAL COLLAPSE B/C CORNER DIV 3
18:50:09	LADDER IN THE AIR
18:50:37	***40 MIN TIME STAMP***
18:54:03	E116 At Scene, 6TH DUE ENGINE
18:54:26	E505 SENDING WATER
18:55:13	TW1002 HAS WATER EST
18:55:28	TW1002 OPENING THE WATER
19:00:32	***50 TIME STAMP***
19:01:12	SAFETY REQ CCRS REHAB
19:10:46	***60 MIN TIME STAMP***
19:11:37	TW1002 BULK OF FIRE KNOCKED DOWN, FULL ROOF COLLAPSE
19:11:55	SAFETY SHUTTING DOWN ALL EXT LINES
19:12:54	SAFETY COMPLETE COLLAPSE OF ROOF LINE DOWN TO DIV 3
19:13:34	ACTIVE FIRE C SIDE IN DORMER AND IN GARAGE
19:13:52	SAFETY ATTEMPTING TO TRANSITION TO INTERIOR
19:14:00	DOMINON IS PULLING THE METER B SIDE
19:14:34	E502 ENTERING Xs 3 DIV 2
19:18:36	SAFETY INTERIOR WITH E502 CREW/
19:18:49	BC1006 ASSUMING SAFETY ON A SIDE
19:19:44	C1201 ADV DOG ON 2ND DIV/ D/C SIDE OF HOME
19:20:18	E502 DEBRIS AROUND STAIRS WITH FIRE ABOVE
19:20:35	***70 MIN TIME STAMP***
19:21:05	SAFETY ROOF IS STARTING TO LIGHT UP AGAIN
19:21:40	CMD ROOF ON B/C SIDE LIGHTING UP AGAIN
19:21:52	L503 SAME ON D SIDE
19:27:53	STILL A GOOD AMT OF FIRE DIV 3 C SIDE
19:28:14	BC508 ALL PERSONNEL HAVE EXITED THE STRUCTURE
19:30:53	***80 MIN TIME STAMP***
19:50:15	FIRE IN EAVES ON B SIDE
21:21:01	C1201 FIRE UNDER CONTROL