

GYLON Gasket Installation & Maintenance Manual

1. Pre-Installation Requirements

- Clean flange surfaces thoroughly
- Inspect for damage, warping, or corrosion
- Ensure flange flatness within ASME B16.5 tolerances
- Check bolt threads and lubricate as needed

2. Gasket Selection & Preparation

- Verify gasket dimensions match flange size
- Check material compatibility with process fluid
- Store gaskets flat in dry conditions
- Handle with clean gloves to avoid contamination

3. Installation Procedure

Step 1: Center gasket on flange face

Step 2: Insert all bolts finger-tight

Step 3: Apply torque in star pattern sequence

Step 4: Tighten in 3-4 passes to final torque

Step 5: Allow gasket to relax 4-24 hours

Step 6: Re-torque bolts before startup

4. Torque Specifications

GYLON 3500 Recommended Torque Values:

- 1/2" bolts: 40-50 ft-lbs
- 5/8" bolts: 70-80 ft-lbs
- 3/4" bolts: 120-140 ft-lbs
- 7/8" bolts: 180-200 ft-lbs
- 1" bolts: 260-280 ft-lbs

5. Maintenance & Inspection

- Inspect for leaks during initial startup
- Monitor bolt tension periodically
- Re-torque after thermal cycling
- Replace gasket if leakage occurs