TrustMark Quality Assurance Non-Compliance Report

Property Address	280 Dallow Road Luton Bedfordshire LU1 1TD
Date of Audit	08/05/2026
QA Auditor	
Project Number	P419977

Installer Report

Created: 10 Aug 2026 09:51

Notification of quality assurance non-compliance

Business Name	TMLN	Project Reference	Date of Inspection
Network Survey Limited	3937934	P419977	08/05/2026
Property Address	280 Dallow Road, Luton, Bedfordshire, LU1 1TD		

Remedial evidence must be provided to TrustMark within 8 weeks or 24 Hours for CAT1 Non-Compliances. Evidence must clearly show the specific remedial work and any other context that is relevant to the non-compliance. All photographic evidence must be Geotagged and Date stamped.

UMR	Measure Name	Work Date
P4199773MXD	Solid wall - External Insulation	23/08/2025
Non-Compliance Reason	EWI - Gas entry tee clearances not achieved	

EWI - Gas entry tee clearances



There are non-compliances regarding a minimum of 250mm clearance above the gas delivery pipe entry tee. This has not been achieved in line with detail 8b of the Specification for the installation of External Wall Insulation ensuring the safety and operation of fuel burning appliances. This is located towards the front of the side elevation.

What to do next:

As the Retrofit Installer for this project please ensure that the work is remediated within the timescales stated above. Ensure that photographic evidence (Geotagged) is provided to the Retrofit Coordinator to upload to the Data Warehouse - Retrofit Portal.

For any technical queries please contact your Scheme Provider in the first instance.
To appeal or discuss any non-compliances please contact **retrofitcoordination@trustmark.org.uk**

Notification of quality assurance non-compliance

Business Name	TMLN	Project Reference	Date of Inspection
Network Survey Limited	3937934	P419977	08/05/2026
Property Address	280 Dallow Road, Luton, Bedfordshire, LU1 1TD		

Remedial evidence must be provided to TrustMark within 8 weeks or 24 Hours for CAT1 Non-Compliances. Evidence must clearly show the specific remedial work and any other context that is relevant to the non-compliance. All photographic evidence must be Geotagged and Date stamped.

UMR	Measure Name	Work Date
P4199773MXD	Solid wall - External Insulation	23/08/2025
Non-Compliance Reason	EWI - Weathering concern	

EWI - Weathering concern



Weathering concern where the threshold sill to the kitchen door on the rear elevation has detached.

EWI - Weathering concern



Context view

What to do next:

As the Retrofit Installer for this project please ensure that the work is remediated within the timescales stated above. Ensure that photographic evidence (Geotagged) is provided to the Retrofit Coordinator to upload to the Data Warehouse - Retrofit Portal.

For any technical queries please contact your Scheme Provider in the first instance.
To appeal or discuss any non-compliances please contact **retrofitcoordination@trustmark.org.uk**

Notification of quality assurance non-compliance

Business Name	TMLN	Project Reference	Date of Inspection
Network Survey Limited	3937934	P419977	08/05/2026
Property Address	280 Dallow Road, Luton, Bedfordshire, LU1 1TD		

Remedial evidence must be provided to TrustMark within 8 weeks or 24 Hours for CAT1 Non-Compliances. Evidence must clearly show the specific remedial work and any other context that is relevant to the non-compliance. All photographic evidence must be Geotagged and Date stamped.

UMR	Measure Name	Work Date
P4199773MXD	Solid wall - External Insulation	23/08/2025
Non-Compliance Reason	EWI Observation - Other - Please see caption	

EWI - Other Observation



The kitchen extract vent installed to the rear left-hand corner of the kitchen is not well sealed internally and is draughty

EWI - Other Observation



Context view

What to do next:

As the Retrofit Installer for this project please ensure that the work is remediated within the timescales stated above. Ensure that photographic evidence (Geotagged) is provided to the Retrofit Coordinator to upload to the Data Warehouse - Retrofit Portal.

For any technical queries please contact your Scheme Provider in the first instance.
To appeal or discuss any non-compliances please contact **retrofitcoordination@trustmark.org.uk**