

DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL

Issue No. 02	Rev. No: 00	Effective Date: 01.11.2019	SOP	/MEC	/181
			,	,	, – – –

Issued By: M.R Approved By: HOD-Mechanical

SOP for Replacement of mill feed flap gate

Scope: This SOP is applicable for Safe working of Standby Mill Feed rotary air lock jam clearing

Work

Responsibility: Section Engineer. **Accountability:** Section Head

PPE:

1. Safety helmet

2. Safety shoe

3. Dust mask

4. Cotton Knitted hand Gloves

5. Ear Plug

6. Full Body harness

7. Goggles

Tools:

1. Spanner set-1 no

2. Poking tools

Hazards:

Risks associated

Mitigating Measures

Hot gas and Fine Dust Wear Goggles and Dust Mask

Training needs:

1. Emergency preparedness

2. On job training

Isolation Required:

• Local isolation for Rotary air lock (mushroom lock) or LOTO

Procedure

- 1. Ask CCR people to keep standby RAL in local mode.
- 2. Create permit with local isolation (mushroom lock)
- 3. Rotate RAL in reverse/forward direction wherever it trips with wet/lump material.
- 4. If it does not rotate, or any major problem take LOTO permit.
- 5. Lock the rotor blade with locking bolt (locking bolts are in casing).
- 6. Open RAL side door and remove accumulated material.
- 7. Don't insert any body part inside RAL casing.
- 8. After removing the jam material, check the RAL blades condition and gap.



DALMIA CEMENT (B) LIMITED - ARIYALUR



MECHANICAL

Issue No. 02	Rev. No: 00	Effe	ctive Date: 01.11.2019	SOP/MEC/181		
Issued By: M.R			Approved By: HOD-Mechanical			

SOP for Replacement of mill feed flap gate

- 9. Clear LOTO permit and rotate in reverse direction in local mode.
- 10. Check the current at empty load.
- 11. When RAL is free, close the man whole door and ask the CCR people to take it in sequence.

Emergency / Emergency Shut OFF:

If any injury takes place, provide First aid and inform to the Safety department or Call Emergency number 3108/9865152222

Records/Annexure:

1. Refer Line clearance certificates. JSA as enclosed below