SERVICE REPORT

JOB NO : 2727 0 1 - 0 0 1 4 1

Customer PRICON MICROELECTRONICS INC.	Date 23-JULY-2016
Person-In Charge MR. GAMBOA Dept ENG'G.	P.O. No
Tel Fax	Remark SV-1607006

Job Title MACHINE CHECKING

Model NC1-8(2)-18 S/No 00208-7119 Instal/Date 1998 (MFD)

Problem
1. SINGLE MODE OF OPERATION MACHINE SLIDER STOP AT 347 DEGREE AT MAXIMUM SPM.
2. LIGHT CURTAIN SENSOR FUNCTIONING ONLY AT 10 DEGREE TO 190 DEGREE OF MACHINE SLIDER POSITION.

Measures
1. NORMALLY THIS MACHINE DESIGNED THAT THE LIGHT CURTAIN SENSOR FUNCTION AT 0 DEGREE (START) TO 180 DEGREE. PLEASE TAKE NOTE THAT THIS MACHINE ~~THE MACHINE~~ ARE DESIGNED FOR HALF CYCLE ONLY TO FUNCTION THE LIGHT CURTAIN SENSOR.
2. CALIBRATION OF SINGLE MODE OPERATION SLIDER STOP AT 357 DEGREE BECAUSE 0 DEGREE IS IMPOSSIBLE FOR THE MACHINE AS PER NOW ELECTRICAL PARTS CONDITION.
3. THE LIGHT CURTAIN SENSOR START FUNCTIONING AT 357 DEGREE TO 177 DEGREE.

Date	Man	Dep	AIDA	Arv	Cus	Dep	Cus	Arv	AIDA	Normal	1½	2	Job Done by
23 JULY		7	00	8	30	12	30	13	30		4		GEORGE

SPARE PART	Qty	U/Price	Amount
LABOUR CHARGES [NORMAL]			
[1½]	4	US$ 37.5	US$ 150
[2]			
TRANSPORT	1	US$ 25	US$ 25
PACKING & DELIVERY CHARGE			
VAT			
TOTAL			US$ 175

Remark
1. AUXILIARY RELAY CR10 HARNING AND BOTH.
2. LIMIT SWITCH FOR ROTARY NEED TO CHANGE.
3. DR 2 UNIT AND EAC UNIT NEED TO CHANGE.
4. ALMOST ALL CR RELAYS NEED TO CHANGE

Authorised	Confirm	Incharge
		G. [illegible], JR/M.

Work carried out to our complete satisfaction

CHARGEABLE

Checked & confirmed by
Name RODERICK T. GAMBOA
Post SR. ENGINEER
Sign
Date 7-23-16

Company Name/Stamp

AIDA GREATER ASIA PHILIPPINES, INC.

CUSTOMER COPY