SERVICE REPORT

JOB NO : 2727 0 1 - 0 0 1 4 2

Customer PRICON MICROELETRONICS INC.	Date 28-JULY-2016
Person-In Charge MR. GAMBOA Dept ENG'G.	P.O. No
Tel Fax	Remark SV-1607007

Job Title MACHINE CHECKING

Model NC1-4(2)-B S/No 00204-0220 Instal/Date 1989 (MFD)

Problem
1. SINGLE MODE OF OPERATION MACHINE SLIDER AT 350 DEGREE AT MAXIMUM SPM.
2. LIGHT CURTAIN SENSOR FUNCTIONING AT ~~0~~ 5 DEGREE TO 185 DEGREE OF THE MACHINE SLIDER POSITION.

MEASURE
1. NORMALLY THIS MACHINE DESIGNED THAT THE LIGHT CURTAIN SENSOR FUNCTION AT 0 DEGREE (START) TO 180 DEGREE.

Measures
PLEASE TAKE NOTE THAT THIS MACHINE ARE DESIGNED FOR HALF CYCLE ONLY TO FUNCTION THE LIGHT CURTAIN SENSOR.
2. CALIBRATION OF SINGLE MODE OPERATION SLIDER STOP AT 357 DEGREE BECAUSE 0 DEGREE IS IMPOSSIBLE FOR THIS MACHINE AS PER NOW ELECTRICAL PART'S CONDITION.
3. THE LIGHT CURTAIN SENSOR START FUNCTIONING AT 357 DEGREE TO 177 DEGREE.

Date	Man	Dep	AIDA	Arv	Cus	Dep	Cus	Arv	AIDA	Normal	1½	2	Job Done by
23 JULY		12	30	13	00	17	30	19	00		4.5		GEORGE

SPARE PART	Qty	U/Price	Amount
LABOUR CHARGES [NORMAL]	4.5	US$37.5	US$168.75
[1½]			
[2]			
TRANSPORT			
PACKING & DELIVERY CHARGE			
VAT			
TOTAL			US$ 168.75

Remark
1. AUXILIARY RELAY OR IS HAMMING/NOISY BUT ALMOST ALL CR RELAYS NEED TO CHANGE.
2. LIMIT SWITCH FOR ROTARY NEED TO CHANGE.
3. DR2 AND TAL UNIT NEED TO CHANGE

Authorised	Confirm	Incharge
		GLACIDE, JR. M.

Work carried out to our complete satisfaction

CHARGEABLE

Checked & confirmed by
Name Roderick A. Gamboa
Post SR. Engineer
Sign
Date 7-23-16

Company Name/Stamp

AIDA GREATER ASIA PHILIPPINES, INC.

CUSTOMER COPY