FANUC PHILIPPINES CORPORATION (PEZA REGISTERED)

FANUC

Unit 1 Orient Goldcrest Bldg. 10 Lot4, Block 1, Phase 7A, Laguna Technopark Inc.
Tel. Nos.049-546-0178/79
Fax No.049-546-0180

Quotation (Revised)

PRICON MICROELECTRONICS, INC.
No.14 Ampere St. Brgy. Diezmo
Light Industry and Science Park 1, Cabuyao, Laguna
Tel No.: 843-0864 to 70/ (049) 544-9221
Fax No.: 889-5015 / 889-5274

Ref No : QT0006488-01
Date : Mar 22, 2022
MR No G03333700
SR No 15887

Attn : Ms. Anna Marie Nueva (amnueva@pricon.ph)
Ms. Rebecca Valenzuela (rdvalenzuela@pricon.ph)

In compliance with your esteemed inquiry, we are pleased to quote you as follows:

Payment Terms : **Net 30 Days after Invoice Date**
Specification : As specified below.
Remarks : Prices are Subject to change without Prior Notice.
Quotation valid only within one month from the date hereof.
Please issue PO the soonest.

Thank you and await for your prompt and valuable order.

HISAO SATO
MANAGING DIRECTOR

ITEM NO.	DESCRIPTION/SPECIFICATION No.	QTY (Hrs/Pcs)	UNIT PRICE (PHP)	AMOUNT (PHP)
1	A06B-6087-H126 (Trade-in) PSM-26	1	262,000.00	262,000.00
2	Basic Charge RENDERED FOR TOYOSK	1 Lot	12,500.00	12,500.00
	TOTAL			**274,500.00**

Confirm :

FANUC POLICY PROHIBITS THESE PRODUCTS FROM BEING USED FOR THE DEVELOPMENT, PRODUCTION, USE OR STOCKPILING OF WEAPONS OF MASS DESTRUCTION (NUCLEAR WEAPONS, BIOLOGICAL WEAPONS, CHEMICAL WEAPONS OR MISSILES).FURTHER, RE-EXPORT TO ANOTHER COUNTRY MAY BE SUBJECT TO THE LICENSE OF THE COUNTRY FROM WHERE THE PRODUCT IS RE-EXPORTED.

FANUC PHILIPPINES CORPORATION

FANUC

Unit 1 Orient Goldcrest Bldg. 10, Lot 4, Block 1, Phase 7A,
Laguna Technopark Inc., Biñan, Laguna
Tel No. (049) 546-0178 / 79 * Fax No. (049) 546-0180

Service Report No. 15887
MR No. 683333 700, complete

PRICON MICROELECTRONICS, INC.
Cabuyao, Laguna
LISP 1

Date	03/18/2022					
	Hrs.	Mins.	Hrs.	Mins.	Hrs.	Mins.
Leave Office	10	30				
Time In	11	00				
Time Out	12	00				
Arrive Office						

Service Request by:				Service by	J. DE GUZMAN / J. BATHAN
CNC Model	FS 21 MB			Serial No.	E9850563 7
MTB	TOYOSK	Model	TVT 30 J	Serial No.	J-197 (MC 1)

Work Request

ALARM 414 ON ALL AXIS (X, Y, Z)
ALARM 751 : SP-1 ALARM DETECT (AL-51 ON SPM)
ALARM 4 ON PSM

Phenomena, Cause, Step

STEPS:

1. CHECKED MACHINE CONDITION → ALARM OCCURED DURING READY CONDITION
2. REPLACED PSM A06B-6087-H126 → OK NO MORE ALARM DURING READY CONDITION
3. PERFORMED DRY CYCLE → AL-1042 ABNORMAL LUBRICATION PRESSURE. OCCURED AFTER ONE CYCLE.
4. TRIED TO REFILL LUBRICATION OIL & RESET INSTANT FEED BUTTON ON LUBRICATION → STILL SAME.

NOTE! PLEASE CONTACT MTB FOR LUBRICATION PROBLEM.

Used Parts

Item	Description	Specification No.	Qty.
1	PSM	A06B-6087-H126-R	1pc.
		SN: V005 15701 (Trade-in)	

E. Valenzuela 3-18-22

Customer's Signature over Printed Name