**Sodick**

**SODICK PHILIPPINES INC**
**Company Regn : CS201501353**
**Company Tin : 008-944-890**
M201 Unit,GRM Bldg.,124 East Science Ave.,cor Trade Ave.,
Laguna Technopark, Binan City, Laguna 4024
TEL#: (049) 544 0936

**№ 001565**

# SERVICE REPORT

(2005.7)

| | | | |
|---|---|---|---|
| CUSTOMER : | Pricon | MACHINE : | HR55EH2 S/N FOG2 |
| PERSON IN CHARGE : | | CONTROLLER : | S/N |
| COUNTRY : | Phils. | SOFTWARE VER. : | 60.05.071 (HMI) |
| INSTALLATION DATE: | | OPTION : | AWT.ATC. OTHERS : |

| SERVICE DATE | STARTING TIME | FINISHING TIME | TOTAL TIME | ENGINEER |
|---|---|---|---|---|
| Nov. 26, 2018 | 2:00Pm | 3:30 Pm | 1 HR 30 MIN | Avel |
| | | | HR MIN | |
| | | | HR MIN | |

**MATTER OF REQUEST / NATURE OF PROBLEM**

E250233; Temperature Control Abnormal
E00717; Eject Amp. Fault Error (OV)

SD: 25
PD: 22

**DESCRIPTION OF SERVICE**

- Check switching Regulator 15-5-15 volt input ⇒ Ok
  ↳ but no output
- Replace switching regulator from machine #7 (FOG1).
- temp. control abnormal back to normal.
- Replacement of Eject Amp. from (FOG1)
- Testrun & Function ⇒ Ok

Necessary Change of: (FOR FOG1)
Switching Regulator: VT15-5FF
Servo Amp: S6DM-10AC-SD2B-R

| | | | |
|---|---|---|---|
| ☐ WARRANTY | ☑ SERVICE CHARGE | ☑ COMPLETED | ☐ MONITORING |
| ☐ F.O.C | ☐ SERVICE CONTRACT | ☐ NOT COMPLETE | RE-ARRANGE DATE: |

| PARTS CODE | DESCRIPTION | QTY | PARTS CODE | DESCRIPTION | QTY |
|---|---|---|---|---|---|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

**SODICK PHILIPPINES, INC.**

A. CIRIACO
*Engineer*

*Signature / Company's Stamp*

Service's Copy