SODICK PHILIPPINES INC
Company Regn : CS201501353
Company Tin : 008-944-890
M201 Unit,GRM Bldg.,124 East Science Ave.,cor Trade Ave.,
Laguna Technopark, Binan City, Laguna 4024
TEL#: (049) 544 0936

№ 002173

SERVICE REPORT

CUSTOMER : PRICON		MACHINE : TR40EHV	S/N 5137
PERSON IN CHARGE :		CONTROLLER : TRDG	S/N
COUNTRY : PHILS.		SOFTWARE VER. : 70.13.033	
INSTALLATION DATE 2007.7		OPTION : AWT.ATC. OTHERS :	

SERVICE DATE	STARTING TIME	FINISHING TIME	TOTAL TIME	ENGINEER
FEB. 18, 2020	10:00AM	4:00PM	6 HR - MIN	AVEL
FEB 19 2020	10:00AM	2:00pm	4 HR - MIN	AVEL
			HR MIN	

MATTER OF REQUEST / NATURE OF PROBLEM

SYSTEM ERROR

SD : 22
PD : 22
Total : 4049
Opt : 20.0 H

DESCRIPTION OF SERVICE

- Replacement of Switching Regulators (9pcs.)
- Switching Regulator voltage check
- Replace Hmi unit - C
- Version Up Software
- Data Restore

New Software

Hmi	70.13.033
IF-Hmi	0761
mpc-SH	74.02.ydc2
IF-SH	0761
mp	74.01.006
mp Firm	0250 0000
Hmi Boot	70.07.6 70.01.6
OS	7.40

☐ WARRANTY	☑ SERVICE CHARGE	☐ COMPLETED	☐ MONITORING
☐ F.O.C	☐ SERVICE CONTRACT	☐ NOT COMPLETE	RE-ARRANGE DATE:

PARTS CODE	DESCRIPTION	QTY	PARTS CODE	DESCRIPTION	QTY
2C44551PT	Sw. Reg. (LCA30S-24-Y)	1Pc.	2C44553PT	Sw. Reg. (LCA100S-5)	1Pc.
G32334QPT	Sw. Reg. (LDC15F-2-Y)	1Pc.	2C44552PT	Sw. Reg. (LCA30S-3 (NC)	1Pc.
2C44010PT	Sw. Reg. (VS15C-24)	1Pc.	2C44006PT	Sw. Reg. (VS30C-12)	1Pc.
2C44548PT	" (LCA100S-24-Y)	1Pc.	P7196A	SP Parts set (Hmi unit-C)	1Pc.
2C44302PT	" LCA30S-5-Y)	1Pc.	2C5C108PT	Compact Flash (DCA HMI2)	1Pc.

SODICK PHILIPPINES, INC.

Avel Cleto
Engineer

ALJHUN P. ANONUEVO
Signature / Company's Stamp

Service's Copy