NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase7
Laguna Technopark-SEZ, Biñan, Laguna Tel. No.: (049) 544-5670 Fax No: (049) 544-5647

SERVICE REPORT

No.: A 0423

Customer: PRICON MICROELECTRONICS INC. **Date:** 04 / 10 / 17

Model: NEX50-5E **Mfg. yy/mm:** 2012.01

Serial Number: H0051109BK1 **Gts.:** 3970257

Controller: TACT

Reason for Maintenance

- machine alarm with:
- 55457: ejector axis amp. control voltage abnormal
- 55157: inj axis amp. control voltage abnormal
- 55257: mtg axis amp. control voltage abnormal
- 53357: clamp axis amp. control voltage abnormal
- 54103: inj axis encoder error
- 5515F: inj axis driver error (servo processor/memory/CPU)
- 5525F: mtg axis driver error (servo processor/memory/CPU)
- 54303: clamp axis encoder error
- 5535F: clamp axis driver error
- 5F201: inverter1 communication
- 54403: no response ejector axis encoder error

Action Taken

- found short circuit on NFB29 (no fuse breaker); w/ output connection of 220VAC
- removed wirings (no attachment on control panel)
- arranged wiring harness for overdrive connection (24VDC)
- power on/test run/confirmation
- all machine movements are functional

SERVICE BY:

1 X. RAMIREZ

2 N. NISHIZAWA

TIME:

Start	End
10 : 20	11 : 30

Total: 1H 10 mins. Hours

Authorized Signature

Service Fee: ₱ 4,000.00

Illustration

- for request of new grease (LUBE NS-1-7) & replaced old grease (for quotation)

SQ No. _____ PO No. _____ SI No. _____ OR No. _____